

12/28/2017
4:43:44PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169536 2008 FORD F350 Utility Body, 1 Ton, 4X4, Vise

Workorder: 747742 **Problem:** PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts
In Date: 11/27/2007	Hours	Description
Close Date: 11/27/2007	Quantity	
- Pre-Delivery Inspection	2.00	
Parts Charge: 0.00	Labor Charge: 120.00	

Workorder: 748312 **Problem:** SISTERS TOWING & TRANSPORTATON TOW FROM BEELINE WE

Meter Reading: 0	Labor	Parts
In Date: 12/07/2007	Hours	Description
Close Date: 12/07/2007	Quantity	
- Sisters Towing & Transportaton Tow From Beeline Westbound-West Of Northlake Blvd - Tow To He Shop		
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 114.00

Workorder: 832298 **Problem:** TRAILER PLUG INOP

Meter Reading: 523	Labor	Parts
In Date: 01/04/2008	Hours	Description
Close Date: 01/07/2008	Quantity	
- Diag Trailer Light Plug.Repl Blown 25 Amp Fuse For Stop Turnsignal Lights.Inspect Connector And Wire No Short Found.	0.50	
Parts Charge: 0.00	Labor Charge: 30.00	

Workorder: 841823 **Problem:** P.M. SERVICE.

Meter Reading: 5391	Labor	Parts
In Date: 07/23/2008	Hours	Description
Close Date: 07/28/2008	Quantity	
- Pm Service	6.00	15/40 OIL 15.00
- Nitro Service Six Tires		7312 OIL FILTERFRM CH9549 WIX 57312 1.00
- Replace Trailer Hitch Safety Chain.		18410 PINTLE PIN 1.00
- Shop Supplies		CS10263 FUEL FILTER (USE CS10263A) 1.00
		SHOP SUPPLIES 1.00
Parts Charge: 116.60	Labor Charge: 30.00	

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169536 2008 FORD F350 Utility Body, 1 Ton, 4X4, Vise

Workorder: 933761

Problem: P.M SERVICE,RECALL,CHECK TRAILER PLUG

Meter Reading: 9734		Labor		Parts	
In Date: 02/09/2009	Close Date: 02/18/2009	Hours	Description		Quantity
- Pm Service		8.70	USED FIREX REFURBED FIRE EXTINGSHERS		1.00
- Diag Test Trailer Plug.Repl Blown Fuse 34 25 Amp.Retest			18410 PINTLE PIN		1.00
Ok No Short In Truck.Replace Missing Pintle Pin.			FUEL FILTER HOUSING GASKET		1.00
- Rotate And Hi Speed Balance All 6 Tires,Nitro Fill Tires.			SHOP SUPPLIES		1.00
- To/Fr Dealer For Recall#08B06 And Trans Leak @ Front Pump			31-20 WIPER BLADES 20" BLADE		2.00
- Shop Supplies			15/40 OIL		15.00
			7312 OIL FILTERFRM CH9549 WIX 57312		1.00
			CS10263 FUEL FILTER (USE CS10263A)		1.00
Parts Charge: 172.08		Labor Charge: 462.00			

Workorder: 936099

Problem: INSTALL COMPUTER STAND AND FLOOR MATS.

Meter Reading: 10671		Labor		Parts	
In Date: 04/06/2009	Close Date: 04/08/2009	Hours	Description		Quantity
- Install Front Floor Mats		4.25	FLOOR MATS		1.00
- Fabricate And Install Computer Stand And Wiring Harness.			SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge: 61.99		Labor Charge: 255.00			

Workorder: 936738

Problem: TIRESOLES OF BROWARD INC

Meter Reading: 0		Labor		Parts	
In Date: 03/25/2009	Close Date: 04/20/2009	Hours	Description		Quantity
- Tiresoles Of Broward Inc					
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 60.00	

Workorder: 938762

Problem: TIRESOLES OF BROWARD INC

Meter Reading: 0		Labor		Parts	
In Date: 06/02/2009	Close Date: 06/08/2009	Hours	Description		Quantity
- Tiresoles Of Broward Inc					
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 60.00	

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169536 2008 FORD F350 Utility Body, 1 Ton, 4X4, Vise

Workorder: 939036	Problem: TIRESOLES OF BROWARD INC				
Meter Reading: 0		Labor		Parts	
In Date: 06/12/2009	Close Date: 06/16/2009	Hours	Description		Quantity
- Tiresoles Of Broward Inc					
	Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 60.00		

Workorder: 943087	Problem: cracked windshield				
Meter Reading: 14334		Labor		Parts	
In Date: 09/09/2009	Close Date: 09/09/2009	Hours	Description		Quantity
- From: 15000 Block Of North Lake Blvd And Hall Blvd					
	Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 114.00		

Workorder: 943132	Problem: P.M. Service.Broken windshield.				
Meter Reading: 14583		Labor		Parts	
In Date: 09/11/2009	Close Date: 09/21/2009	Hours	Description		Quantity
- P.M Service. 7.90 CA10270 AIR FILTER MTC FA1886 WIX 49886 1.00					
- Mount Two New Tires, Rotate & Balance All Six Tires. 179636492 LT245/75R17 WRANGLER SR-A E 2.00					
- Diagnose & Repair Ground Circuit For Tag Lamp. SHOP SUPPLIES 1.00					
- Front Tool Box Latch Come Loose, Drill Out Broken Rivets TIRE DISPOSAL FEE 2.00					
& Rerivet Latch Assenbly. 7312 OIL FILTERFRM CH9549 WIX 57312 1.00					
- Shop Supplies 15/40 OIL 15.00					
CS10263 FUEL FILTER (USE CS10263A) 1.00					
	Parts Charge: 495.13	Labor Charge: 474.00			

Workorder: 943196	Problem: repalce broken windsheild				
Meter Reading: 14583		Labor		Parts	
In Date: 09/14/2009	Close Date: 09/16/2009	Hours	Description		Quantity
- Set Up Glass Replacement 2.00 SHOP SUPPLIES 1.00					
- Install New Asset Numbers And County Decals					
- Shop Supplies					
	Parts Charge: 2.00	Labor Charge: 120.00	Commercial Charge: 409.18		

12/28/2017
4:43:44PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169536 2008 FORD F350 Utility Body, 1 Ton, 4X4, Vise

Workorder: 1003042

Problem: P.M service.

Meter Reading: 18324		Labor		Parts	
In Date: 03/25/2010	Close Date: 04/05/2010	Hours	Description	Quantity	
-	P.M Service.	10.00	15/40 OIL	15.00	
-	Test Starting & Charging System, Charge & Test Batteries, Replace Failed L/S Battery.		7312 OIL FILTERFRM CH9549 WIX 57312	1.00	
-	Mount Four New Tires, Rotate & Balance All Six Tires.		CS10263 FUEL FILTER (USE CS10263A)	1.00	
-	Alignment.		31-20 WIPER BLADES 20" BLADE	2.00	
-	Shop Supplies		GROUP 65 BATTERY (MTC BXT-65-850)	1.00	
			179636492 LT245/75R17 WRANGLER SR-A E	4.00	
			TR416 VALVE STEM	4.00	
			SHOP SUPPLIES	1.00	
			TIRE DISPOSAL FEE	4.00	
Parts Charge: 981.62		Labor Charge: 600.00			

Workorder: 1003221

Problem: Flat on R/R/I flat tire

Meter Reading: 18176		Labor		Parts	
In Date: 03/17/2010	Close Date: 03/30/2010	Hours	Description	Quantity	
-	From: Seminole Pratt Whitney Rd Northbound Just Pass Tan				
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 90.00	

Workorder: 1011690

Problem: P.M. service.

Meter Reading: 22671		Labor		Parts	
In Date: 10/19/2010	Close Date: 10/21/2010	Hours	Description	Quantity	
-	Perform Pm Service.	8.00	15/40 OIL	15.00	
-	Test Starting And Charging System.Right Side Battery Failed Load Test After Recharge.Replace Failed Battery With New.		CA10270 AIR FILTER MTC FA1886 WIX 49886	1.00	
-	Repair Two Flat Tires In Rear.Rotate Ahd Balance All Six Tires.		31-20 WIPER BLADES 20" BLADE	2.00	
-	Shop Supplies		SHOP SUPPLIES	1.00	
			7312 OIL FILTERFRM CH9549 WIX 57312	1.00	
			USED FIREX REFURBED FIRE EXTINGSHERS	1.00	
			GROUP 65 BATTERY (MTC BXT-65-850)	1.00	
			CS10263 FUEL FILTER (USE CS10263A)	1.00	
Parts Charge: 273.42		Labor Charge: 480.00			

12/28/2017
4:43:44PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169536 2008 FORD F350 Utility Body, 1 Ton, 4X4, Vise

Workorder: 1104524

Problem: P.M. Service.

Meter Reading: 28005 In Date: 04/27/2011	Close Date: 05/09/2011	Labor Hours	Description	Parts	Quantity
- Perform Pm Service.		5.50	SHOP SUPPLIES		1.00
- Rotate And Balance All Six Tires.			15/40 OIL		15.00
- Shop Supplies			7312 OIL FILTERFRM CH9549 WIX 57312		1.00
			CS10263 FUEL FILTER (USE CS10263A)		1.00
			CA10270 AIR FILTER MTC FA1886 WIX 49886		1.00
			31-20 WIPER BLADES 20" BLADE		2.00
			8C3Z9A343A SEAL KIT FUEL FILTER (FORD)		1.00
			PM-22-A ADDITIVE DIESEL FUEL (M/CRAFT)		1.00
Parts Charge:		183.32	Labor Charge:		330.00

Workorder: 1109017

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 31686 In Date: 08/25/2011	Close Date: 08/25/2011	Labor Hours	Description	Parts	Quantity
- 1 - Detail Vehicle Wash Ticket(S) Issued					
Parts Charge:		0.00	Labor Charge:		0.00
			Commercial Charge:		97.92

Workorder: 1109145

Problem: service call

Meter Reading: 31998 In Date: 08/16/2011	Close Date: 08/29/2011	Labor Hours	Description	Parts	Quantity
- 12500 40Th Street North					
Parts Charge:		0.00	Labor Charge:		0.00
			Commercial Charge:		60.00

12/28/2017
4:43:44PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169536 2008 FORD F350 Utility Body, 1 Ton, 4X4, Vise

Workorder: 1110408

Problem: P.M. Service.Install light bar,tool box and cooler rack.

Meter Reading: 32977	Labor	Parts	
In Date: 09/29/2011	Hours	Description	Quantity
- P.M. Service.	16.30	15/40 OIL	15.00
- Replace Dome Light Bulb And Right Rear Light Assemble.		7312 OIL FILTERFRM CH9549 WIX 57312	1.00
- Fadricate Abd Install Light Bar Assemble.Install Wiring		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
And Controller.		44202R TAIL LIGHT 4" RED 42 LED	1.00
- Install Tool Box And Water Cooler Rack.		PCC6RFL SWITCH BOX (WHELEN)	1.00
- Rotate And Balance All Six Tires.		80865 FUSEHOLDER IMPERIAL 80865	1.00
- Shop Supplies		SX2AAAA LIGHT BAR LED 54" AMBER (WHELEN)	1.00
		31-20 WIPER BLADES 20" BLADE	2.00
		3963 FUEL FILTER FRM CS10263A WIX 33963	1.00
		SHOP SUPPLIES	1.00
		3/16X2X24 SQ ALUM TUBE 2X2X3/16X24 BOX TUBING	6.00
		06133 3M ELECTRIC TAPE STOCK #832260101	1.00
Parts Charge:	1,962.14	Labor Charge:	978.00

Workorder: 1111118

Problem: fab mounts for light

Meter Reading: 32977	Labor	Parts	
In Date: 10/19/2011	Hours	Description	Quantity
- Fab Mounts For Light Bar	3.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	180.00

Workorder: 1201438

Problem: need extra key

Meter Reading: 35287	Labor	Parts	
In Date: 02/13/2012	Hours	Description	Quantity
- Make One Extra Key	0.50		
Parts Charge:	0.00	Labor Charge:	30.00

12/28/2017
4:43:44PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169536 2008 FORD F350 Utility Body, 1 Ton, 4X4, Vise

Workorder: 1203039

Problem: Pm service.

Meter Reading: 36276	Labor	Parts	
In Date: 03/29/2012	Hours	Description	Quantity
- P.M. Service.	8.75	PM-22-A ADDITIVE DIESEL FUEL (M/CRAFT)	1.00
- Blower Does Not Work On Fan Speed #1.Diagnose		19006R MARKER LIGHT 4" RECTANGULAR RED LED	1.00
- Circuit And Replace Defective Blower Resistot.		TIRE DISPOSAL FEE	2.00
- Replace Right Rear Marker Lamp.Fabricate New Wiring.		SHOP SUPPLIES	1.00
- Replace Two Tires,Rotate And Balance All Six.		BIG G DEGREASER STOCK# 485180002	1.00
- Shop Supplies		179636492 LT245/75R17 WRANGLER SR-A E	2.00
		15/40 OIL	15.00
		3963 FUEL FILTER FRM CS10263A WIX 33963	1.00
		7312 OIL FILTERFRM CH9549 WIX 57312	1.00
		A/C BLOWER RESISTOR	1.00
		CA10270 AIR FILTER MTC FA1886 WIX 49886	1.00
Parts Charge:	551.24	Labor Charge:	525.00

Workorder: 1208104

Problem: P.M. Service.

Meter Reading: 42500	Labor	Parts	
In Date: 08/27/2012	Hours	Description	Quantity
- P.M. Service.	11.00	W/WASHER NOZZLE	2.00
- Replace Washer Nozzles.Replace Broken Left Side		TR416 VALVE STEM	4.00
- Running Board.		15/40 OIL	15.00
- Replace Four Tire,Rotate And Balance All Six.		PM-22-A ADDITIVE DIESEL FUEL (M/CRAFT)	1.00
- Complete Wheel Alignment.Test Drive.		LEFT SIDE RUNNING BOARD	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		3963 FUEL FILTER FRM CS10263A WIX 33963	1.00
		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
		15319476 FUSE 20 AMP GMC	1.00
		TIRE DISPOSAL FEE	4.00
		179636492 LT245/75R17 WRANGLER SR-A E	4.00
		7312 OIL FILTERFRM CH9549 WIX 57312	1.00
		31-20 WIPER BLADES 20" BLADE	2.00
Parts Charge:	1,236.68	Labor Charge:	660.00

12/28/2017
4:43:44PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169536 2008 FORD F350 Utility Body, 1 Ton, 4X4, Vise

Workorder: 1301339 **Problem:** right front flat
Meter Reading: 47132 **Labor**
In Date: 02/04/2013 **Hours** **Parts** **Quantity**
Close Date: 02/06/2013

-	Tire Service Southern West Of Rpb Blvd - Right Front Flat				
	Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 211.99

Workorder: 1301340 **Problem:** service call
Meter Reading: 47132 **Labor**
In Date: 02/05/2013 **Hours** **Parts** **Quantity**
Close Date: 02/06/2013

-	Tire Service Southern Blvd W Of Rpb Blvd - Service Call				
	Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 46.40

Workorder: 1301396 **Problem:** Pm service.
Meter Reading: 47424 **Labor**
In Date: 02/07/2013 **Hours** **Parts** **Quantity**
Close Date: 02/27/2013

-	P.M. Service.				
		12.50			
-	Replace Left Rear Marker Lamp.			15-40 OIL	15.00
-	Test Batteries And Charging System.Replace Both Bad Batteries.			OIL FILTER	1.00
-	Resurface Rear Brake Rotors,Replace Rear Brake Pads.Service And Lube Rear Calipers,Flush And Bleed System And Test Drive.			NAPAGOLD AIR FILTER	1.00
-	Rotate And Balance All Six Tires.			31-20 WIPER BLADES 20	2.00
-	Shop Supplies			BATTERY 65	2.00
				NAPAGOLD FUEL FILTER	1.00
				05046 BATTERY PROTECT	1.00
				BRAKE PADS	1.00
				BRAKE CLEANER	1.00
				SHOP SUPPLIES	1.00
				PM-22-A ADDITIVE DIES	1.00
				19006R MARKER LIGHT 4	1.00
				8C3Z9A343A SEAL KIT	1.00
	Parts Charge:	570.57	Labor Charge:	750.00	

12/28/2017
4:43:44PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169536 2008 FORD F350 Utility Body, 1 Ton, 4X4, Vise

Workorder: 1306999

Problem: Pm service and right rear tire flat.

Meter Reading: 52941		Labor		Parts	
In Date: 07/12/2013	Close Date: 07/25/2013	Hours	Description		Quantity
-	P.M. Service.	6.50	SHOP SUPPLIES		1.00
-	Replace Two Tires,Rotate And Balance All Six.		TIRE DISPOSAL FEE		2.00
-	Shop Supplies		NAPAGOLD OIL FILTER		1.00
			NAPAGOLD FUEL FILTER		1.00
			31-20 WIPER BLADES 20		2.00
			USED FIRE X REFURBISHED		1.00
			179636492 LT245-75R17		2.00
			TR416 VALVE STEM		2.00
			15-40 OIL		15.00
Parts Charge:		605.60	Labor Charge:	390.00	

Workorder: 1311966

Problem: P.M. service.

Meter Reading: 57608		Labor		Parts	
In Date: 12/02/2013	Close Date: 12/10/2013	Hours	Description		Quantity
-	P.M. Service.	12.50	TIRE DISPOSAL FEE		2.00
-	Pressure Test And Inspect Cooling System.Replace		SHOP SUPPLIES		1.00
	Leaking Upper And Lower Radiator Hoses.Flush And Rfill		CURVED RADIATOR HOSE		1.00
	Coling System.		15-40 OIL		15.00
-	Replace Two Tires,Rotate And Balance All Six.		RADIATOR HOSE		1.00
-	Make Up And Replace Rear Asset # Decal.		FUEL FILTER FORD ONLY		1.00
-	Shop Supplies		179636492 LT245-75R17		2.00
			ACCUFIT CONVENTIONAL		2.00
			TR416 VALVE STEM		2.00
			PEAK GLOBAL		3.00
			CURVED RADIATOR HOSE		1.00
			NAPAGOLD OIL FILTER		1.00
Parts Charge:		883.90	Labor Charge:	750.00	

Workorder: 1402778

Problem: service

Meter Reading: 60782		Labor		Parts	
In Date: 03/20/2014	Close Date: 03/21/2014	Hours	Description		Quantity
-	Tire Service 11482 Okeechobee Blvd - Service				
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 46.40

12/28/2017
4:43:44PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169536 2008 FORD F350 Utility Body, 1 Ton, 4X4, Vise

Workorder: 1402779

Problem: Flat tire on D/F

Meter Reading: 60782	Labor	Parts	
In Date: 03/20/2014	Hours	Description	Quantity
- Tire Service 11482 Okeechobee Blvd, Royal Palm Beach - Flat Tire On D/F			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	215.66

Workorder: 1403245

Problem: Light Tower

Meter Reading: 60782	Labor	Parts	
In Date: 04/02/2014	Hours	Description	Quantity
- Order Light Tower Parts			
- Shop Supplies			
		POWER SUPPLY CORD	1.00
		U-BOLT	2.00
		PERMANENT MOUNT W WIR	1.00
		HITCH MOUNT LIGHT POLE	1.00
		FUSE HOLDER	1.00
		SHOP SUPPLIES	1.00
Parts Charge:	793.07	Labor Charge:	0.00

Workorder: 1405347

Problem: P.M. service.

Meter Reading: 63080	Labor	Parts	
In Date: 06/02/2014	Hours	Description	Quantity
- Perform Pm Service.			
- Install New Front And Rear Brake Pads.Resurface All			
Four Brake Rotors.Service Calipers And Flush Brake			
Fluid.Automated Bleed Hydraulic System With Scan Tool			
And Road Test.			
- Install Three New Tires.Nitrogen Fill And Balance All Six.			
- Perform Wheel Alignment Complete.			
- Inspect And Service Hydraulic Crane.			
- Shop Supplies			
	20.00	BRAKE PAD	1.00
		TR416 VALVE STEM	3.00
		179636492 LT245-75R17	3.00
		TIRE DISPOSAL FEE	3.00
		SHOP SUPPLIES	1.00
		15-40 OIL	15.00
		NAPAGOLD OIL FILTER	1.00
		WIPER BLADE	2.00
		BRAKE PADS	1.00
		FUEL FILTER FORD ONLY	1.00
Parts Charge:	1,053.24	Labor Charge:	1,200.00

12/28/2017
4:43:44PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169536 2008 FORD F350 Utility Body, 1 Ton, 4X4, Vise

Workorder: 1408765

Problem: Towed in, wont start.

Meter Reading: 65623	Labor	Parts		
In Date: 09/02/2014	Hours	Description	Quantity	
- Computer Diagnose For No Start. Code P242D.Test And Replace All Three Exhaust Gas Temperature.Clear Code And Retest.Reprogram Pcm With Updated Calibration.Test Drive.	4.00	SHOP SUPPLIES exhaust sensor	1.00 3.00	
- Shop Supplies				
Parts Charge:	228.71	Labor Charge:	240.00	

Workorder: 1408837

Problem: NO Start

Meter Reading: 65343	Labor	Parts		
In Date: 08/29/2014	Hours	Description	Quantity	
- Tow From: 8100 Forest Hill Blvd To: Lv				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 134.77

Workorder: 1409984

Problem: Driver seat belt buckle inop and wiper blades.send to HE shop for work lamp.

Meter Reading: 66547	Labor	Parts		
In Date: 10/03/2014	Hours	Description	Quantity	
- Diagnose Driver Seat Belt Inop.Test And Replace Defective Driver Seat Belt Buckle.Also Replace Two Wiper Blades.	1.50	SHOP SUPPLIES WIPER BLADE SEAT BELT	1.00 2.00 1.00	
- Shop Supplies				
Parts Charge:	238.82	Labor Charge:	90.00	

12/28/2017
4:43:44PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169536 2008 FORD F350 Utility Body, 1 Ton, 4X4, Vise

Workorder: 1410087

Problem: Install flood light

Meter Reading: 66549	Labor	Parts	
In Date: 10/07/2014	Hours	Description	Quantity
- Install Go Light	8.50	SHOP SUPPLIES	1.00
- Test Run		TRAILER WIRE	45.00
- Shop Supplies		2000 GO LIGHT	1.00
		FUSE HOLDER	1.00
		HITCH MOUNT LIGHT POLE	1.00
		U-BOLT	2.00
		POWER SUPPLY CORD	1.00
Parts Charge:	916.22	Labor Charge:	510.00

Workorder: 1410607

Problem: 1 - Key(s) issued

Meter Reading: 66549	Labor	Parts	
In Date: 10/23/2014	Hours	Description	Quantity
- 1 - Key(S) Issued	0.20	DUPLICATE VEHICLE KEYS	1.00
Parts Charge:	3.00	Labor Charge:	18.00

12/28/2017
4:43:44PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169536 2008 FORD F350 Utility Body, 1 Ton, 4X4, Vise

Workorder: 1500670

Problem: Pm service.Power outlet inop.Install vise on rear bumper.

Meter Reading: 68684	Labor	Parts	Quantity
In Date: 01/20/2015	Hours	Description	Quantity
- P.M. Service.	10.50	15-40 OIL	15.00
- Replace Two Tires,Rotate And Balance All Six.		NAPAGOLD OIL FILTER	1.00
- Replace Both Leaking Front Shocks.		FUEL FILTER FORD ONLY	1.00
- Replace Both Headlamps And Tag Lamp.Check Power		WIPER BLADE	2.00
Outlet And Freplace Blown Fuse.Replace Roof Marker		WASHER FLUID CONCENTR	1.00
Light Bulb.		USED FIRE X REFURBISHED	1.00
- Fabricate And Install Costomer Supplied Vise.		NAPAGOLD AIR FILTER	1.00
- Shop Supplies		LT245 75R17 M/S2 TIRE	2.00
		HALOGEN LAMP	2.00
		BULB	3.00
		PINTLE PIN W/CHAIN	1.00
		FUSE	1.00
		GAS GRANDE SHOCK	2.00
		LICENSE BRACKET W/LIGHT	1.00
		TIRE DISPOSAL FEE	2.00
		SHOP SUPPLIES	1.00
Parts Charge:	969.60	Labor Charge:	630.00

Workorder: 1504580

Problem: Ckeck engine light on and loss power.Power outlets inop.

Meter Reading: 71032	Labor	Parts	Quantity
In Date: 05/05/2015	Hours	Description	Quantity
- Computer Diagnose For Check Engine Light On And Lost	9.50	THERMOSTAT KIT	1.00
Power.Code P00B7.Pinpoint Test And Replace Both		O-RING	1.00
Defective Thermostats,Gaskets And Upper Radiator		BRAKE CLEANER	1.00
Hose.Flush And Refill Cooling System.Clear Codes W		FUSE	2.00
- Test And Replace Both Open Power Outlet And Cigarette		CURVED RADIATOR HOSE	1.00
Lighter Fuses.Test And Replace Defective Brake Pressure		SHOP SUPPLIES	1.00
Switch For Code P0703.Retest.		BRAKE PRESSURE SWITCH	1.00
- Shop Supplies		COOLANT FORD GOLD	3.00
Parts Charge:	230.60	Labor Charge:	570.00

12/28/2017
4:43:44PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169536 2008 FORD F350 Utility Body, 1 Ton, 4X4, Vise

Workorder: 1506441

Problem: Pm service.Ac blower and power outlets inop.Tailgate hard to open or close.

Meter Reading: 72623		Labor		Parts	
In Date: 06/26/2015	Close Date: 07/15/2015	Hours	Description	Quantity	
- Pm Service.		16.00	15-40 OIL		15.00
- Inspect And Service Transfer Case.			WIPER BLADE		2.00
- Replace Two Tires.Rotate And Balance All Six.			FUEL FILTER FORD ONLY		1.00
- Replace Two Front Body Mounts.			SHOP SUPPLIES		1.00
- Test And Replace Defective Left Front Marker			PWR OUTL		1.00
Lamp.Repair Ground Circuit.Replace Defective Right Rear			WD40 16OZ		1.00
Led Tail Lamp.Fabricate Wiring Harness,Install Fuse			LED M C LAMP		1.00
Holder And Heavy Duty Auxiliary Power Outlet.			LED SUP MDL 44 42 DIO		1.00
- Diagnose For Ac Blower Inop.Test And Replace Defective			NAPAGOLD OIL FILTER		1.00
Blower Resistor.			FUSE		2.00
- Complete Front End Alignment.			FAB LOOM-SPLIT POLY		8.00
- Shop Supplies			BODY MOUNT KIT		2.00
			BLOWER MOTOR RESISTOR		1.00
			FUSE HOLDER		1.00
			TIRE DISPOSAL FEE		2.00
			PEDAL PAD		1.00
			LT245 75R17 M/S2 TIRE		2.00
			FORD TRANSFER CASE FLUID		2.00
	Parts Charge: 993.26	Labor Charge: 960.00			

Workorder: 1506863

Problem: fix tailgate

Meter Reading: 72622		Labor		Parts	
In Date: 07/09/2015	Close Date: 07/14/2015	Hours	Description	Quantity	
- Repair Tailgate		3.00	SHOP SUPPLIES		1.00
- Shop Supplies					
	Parts Charge: 2.00	Labor Charge: 180.00			

12/28/2017
4:43:44PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169536 2008 FORD F350 Utility Body, 1 Ton, 4X4, Vise

Workorder: 1507399

Problem: A/C will not blow out of vents at times.

Meter Reading: 73244		Labor		Parts	
In Date: 07/24/2015	Close Date: 07/30/2015	Hours	Description		Quantity
-	A/C Performance Test.Clean Evaporator.Replace Mode Door Actuator.	4.50	SHOP SUPPLIES		1.00
-	R&R Driveshaft And Replace 'U' Joints.		BLEND DOOR MOTOR		1.00
-	Shop Supplies		U JOINT		2.00
Parts Charge:		153.17	Labor Charge:	270.00	

Workorder: 1507732

Problem: Tailgate hard to open and A/C freezes up.

Meter Reading: 73273		Labor		Parts	
In Date: 08/03/2015	Close Date: 08/11/2015	Hours	Description		Quantity
-	Diagnose A/C System For Freezing Up Complain.Replace Defective High Pressure Line,Accumulator And Orifice.Vacuum And Recharge System To Specs.	3.50	ACCUMULATOR		1.00
-	Fabricate And Adjust Tailgate Latch System.		TUBE FILTER		1.00
-	Shop Supplies		LINE ASY		1.00
			RAPID SEAL KIT		1.00
			E8 A/C OIL UNIV W DYE		1.00
			R134A LV SHOP 2		2.00
			SHOP SUPPLIES		1.00
Parts Charge:		318.81	Labor Charge:	210.00	

Workorder: 1513021

Problem: Pm service.Pipe rack loose.

Meter Reading: 78088		Labor		Parts	
In Date: 12/29/2015	Close Date: 01/20/2016	Hours	Description		Quantity
-	Pm Service.	7.50	bumper		2.00
-	Check Electrical Circuit To Both Brake Light Inop.Replace Both Defective Brake Lamps.Internal Short.		SHOP SUPPLIES		1.00
-	Replace Both Worn/Broken Front Suspension Bump Stops.		15-40 OIL		15.00
-	Rotate And Balance All Six Wheels.		NAPAGOLD OIL FILTER		1.00
-	Inspect-Fabricate Rear Pipe Cage Loose.Secure Pipe Cage To Tool Box.		FUEL FILTER FORD ONLY		1.00
-	Shop Supplies		USED FIRE X REFURBISHED		1.00
			20" WIPER BLADE		2.00
			LED SUP MDL 44 42 DIO		2.00
			WASHER FLUID CONCENTR		1.00
Parts Charge:		304.21	Labor Charge:	450.00	

12/28/2017
4:43:44PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169536 2008 FORD F350 Utility Body, 1 Ton, 4X4, Vise

Workorder: 1603880

Problem: Had to jump start in A/M .

Meter Reading: 81897		Labor		Parts	
In Date: 04/13/2016	Close Date: 04/20/2016	Hours	Description	Quantity	
-	Test Both Batteries And Charging System.Replace Bad Batteries.	6.00	SHOP SUPPLIES		1.00
-	Diagnose Noise Coming From Belt Area.Replace Defective Belt,Tensioner And Idler Pulley.		DRIVEALIGN PULLEY		1.00
-	Shop Supplies		BATTERY		2.00
			TENSIONER-HEAVY DUTY		1.00
			SERPENTINE BELT		1.00
			B S PULLEY		1.00
			MAC BATTERY PROTECT		1.00
Parts Charge: 456.85		Labor Charge: 360.00			

Workorder: 1605996

Problem: P.M. service and exhaust fumes in cab and dome light inop and right headlight inop and spot light.

Meter Reading: 84222		Labor		Parts	
In Date: 06/10/2016	Close Date: 07/19/2016	Hours	Description	Quantity	
-	P.M. Service.	14.00	TIRE DISPOSAL FEE		4.00
-	Replace Four Tires,Rotate And Balance All Six.		SHOP SUPPLIES		1.00
-	Replace Right Back Up Lamp,One Body Marker Lamp.Replace Right Headlamp.		15-40 OIL		15.00
-	Transport Vehicle To Dealer To Remove Cab And Replace Exhaust Crossover Pipe And Body Bushing.		20" WIPER BLADE		2.00
-	Service Transmission,Flush And Refill System.		TR416 VALVE STEM		4.00
-	R&R Seat For Upholtery Repairs.		HALOGEN LAMP		1.00
-	R/R Exhaust Leak		BULB		4.00
-	Shop Supplies		FT144 TRANS FILTER SC		1.00
			SEAT R AND R		1.00
			179636492 LT245-75R17		4.00
			SYN-ATF TRANS FLUID S		24.00
			BULB		2.00
			LED BACK-UP LAMP SYS		1.00
			TRANS FILTER		1.00
			USED FIRE X REFURBISHED		1.00
			NAPAGOLD OIL FILTER		1.00
			FUEL FILTER FORD ONLY		1.00
			BODY MOUNT KIT		4.00
Parts Charge: 2,256.02		Labor Charge: 840.00	Commercial Charge: 938.27		

12/28/2017
4:43:44PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169536 2008 FORD F350 Utility Body, 1 Ton, 4X4, Vise

Workorder: 1608075

Problem: Trailer lights inop.

Meter Reading: 85404	Labor	Parts	
In Date: 08/05/2016	Hours	Description	Quantity
- Replace And Rewire Corroded Trailer Connector.	1.25	SHOP SUPPLIES	1.00
- Shop Supplies		trailer plug	1.00
		FMX-30 FUSE	1.00
Parts Charge:	17.76	Labor Charge:	75.00

Workorder: 1611795

Problem: P.M. service and left front door pops when opening and stalled last week.

Meter Reading: 89061	Labor	Parts	
In Date: 11/16/2016	Hours	Description	Quantity
- P.M. Service	24.00	20" WIPER BLADE	2.00
- Replace Broken Pintle Pin.R&R Left Front Door Panel		REAL SUSPENSION BUMPSTOPS	2.00
- And Replace Broken Check Strap.Replace Rusted Water Cooler Rack.		PUMP	1.00
- Replace Rear Suspension Bump Stops.		THERMOSTAT KIT	1.00
- Pressure Test And Inspect Coling System.Replace Leaking Water Pump,Thermostat And Drivoe Belt.Flush And Refill Cooling System.		SHOP SUPPLIES	1.00
- Remove Diesel Particulate Filter And Pressure Wash.		EXHA	1.00
- Service And Clean Induction System And Egr Ports.Flush Injectors.		DIESEL FUEL INJECTION SERVICE KIT	1.00
- Rotate And Balance All Six Tires.		DIESEL EGR INDUCTION SERVICE KIT	1.00
- Shop Supplies		DRIVE BELT	1.00
		O-RING	1.00
		A/C BELT	1.00
		left door check asy	1.00
		cooler wire rack	1.00
		PINTLE PIN W/CLIP	1.00
		NAPAGOLD OIL FILTER	1.00
		FUEL FILTER FORD ONLY	1.00
		15-40 OIL	15.00
		WASHER FLUID CONCENTR	1.00
		COOLANT FORD GOLD	3.00
Parts Charge:	1,360.63	Labor Charge:	1,440.00

12/28/2017
4:43:44PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169536 2008 FORD F350 Utility Body, 1 Ton, 4X4, Vise

Workorder: 1612655

Problem: Check for oil leak and left front window inop.

Meter Reading: 89774	Labor	Parts
In Date: 12/09/2016	Hours	Quantity
Close Date: 01/03/2017	Description	
- Inspect And Replace Leaking Engine Oil Drain Plug.Refill Oil.	2.50	15-40 OIL 15.00 DRAINING PLUG 1.00
- R&R Left Door Panel And Replace Damaged Window Channel.		LF WINDOW TRUCK RUN 1.00 SHOP SUPPLIES 1.00
- Shop Supplies		
Parts Charge: 227.12	Labor Charge: 150.00	

Workorder: 1704378

Problem: P.M. service.

Meter Reading: 94200	Labor	Parts
In Date: 05/01/2017	Hours	Quantity
Close Date: 05/11/2017	Description	
- P.M. Service.	10.50	LED SUP MDL 44 42 DIO 1.00
- Replace Two Outer Overhead Light Bulbs.Replacerear Id Bar Assembly.Replace Right Rear Tail Light.		FUEL CAP 2.00 LED ID BAR 6 CTRS 1.00
- Replace Two Tires And Balance Six Tires .Nitro Service.		FUEL FILTER FORD ONLY 1.00
- Perform Front End Alignment.		BULB 2.00
- Shop Supplies		179636492 LT245-75R17 2.00 NAPAGOLD AIR FILTER 1.00 20" WIPER BLADE 2.00 TIRE DISPOSAL FEE 2.00 NAPAGOLD OIL FILTER 1.00 15-40 OIL 15.00 SHOP SUPPLIES 1.00
Parts Charge: 852.03	Labor Charge: 630.00	

12/28/2017
4:43:44PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169536 2008 FORD F350 Utility Body, 1 Ton, 4X4, Vise

Workorder: 1707235		Problem: Check engine light on.			
Meter Reading: 97030		Labor		Parts	
In Date: 07/24/2017	Close Date: 07/31/2017	Hours	Description	Quantity	
-		4.90	SHOP SUPPLIES	1.00	
- Scan Computer ,Pulled Code P0672.Diagnoise #Two			GLOW PLUG	1.00	
Cylinder Glow Plug Bad.Replace Glow Plug, Clear			SENSOR	1.00	
Code.Perform Glow Plug Self Test.					
-					
- Diagnose Abs Code P1155 Left Front Wheel Speed					
Sensor Circuit.Replace Wheel Speed Sensor.Clear Codes					
Test Drive.					
-					
- Shop Supplies					
Parts Charge:		90.72	Labor Charge:	294.00	
Workorder: 1709771		Problem: PM Service			
Meter Reading: 99111		Labor		Parts	
In Date: 10/05/2017	Close Date:	Hours	Description	Quantity	
-					
Parts Charge:		0.00	Labor Charge:	0.00	
Workorder: 1710243		Problem: Transition Prep Charge			
Meter Reading: 99111		Labor		Parts	
In Date: 10/19/2017	Close Date: 10/19/2017	Hours	Description	Quantity	
-		2.00			
- Transition Prep Charge					
Parts Charge:		0.00	Labor Charge:	0.00	
Total Parts Charges:		19,564.13	Total Labor Charges:	16,281.00	Total Comm. Charges: 2,658.59