Workorder:	742291	Meter				In Date:	07/31/2007	Closed:	07/31/2	007
Problem:	PRE-DE	LIVERY INSF	PECTION							
- Pre-delivery	Inspectio	n								
		Hours 2.00		Labor:	110.00	Parts:	0.00	Total:	110.00	
Workorder: Problem:	835207 P.M SEF	Meter RVICE,SEE N				In Date:	03/07/2008	Closed:	03/12/2	008
- Pm Service					Parts Li	st				Qty
- Test For Ste					Shop Su	upplies				1.00
Joints,power S This Time	steering S	Sys And Braki	ng Sys.no Pro	b Found At	1372 O	il Filter Frm	Ph2 Wix 51	372		1.00
- Shop Suppli	26				G8018 F	Fuel Filter Ll	of G6593 Wix	33595		1.00
- Shop Suppli	53				5w20 Er	ngine Oil				7.00
					31-20 W	/iper Blades	20" Blade			2.00
		Hours 4.50		Labor:	270.00	Parts:	34.25	Total:	304.25	
Workorder: Problem:	844780 P.M SEF	Meter RVICE	: 6633			In Date:	09/26/2008	Closed:	09/30/2	008
- Pm Service					Parts Li	st				Qty
- Rotate & Hig	h Speed	Balance 4 Tir	es.fill W/nitro	gen.	Shop Su	upplies				1.00
- Shop Suppli	es				Ca8039	Air Filter Lb	of Af1615 Wix	46418		1.00
					1372 O	il Filter Frm	Ph2 Wix 51	372		1.00
					G8018 F	Fuel Filter Ll	of G6593 Wix	33595		1.00
					5w20 Er	ngine Oil				7.00
					Wd40 S	pray Lube S	Stock# 405540	0002		1.00
					31-20 W	/iper Blades	20" Blade			2.00
					Used Fi	rex Refurbe	d Fire Extings	hers		1.00
		Hours 4.00		Labor:	240.00	Parts:	59.11	Total:	299.11	
Workorder: Problem:	936727 P.M SEF	Meter RVICE	: 9000			In Date:	04/20/2009	Closed:	04/24/2	009
- Pm Service					Parts Li	st				Qty
- Rotate And I	Hi Speed	Balance 4 Tir	es.fill W/nitro	aen.	Shop St					1.00
- Shop Suppli	-			5		• •	Ph2 Wix 51	372		1.00
						ngine Oil				7.00
						-	d Fire Extings	hers		1.00
		Hours 5.00		Labor:	300.00		35.02		335.02	
Workorder: Problem:	946874 void	Meter	: 11784			In Date:	12/09/2009	Closed:		
-										

Workorder: Problem:	947169 pm	Meter:	11784			In Date:	12/18/2009	Closed:	12/30/20	009
- Pm					Parts Li	st				Qty
- Rotate and	high speed ba	alance 4 tire	S		Shop Su	pplies				1.00
- Shop Suppli	es				1372 Oi	I Filter Frm	Ph2 Wix 51	372		1.00
					5w20 Er	gine Oil				7.00
					31-20 W	iper Blades	20" Blade			2.00
	Ho :	urs 5.00		Labor:	300.00	Parts:	48.27	Total:	348.27	
Workorder: Problem:	1007915 Pm service.	Meter:	14831			In Date:	07/26/2010	Closed:	08/04/20	010
- Perform pm	service.				Parts Li	st				Qty
- Rotate and balance all four tires.					Shop Su	pplies				1.00
- Shop Suppli	- Shop Supplies					I Filter Frm	Ph2 Wix 51	372		1.00
					Ca8039	Air Filter Lt	of Af1615 Wix	46418		1.00
					G8018 F	uel Filter L	bf G6593 Wix	33595		1.00
					5w20 Er	gine Oil				7.00
					1066 W	hite Lithium	n (crc 05037)			1.00
					Used Fir	ex Refurbe	d Fire Extings	hers		1.00
	Ho	urs 5.00		Labor:	300.00	Parts:	44.25	Total:	344.25	
Workorder: Problem:	1009099 Tow in,dead	Meter: battery.	14966			In Date:	08/23/2010	Closed:	08/26/20	010
- Recharge a			st.replace d	efective	Parts Li	st				Qty
battery.check		tem,okay.			Shop Su	pplies				1.00
- Shop Suppli	es				Group 6	5 Battery (n	ntc Bxt-65-850	))		1.00
	Ho	urs 1.00		Labor:	60.00	Parts:	132.50	Total:	192.50	
Workorder: Problem:	1009101 No start	Meter:	14842			In Date:	08/23/2010	Closed:	08/23/20	010
- From: 3650	Summit Blvd	To: Lv Sł	aor							
		urs 0.00	F	Labor:	0.00	Parts:	0.00	Total:	0.00	
		Meter:	17047			In Date:	01/28/2011	Closed:	02/07/20	011
Workorder: Problem:	1101098 P.M. Service									
	P.M. Service				Parts Li	st				Qty
Problem:	P.M. Service service.	9.			Parts Li Shop Su					<b>Qty</b> 1.00
Problem: - Perform pm	P.M. Service service. balance all fo	9.			Shop Su	pplies	1 Ph2 Wix 513	372		-
Problem: - Perform pm - Rotate and I	P.M. Service service. balance all fo	9.			Shop Su 1372 Oi	pplies I Filter Frm	n Ph2 Wix 513 Stock# 405540			1.00
Problem: - Perform pm - Rotate and I	P.M. Service service. balance all fo	9.			Shop Su 1372 Oi	pplies I Filter Frm pray Lube S				1.00 1.00
Problem: - Perform pm - Rotate and I	P.M. Service service. balance all fo	9.			Shop Su 1372 Oi Wd40 Sj 5w20 Er	pplies I Filter Frm pray Lube S	Stock# 405540			1.00 1.00 1.00

Workorder: Problem:	1109531 P.M. service.	Meter:	18910		I	n Date:	09/06/2011	Closed:	09/15/201	11
- Perform pm	service.				Parts List	t				Qty
- Rotate and I	balance all foui	r tires.			Shop Sup	plies				1.00
- Shop Suppli	ies				1372 Oil	372	1.00			
					G8018 Fu	el Filter L	of G6593 Wix	33595		1.00
					5w20 Eng	jine Oil				7.00
					31-20 Wip	per Blades	20" Blade			2.00
					Used Fire	x Refurbe	d Fire Extings	hers		1.00
	Hour :	rs 5.00		Labor:	300.00	Parts:	48.81	Total:	348.81	
Workorder: Problem:	1200469 Fuel Leak (Dr	<b>Meter:</b> iver saw p	19440 uncture hole	in gas tan		n Date:	01/13/2012	Closed:	01/13/201	12
- Tow From: 3	3650 Summit L	ibrary To:	Lv Shop							
	Hour	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder:	1200485	Meter:	19526		I	n Date:	01/13/2012	Closed:	02/09/202	12
Problem:	Towed in.Ho	le drilled in	bottom of fu	el tank and	d tank emp	oty				
	Towed in.Hol maged fuel tanl				d tank emp Parts List					Qty
- Replace dar vehicle.	maged fuel tan					t				<b>Qty</b> 1.00
- Replace dar	maged fuel tan				Parts List	t plies				-
- Replace dar vehicle.	maged fuel tan				Parts List Shop Sup	<b>t</b> plies p Gasket				1.00
- Replace dar vehicle.	maged fuel tanl ies			st drive	Parts List Shop Sup Fuel Pum	t plies p Gasket	860.38	Total:		1.00 1.00
- Replace dar vehicle. - Shop Suppli	maged fuel tanl ies	k assemble rs 3.50 Meter:	e.refill and tes	st drive Labor:	Parts List Shop Sup Fuel Pum Fuel Tank 210.00	t plies p Gasket	860.38 04/24/2012	Total: Closed:		1.00 1.00 1.00
- Replace dar vehicle. - Shop Suppli	maged fuel tanl ies Hour : 1203864 Pm service ar	k assemble rs 3.50 Meter:	e.refill and tes	st drive Labor:	Parts List Shop Sup Fuel Pum Fuel Tank 210.00	t plies p Gasket Parts: <b>n Date:</b>			1,070.38	1.00 1.00 1.00
<ul> <li>Replace dar vehicle.</li> <li>Shop Suppli</li> <li>Workorder: Problem:</li> <li>Perform pm</li> </ul>	maged fuel tanl ies Hour : 1203864 Pm service ar	k assemble rs 3.50 <b>Meter:</b> nd radio an	e.refill and tes 20990 Itenna broker	st drive Labor:	Parts List Shop Sup Fuel Pum Fuel Tank 210.00	t plies p Gasket Parts: <b>n Date:</b>			1,070.38 05/07/20 <sup>7</sup>	1.00 1.00 1.00
<ul> <li>Replace dar vehicle.</li> <li>Shop Suppli</li> <li>Workorder: Problem:</li> <li>Perform pm</li> <li>Replace bro</li> <li>Rotate and b</li> </ul>	maged fuel tan ies Hour : 1203864 Pm service ar service. service. ken antenna m balance all fou	k assemble rs 3.50 <b>Meter:</b> nd radio an	e.refill and tes 20990 Itenna broker	st drive Labor:	Parts List Shop Sup Fuel Pum Fuel Tank 210.00	t plies p Gasket Parts: <b>n Date:</b> t plies Filter Frm		Closed:	1,070.38 05/07/20 <sup>-</sup>	1.00 1.00 1.00 12 <b>Qty</b> 1.00 1.00
<ul> <li>Replace dar vehicle.</li> <li>Shop Suppli</li> <li>Workorder: Problem:</li> <li>Perform pm</li> <li>Replace bro</li> </ul>	maged fuel tan ies Hour : 1203864 Pm service ar service. service. ken antenna m balance all fou	k assemble rs 3.50 <b>Meter:</b> nd radio an	e.refill and tes 20990 Itenna broker	st drive Labor:	Parts List Shop Sup Fuel Pum Fuel Tank 210.00	t plies p Gasket Parts: <b>In Date:</b> t plies Filter Frm jine Oil	04/24/2012 Ph2 Wix 51	Closed:	1,070.38 05/07/201	1.00 1.00 1.00 12 12 <b>Qty</b> 1.00 1.00 7.00
<ul> <li>Replace dar vehicle.</li> <li>Shop Suppli</li> <li>Workorder: Problem:</li> <li>Perform pm</li> <li>Replace bro</li> <li>Rotate and b</li> </ul>	maged fuel tan ies Hour : 1203864 Pm service ar service. service. ken antenna m balance all fou	k assemble rs 3.50 <b>Meter:</b> nd radio an	e.refill and tes 20990 Itenna broker	st drive Labor:	Parts List Shop Sup Fuel Pum Fuel Tank 210.00	t plies p Gasket Parts: n Date: t plies Filter Frm ine Oil per Blades	04/24/2012 Ph2 Wix 513	Closed:	1,070.38 05/07/20 <sup>-</sup>	1.00 1.00 1.00 12 <b>Qty</b> 1.00 1.00 7.00 2.00
<ul> <li>Replace dar vehicle.</li> <li>Shop Suppli</li> <li>Workorder: Problem:</li> <li>Perform pm</li> <li>Replace bro</li> <li>Rotate and b</li> </ul>	maged fuel tan ies Hour : 1203864 Pm service ar service. service. ken antenna m balance all fou	k assemble rs 3.50 <b>Meter:</b> nd radio an	e.refill and tes 20990 Itenna broker	st drive Labor:	Parts List Shop Sup Fuel Pum Fuel Tank 210.00	t plies p Gasket Parts: n Date: t plies Filter Frm plies Filter Frm plies x Refurbe	04/24/2012 Ph2 Wix 51	Closed:	1,070.38 05/07/20 <sup>7</sup>	1.00 1.00 1.00 12 <b>Qty</b> 1.00 7.00 2.00 1.00
<ul> <li>Replace dar vehicle.</li> <li>Shop Suppli</li> <li>Workorder: Problem:</li> <li>Perform pm</li> <li>Replace bro</li> <li>Rotate and b</li> </ul>	maged fuel tan ies Hour : 1203864 Pm service ar service. service. service all four balance all four ies	k assemble rs 3.50 <b>Meter:</b> nd radio an	e.refill and tes 20990 Itenna broker	st drive Labor: n.	Parts List Shop Sup Fuel Pum Fuel Tank 210.00	t plies p Gasket Parts: n Date: t plies Filter Frm plies Filter Frm plies x Refurbe	04/24/2012 h Ph2 Wix 513 20" Blade d Fire Extings	Closed: 372 hers	1,070.38 05/07/20 <sup>7</sup>	1.00 1.00 1.00 12 <b>Qty</b> 1.00 1.00 7.00 2.00

Palm Beach County Fleet Management
Asset Maintenance History

Workorder: Problem:	1211563 P.M. service.	Meter:	23096			In Date:	11/30/2012	Closed:	12/13/2012
- Perform pm	service.				Parts Lis	t			Q
•	ew tires.nitrog	en fill and t	balance all fou	ır.	5w20 Eng	gine Oil			7.0
- Perform whe	eel alignment c	complete.			-	ilter Lbf Pł	l		1.(
- Shop Suppli	es	·			31-20 Wij	per Blades		2.0	
					G8018 Fi	uel Filter L	of		1.(
					Ca8039 A	Air Filter Lt	of		1.(
					17974749	92 Lt245-7	5r16		4.(
					Tr416 Va	lve Stem			4.(
					Shop Sup	plies			1.(
					Tire Dispo	osal Fee			4.(
	Hour :	rs 8.50		Labor:	510.00	Parts:	945.34	Total:	1,455.34
Workorder: Problem:	1300120 repaint roof	Meter:	23096			In Date:	12/13/2012	Closed:	01/03/2013
- repaint roof	Hou	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
	:								
Workorder: Problem:	1305950 Pm service ar	Meter: nd head ligl	25017 hts inop.			In Date:	06/14/2013	Closed:	06/25/2013
- P.m. Service	Э.				Parts Lis	t			Q
- Replace left	headlamp.				5w20 Eng	gine Oil			7.0
- Test battery	and charging	system.rep	lace bad batte	ery.	Napagold	Oil Filter			1.(
<ul> <li>Rotate and b</li> </ul>	balance all tires	S.			31-20 Wij	per Blades	20		2.0
<ul> <li>Shop Suppli</li> </ul>	es				Brake Cle	eaner			1.(
					Used Fire	X Refurb	shed		1.(
					Halogen I	Lamp			1.(
					Battery 6	5			1.(
					Shop Sup	plies			1.0
	Houi :	rs 6.50		Labor:	390.00	Parts:	206.14	Total:	596.14
	Hour : 1312372 P.M. service a	Meter:	26293 s hard to star			In Date:	206.14 12/12/2013	Total: Closed:	596.14 12/30/2013
Problem:	: 1312372 P.M. service a	Meter:				In Date: driving.			
Problem: - Perform pm	: 1312372 P.M. service a	Meter: and at time	s hard to star	t and cuts	s out while Parts Lis	In Date: driving. t			12/30/2013
Problem: - Perform pm - Computer di ailed ignition s	: 1312372 P.M. service a service. iagnose for inte switch and lock	Meter: and at time: ermittent no	s hard to start	t and cuts	s out while Parts Lis	In Date: driving. t gine Oil			12/30/2013 Q
Problem: - Perform pm - Computer di ailed ignition s cylinder to orig	: 1312372 P.M. service a service. iagnose for inte switch and lock ginal key.	Meter: and at times ermittent no k cylinder w	s hard to start	t and cuts	s out while <b>Parts Lis</b> 5w20 Eng	In Date: driving. t gine Oil I Oil Filter			12/30/2013 Q 7.0
Problem: - Perform pm - Computer di ailed ignition s cylinder to orig - Rotate and b	: 1312372 P.M. service a service. iagnose for inte switch and lock ginal key. balance all four	Meter: and at times ermittent no k cylinder w	s hard to start	t and cuts	s out while <b>Parts Lis</b> 5w20 Eng Napagold	In Date: driving. t gine Oil I Oil Filter ade			12/30/2013 Q 7.0 1.0
Problem: - Perform pm - Computer di ailed ignition s cylinder to orig - Rotate and b	: 1312372 P.M. service a service. iagnose for inte switch and lock ginal key. balance all four	Meter: and at times ermittent no k cylinder w	s hard to start	t and cuts	s out while <b>Parts Lis</b> 5w20 Eng Napagold Wiper Bla Bigg Deg	In Date: driving. t gine Oil I Oil Filter ade	12/12/2013		12/30/2013 Q 7.0 1.0 2.0
Problem: - Perform pm - Computer di ailed ignition s cylinder to orig - Rotate and b	: 1312372 P.M. service a service. iagnose for inte switch and lock ginal key. balance all four	Meter: and at times ermittent no k cylinder w	s hard to start	t and cuts	s out while <b>Parts Lis</b> 5w20 Eng Napagold Wiper Bla Bigg Deg	In Date: driving. t gine Oil I Oil Filter de reaser I Fuel Filte	12/12/2013		12/30/2013 Q 7.0 1.0 2.0 1.0
Problem: - Perform pm - Computer di failed ignition s cylinder to orig - Rotate and b	: 1312372 P.M. service a service. iagnose for inte switch and lock ginal key. balance all four	Meter: and at times ermittent no k cylinder w	s hard to start	t and cuts	s out while <b>Parts Lis</b> 5w20 Eng Napagold Wiper Bla Bigg Deg Napagold ignition sy	In Date: driving. t gine Oil I Oil Filter de reaser I Fuel Filte	12/12/2013 r		12/30/2013 Q 7.0 1.0 2.0 1.0 1.0
<ul> <li>Perform pm</li> <li>Computer di failed ignition s</li> <li>cylinder to orig</li> </ul>	: 1312372 P.M. service a service. iagnose for inte switch and lock ginal key. balance all four	Meter: and at times ermittent no k cylinder w	s hard to start	t and cuts	s out while <b>Parts Lis</b> 5w20 Eng Napagold Wiper Bla Bigg Deg Napagold ignition sy	In Date: driving. t gine Oil I Oil Filter ade reaser I Fuel Filte witch asy ck switch	12/12/2013 r		12/30/2013 Q 7.0 1.0 2.0 1.0 1.0 1.0 1.0

Workorder:1406118Meter:27605Problem:Pm service		In Date: 06	6/20/2014	Closed:	06/30/2014	
- Perform pm service.		Parts List	Qt			
- Rotate and balance all four tires.		5w20 Engine Oil	7.0			
- Shop Supplies		Napagold Oil Filter	1.0			
		Napagold Air Filter			1.0	
		Wiper Blade			2.0	
		Used Fire X Refurbish	ed		1.0	
		Silicone Spray 10oz			1.0	
		Shop Supplies			1.0	
Hours 5.00	Labor:	300.00 Parts: 67	1.07	Total:	361.07	
Workorder: 1500202 Meter: 28703 Problem: Pm service.		In Date: 07	1/07/2015	Closed:	01/23/2015	
- Pm service.		Parts List			Qt	
- Inspect, flush and refill automatic transmission fluid.		5w20 Engine Oil	7.0			
- Rotate and balance all four tires.		Napagold Oil Filter		1.0		
- Shop Supplies		Napagold Fuel Filter		1.0		
		Accufit Conventional			2.0	
		Syn-atf Trans Fluid S			14.0	
		Shop Supplies			1.0	
Hours 6.50	Labor:	390.00 Parts: 10	)8.28	Total:	498.28	
Workorder: 1506632 Meter: 29661 Problem: Pm service.Check AC cuts off.		In Date: 07	7/01/2015	Closed:	07/21/2015	
- Pm service.		Parts List			Qt	
- Perform engine coolant flush and refill system.		5w20 Engine Oil				
- Diagnose air conditioning for warm air.replace defect	ctive	Napagold Oil Filter				
condenser, accumulator and orifice tube.vacuum and		Used Fire X Refurbish	1.0			
recharge system Rotate and balance all four tires.		Wiper Blade	2.0			
- Rolate and balance all four tires.	Peak Global			2.0		
Chan Supplies	- Shop Supplies					
- Shop Supplies		R134a Lv Shop 1			2.0	
- Shop Supplies		R134a Lv Shop 1 E8 A/c Oil Univ W Dye	1		2.0 1.0	
- Shop Supplies		•	1			
- Shop Supplies		E8 A/c Oil Univ W Dye			1.0	
- Shop Supplies		E8 A/c Oil Univ W Dye Condensr	1		1.0 1.0	
- Shop Supplies		E8 A/c Oil Univ W Dye Condensr Accumulator			1.0 1.0 1.0	

Workorder: Problem:	1600387 Pm service.	Meter:	30612			In Date:	01/12/2016	Closed:	01/27/2	016
- Pm service.					Parts Li	st				Qty
	balance all four	tires.			5w20 Er	ngine Oil				7.00
- Shop Suppli	es				Napagold Oil Filter					
					20" Wip				2.00	
					-	Fluid Conc	entr			1.00
					Napago	d Fuel Filte	r			1.00
					Shop Su	pplies				1.00
	Hour	s 5.00		Labor:	300.00		34.25	Total:	334.25	
Workorder: Problem:	1607752 P.M. service.	Meter:	32481			In Date:	07/29/2016	Closed:	08/16/2	016
- P.m. Service	Э.				Parts Li	st				Qty
- Test battery	and charging	system.rep	lace bad bat	ttery.	5w20 Engine Oil					7.00
- Replace righ	nt rear door loc	k assemble	э.		Napagold Oil Filter					
- Rotate and I	balance all tires	6.			Napagold Air Filter					
- Shop Suppli	es				Used Fi	e X Refurb			1.00	
					20" Wip	er Blade				2.00
					Battery					1.00
					Remote					1.00
					Shop Su	ipplies				1.00
	Hour :	s 7.50		Labor:	450.00	Parts:	269.93	Total:	719.93	
Workorder: Problem:	1702604 P.M. service	Meter:	33760			In Date:	03/14/2017	Closed:	03/28/2	017
- P.m. Service	Э.				Parts Li	st				Qty
- Replace mis	dsing left front	hub cap.			5w20 Er	ngine Oil				7.00
- Rotate and I	-					d Oil Filter				1.00
- Shop Suppli					20" Wip					2.00
						Fluid Conc	entr			1.00
					Cover					1.00
					Shop Su	pplies				1.00
	Hour	s 5.25		Labor:	315.00		88.42	Total:	403.42	
Workorder: Problem:	1710968 Transition Pre	Meter: ep Charge	35574			In Date:	11/03/2017	Closed:	11/03/20	017
- Transition P	rep Charge									
	Hour :	s 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00	