10178712 2009 SATURN VUE Suv, Mid Size, Hybrid

Workorder: 936399 Meter: In Date: 04/13/2009 Closed: 04/13/2009 Problem: PRE-DELIVERY INSPECTION - Pre-delivery Inspection Labor: 120.00 Hours 2.00 Parts: 0.00 Total: 120.00 Workorder: 942915 Meter: 2664 In Date: 09/03/2009 Closed: 09/09/2009 Problem: LOW TIRE LIGHT STAYS ON - Transport & Pick Up At Dealer For Warranty Repair; Defective L/f Tire Pressure Sensor Hours 2.00 Total: 120.00 Labor: 120.00 Parts: 0.00 Meter: Workorder: 946021 4656 In Date: 11/16/2009 Closed: 11/23/2009 Problem: P.M.Service, also Check Tire Pressure lights on for 2 tires (per customer) - P. M. Service **Parts List** Qtv 1.00 - c/c Check tire light on. R/r tire Ch9018 Oil Filter Acd Pf457g Wix 57082 - Repair, nail in front right tire. 5w30 Oil 5.00 Tire 1.00 Waste Fee 1.00 Tire Disposal Fee 1.00 Hours 4.00 Labor: 240.00 Parts: 133.31 Total: 373.31 Workorder: 1001260 Meter: 4473 In Date: 02/03/2010 Closed: 02/09/2010 Problem: R/R Windshield reservoir (ran over branch on street, caused crack in reservoir) - C/s: Ran over branch on street, caused crack in washer **Parts List** Qty reservoir. Verified. Removed front bumper & I/fender well to W/washer Reservoir 1.00 inspect. Replaced damaged w/washer reservoir. Hours 2.50 Labor: 150.00 Parts: 70.44 Total: 220.44 In Date: 1004709 Meter: 05/06/2010 Closed: 05/14/2010 Workorder: 6145 Problem: P. M. SERVICE - P. M. Service **Parts List** Qty Ch9018 Oil Filter Acd Pf457g Wix 57082 1.00 5w30 Oil 5.00 Labor: 120.00 Hours 2.00 Parts: 18.68 Total: 138.68 Workorder: 1008857 Meter: 8653 In Date: 08/17/2010 Closed: 08/19/2010 Problem: reflash canceiver - Reflash Canceiver and reprogram Hours 1.00 Labor: 60.00 Parts: 0.00 Total: 60.00 Workorder: 1008888 Meter: 8682 In Date: 08/18/2010 Closed: 08/25/2010 Problem: REFLASH THE CANCEIVER - Travel to S.e. shop for canceiver reflash.

Labor: 120.00

Parts: 0.00

Total: 120.00

Hours 2.00

1012418 Workorder: 9310 In Date: 11/04/2010 Closed: 11/18/2010 Meter: Problem: P.M.SERVICE/RECALL - P. M. **Parts List** Qty - Install "how's my driving" decal. 1.00 Ch9018 Oil Filter Acd Pf457g Wix 57082 - Dealer Replace Hybrid Battery. (recall # V2243). 5w30 Oil 5.00 - Dealer Replace Vehicle Battery. - Travel to dealer to pick up vehicle for recall. Hours 3.25 Labor: 195.00 Parts: 18.19 Total: 213.19 1106004 Workorder: Meter: 12338 In Date: 06/07/2011 Closed: 07/14/2011 Problem: P.M.SERVICE, CHECK ENGINE LIGHT STAYS ON - P. M. Service. **Parts List** Qty - Check engine light is on, scan for codes & send to dealer Ch9018 Oil Filter Acd Pf457g Wix 57082 1.00 for warranty. 5.00 5w30 Oil - Transport & pick up vehicle at dealer for warranty repairs. - Dealer to replace defective R/rear hub & sensor. Hours 4.75 Labor: 285.00 Parts: 21.00 Total: 306.00 Workorder: 1108467 Meter: 12623 In Date: 08/11/2011 Closed: 08/12/2011 **Problem:** Right rear tire (tire light is on) - C/c: Right rear tire. Dismount, patch, mount, balance, add N2. Hours 1.00 Labor: 60.00 Parts: 0.00 Total: 60.00 Workorder: 1201053 Meter: 02/01/2012 **Closed:** 02/08/2012 15369 In Date: Problem: P. M. SERVICE - P. M. Service. **Parts List** Qty - Remove electronic pannel to Service & check battery Ch9018 Oil Filter Acd Pf457g Wix 57082 1.00 reassemble. 5w30 Oil 5.00 - Verify nail in R/r tire. Dismount, patch, mount, & balance. - Vacuum tires. Refill with nitrogen. Labor: 285.00 Hours 4.75 Parts: 20.98 Total: 305.98 1209426 Workorder: Meter: 20390 In Date: 10/02/2012 Closed: 10/04/2012 Problem: low tire rr - repair right rear tire Hours 1.00 Labor: 60.00 Parts: 0.00 Total: 60.00 Workorder: 1210278 Meter: 22300 In Date: 10/25/2012 Closed: 10/29/2012 **Problem:** NEEDS W/BLADES - install new wiper blades **Parts List** Qty 31-24 Wiper Blades 2 1.00 31-16 Wiper Blades 16 1.00 Hours 0.25 Labor: 15.00 Parts: 11.57 Total: 26.57

Workorder: Problem:	1300177 P.M.SERVICE	Meter:	25058			In Date:	01/04/2013	Closed:	01/31/2013	
- pm					Parts Lis	st			Qt	
- Ir turn out rr		Oil Filter				1.0				
- tire light on		Napa Qu	art 5w30			5.0				
- removed ele	Mac Wite	1.0								
recharged and	Wiper Blade				1.0					
					Miniature	Bulb			1.0	
	Hours :	5.00		Labor:	300.00	Parts:	42.48	Total:	342.48	
Workorder: Problem:	1302129 screw If tire	Meter:	26650			In Date:	03/01/2013	Closed:	03/13/2013	
- repair left fro	oint tire									
•	Hours	s 1.00		Labor:	60.00	Parts:	0.00	Total:	60.00	
Workorder:	1312730 P.M.SERVICE	Meter:	29751 FCK ENGINE	LIGHT S		In Date:	12/20/2013	Closed:	04/08/2014	
- pm		,, 120, 01 11		. 2.0	Parts Lis				Qt	
-	d ck battery ck	charding s	svs and found	l had	Abs Sens			2.0		
	e battery covers			· buu		d Oil Filter		1.0		
- replace 4 tir		Napa Qu			6.0					
- replace both	n high and low s	ide valve	and recharge	sys	Mac Wite	1.0				
	ht and abs light			Washer F	1.0					
	pinpoint test tra				Group 90	1.0				
abs harness found bad abs snesor replace bith rear abs sensor and codes codes						738168571 225-60r17				
- fill all tires w		Couplr 14		4.0 1.0						
	hicle before and	d after rep	air		Couplr 14		1.0			
		·			Tire Disp			4.0		
	Hours	12.75		Labor:	765.00		1,071.65	Total:	1,836.65	
	1403312 1 - Detail Vehic		. ,	ıed		In Date:	04/04/2014	Closed:	04/04/2014	
- 1 - Detail Ve	hicle Wash Ticl	ket(s) Issu	ıed							
	Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1406052 abs,service tra	Meter: ction con	30505 trl,check engi	ne light st		In Date:	06/19/2014	Closed:	07/10/2014	
test and found	s light found cod I bad front abs s r and clear code	ensor rer			Parts Lis Abs Sens				Qt 2.0	
- test drive 45	miles before ar	nd after re	epair							
	Hours	6.50		Labor:	390.00	Parts:	149.10	Total:	539.10	
	•									

Workorder: Problem:	1406611 battery issues/	Meter: remove o	30505 canceiver			In Date:	07/03/2014	Closed:	07/08/20	014	
- Test and rer	nove canceiver i	issue fue	l card								
	Hours :	1.00		Labor:	60.00	Parts:	0.00	Total:	60.00		
Workorder: Problem:	1410379 P.M.SERVICE	Meter:	33009			In Date:	10/16/2014	Closed:	10/23/20	014	
- pm					Parts Li	st				Qty	
					Napagol	d Oil Filter				1.00	
					Napa Qı	uart 5w30				6.00	
					Washer	Fl				1.00	
					31-24 Wiper Blades 2					1.00	
					Wiper B	lade				1.00	
	Hours :	2.00		Labor:	120.00	Parts:	38.94	Total:	158.94		
Workorder: Problem:	1504155 P.M.SERVICE	Meter:	35879			In Date:	04/22/2015	Closed:	04/30/20	015	
- pm					Parts Li	st				Qty	
- repair I rear	tail light socket a	and wire			Napagold Oil Filter						
					Napa Qı	uart 5w30				6.00	
	Hours :	2.50		Labor:	150.00	Parts:	25.97	Total:	175.97		
Workorder: Problem:	1509960 P.M.SERVICE	Meter:	40853			In Date:	10/01/2015	Closed:	10/20/20	015	
- pm					Parts List Q						
- repair left rear tire					Napa Quart 5w30						
- install hows my driving decal					Napagol	d Oil Filter				1.00	
					Wiper B	lade				1.00	
					Wiper B	lade				1.00	
					Washer	Fluid Conce	entr			1.00	
		Napagol	d Air Filter				1.00				

Workorder: Problem:	1603928 p.m.service	Meter:	45033		-	In Date:	04/14/2016	Closed:	04/26/2016		
- Pm service.					Parts Lis	t			Qty		
- Remove alte	Wiper Bla	ide			1.00						
drive belt.	Belt Tens	ioner			1.00						
- Resurface re	e brake	Belt	1.00								
pads.					Rear Brak	ke Pad A/d	Delco		1.00		
					Napagold	Oil Filter			1.00		
					Napa Qua	6.00					
					Wiper Bla	ides 24"			1.00		
					Wiper				1.00		
					Washer F	luid Conc	entr		1.00		
					B Fluid D	ot 3-32oz			1.00		
					Brake Cle	eaner			1.00		
	Ηοι :	ırs 10.00		Labor:	600.00	Parts:	453.63	Total:	1,053.63		
- Diagnose fo voltage battery - Trasnsport v	r check enging y temperature yehicle to and	e light on.m sensors. from dealer	AYS ON (SER ultiple codes for repairing h	or high	YBRID SYS	STEM)					
voltage batter	•	,	rranty repairs)								
	Ηοι :	ırs 3.75		Labor:	225.00	Parts:	0.00	Total:	225.00		
Workorder: Problem:	1700849 Recall	Meter:	48305		ı	In Date:	01/27/2017	Closed:	01/30/2017		
- Transport ve 15806	ehicle to and f	rom dealer	for safety reca	II #							
	Hou :	ırs 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00		
Workorder: Problem:	1702690 PM Service.I	Meter: Right rear ti	50926 re damage.			In Date:	03/16/2017	Closed:	03/31/2017		
- Pm Service					Parts Lis	t			Qty		
- Replace bot	Napagold	1.00									
nitrogen.	Napa Qua	6.00									
					Washer F	1.00					
					Napagold	1.00					
						Wiper Blades 24"					
						Wiper					
							738168571 225-60r17				
					Tire Dispo				2.00 2.00		
	Hou	ırs 3.50		Labor:	210.00		381.61	Total:	591.61		

Workorder: 1707051 In Date: 07/19/2017 Meter: 52363 Closed: 07/24/2017 Problem: ROAD CALL, R/REAR TIRE FLAT AS PER KATHY FROM HEALTH DEPT. - Travel to health department to inflate tire.return to Sr Shop for repairs. - Repair right rear tire.mount.balance.add N2.relearn Tpms. Hours 3.00 Labor: 180.00 Parts: 0.00 Total: 180.00 Meter: 52446 08/28/2017 Workorder: 1708031 In Date: 08/16/2017 Closed: Problem: A/C INOP. - Ac not working trace wiring harness found short **Parts List** Qty circuit,repair wiring harness,replace blower motor,resistor and A/c Blower Motor 1.00 check system pressure. A/c Blower Resister 1.00 Hours 6.00 Labor: 360.00 Parts: 553.41 Total: 913.41 Workorder: 1709955 Meter: 52856 In Date: 10/12/2017 Closed: 10/18/2017 Problem: PM Service - Pm Service **Parts List** Qty - Rotate and balance tires. Napagold Oil Filter 1.00 Napa Quart 5w30 6.00 Washer Fluid Concentr 1.00 Hours 2.75 Labor: 165.00 Parts: 28.32 Total: 193.32 Workorder: 1804849 Meter: 55934 In Date: 05/09/2018 **Closed:** 05/09/2018

- Transition Prep Charge

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00

:

Problem: Transition Prep Charge