

**Palm Beach County Fleet Management  
Asset Maintenance History**

**10175002 2008 FORD F150 Pickup, 1/2 Ton, 4X4, W/Super Crew Cab**

**Workorder:** 841241      **Meter:** 0      **In Date:** 07/10/2008      **Closed:** 07/10/2008  
**Problem:** PRE-DELIVERY INSPECTION

- Pre-delivery Inspection

Hours 2.00      Labor: 120.00      Parts: 0.00      Total: 120.00  
:

**Workorder:** 841574      **Meter:** 312      **In Date:** 07/17/2008      **Closed:** 07/17/2008  
**Problem:** HITCH PIN LOCK

- Supply Hitch Pin Lock For Greg C

**Parts List**

**Qty**

2571 Receiver Lock 5/8"      1.00

Hours 0.50      Labor: 30.00      Parts: 14.58      Total: 44.58  
:

**Workorder:** 934327      **Meter:** 6476      **In Date:** 02/23/2009      **Closed:** 03/03/2009  
**Problem:** P.M. SERVICE.

- Pm Service

**Parts List**

**Qty**

- Replace Missing Trailer Hitch Safety Chain.

Shop Supplies      1.00

- Repair Bent Frame At Left Lower Control Arm.repair Damaged Heat Shield.

1372 Oil Filter Frm Ph2 Wix 51372      1.00

- Complete Frotn End Alignment. Test Drive.

5w20 Engine Oil      7.00

- Shop Supplies

18410 Pintle Pin      1.00

Hours 8.75      Labor: 525.00      Parts: 23.88      Total: 548.88  
:

**Workorder:** 934630      **Meter:** 6476      **In Date:** 03/02/2009      **Closed:** 03/03/2009  
**Problem:** CHECK CANCEIVER/GIVE TO CYNTHIA FOR DETAIL

- Reprogram Canceiver With Proper Template Id#

Hours 0.50      Labor: 30.00      Parts: 0.00      Total: 30.00  
:

**Workorder:** 934900      **Meter:** 0      **In Date:** 03/04/2009      **Closed:** 03/09/2009  
**Problem:** 001 DETAIL VEHICLE      03/04/09

- 001 Detail Vehicle      03/04/09

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
:

**Workorder:** 938407      **Meter:** 9641      **In Date:** 05/29/2009      **Closed:** 06/22/2009  
**Problem:** WINCH WONT UNLOCK,CK TRAILER PLUG

- Winch Internal Failure From Water Intrusion.rr Failed Winch Assy W/new & Rewire W/new Circuit Breaker.

**Parts List**

**Qty**

Shop Supplies      1.00

- Front Drive Shaft Bellows Boot Leaking Grease.rr Front Driveshaft & Replace Fialed Bellows Boot With New To Correct Problem.

82-2178 Circuit Breaker 100amp      1.00

Cs2rv Red Cable 2 Gauge      2.00

- Rewire Trailer Pllug.inslulate And Secure Harness.

Clamp      1.00

- Fabricate & Repair Bent Frame.rr Lower Control Arms To Access Repairs

Front Drive Shaft Bellows Boot      1.00

Clamp      1.00

- Perform Wheel Alignment. Complete After Frame Repairs To Correct Toe Specs.

Winch      1.00

- Shop Supplies

Hours 11.00      Labor: 660.00      Parts: 925.47      Total: 1,585.47  
:

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 941947      **Meter:** 11164      **In Date:** 08/11/2009      **Closed:** 08/27/2009  
**Problem:** P.M service, tire light on.

- P.m service.	<b>Parts List</b>	<b>Qty</b>
- machine front & rear brake rotors, install new brake pads in rear, flush & bleed system, test drive.	Shop Supplies	1.00
- Rotate & balance all four tires.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Shop Supplies	Ca8039 Air Filter Lbf Af1615 Wix 46418	1.00
	G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
	Mkd1012 Brake Pads	1.00
	1401 Brake Fluid Brake Fluid	1.00
	5w20 Engine Oil	7.00
	Used Firex Refurbed Fire Extingshers	1.00
Hours 8.75	Labor: 525.00	Parts: 100.85
:		Total: 625.85

**Workorder:** 1003091      **Meter:** 17575      **In Date:** 03/26/2010      **Closed:** 04/05/2010  
**Problem:** PM service

- P.m service.	<b>Parts List</b>	<b>Qty</b>
- Inspect & service winch.	Shop Supplies	1.00
- Rotate & balance all four tires.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Shop Supplies	5w20 Engine Oil	7.00
	31-20 Wiper Blades 20" Blade	2.00
	Used Firex Refurbed Fire Extingshers	1.00
Hours 4.75	Labor: 285.00	Parts: 41.04
:		Total: 326.04

**Workorder:** 1006462      **Meter:** 20283      **In Date:** 06/18/2010      **Closed:** 06/29/2010  
**Problem:** Engine idles rough and shakes.

- Computer diagnose and power balance test.remove fan shroud and replace falied fan blade with new.	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
	Ca8039 Air Filter Lbf Af1615 Wix 46418	1.00
	Engine Cooling Fan Blade	1.00
Hours 2.50	Labor: 150.00	Parts: 55.51
:		Total: 205.51

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1008743      **Meter:** 21800      **In Date:** 08/13/2010      **Closed:** 08/18/2010  
**Problem:** Left front brake noisy.

- Perform pm service.	<b>Parts List</b>	<b>Qty</b>
- Install new front and rear brake pads,new front and rear brake rotors,new front calipers and service rear calipers.perform brake fluid flush and automated bleed hydraulic system with scan tool.	Big G Degreaser Stock# 485180002	1.00
- Inspect and perform power winch service.inspect and overhaul frozen and binding planetary gears.	Shop Supplies	1.00
- Rotate and balance all four tires.	Front Caliper	1.00
- Shop Supplies	Rear Rotor	2.00
	1372 Oil Filter Frm Ph2 Wix 51372	1.00
	Ca8039 Air Filter Lbf Af1615 Wix 46418	1.00
	G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
	Mkd1012 Brake Pads	1.00
	09997 Brake Clean	1.00
	Mx1083 Brake Pads	1.00
	Rotors Front	2.00
	Front Caliper	1.00
	1401 Brake Fluid Brake Fluid	1.00
	5w20 Engine Oil	7.00
Hours 13.75	Labor: 825.00	Parts: 771.99
:		Total: 1,596.99

**Workorder:** 1008830      **Meter:** 21808      **In Date:** 08/17/2010      **Closed:** 08/19/2010  
**Problem:** reflash canceiver-spot # 185

- Reflash Canceiver & Reprogram	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

**Workorder:** 1009262      **Meter:** 22025      **In Date:** 08/20/2010      **Closed:** 08/26/2010  
**Problem:** tires

- elpex	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:				

**Workorder:** 1101430      **Meter:** 26358      **In Date:** 02/07/2011      **Closed:** 03/03/2011  
**Problem:** P.M. service and winch engage knob broken.

- Perform pm service.	<b>Parts List</b>	<b>Qty</b>
- Diagnose and replace failed power winch housing/knob with new.inspect and service power winch.	Shop Supplies	1.00
- Shop Supplies	1372 Oil Filter Frm Ph2 Wix 51372	1.00
	5w20 Engine Oil	7.00
	31-20 Wiper Blades 20" Blade	2.00
	End Housing Assembly	1.00
	18410 Pintle Pin	1.00
Hours 4.75	Labor: 285.00	Parts: 200.64
:		Total: 485.64

**Workorder:** 1104613      **Meter:** 28733      **In Date:** 04/29/2011      **Closed:** 04/29/2011  
**Problem:** No Start

- From: 1 m pass Riverbend Park on right side of rd (gate) To: Lv Shop	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:				

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1104628      **Meter:** 28912      **In Date:** 04/29/2011      **Closed:** 05/03/2011  
**Problem:** Towed in for no crank,no start.

- Test battery and charging system.recharge and reterst battery,fail load test.replace defective battery.	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
	Group 65 Battery (mtc Bxt-65-850)	1.00
Hours 1.00	Labor: 60.00	Parts: 130.75
:		Total: 190.75

**Workorder:** 1107185      **Meter:** 31209      **In Date:** 07/07/2011      **Closed:** 07/20/2011  
**Problem:** Pm service.

- Perform pm service.	<b>Parts List</b>	<b>Qty</b>
- Inspect and replace failed groved idler pulley with new.	Shop Supplies	1.00
- Rotate and balance all four tires	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Perform winch service.	G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
- Shop Supplies	Ca8039 Air Filter Lbf Af1615 Wix 46418	1.00
	5w20 Engine Oil	7.00
	31-20 Wiper Blades 20" Blade	2.00
	Used Firex Refurbed Fire Extingshers	1.00
	Pulley	1.00
Hours 5.50	Labor: 330.00	Parts: 96.66
:		Total: 426.66

**Workorder:** 1112874      **Meter:** 36505      **In Date:** 12/06/2011      **Closed:** 12/15/2011  
**Problem:** Pm service

- Perform pm service.	<b>Parts List</b>	<b>Qty</b>
- Inspect and service power winch.	Shop Supplies	1.00
- Rotate and balance all four tires.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Shop Supplies	Ca8039 Air Filter Lbf Af1615 Wix 46418	1.00
	5w20 Engine Oil	7.00
Hours 4.75	Labor: 285.00	Parts: 29.77
:		Total: 314.77

**Workorder:** 1204285      **Meter:** 41850      **In Date:** 05/07/2012      **Closed:** 05/16/2012  
**Problem:** P.M. service.

- P.m. Service.	<b>Parts List</b>	<b>Qty</b>
- Replace both idler pulleys and serpentine belt.	Shop Supplies	1.00
- Inspect and service winch.	Serp Belt	1.00
- Rotate and balance all tires.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Shop Supplies	Ca8039 Air Filter Lbf Af1615 Wix 46418	1.00
	G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
	5w20 Engine Oil	7.00
	31-20 Wiper Blades 20" Blade	2.00
	Idler Pulleys Smooth	2.00
Hours 6.75	Labor: 405.00	Parts: 174.58
:		Total: 579.58

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1209267      **Meter:** 46775      **In Date:** 09/27/2012      **Closed:** 10/15/2012  
**Problem:** P.M. service.

- P.m. Service.	<b>Parts List</b>	<b>Qty</b>
- Inspect and service winch.	5w20 Engine Oil	7.00
- Rotate and balance all tires.	Ph2 Oil Filter Lbf Ph	1.00
- Shop Supplies	Ca8039 Air Filter Lbf	1.00
	31-20 Wiper Blades 20	2.00
	1401 Brake Fluid Bra	1.00
	Used Firex Refurbed F	1.00
	Shop Supplies	1.00
Hours 4.75	Labor: 285.00	Parts: 90.22
:		Total: 375.22

**Workorder:** 1210859      **Meter:** 47702      **In Date:** 11/06/2012      **Closed:** 11/30/2012  
**Problem:** Grinding noise from drive train sometimes.

- Diagnose drive train for noises.inspect and replace failed left front wheel bearing assembly with new.remove front axles,replace both failed locking hub actuators and solenoid control valve with new.	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Valve Assembly	1.00
	Actuator	2.00
	Hub Assembly	1.00
	Shop Supplies	1.00
Hours 5.00	Labor: 300.00	Parts: 635.38
:		Total: 935.38

**Workorder:** 1303863      **Meter:** 52176      **In Date:** 04/18/2013      **Closed:** 04/26/2013  
**Problem:** Pm service

- Perform pm service.	<b>Parts List</b>	<b>Qty</b>
- Install four new tires.nitrogen fill and balnce all four.	5w20 Engine Oil	7.00
- Remove right front axle and replace failed inner axle boot with new.	Napagold Oil Filter	1.00
- Perform wheel alignment complete.	Napagold Fuel Filter	1.00
- Inspect and service power winch.	Stg Wheel Cov - Ford	1.00
- Shop Supplies	31-20 Wiper Blades 20	2.00
	Lt265/70r17 Hnk Dyn Mt	4.00
	Boot	1.00
	Clamp	1.00
	Clamp	1.00
	Grease	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 9.75	Labor: 585.00	Parts: 1,480.60
:		Total: 2,065.60

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1308992      **Meter:** 57489      **In Date:** 09/05/2013      **Closed:** 09/20/2013  
**Problem:** Pm service.

- P.m. Service.	<b>Parts List</b>	<b>Qty</b>
- Test battery and charging system.replace bad battery.	5w20 Engine Oil	7.00
- Resurface rear brake rotors,replace rear pads.service and lube calipers.flush and bleed system.	Napagold Oil Filter	1.00
- Inspect and service winch.	31-20 Wiper Blades 20	2.00
- Rotate and balance all tires.	Pedal Pad	1.00
- Shop Supplies	Battery	1.00
	Brake Pads D1012	1.00
	Brake Cleaner	1.00
	Shop Supplies	1.00
Hours 10.25	Labor: 615.00	Parts: 207.19
:		Total: 822.19

**Workorder:** 1401531      **Meter:** 62684      **In Date:** 02/18/2014      **Closed:** 02/27/2014  
**Problem:** P.M. service.

- P.m. Service.	<b>Parts List</b>	<b>Qty</b>
- Inspect and service transfer case.	5w20 Engine Oil	7.00
- Service transmission.flush and refill system.	Napagold Oil Filter	1.00
- R&r front drive shaft and replace 'u' joints.	Napagold Fuel Filter	1.00
- Inspect and service winch.	Napagold Air Filter	1.00
- Rotate and balance all tires.	Wiper Blade	2.00
- Shop Supplies	Used Fire X Refurbished	1.00
	Ford Transfer Case Fluid	2.00
	Syn-atf Trans Fluid S	14.00
	Filter	1.00
	U Joint	1.00
	U-joint	2.00
	Shop Supplies	1.00
Hours 10.25	Labor: 615.00	Parts: 291.22
:		Total: 906.22

**Workorder:** 1402829      **Meter:** 63137      **In Date:** 03/24/2014      **Closed:** 03/28/2014  
**Problem:** Check engine light on and runs rough.

- Computer diagnose for check engine light on.perform major tune up and replace all eight failed sparkplugs and five ignition coils with new.	<b>Parts List</b>	<b>Qty</b>
- Perform air induction service and clean trottle body.flush fuel injectors and clear codes with scan tool.	Spark Plug	8.00
- Inspect and replace failed vacume line from Egr to intake for fail code P0106.clear codes with scan tool and roadtest.	Ford Ignition Coil	5.00
- Test and replace failed left rear turnsignal lamp bulb with new.	Ka8a Throttle Body- U	1.00
- Shop Supplies	408 Fuel Injection CI	1.00
	Bigg Degreaser	1.00
	connector	1.00
	Bulb	1.00
	Shop Supplies	1.00
Hours 7.75	Labor: 465.00	Parts: 490.84
:		Total: 955.84

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1403228      **Meter:** 63342      **In Date:** 04/02/2014      **Closed:** 04/08/2014  
**Problem:** wont fuel

- test and remove canceiver issue fuel card	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

**Workorder:** 1407751      **Meter:** 68077      **In Date:** 08/06/2014      **Closed:** 08/19/2014  
**Problem:** Pm service

- Pm service.	<b>Parts List</b>	<b>Qty</b>
- Inspect and service front differential.	5w20 Engine Oil	7.00
- Replace rear differential pinnion seal.inspect and service rear differential.	Napagold Oil Filter	1.00
- Rotate and balance all four tires.	Wiper Blade	2.00
- Inspect and service winch	Macs Chain Cable Lube	1.00
- Shop Supplies	75w140 Ford Axle Lube	2.00
	75w140 Ford Axle Lube	3.00
	Ptex Ultra Grey 3oz	1.00
	Friction Modifier	1.00
	Seal Asy	1.00
	Shop Supplies	1.00
Hours 9.25	Labor: 555.00	Parts: 217.25
:		Total: 772.25

**Workorder:** 1501580      **Meter:** 73299      **In Date:** 02/11/2015      **Closed:** 02/27/2015  
**Problem:** Pm service.Noise in right front when driving.

- Pm service.	<b>Parts List</b>	<b>Qty</b>
- Diagnose for noise and replace defective right front locking wheel hub actuator.	Actuator	1.00
- Inspect and replace both defective front struts.	Response Cmplt Assmby	2.00
- R&r damage driver seat..send out for repairs.	Seat R And R	1.00
- Inspect and service power winch.	5w20 Engine Oil	7.00
- Rotate and balance all four tires.	Napagold Oil Filter	1.00
- Shop Supplies	Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Napagold Fuel Filter	1.00
	Stg Wheel Cov - Ford	1.00
	Napagold Air Filter	1.00
	Shop Supplies	1.00
Hours 9.35	Labor: 561.00	Parts: 757.85
:		Total: 1,318.85

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1509558      **Meter:** 79563      **In Date:** 09/22/2015      **Closed:** 10/27/2015  
**Problem:** Pm service.

<ul style="list-style-type: none"> <li>- Pm service.</li> <li>- Inspect and replace broken front sway bar links.</li> <li>- Install two new tires.rotate and balance all four.</li> <li>- Pressure test and inspect cooling system.flush and replace antifreeze.</li> <li>- Replace front brake pads and two front calipers.resurface front brake rotors.flush and bleed system.replace parking brake shoes.</li> <li>- Test and replace both defective left and right headlamp bulbs.</li> <li>- Inspect and service winch.replace defective winch motor.</li> <li>- Shop Supplies</li> </ul>	<table border="0"> <thead> <tr> <th align="left" colspan="2"><b>Parts List</b></th> <th align="right"><b>Qty</b></th> </tr> </thead> <tbody> <tr><td>Reman Brake Shoes</td><td></td><td align="right">1.00</td></tr> <tr><td>5w20 Engine Oil</td><td></td><td align="right">7.00</td></tr> <tr><td>Napagold Oil Filter</td><td></td><td align="right">1.00</td></tr> <tr><td>Wiper Blade</td><td></td><td align="right">2.00</td></tr> <tr><td>Washer Fluid Concentr</td><td></td><td align="right">1.00</td></tr> <tr><td>Used Fire X Refurbished</td><td></td><td align="right">1.00</td></tr> <tr><td>Sway Bar Link</td><td></td><td align="right">2.00</td></tr> <tr><td>Peak Global</td><td></td><td align="right">2.00</td></tr> <tr><td>Caliper w/ Hardware - Left Front (eclips</td><td></td><td align="right">1.00</td></tr> <tr><td>Caliper w/ Hardware - Right Front (eclip</td><td></td><td align="right">1.00</td></tr> <tr><td>Brake Cleaner</td><td></td><td align="right">1.00</td></tr> <tr><td>Halogen Capsule</td><td></td><td align="right">2.00</td></tr> <tr><td>Disc Brake Pads</td><td></td><td align="right">1.00</td></tr> <tr><td>Lt265/70r17 Hnk Dyn Mt</td><td></td><td align="right">2.00</td></tr> <tr><td>Mtos P Motor Saco</td><td></td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> <tr><td>Tire Disposal Fee</td><td></td><td align="right">2.00</td></tr> <tr><td>Freight Charge</td><td></td><td align="right">1.00</td></tr> </tbody> </table>	<b>Parts List</b>		<b>Qty</b>	Reman Brake Shoes		1.00	5w20 Engine Oil		7.00	Napagold Oil Filter		1.00	Wiper Blade		2.00	Washer Fluid Concentr		1.00	Used Fire X Refurbished		1.00	Sway Bar Link		2.00	Peak Global		2.00	Caliper w/ Hardware - Left Front (eclips		1.00	Caliper w/ Hardware - Right Front (eclip		1.00	Brake Cleaner		1.00	Halogen Capsule		2.00	Disc Brake Pads		1.00	Lt265/70r17 Hnk Dyn Mt		2.00	Mtos P Motor Saco		1.00	Shop Supplies		1.00	Tire Disposal Fee		2.00	Freight Charge		1.00
<b>Parts List</b>		<b>Qty</b>																																																								
Reman Brake Shoes		1.00																																																								
5w20 Engine Oil		7.00																																																								
Napagold Oil Filter		1.00																																																								
Wiper Blade		2.00																																																								
Washer Fluid Concentr		1.00																																																								
Used Fire X Refurbished		1.00																																																								
Sway Bar Link		2.00																																																								
Peak Global		2.00																																																								
Caliper w/ Hardware - Left Front (eclips		1.00																																																								
Caliper w/ Hardware - Right Front (eclip		1.00																																																								
Brake Cleaner		1.00																																																								
Halogen Capsule		2.00																																																								
Disc Brake Pads		1.00																																																								
Lt265/70r17 Hnk Dyn Mt		2.00																																																								
Mtos P Motor Saco		1.00																																																								
Shop Supplies		1.00																																																								
Tire Disposal Fee		2.00																																																								
Freight Charge		1.00																																																								
Hours 17.25 :	Labor: 1,035.00	Parts: 1,425.08	Total: 2,460.08																																																							
	0																																																									

**Workorder:** 1511299      **Meter:** 79834      **In Date:** 11/04/2015      **Closed:** 11/09/2015  
**Problem:** lights

<ul style="list-style-type: none"> <li>- Ck Brake lights on truck and all lights with trailer plugged in inop. Trace Electrical short, replace trailer plug on truck, brake light switch, rear bulbs amd 2 blown fuse for trailer tow in juncton box</li> <li>- Shop Supplies</li> </ul>	<table border="0"> <thead> <tr> <th align="left" colspan="2"><b>Parts List</b></th> <th align="right"><b>Qty</b></th> </tr> </thead> <tbody> <tr><td>Female Conn Socket</td><td></td><td align="right">1.00</td></tr> <tr><td>Bulb</td><td></td><td align="right">2.00</td></tr> <tr><td>Atm-10 Fuse</td><td></td><td align="right">1.00</td></tr> <tr><td>Brake Light Switch</td><td></td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> </tbody> </table>	<b>Parts List</b>		<b>Qty</b>	Female Conn Socket		1.00	Bulb		2.00	Atm-10 Fuse		1.00	Brake Light Switch		1.00	Shop Supplies		1.00
<b>Parts List</b>		<b>Qty</b>																	
Female Conn Socket		1.00																	
Bulb		2.00																	
Atm-10 Fuse		1.00																	
Brake Light Switch		1.00																	
Shop Supplies		1.00																	
Hours 4.50 :	Labor: 270.00	Parts: 65.06	Total: 335.06																

**Workorder:** 1512919      **Meter:** 80552      **In Date:** 12/22/2015      **Closed:** 12/31/2015  
**Problem:** Check engine light on and no power.

<ul style="list-style-type: none"> <li>- Computer diagnose for check engine light on.code P0308 and P0316.replace defective #8 ignition coil.retest.</li> <li>- Diagnose for code P0401.replace defective Egr valve.and clear all codes.test drive.</li> <li>- Shop Supplies</li> </ul>	<table border="0"> <thead> <tr> <th align="left" colspan="2"><b>Parts List</b></th> <th align="right"><b>Qty</b></th> </tr> </thead> <tbody> <tr><td>Ford Ignition Coil</td><td></td><td align="right">1.00</td></tr> <tr><td>Egr Valve</td><td></td><td align="right">1.00</td></tr> <tr><td>5068 Penetrating Oil</td><td></td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> </tbody> </table>	<b>Parts List</b>		<b>Qty</b>	Ford Ignition Coil		1.00	Egr Valve		1.00	5068 Penetrating Oil		1.00	Shop Supplies		1.00
<b>Parts List</b>		<b>Qty</b>														
Ford Ignition Coil		1.00														
Egr Valve		1.00														
5068 Penetrating Oil		1.00														
Shop Supplies		1.00														
Hours 6.00 :	Labor: 360.00	Parts: 297.97	Total: 657.97													

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

**Workorder:** 1600968      **Meter:** 81677      **In Date:** 01/28/2016      **Closed:** 02/04/2016  
**Problem:** Ac inop

- Ac Performance and Leak test.recover freon.replace defective high side shrader valve.vacume and recharge system to specs.      **Parts List**      **Qty**  
Ac Valve Core High      1.00  
R134a Lv Shop 1      2.00  
- Shop Supplies      Shop Supplies      1.00

Hours 2.50      Labor: 150.00      Parts: 27.46      Total: 177.46  
:

---

**Workorder:** 1603785      **Meter:** 84246      **In Date:** 04/11/2016      **Closed:** 04/19/2016  
**Problem:** P.M. service and check engine light on.

- P.m. Service.      **Parts List**      **Qty**  
- Diagnose check engine light.p0606,p0316.perform pinpoint test and replace defective #6 coil.clear codes.      5w20 Engine Oil      7.00  
Napagold Oil Filter      1.00  
- Replace broken pintle pin.      20" Wiper Blade      2.00  
- Inspect and service winch.      Washer Fluid Concentr      1.00  
- Rotate and balance all tires.      Napagold Fuel Filter      1.00  
- Shop Supplies      Ford Ignition Coil      1.00  
Pintle Pin W/chain      1.00  
Shop Supplies      1.00

Hours 7.50      Labor: 450.00      Parts: 106.61      Total: 556.61  
:

---

**Workorder:** 1605465      **Meter:** 85566      **In Date:** 05/26/2016      **Closed:** 06/08/2016  
**Problem:** Had to jump start.

- Test battery and charging system.replace bad battery.      **Parts List**      **Qty**  
- Shop Supplies      Battery      1.00  
Shop Supplies      1.00

Hours 1.00      Labor: 60.00      Parts: 120.41      Total: 180.41  
:

---

**Workorder:** 1610249      **Meter:** 89466      **In Date:** 09/29/2016      **Closed:** 10/20/2016  
**Problem:** P.M. Service.

- P.m. Service.      **Parts List**      **Qty**  
- Replace two tires,rotate and balance all four.      Napagold Oil Filter      1.00  
- Inspect and service winch.      5w20 Engine Oil      6.00  
- Ccomplete wheel alignment.      22" Wiper Blade      2.00  
- Shop Supplies      Napagold Air Filter      1.00  
Used Fire X Refurbished      1.00  
Lt265/70r17 Hnk Dyn Mt      2.00  
Shop Supplies      1.00  
Tire Disposal Fee      2.00

Hours 8.25      Labor: 495.00      Parts: 693.06      Total: 1,188.06  
:

---

**Workorder:** 1701629      **Meter:** 92871      **In Date:** 02/15/2017      **Closed:** 02/15/2017  
**Problem:** Transition Prep Charge

- Transition Prep Charge

Hours 2.00      Labor: 120.00      Parts: 0.00      Total: 120.00  
:

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

<b>Workorder:</b> 1703085	<b>Meter:</b> 93053	<b>In Date:</b> 03/28/2017	<b>Closed:</b> 04/06/2017
<b>Problem:</b> pm/ prepare for transfer			
- Pm		<b>Parts List</b>	<b>Qty</b>
- Replace intake manifold and gasket		Napagold Oil Filter	1.00
- Replace r/f headlamp bulb		Napa Quart 5w20	7.00
- Replace Asset#'s		22" Wiper Blade	2.00
- Shop Supplies		Napagold Fuel Filter	1.00
		Distilled Water 1gal	2.00
		Thermostat	1.00
		Peak Global Antifrz	2.00
		Manifold Gasket Set	1.00
		Intake Manifold	1.00
		Hose Clamp	2.00
		Radiator Cap	1.00
		Halogen Capsule	1.00
		Shop Supplies	1.00
Hours 9.75	Labor: 585.00	Parts: 432.11	Total: 1,017.11
:			

---

<b>Workorder:</b> 1703406	<b>Meter:</b> 93161	<b>In Date:</b> 04/05/2017	<b>Closed:</b> 04/05/2017
<b>Problem:</b> 1 - Detail Vehicle Wash Ticket(s) Issued			
- 1 - Detail Vehicle Wash Ticket(s) Issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

---

<b>Workorder:</b> 1704030	<b>Meter:</b> 93206	<b>In Date:</b> 04/21/2017	<b>Closed:</b> 04/28/2017
<b>Problem:</b> Brakes are spongy.			
- Road test and verify complaint spongy brakes while braking.replace faulty brake master cylinder with new. flush and bleed brake system and road test.		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Brake Master Cylinder	1.00
		B Fluid Dot 3-32oz	2.00
		Non-chlor Brake Clnr	1.00
		Pedal Pad	1.00
		Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 222.86	Total: 342.86
:			

---

<b>Workorder:</b> 1705477	<b>Meter:</b> 93438	<b>In Date:</b> 06/01/2017	<b>Closed:</b> 06/06/2017
<b>Problem:</b> Check engine light on.			
- Computer diagnose check engine light .p0307,p0316.perform power balance test.r&r defective #7 coil and retest.reset Kam.clear codes and test drive.		<b>Parts List</b>	<b>Qty</b>
- Install steering wheel cover.		Ford Ignition Coil	1.00
- Shop Supplies		Stg Wheel Cov - Ford	1.00
		Shop Supplies	1.00
Hours 2.70	Labor: 162.00	Parts: 87.49	Total: 249.49
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1709391      **Meter:** 94217      **In Date:** 09/27/2017      **Closed:** 10/17/2017  
**Problem:** P.M. service.

- P.m. service.	<b>Parts List</b>	<b>Qty</b>
- Replace both worn front sway bar links.	5w20 Engine Oil	7.00
- Replace two cracked engine mounts and one transmission mount.	Napagold Oil Filter	1.00
	22" Wiper Blade	2.00
- Replacecorroded trailer plug socket and repair wiring.	Sway Bar Link	2.00
- Inspect and service power winch.	Socket	1.00
- Rotate and balance four tires.nitrofill.	Napagold Oil Filter	1.00
- Perform wheel alignment to center steering wheel.test drive.	Left Engine Mount	1.00
	Right Engine Mount	1.00
- Shop Supplies	Tram Mount	1.00
	Shop Supplies	1.00
Hours 15.00	Labor: 900.00	Parts: 545.15
:		Total: 1,445.15

**Workorder:** 1803334      **Meter:** 95403      **In Date:** 03/29/2018      **Closed:**  
**Problem:** P.M. service.

-	<b>Parts List</b>	<b>Qty</b>
- Stock Parts entry	5w20 Engine Oil	7.00
	Napagold Oil Filter	1.00
	Napagold Fuel Filter	1.00
	20" Wiper Blade	2.00
	Silicone Spray 10oz	1.00
	Lamp Assy	1.00
	Tag Lamp	1.00
	Ptex Ultra Grey 3oz	1.00
	Friction Modifier	2.00
	Chain	1.00
	Gasket	1.00
Hours 0.00	Labor: 0.00	Parts: 440.01
:		Total: 440.01

**Workorder:** 1805485      **Meter:** 95643      **In Date:** 05/30/2018      **Closed:** 05/30/2018  
**Problem:** Transition Prep Charge

- Transition Prep Charge	Hours 2.00	Labor: 120.00	Parts: 0.00	Total: 120.00
:				