

**Palm Beach County Fleet Management
Asset Maintenance History**

10152256 2004 GMC 1500 Pickup, 1/2 Ton, W/Toolbox

Workorder: 438567 **Meter:** 0 **In Date:** 03/18/2004 **Closed:** 03/18/2004
Problem: 001 WASH TICKET ISSUED OUT 03/18/04

- 001 Wash Ticket Issued Out 03/18/04

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 438611 **Meter:** 0 **In Date:** 03/19/2004 **Closed:** 03/19/2004
Problem: WASH VEHICLE

- Wash Vehicle
- Pre-delivery Inspection

Hours 2.50 Labor: 125.00 Parts: 0.00 Total: 125.00
:

Workorder: 539446 **Meter:** 6220 **In Date:** 03/18/2005 **Closed:** 03/23/2005
Problem: PM SERV

- Pm

Parts List	Qty
Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00
10w30 Motor Oil	5.00

Hours 2.00 Labor: 100.00 Parts: 8.51 Total: 108.51
:

Workorder: 555761 **Meter:** 8930 **In Date:** 09/26/2005 **Closed:** 09/27/2005
Problem: P.M SERVICE

- Pm Service

Parts List	Qty
Af1519 Air Filter Use Laf1520 Frm Ca8755a	1.00
1036 Oil Filter Frm Ph3980 Wix 51036	1.00
3481 Fuel Filter Frm G3727 Wix 33481	1.00
10020 Injector Cleaner Don't Reorder	1.00
10w30 Motor Oil	5.00

Hours 2.00 Labor: 100.00 Parts: 28.15 Total: 128.15
:

Workorder: 556848 **Meter:** 9058 **In Date:** 10/17/2005 **Closed:** 10/17/2005
Problem: TOOL BOX VANDALIZED

- Vandalism: Repair Locks And Repair Bent Lid On Tool Box.

Hours 2.00 Labor: 100.00 Parts: 0.00 Total: 100.00
:

Workorder: 632216 **Meter:** 9637 **In Date:** 01/03/2006 **Closed:** 01/10/2006
Problem: PICK UP TRUCK IN WPB

- Pick Up At Fleet After Body Repairs

Hours 1.00 Labor: 50.00 Parts: 0.00 Total: 50.00
:

Workorder: 632260 **Meter:** 0 **In Date:** 11/14/2005 **Closed:** 01/04/2006
Problem: QUALITY CAR REPAIR INC

- Quality Car Repair Inc

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 636539	Meter: 10095	In Date: 03/30/2006	Closed: 03/31/2006
Problem: P.M SERVICE			
- Pm Service		Parts List	Qty
		6678 Air Filter Frm Ca8755a Wix 46678	1.00
		1036 Oil Filter Frm Ph3980 Wix 51036	1.00
		3481 Fuel Filter Frm G3727 Wix 33481	1.00
		10020 Injector Cleaner Don't Reorder	1.00
		10w30 Motor Oil	5.00
Hours 2.00	Labor: 100.00	Parts: 39.48	Total: 139.48
:			
Workorder: 644105	Meter: 11917	In Date: 08/15/2006	Closed: 08/17/2006
Problem: REPLACE WIPER BLADES			
- Replace Wiper Blades		Parts List	Qty
		31-22 Wiper Blades 22" Wiper Blade	2.00
Hours 0.50	Labor: 25.00	Parts: 11.63	Total: 36.63
:			
Workorder: 646420	Meter: 12571	In Date: 10/02/2006	Closed: 10/04/2006
Problem: P.M SERVICE			
- Pm Service		Parts List	Qty
- Fill Tires W/nitrogen		1036 Oil Filter Frm Ph3980 Wix 51036	1.00
		3481 Fuel Filter Frm G3727 Wix 33481	1.00
		10020 Injector Cleaner Don't Reorder	1.00
		10w30 Motor Oil	5.00
		31-22 Wiper Blades 22" Wiper Blade	2.00
		Used Firex Refurbed Fire Extingshers	1.00
Hours 2.75	Labor: 151.25	Parts: 47.57	Total: 198.82
:			
Workorder: 735848	Meter: 14435	In Date: 03/19/2007	Closed: 03/20/2007
Problem: P.M.SERVICE			
- Pm Service		Parts List	Qty
- Differential Service		765-1589 Black Silicone	1.00
- Transmission Flush		6678 Air Filter Frm Ca8755a Wix 46678	1.00
- Repair Tag Light		1036 Oil Filter Frm Ph3980 Wix 51036	1.00
- Road Test		3481 Fuel Filter Frm G3727 Wix 33481	1.00
		10020 Injector Cleaner Don't Reorder	1.00
		85/140 Gear Oil Gear Lube	3.00
		Syn/atf Trans Fluid Synthetic	16.00
		10w30 Motor Oil	6.00
		31-22 Wiper Blades 22" Wiper Blade	2.00
Hours 5.75	Labor: 316.25	Parts: 133.62	Total: 449.87
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 744156	Meter: 17263	In Date: 09/14/2007	Closed: 09/18/2007
Problem: P.M.SERVICE			
- Pm Service		Parts List	Qty
		1036 Oil Filter Frm Ph3980 Wix 51036	1.00
		3481 Fuel Filter Frm G3727 Wix 33481	1.00
		10w30 Motor Oil	6.00
		31-22 Wiper Blades 22" Wiper Blade	2.00
Hours 2.00	Labor: 110.00	Parts: 34.39	Total: 144.39
:			
Workorder: 745618	Meter: 0	In Date: 10/15/2007	Closed: 10/15/2007
Problem: 001 WASH TICKET ISSUED OUT 10/15/07			
- 001 Wash Ticket Issued Out 10/15/07			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 833503	Meter: 19830	In Date: 02/01/2008	Closed: 02/05/2008
Problem: R/REAR TAIL LIGHT BROKEN			
- Remove Both Broken Tailights & Harnesses; Replace Both Harnesses & Lamp Housings		Parts List	Qty
		L/r Tailight	1.00
		R/r Tailight	1.00
Hours 1.00	Labor: 60.00	Parts: 294.44	Total: 354.44
:			
Workorder: 836011	Meter: 20837	In Date: 03/25/2008	Closed: 04/07/2008
Problem: P.M.SERVICE			
- Pm Service		Parts List	Qty
- R&r 4 Tires; Mount & Balance		1036 Oil Filter Frm Ph3980 Wix 51036	1.00
- Add Nitrogen		3481 Fuel Filter Frm G3727 Wix 33481	1.00
		1066 White Lithium (crc 05037)	1.00
		10020 Injector Cleaner Don't Reorder	1.00
		10w30 Motor Oil	6.00
		31-22 Wiper Blades 22" Wiper Blade	2.00
		Tire Disposal Fee	4.00
		Tires 235/75r16	4.00
		Waste Fees	4.00
Hours 4.75	Labor: 285.00	Parts: 525.15	Total: 810.15
:			
Workorder: 844216	Meter: 24425	In Date: 09/15/2008	Closed: 09/23/2008
Problem: SHUTS OFF/TRANSMISSION			
- Pm Service		Parts List	Qty
- C/s Shuts Off;scan For Dtc;test Fuel Sys,ign&timing;no Prob;test Fuel Press;ck Cap,rotor&coil;pinpoint Test;broken Wire In Harness;repair		6678 Air Filter Frm Ca8755a Wix 46678	1.00
		1036 Oil Filter Frm Ph3980 Wix 51036	1.00
		3481 Fuel Filter Frm G3727 Wix 33481	1.00
- Remove, Clean & Lubricate Steering Shaft		10w30 Motor Oil	6.00
- Transport & Pick Up At Dealer; Defective Instrument Cluster		31-22 Wiper Blades 22" Wiper Blade	2.00
		Used Firex Refurbed Fire Extingshers	1.00
Hours 10.00	Labor: 600.00	Parts: 56.35	Total: 656.35
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 940724	Meter: 31097	In Date: 07/15/2009	Closed: 07/22/2009
Problem: p.m.service			
- P.m.service		Parts List	Qty
- Install New Smoking Decals		1036 Oil Filter Frm Ph3980 Wix 51036	1.00
		10w30 Motor Oil	6.00
		Used Firex Refurbed Fire Extingshers	1.00
Hours 2.25	Labor: 135.00	Parts: 32.20	Total: 167.20
:			
Workorder: 941511	Meter: 31097	In Date: 07/17/2009	Closed: 08/03/2009
Problem: damage to rgt doorf			
- damage to rgt doorf			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1001079	Meter: 36137	In Date: 01/29/2010	Closed: 01/29/2010
Problem: LIGHT BULB OUT			
- Repair L/rear brake light.		Parts List	Qty
		3157 Tail Light Bulbs	1.00
Hours 0.50	Labor: 30.00	Parts: 1.20	Total: 31.20
:			
Workorder: 1001627	Meter: 36795	In Date: 02/16/2010	Closed: 02/22/2010
Problem: P.M.SERVICE			
- P. M. Service.		Parts List	Qty
		1036 Oil Filter Frm Ph3980 Wix 51036	1.00
		3481 Fuel Filter Frm G3727 Wix 33481	1.00
		10w30 Motor Oil	6.00
		31-22 Wiper Blades 22" Wiper Blade	2.00
Hours 2.00	Labor: 120.00	Parts: 37.43	Total: 157.43
:			
Workorder: 1007158	Meter: 38578	In Date: 07/08/2010	Closed: 07/19/2010
Problem: CHECK ENGINE LIGHT ON(INTERMITTENTLY)			
- C/s: Check enging light is on. Test drive, scan for codes & was unable to verify concern at this time.			
Hours 1.00	Labor: 60.00	Parts: 0.00	Total: 60.00
:			
Workorder: 1009232	Meter: 39222	In Date: 08/25/2010	Closed: 09/08/2010
Problem: P.M.SERVICE			
- P. M. Service.		Parts List	Qty
		1036 Oil Filter Frm Ph3980 Wix 51036	1.00
		6678 Air Filter Frm Ca8755a Wix 46678	1.00
		10w30 Motor Oil	6.00
		Used Firex Refurbed Fire Extingshers	1.00
Hours 2.00	Labor: 120.00	Parts: 42.30	Total: 162.30
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1103597 **Meter:** 42531 **In Date:** 04/04/2011 **Closed:** 04/11/2011
Problem: P. M. SERVICE

- P. M. Service.

- Verify needs rear brake pads. R&r brake pads, service calipers, turn rotors. Test drive. Verify, calipers locked up, disassemble. R&r calipers, bleed brake fluid system, & test drive.

- Verify, needs 4 tires, P235/75r16. Dismount, mount, balance, add 35 Psi of N2.

- Verify cargo light out & L/r turn signal. Replace cargo light bulb, repair L/r turn signal socket.

- Lube steering shaft, & reinstall.

Parts List	Qty
3481 Fuel Filter Frm G3727 Wix 33481	1.00
1036 Oil Filter Frm Ph3980 Wix 51036	1.00
Rear Brake Caliper	1.00
Rear Brake Caliper Assy.	1.00
Rear Brake Pads	1.00
10w30 Motor Oil	6.00
1401 Brake Fluid Brake Fluid	1.00
31-22 Wiper Blades 22" Wiper Blade	2.00
Used Firex Refurbed Fire Extingshers	1.00
P235/75r16 106s Wrangler St	4.00
Waste Fee	4.00
Tire Disposal Fee	4.00

Hours 9.00 Labor: 540.00 Parts: 770.30 Total: 1,310.30
:

Workorder: 1105813 **Meter:** 43330 **In Date:** 06/01/2011 **Closed:** 06/10/2011
Problem: NO START

- C/c: No start. Verify, test battery. Verify, bad. Replace battery, check charging system.

Parts List	Qty
Group 78 Battery (acd 78ps)	1.00

Hours 0.75 Labor: 45.00 Parts: 88.91 Total: 133.91
:

Workorder: 1109707 **Meter:** 47377 **In Date:** 09/12/2011 **Closed:** 09/20/2011
Problem: Left rear light out

- Replace right rear turn signal bulb.

Parts List	Qty
3157 Tail Light Bulbs	1.00

Hours 0.50 Labor: 30.00 Parts: 0.83 Total: 30.83
:

Workorder: 1110265 **Meter:** 47507 **In Date:** 09/26/2011 **Closed:** 09/29/2011
Problem: P.M.SERVICE

- P.m.service.

Parts List	Qty
1036 Oil Filter Frm Ph3980 Wix 51036	1.00
6678 Air Filter Frm Ca8755a Wix 46678	1.00
10w30 Motor Oil	6.00

Hours 2.00 Labor: 120.00 Parts: 29.86 Total: 149.86
:

Workorder: 1204695 **Meter:** 52321 **In Date:** 05/17/2012 **Closed:** 05/24/2012
Problem: p.m.service

- P. M. Service

- Clean leaves from vents. Clean out interior of cab.

Parts List	Qty
3481 Fuel Filter Frm G3727 Wix 33481	1.00
1036 Oil Filter Frm Ph3980 Wix 51036	1.00
10w30 Motor Oil	6.00
31-22 Wiper Blades 22" Wiper Blade	2.00
Used Firex Refurbed Fire Extingshers	1.00

Hours 3.00 Labor: 180.00 Parts: 48.10 Total: 228.10
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1206449	Meter: 52798	In Date: 07/10/2012	Closed: 07/11/2012
Problem: lr blinker, chargers do not work in truck			
- replace left rear turn signal bulb		Parts List	Qty
- ck charger not working verify concern and found both lighter and power point fuse blown and damage wire harness for power point replace fuse and repair wire harness		3157 Tail Light Bulbs	1.00
Hours 2.50	Labor: 150.00	Parts: 0.65	Total: 150.65
:			
Workorder: 1303316	Meter: 57357	In Date: 04/05/2013	Closed: 04/10/2013
Problem: pm			
- pm		Parts List	Qty
- verify leaking coolant remove thermostate housing silicone and reassemble test run		Napagold Oil Filter	1.00
		10w30 Bulk Sr	6.00
		Ptex Ultra Black 30z	1.00
Hours 4.00	Labor: 240.00	Parts: 33.03	Total: 273.03
:			
Workorder: 1304239	Meter: 57524	In Date: 04/30/2013	Closed: 05/06/2013
Problem: no air			
- ck ac operation installed gauges and checked presssure road test ck all connections rr low pressure switch sith a used one road tested aain ok			
Hours 2.00	Labor: 120.00	Parts: 0.00	Total: 120.00
:			
Workorder: 1308669	Meter: 60607	In Date: 08/27/2013	Closed: 08/29/2013
Problem: SCREW IN L/FRONT TIRE			
- ck nail in tdire dismount fl tire patch mount balance add n2			
- verify parking brake wont release remove assy grease lube and reinstall			
Hours 2.50	Labor: 150.00	Parts: 0.00	Total: 150.00
:			
Workorder: 1310013	Meter: 61106	In Date: 10/03/2013	Closed: 10/04/2013
Problem: DEAD BATTERY			
- dead battery charge battery test battery bad replace battery ck charging sys		Parts List	Qty
		Group 78 Battery	1.00
Hours 0.75	Labor: 45.00	Parts: 95.60	Total: 140.60
:			
Workorder: 1402584	Meter: 64195	In Date: 03/18/2014	Closed: 03/24/2014
Problem: P.M.SERVICE			
- pm		Parts List	Qty
- verify needs 4 tires		Napagold Fuel Filter	1.00
		Napagold Oil Filter	1.00
		10w30 Bulk Sr	6.00
		Wiper Blade	2.00
		183680418 P235-75r16	4.00
		Tire Disposal Fee	4.00
Hours 4.00	Labor: 240.00	Parts: 781.73	Total: 1,021.73
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1403031 **Meter:** 64476 **In Date:** 03/27/2014 **Closed:** 04/08/2014
Problem: R/REAR BRAKE LIGHT INOP.

- repair right rear	Parts List	Qty
	Bulb	1.00
Hours 0.50	Labor: 30.00	Parts: 0.99
:		Total: 30.99

Workorder: 1406405 **Meter:** 67772 **In Date:** 06/30/2014 **Closed:** 07/07/2014
Problem: LEFT FRONT TIRE REMOVE SCREW AND FIX

- replace left front tire damage side wall	Parts List	Qty
- remove dash board panel and repair wire for lighter	183680418 P235-75r16	1.00
	Tire Disposal Fee	1.00
Hours 2.50	Labor: 150.00	Parts: 189.68
:		Total: 339.68

Workorder: 1407800 **Meter:** 68931 **In Date:** 08/07/2014 **Closed:** 08/12/2014
Problem: p.m.service

- pm	Parts List	Qty
- vacuume and wash	Napagold Air Filter	1.00
	Napagold Oil Filter	1.00
	10w30 Bulk Sr	6.00
Hours 3.00	Labor: 180.00	Parts: 31.71
:		Total: 211.71

Workorder: 1412092 **Meter:** 70649 **In Date:** 12/03/2014 **Closed:** 12/29/2014
Problem: ck engine light stays on

- ck engine light is on scan and found code po341 perform pinpoint test found bad cmp sensor replace cmp sensor distributor cap rotor and clear codes	Parts List	Qty
	Distributor Cap	1.00
	Rotor	1.00
- test drive after repair	Cam Sensor W Pick-up	1.00
Hours 5.75	Labor: 345.00	Parts: 81.92
:		Total: 426.92

Workorder: 1501747 **Meter:** 71894 **In Date:** 02/18/2015 **Closed:** 02/24/2015
Problem: REPAIR HEAD LINER

- rr head liner assy	Parts List	Qty
	Headliner R&R	2.00
Hours 1.50	Labor: 90.00	Parts: 544.50
:		Total: 634.50

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1503787 **Meter:** 73373 **In Date:** 04/13/2015 **Closed:** 04/23/2015
Problem: pm

- pm	Parts List	Qty
- verify need front pads replace front pads turn rotors svc clipers	Napagold Fuel Filter	1.00
	Napagold Oil Filter	1.00
- verify front running light and third brake light out	10w30 Bulk Sr	6.00
	Washer Fl	1.00
	Wiper Blade	2.00
	Disc Brake Pads	1.00
	Bulb	2.00
Hours 6.00	Labor: 360.00	Parts: 106.38
:		Total: 466.38

Workorder: 1510108 **Meter:** 76530 **In Date:** 10/06/2015 **Closed:** 10/20/2015
Problem: P.M.SERVICE,CHECK A/C., CIG. LIGHTER INOP.

- pm	Parts List	Qty
- remove dash board panel ck and replace cig lighter socket power point socket and blown fuse	Napagold Oil Filter	1.00
	10w30 Bulk Sr	6.00
- ck ac found blend door acuator sticking and bad blower resistor replace blend door acuator and blower motor resistor	Washer Fluid Concentr	1.00
	Napagold Air Filter	1.00
- install how my driving decal	Used Fire X Refurbished	1.00
	Air Door Actuator	1.00
	Blower Motor Resistor	1.00
	25774623 Receptacle P	1.00
	Cig Lighter Assm	1.00
	Cig Retainer Clip	2.00
	Atm-20 Fuse	1.00
	Heat Ac Actuator Motr	1.00
Hours 9.00	Labor: 540.00	Parts: 303.78
:		Total: 843.78

Workorder: 1602220 **Meter:** 78688 **In Date:** 03/02/2016 **Closed:** 03/02/2016
Problem: Vehicle was towed by Priority Residence because it was Parked in a Complex that did not allow business vehicle

- Tow From: Priority Towing To: Fleet Management			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1607863 **Meter:** 81031 **In Date:** 08/01/2016 **Closed:** 08/12/2016
Problem: Pm service.

- p,m,service.	Parts List	Qty
- Repair Rear Reverse Light And L/front Marker Light	Used Fire X Refurbished	1.00
	Napagold Oil Filter	1.00
	10w30 Bulk Sr	6.00
	Napagold Fuel Filter	1.00
	22" Wiper Blade	2.00
	Washer Fluid Concentr	1.00
	Bulb	1.00
	Bulb	2.00
Hours 3.00	Labor: 180.00	Parts: 57.27
:		Total: 237.27

Workorder: 1611647 **Meter:** 83030 **In Date:** 11/14/2016 **Closed:** 11/21/2016
Problem: Has to jump start .

- C/c dead battery.check charging system.test battery.bad.replace battery.	Parts List	Qty
	Battery	1.00
	Battery	1.00
Hours 0.75	Labor: 45.00	Parts: 214.25
:		Total: 259.25

Workorder: 1612370 **Meter:** 83957 **In Date:** 12/01/2016 **Closed:** 12/19/2016
Problem: C/K ENGINE LIGHT STAYS ON, PASSENGER WINDOW INOP.

- Computer diagnose for check engine light on.codes P0128 and P0456.replace defective thermostat.flush cooling system.clear codes with scan tool and roadtest.	Parts List	Qty
- Diagnose and replace defective canister vent control valve.clear code with scan tool and test drive.	Vapor Can Vent Valve	1.00
	Thermostat	1.00
- Repair and balance right front tire.nitrogen fill all.	Thermostat Gasket	1.00
	Peak Global Antifrz	1.00
	Vapor Can Vent Valve	1.00
Hours 5.25	Labor: 315.00	Parts: 142.88
:		Total: 457.88

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1704999 **Meter:** 86770 **In Date:** 05/19/2017 **Closed:** 05/31/2017
Problem: PM Service.Dead battery.Headlamp inop.

- Pm Service	Parts List	Qty
- Rear brake job.cut rotors.service calipers.flush and bleed system.	Napagold Oil Filter	1.00
- Mount and balance four tires.	10w30 Bulk Sr	6.00
- R/r starter motor.test electrical and starting system	Used Fire X Refurbished	1.00
- Load test battery and replace bad battery.clean terminals and battery box	22" Wiper Blade	2.00
	Washer Fluid Concentr	1.00
	Napagold Fuel Filter	1.00
	Disc Brake Pads	1.00
	Non-chlor Brake Clnr	1.00
	183407418 P235-70r16	4.00
	New Starter	1.00
	Battery	1.00
	Battery	1.00
	Tire Disposal Fee	4.00
Hours 11.50	Labor: 690.00	Parts: 1,249.01
:		Total: 1,939.01

Workorder: 1709350 **Meter:** 88578 **In Date:** 09/26/2017 **Closed:** 11/13/2017
Problem: Towed in for crank but no start.

- Diagnose no start found bad fuel pump.replace fuel pump assembly and wiring harness.	Parts List	Qty
- Test drive vehicle after repairs and fill tank with 11 gallons of gas	Fuel Pump Assembly	1.00
Hours 5.50	Labor: 330.00	Parts: 270.17
:		Total: 600.17

Workorder: 1709442 **Meter:** 88515 **In Date:** 09/26/2017 **Closed:** 09/27/2017
Problem: Won't Start

- Tow From: 7001 Charleston shores Blvd To: Sr shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1712339 **Meter:** 90425 **In Date:** 12/15/2017 **Closed:** 12/18/2017
Problem: Pm Service

- Pm Service.	Parts List	Qty
- Rotate and balance.	Napagold Oil Filter	1.00
- Wash interior and tool box.remove trash.	10w30 Bulk Sr	6.00
	Washer Fluid Concentr	1.00
	22" Wiper Blade	2.00
Hours 5.25	Labor: 315.00	Parts: 30.45
:		Total: 345.45

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1806376 **Meter:** 93718 **In Date:** 06/21/2018 **Closed:** 06/29/2018
Problem: PM Service

- Pm Service.	Parts List	Qty
- Rotate and balalce four tires.patch and repaired right rear tire.	10w30 Bulk Sr	6.00
- Vacume debris from cowl.	Napagold Oil Filter	1.00
	22" Wiper Blade	2.00
	Washer Fluid Concentr	1.00
	Used Fire X Refurbished	1.00
	Napagold Fuel Filter	1.00
Hours 5.25	Labor: 315.00	Parts: 51.08
:		Total: 366.08

Workorder: 1809337 **Meter:** 95345 **In Date:** 09/11/2018 **Closed:** 09/11/2018
Problem: Transition Prep Charge

- Transition Prep Charge			
Hours 2.00	Labor: 120.00	Parts: 0.00	Total: 120.00
:			