Workorder:	938926	Meter: IVERY INSPE	•			In Date:	06/11/2009	Closed:	06/11/2009
		VERTINOPE	CTION						
- Pre-delivery	•					_			
	H	lours 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00
Workorder: Problem:	1004015 PM service	Meter: e.	4976			In Date:	04/19/2010	Closed:	04/23/2010
- P.m service.					Parts Li	st			(
- Shop Suppli	es				Shop Su	upplies			1
					1372 O	il Filter Frm	Ph2 Wix 513	372	1
					5w20 Er	ngine Oil			7
					31-22 W	/iper Blades	22" Wiper Bla	ade	2
	H	lours 2.00		Labor:	120.00	Parts:	27.26	Total:	147.26
Workorder:	. 1010238	Meter:	7197			In Date:	09/17/2010	Closed:	09/27/2010
Problem:	P.m. servi	ce and r/r tire	has slow	leak and can	ceiver.				
- Perform pm	service.				Parts Li	st			(
- Repair flat ri				ssure sensor	Shop Su	upplies			1
with new.rotate		ice all four tire	es.		1372 O	il Filter Frm	Ph2 Wix 513	372	1
- Shop Suppli	es				5w20 Er	ngine Oil			7
					Used Fi	rex Refurbe	d Fire Extings	hers	1
					Tire Pre	ssure Sens	or		1
	H	lours 4.00		Labor:	240.00	Parts:	84.17	Total:	324.17
Workorder: Problem:	1010521 flash canc	Meter: eiver. in spot	7197 # 186			In Date:	09/24/2010	Closed:	09/24/2010
- Reflash Can	ceiver				Parts Li	st			(
- Shop Suppli	es				Shop Su	upplies			1
	H	lours 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00
Workorder: Problem:	1012173 1 - Wash t	Meter: ticket(s) issued	7197 d			In Date:	10/29/2010	Closed:	10/29/2010
- 1 - Wash ticl	ket(s) issue	d							
	H :	lours 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
	1105386 Pm service	Meter: e and reset oil	10488 I life remir	nder see note	S.	In Date:	05/20/2011	Closed:	05/31/201
Workorder: Problem:					Parts Li	st			(
Problem:	service.								
		four tires.			Shop Su	upplies			1
Problem: - Perform pm	balance all	four tires.				• •	Ph2 Wix 513	372	1
Problem: - Perform pm - Rotate and b	balance all	four tires.			1372 O	• •	Ph2 Wix 513	372	
Problem: - Perform pm - Rotate and b	balance all	four tires.			1372 O 5w20 Er	il Filter Frm ngine Oil	Ph2 Wix 513		1

	1200894 Pm service.	Meter:	12500		lı	n Date:	01/27/2012	Closed:	02/22/20	12			
- Perform pm s	service.				Parts List					Qty			
- Rotate and b		r tires.			Shop Supp	olies				1.00			
- Shop Supplie							Ph2 Wix 513	372		1.00			
					5w20 Engi					7.00			
					-		22" Wiper Bla	ade		2.00			
		•		d Fire Extings			1.00						
							ats (rubber Qu		1.00				
	Hou :	rs 3.00		Labor:	180.00	Parts:	74.55	Total:	254.55				
	1204761 Install hitch,c	Meter: omputer sta	13768 and and traile	er plug.	lı	n Date:	05/21/2012	Closed:	06/11/20	12			
- Fabricate and			and and traile	er	Parts List					Qty			
connector.insta	-	tand.			Shop Supp	olies				1.00			
- Shop Supplie	es				Computer	Stand				1.00			
					5404 Fem	ale Conn	ector			1.00			
					5402 Sock	et Bracke	et			1.00			
					Trailer Hite	ch Receiv	er			1.00			
					18410 Pini	tle Pin				1.00			
	Hou :	rs 6.00		Labor:	360.00	Parts:	701.68	Total:	1,061.68				
	1207553 P.M. service.	Meter:	16342		h	n Date:	08/10/2012	Closed:	08/22/20	12			
- P.m. Service					Parts List					Qty			
- P.m. Service - Rotate and b		s.					Formula 50 Rt	u (zep)		Qty 2.00			
	alance all tire	S.				egreaser	Formula 50 Rf	u (zep)		-			
- Rotate and b	alance all tire	S.			F50001 De Shop Supp	egreaser olies	Formula 50 Rf /Itc Fa1883 W			2.00			
- Rotate and b	alance all tire	S.			F50001 De Shop Supp Ca10262 /	egreaser blies Air Filter N		ix 49883		2.00 1.00			
- Rotate and b	alance all tire	S.			F50001 De Shop Supp Ca10262 /	egreaser blies Air Filter M Filter Frm	∕ltc Fa1883 W	ix 49883		2.00 1.00 1.00			
- Rotate and b	alance all tire	S.			F50001 De Shop Supp Ca10262 A 1372 Oil F 5w20 Engi	egreaser blies Air Filter M Filter Frm ne Oil	∕ltc Fa1883 W	ix 49883 872		2.00 1.00 1.00			
- Rotate and b	alance all tire es	s. rs 3.00		Labor:	F50001 De Shop Supp Ca10262 A 1372 Oil F 5w20 Engi	egreaser blies Air Filter N Filter Frm ne Oil er Blades	/tc Fa1883 W) Ph2 Wix 513	ix 49883 372 ade	230.03	2.00 1.00 1.00 1.00 7.00			
- Rotate and b - Shop Supplie Workorder:	alance all tire es	rs 3.00 Meter:	16111 Ticket(s) Issu		F50001 De Shop Supp Ca10262 A 1372 Oil F 5w20 Engi 31-22 Wip 180.00	egreaser blies Air Filter N Filter Frm ne Oil er Blades	Mtc Fa1883 W 9 Ph2 Wix 513 9 22" Wiper Bla	ix 49883 372 ade	230.03 08/21/20	2.00 1.00 1.00 7.00 2.00			
- Rotate and b - Shop Supplie Workorder:	alance all tire es Hou : 1207945 1 - Detail Ver	rs 3.00 Meter: hicle Wash	Ticket(s) Issu		F50001 De Shop Supp Ca10262 A 1372 Oil F 5w20 Engi 31-22 Wip 180.00	egreaser blies Air Filter M Filter Frm ne Oil er Blades Parts:	Atc Fa1883 W Ph2 Wix 513 22" Wiper Bla 50.03	ix 49883 372 ade Total:		2.00 1.00 1.00 7.00 2.00			
- Rotate and b - Shop Supplie Workorder: Problem:	Hou Hou 1207945 1 - Detail Ver hicle Wash Ti	rs 3.00 Meter: hicle Wash	Ticket(s) Issu		F50001 De Shop Supp Ca10262 A 1372 Oil F 5w20 Engi 31-22 Wip 180.00	egreaser blies Air Filter M Filter Frm ne Oil er Blades Parts:	Mtc Fa1883 W n Ph2 Wix 513 5 22" Wiper Bla 50.03 08/21/2012	ix 49883 372 ade Total:	08/21/20	2.00 1.00 1.00 7.00 2.00			
 Rotate and b Shop Supplie Workorder: Problem: 1 - Detail Vel Workorder: 	Hou Hou 1207945 1 - Detail Ver hicle Wash Ti	rs 3.00 Meter: hicle Wash cket(s) Issu rs 0.00 Meter:	Ticket(s) Issu ied 20037	ied	F50001 De Shop Supp Ca10262 A 1372 Oil F 5w20 Engi 31-22 Wip 180.00	egreaser blies Air Filter M Filter Frm ne Oil er Blades Parts: n Date:	Mtc Fa1883 W n Ph2 Wix 513 5 22" Wiper Bla 50.03 08/21/2012	ix 49883 372 ade Total: Closed:	08/21/20	2.00 1.00 1.00 7.00 2.00			
 Rotate and b Shop Supplie Workorder: Problem: 1 - Detail Vel Workorder: 	Hou es Hou : 1207945 1 - Detail Ver hicle Wash Ti Hou : 1211512 Had to jump s	rs 3.00 Meter: hicle Wash cket(s) Issu rs 0.00 Meter: start in AM.	Ticket(s) Issu led 20037	ied Labor:	F50001 De Shop Supp Ca10262 A 1372 Oil F 5w20 Engi 31-22 Wip 180.00	egreaser blies Air Filter M Filter Frm ne Oil er Blades Parts: n Date:	Mtc Fa1883 W h Ph2 Wix 513 5 22" Wiper Bla 50.03 08/21/2012 0.00	ix 49883 872 ade Total: Closed: Total:	08/21/20	2.00 1.00 1.00 7.00 2.00			
 Rotate and b Shop Supplie Workorder: Problem: 1 - Detail Vet Workorder: Problem: 	Hou Hou 1207945 1 - Detail Ver hicle Wash Ti Hou 1211512 Had to jump s and charging	rs 3.00 Meter: hicle Wash cket(s) Issu rs 0.00 Meter: start in AM. system.ba	Ticket(s) Issu ied 20037 ttery failed loa	ied Labor:	F50001 De Shop Supp Ca10262 A 1372 Oil F 5w20 Engi 31-22 Wip 180.00 II 0.00	egreaser blies Air Filter M Filter Frm ne Oil er Blades Parts: n Date:	Mtc Fa1883 W h Ph2 Wix 513 5 22" Wiper Bla 50.03 08/21/2012 0.00	ix 49883 872 ade Total: Closed: Total:	08/21/20	2.00 1.00 1.00 7.00 2.00			
 Rotate and b Shop Supplie Workorder: Problem: 1 - Detail Vel Workorder: Problem: Test starting 	Hou Hou 1207945 1 - Detail Ver hicle Wash Ti Hou 1211512 Had to jump s and charging replace failed	rs 3.00 Meter: hicle Wash cket(s) Issu rs 0.00 Meter: start in AM. system.ba	Ticket(s) Issu ied 20037 ttery failed loa	ied Labor:	F50001 De Shop Supp Ca10262 A 1372 Oil F 5w20 Engi 31-22 Wip 180.00	egreaser blies Air Filter M Filter Frm ne Oil er Blades Parts: n Date:	Mtc Fa1883 W h Ph2 Wix 513 5 22" Wiper Bla 50.03 08/21/2012 0.00	ix 49883 872 ade Total: Closed: Total:	08/21/20	2.00 1.00 1.00 7.00 2.00 12			
 Rotate and b Shop Supplie Workorder: Problem: 1 - Detail Vel Workorder: Problem: Test starting after recharge. 	Hou Hou 1207945 1 - Detail Ver hicle Wash Tiv Hou 1211512 Had to jump s and charging replace failed	rs 3.00 Meter: hicle Wash cket(s) Issu rs 0.00 Meter: start in AM. system.ba	Ticket(s) Issu ied 20037 ttery failed loa	ied Labor:	F50001 De Shop Supp Ca10262 A 1372 Oil F 5w20 Engi 31-22 Wip 180.00 II 0.00 II Parts List Battery 65 Shop Supp	egreaser blies Air Filter M Filter Frm ne Oil er Blades Parts: n Date: N Date:	Mtc Fa1883 W h Ph2 Wix 513 5 22" Wiper Bla 50.03 08/21/2012 0.00	ix 49883 872 ade Total: Closed: Total: Closed:	08/21/20	2.00 1.00 1.00 7.00 2.00 112 112 112 112			

:

Workorder: Problem:	1302162 P.M. Service.	Meter:	22510			In Date:	03/04/2013	Closed:	03/20/20	013
- P.m. Service	Э.				Parts Lis	st				Qty
- Replace mis	sing pintle pin.				5w20 Eng	gine Oil				7.00
- Rotate and	balance all tires				1372 Oil	Filter				1.00
- Shop Suppli	es				31-22 Wi	per Blades	22			2.00
					Used Fire	ex Refurbe	d F			1.00
					Washer F	=				1.00
					18410 Pi	ntle Pin				1.00
					Shop Sup	pplies				1.00
	Hours :	\$ 3.25		Labor:	195.00	Parts:	58.69	Total:	253.69	
Workorder: Problem:	1303226 put spare tire o	Meter:	23194			In Date:	04/02/2013	Closed:	04/02/20	013
- Tow From: f	orest hill and jo	g								
	Hours	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
	:									
Workorder: Problem:	: 1303238 Right rear tire	Meter: flat.	23339			In Date:	04/03/2013	Closed:	04/05/20	013
Problem:		flat.		ame.	Parts Lis		04/03/2013	Closed:	04/05/20	
Problem:	Right rear tire ght rear tire.nitr	flat.		ame.		st	04/03/2013	Closed:	04/05/20	Qty
Problem: - Repair flat ri	Right rear tire ght rear tire.nitr es	flat.		ame. Labor:	Parts Lis Shop Su	st			04/05/20 62.00	Qty
Problem: - Repair flat ri - Shop Suppli Workorder:	Right rear tire ight rear tire.nitr ies Hours : 1303664	flat. ogen fill a s 1.00 Meter:	and balance sa	Labor:	Parts Lis Shop Sup 60.00	st pplies				Qty 1.00
Problem: - Repair flat ri - Shop Suppli Workorder: Problem:	Right rear tire ight rear tire.nitr ies Hours : 1303664 Install compute	flat. ogen fill a s 1.00 Meter: er stand.F	and balance sa 23792 Parts supplied	Labor: in vehicle	Parts Lis Shop Sup 60.00	st pplies Parts: In Date:	2.00	Total:	62.00	Qty 1.00
Problem: - Repair flat ri - Shop Suppli Workorder: Problem:	Right rear tire ight rear tire.nitr ies Hours : 1303664 Install compute ind install new co	flat. ogen fill a s 1.00 Meter: er stand.F	and balance sa 23792 Parts supplied	Labor: in vehicle	Parts Lis Shop Sup 60.00	st pplies Parts: In Date:	2.00	Total:	62.00	Qty 1.00
Problem: - Repair flat ri - Shop Suppli Workorder: Problem: - Fabricate ar and secure.	Right rear tire ight rear tire.nitr ies Hours : 1303664 Install compute ind install new co	flat. ogen fill a s 1.00 Meter: er stand.F	and balance sa 23792 Parts supplied	Labor: in vehicle stomer	Parts Lis Shop Sup 60.00	st pplies Parts: In Date:	2.00 04/15/2013	Total: Closed:	62.00	Qty 1.00 013 Qty
Problem: - Repair flat ri - Shop Suppli Workorder: Problem: - Fabricate ar and secure. - Shop Suppli Workorder:	Right rear tire ight rear tire.nitr ies Hours : 1303664 Install compute ind install new co	flat. ogen fill a s 1.00 Meter: er stand.F omputer s s 2.00 Meter:	23792 Parts supplied upplied by cus	Labor: in vehicle stomer	Parts Lis Shop Sup 60.00	st pplies Parts: In Date: st pplies	2.00 04/15/2013	Total: Closed:	62.00 04/19/20	Qty 1.00 013 Qty 1.00
Problem: - Repair flat ri - Shop Suppli Workorder: Problem: - Fabricate ar and secure. - Shop Suppli Workorder: Problem:	Right rear tire ight rear tire.nitries Hours : 1303664 Install compute id install new co ies Hours : 1307382	flat. Flat. Fogen fill a s 1.00 Meter: For stand.F For puter s s 2.00 Meter: at ,spare of	23792 Parts supplied upplied by cus 27027 on truck.	Labor: in vehicle stomer Labor:	Parts Lis Shop Sup 60.00	st pplies Parts: In Date: st pplies Parts: In Date:	2.00 04/15/2013 2.00	Total: Closed: Total:	62.00 04/19/20 122.00	Qty 1.00 013 Qty 1.00
Problem: - Repair flat ri - Shop Suppli Workorder: Problem: - Fabricate ar and secure. - Shop Suppli Workorder: Problem:	Right rear tire ight rear tire.nitri ies Hours : 1303664 Install compute ind install new co ies Hours : 1307382 Left rear tire fla	flat. Flat. Fogen fill a s 1.00 Meter: For stand.F For puter s s 2.00 Meter: at ,spare of	23792 Parts supplied upplied by cus 27027 on truck.	Labor: in vehicle stomer Labor:	Parts Lis Shop Sup 60.00 Parts Lis Shop Sup 120.00 Parts Lis	st pplies Parts: In Date: st pplies Parts: In Date:	2.00 04/15/2013 2.00 07/24/2013	Total: Closed: Total:	62.00 04/19/20 122.00	Qty 1.00 013 Qty 1.00 013 Qty
Problem: - Repair flat ri - Shop Suppli Workorder: Problem: - Fabricate ar and secure. - Shop Suppli Workorder: Problem: - Replace and	Right rear tire ight rear tire.nitri ies Hours : 1303664 Install compute ind install new co ies Hours : 1307382 Left rear tire fla	flat. Flat. Fogen fill a s 1.00 Meter: For stand.F For puter s s 2.00 Meter: at ,spare of	23792 Parts supplied upplied by cus 27027 on truck.	Labor: in vehicle stomer Labor:	Parts Lis Shop Sup 60.00 Parts Lis Shop Sup 120.00 Parts Lis	st pplies Parts: In Date: st pplies Parts: In Date: st 18 P235-7	2.00 04/15/2013 2.00 07/24/2013	Total: Closed: Total:	62.00 04/19/20 122.00	Qty 1.00 013 Qty 1.00
Problem: - Repair flat ri - Shop Suppli Workorder: Problem: - Fabricate ar and secure. - Shop Suppli Workorder: Problem: - Replace and	Right rear tire ight rear tire.nitri ies Hours : 1303664 Install compute ind install new co ies Hours : 1307382 Left rear tire fla	flat. Flat. Fogen fill a s 1.00 Meter: For stand.F For puter s s 2.00 Meter: at ,spare of	23792 Parts supplied upplied by cus 27027 on truck.	Labor: in vehicle stomer Labor:	Parts Lis Shop Sup 60.00 Parts Lis Shop Sup 120.00 Parts Lis 1837834	st pplies Parts: In Date: st Parts: In Date: st 18 P235-7 pplies	2.00 04/15/2013 2.00 07/24/2013	Total: Closed: Total:	62.00 04/19/20 122.00	Qty 1.00 013 Qty 1.00 013 Qty 2.00

Problem:	1308987 Pm service.	Meter:	28692			In Date:	09/05/2013	Closed:	09/20/20	013	
- P.m. Service).				Parts Lis	t				Qty	
- Replace two	tires,rotate a	nd balance	all four.		5w20 Eng	gine Oil				7.00	
- Complete wh	neel alignmen	t.test drive.			Napagold Oil Filter						
- Shop Supplie	es				Wiper Bla	ade				2.00	
					Washer F	-I				1.00	
					18378341	18 P235-7	70r17			2.00	
					Used Fire	e X Refurb	ished			1.00	
					Shop Sup	oplies				1.00	
					Tire Dispo					2.00	
	Hou :	ırs 6.50		Labor:	390.00	Parts:	478.17	Total:	868.17		
	1309791 Left rear tire	Meter: flat.	29181			In Date:	09/27/2013	Closed:	09/30/20	013	
- Repair and b	alance left re	ar tire.			Parts List					Qty	
- Shop Supplie					Shop Sup	oplies				1.00	
		ırs 1.00		Labor:		Parts:	2.00	Total:	62.00		
	1402278 P.M. service	Meter: had to jump	33964 start in A.m	٦.		In Date:	03/07/2014	Closed:	03/19/20	014	
- P.m. Service) .				Parts Lis	t				Qty	
- Test battery	and charging	system.rep	lace bad bat	ttery.	Napagold	I Oil Filter				1.00	
- Resurface fro	ont brake roto				1 0						
lube front and I					5w20 Eng	gine Oil					
Detete e H	rear calipers.f	lush and bl			5w20 Eng	gine Oil I Air Filter				6.00 1.00	
- Rotate and b	rear calipers.f palance all tire	lush and bl			5w20 Eng Napagold	-				6.00 1.00 1.00	
- Rotate and b - Shop Supplie	rear calipers.f palance all tire	lush and bl			5w20 Eng Napagold Mac Wite Battery 6	I Air Filter Lithium G 5				6.00 1.00 1.00 1.00	
	rear calipers.f palance all tire	lush and bl			5w20 Eng Napagold Mac Wite Battery 65 Front Pac	I Air Filter Lithium G 5 ds				6.00 1.00 1.00 1.00	
	rear calipers.f palance all tire	lush and bl			5w20 Eng Napagold Mac Wite Battery 68 Front Pac Brake Cle	I Air Filter Lithium G 5 ds eaner				6.00 1.00 1.00 1.00 1.00	
	rear calipers.f palance all tire es	ilush and bl		ystem.	5w20 Eng Napagold Mac Wite Battery 65 Front Pac Brake Cle Shop Sup	I Air Filter Lithium G 5 ds eaner oplies	ires			6.00 1.00 1.00 1.00 1.00	
	rear calipers.f palance all tire es	lush and bl		ystem.	5w20 Eng Napagold Mac Wite Battery 68 Front Pac Brake Cle	I Air Filter Lithium G 5 ds eaner oplies		Total:	759.97	6.00	
- Shop Supplie	rear calipers.f palance all tire es	ilush and bl es. Irs 8.50 Meter:	eed brake sy 37638	ystem. Labor:	5w20 Eng Napagold Mac Wite Battery 69 Front Pac Brake Cle Shop Sup 510.00	I Air Filter Lithium G 5 ds eaner oplies Parts: In Date:	ires	Total: Closed:	759.97 08/19/20	6.00 1.00 1.00 1.00 1.00 1.00	
- Shop Supplie	rear calipers.f palance all tire es Hou : 1407779	ilush and bl es. Irs 8.50 Meter:	eed brake sy 37638	ystem. Labor:	5w20 Eng Napagold Mac Wite Battery 69 Front Pac Brake Cle Shop Sup 510.00	I Air Filter Lithium G 5 ds eaner oplies Parts: In Date: arge.	Bres 249.97			6.00 1.00 1.00 1.00 1.00 1.00 1.00	
 Shop Supplie Workorder: Problem: Pm service. Test starting 	rear calipers.f palance all tire es Hou : 1407779 Pm service.C and charging	ilush and bl es. urs 8.50 Meter: Check engin	eed brake sy 37638 le light on.Ba	vstem. Labor: attery will n	5w20 Eng Napagold Mac Wite Battery 65 Front Pac Brake Cle Shop Sup 510.00	I Air Filter Lithium G 5 ds eaner oplies Parts: In Date: arge.	Bres 249.97			6.00 1.00 1.00 1.00 1.00 1.00 014	
 Shop Supplie Workorder: Problem: Pm service. Test starting with warranty p 	rear calipers.f palance all tire es Hou : 1407779 Pm service.C and charging part.	ilush and bl es. Irs 8.50 Meter: Check engin	eed brake sy 37638 le light on.Ba blace defecti	vstem. Labor: attery will n ve battery	5w20 Eng Napagold Mac Wite Battery 65 Front Pac Brake Cle Shop Sup 510.00 hot stay cha Parts Lis 5w20 Eng	I Air Filter Lithium G 5 ds eaner oplies Parts: In Date: arge.	Bres 249.97			6.00 1.00 1.00 1.00 1.00 1.00	
 Shop Supplie Workorder: Problem: Pm service. Test starting with warranty p Computer dia 	rear calipers.f palance all tire es Hou : 1407779 Pm service.C and charging part. agnose for ch	ilush and bl es. urs 8.50 Meter: Check engin i system.rep eck engine	eed brake sy 37638 le light on.Ba blace defecti light on.fail o	vstem. Labor: attery will n ve battery code	5w20 Eng Napagold Mac Wite Battery 65 Front Pac Brake Cle Shop Sup 510.00 hot stay cha Parts Lis 5w20 Eng	I Air Filter Lithium G 5 ds eaner oplies Parts: In Date: arge. t gine Oil I Oil Filter	Bres 249.97			6.00 1.00 1.00 1.00 1.00 1.00 014 014 7.00 1.00	
 Shop Supplie Workorder: Problem: Pm service. Test starting with warranty p Computer dia P0150.test and 	rear calipers.f palance all tire es Hou : 1407779 Pm service.C and charging part. agnose for ch d replace oxyg	flush and bl es. Irs 8.50 Meter: Check engin I system.rep eck engine gen sensor	eed brake sy 37638 le light on.Ba blace defecti light on.fail o	vstem. Labor: attery will n ve battery code	5w20 Eng Napagold Mac Wite Battery 65 Front Pac Brake Cle Shop Sup 510.00 hot stay cha Parts Lis 5w20 Eng Napagold	I Air Filter Lithium G 5 ds eaner oplies Parts: In Date: arge. t gine Oil I Oil Filter ade	Bres 249.97			6.00 1.00 1.00 1.00 1.00 1.00 7.00 1.00 2.00	
 Shop Supplie Workorder: Problem: Pm service. Test starting with warranty p Computer dia P0150.test and Rotate and b 	rear calipers.f palance all tire es Hou : 1407779 Pm service.C and charging part. agnose for ch d replace oxyg palance all fou	flush and bl es. Irs 8.50 Meter: Check engin I system.rep eck engine gen sensor	eed brake sy 37638 le light on.Ba blace defecti light on.fail o	vstem. Labor: attery will n ve battery code	5w20 Eng Napagold Mac Wite Battery 65 Front Pac Brake Cle Shop Sup 510.00 hot stay cha Parts Lis 5w20 Eng Napagold Wiper Bla Battery 65	I Air Filter Lithium G 5 ds eaner oplies Parts: In Date: arge. t gine Oil I Oil Filter ade	3res 249.97 08/07/2014			6.00 1.00 1.00 1.00 1.00 1.00 014 Qty 7.00 1.00 2.00 1.00	
 Shop Supplie Workorder: Problem: Pm service. Test starting with warranty p Computer dia P0150.test and 	rear calipers.f palance all tire es Hou : 1407779 Pm service.C and charging part. agnose for ch d replace oxyg palance all fou	flush and bl es. Irs 8.50 Meter: Check engin I system.rep eck engine gen sensor	eed brake sy 37638 le light on.Ba blace defecti light on.fail o	vstem. Labor: attery will n ve battery code	5w20 Eng Napagold Mac Wite Battery 65 Front Pac Brake Cle Shop Sup 510.00 hot stay cha Parts Lis 5w20 Eng Napagold Wiper Bla Battery 65	I Air Filter Lithium G 5 ds eaner oplies Parts: In Date: arge. t gine Oil I Oil Filter ade 5	3res 249.97 08/07/2014			6.00 1.00 1.00 1.00 1.00 1.00 014 Qty 7.00 1.00 2.00 1.00	
 Shop Supplie Workorder: Problem: Pm service. Test starting with warranty p Computer dia P0150.test and Rotate and b 	rear calipers.f palance all tire es Hou : 1407779 Pm service.C and charging part. agnose for ch d replace oxyg palance all fou	flush and bl es. Irs 8.50 Meter: Check engin I system.rep eck engine gen sensor	eed brake sy 37638 le light on.Ba blace defecti light on.fail o	vstem. Labor: attery will n ve battery code	5w20 Eng Napagold Mac Wite Battery 65 Front Pac Brake Cle Shop Sup 510.00 Not stay cha Parts Lis 5w20 Eng Napagold Wiper Bla Battery 65 Used Fire	Air Filter Lithium G 5 ds eaner oplies Parts: In Date: arge. t gine Oil I Oil Filter ade 5 X Refurb	3res 249.97 08/07/2014			6.00 1.00 1.00 1.00 1.00 1.00 014 014	

	1501454 Pm service.Pe	Meter: ower steeri	43180 ing noise.			In Date:	02/09/2015	Closed:	02/26/20)15
- Pm service.			5		Parts Lis	st				Qty
- Replace and	balance all fo	ur tires.			5w20 Eng					7.00
- Pressure test			tem.flush and	renew		d Oil Filter				1.00
engine coolant		0,				Air Filter				1.00
- Complete fro	ont end alignm	ent.			Wiper Bla					2.00
- Shop Supplie	es				Peak Glo	bal				2.00
					1837834	18 P235-7	′0r17			4.00
					Shop Sup	oplies				1.00
					Tire Disp	osal Fee				4.00
	Hour :	s 8.50		Labor:	510.00	Parts:	969.75	Total:	1,479.75	5
	1504707 Mount Spare	Meter:	44829			In Date:	05/07/2015	Closed:	05/08/20)15
- Tire Service	8100 Forest H	ill Blvd - M	ount Spare							
	Hour	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
	1504877 Right front tire	Meter: e flat.Check	45123 k turnsignal liq	ghts		In Date:	05/13/2015	Closed:	05/14/20)15
- Test and rep	lace both left r	ear turnsig	jnal lamp bulk	DS.	Parts Lis	st				Qty
- Repair flat ar	nd balance rigl	nt front tire	•		Long Life Small Bulb 2.0					
- Shop Supplie	es				Shop Sup	oplies				1.00
	Hour :	rs 1.50		Labor:	90.00	Parts:	11.54	Total:	101.54	
	1508267 Pm service.W	Meter: /iper blade:	48764 s.			In Date:	08/18/2015	Closed:	08/31/20)15
- Pm service.					Parts Lis	st				Qty
- Rotate and b	alance all four	tires.			5w20 Eng	gine Oil				7.00
- Shop Supplie	es				Napagolo	d Oil Filter				1.00
					Used Fire	e X Refurbi	ished			1.00
					Wiper Bla					2.00
						Fluid Conce	entr			1.00
					Drain Plu	a				1.00
						-				
					Shop Sup	oplies				1.00
	Hour :	rs 3.00		Labor:		oplies	57.70	Total:	237.70	1.00
	Hour : 1509387 need spare ke	Meter:	49641	Labor:	Shop Sup 180.00	oplies	57.70 09/17/2015	Total: Closed:	237.70 09/24/20	
	: 1509387 need spare ke	Meter:	49641	Labor:	Shop Sup 180.00	Parts:				
Problem:	: 1509387 need spare ke ogram extra ke	Meter:	49641	Labor:	Shop Sup 180.00 Parts Lis	Parts:	09/17/2015)15
Problem: - Make and pro	: 1509387 need spare ke ogram extra ke	Meter:	49641	Labor:	Shop Sup 180.00 Parts Lis	Parts: Parts: In Date: In Cate:	09/17/2015)15 Qty

Workorder: Problem:	1602022 Pm service.	Meter: Sun visor cli	54907 p broken.		Ir	n Date:	02/26/2016	Closed:	03/07/20	016
- Pm service.					Parts List					Qty
- Transmissio	on filter change	e,service an	d flush.		Napagold	Oil Filter				1.0
- Repair sunv	•				5w20 Engi					6.0
- Rotate and I					22" Wiper					2.0
- Shop Suppli	ies				Napagold	Air Filter				1.0
					Syn-atf Tra	ans Fluid	S			16.0
					Transmiss	ion Filter	Oe			1.0
					Used Fire	X Refurbi	ished			1.0
					Shop Supp	olies				1.0
	Hou :	urs 6.00		Labor:	360.00	Parts:	159.38	Total:	519.38	
Workorder: Problem:	1602677 Right front ti	Meter: re going flat	55213		lı	n Date:	03/14/2016	Closed:	03/17/20	016
- Replace and	d balance righ	nt front tire.			Parts List					Q
- Shop Suppli	ies				183783418		1.0			
					Shop Supp	olies				1.0
					Tire Dispo	cal Eag				1.0
						Salree				1.0
	Hou :	urs 0.50		Labor:			216.90	Total:	246.90	1.0
Workorder: Problem:	Hou : 1609799 P.M. service	Meter:	60671 lights.	Labor:	30.00		216.90 09/20/2016	Total: Closed:	246.90 09/29/20	
	: 1609799 P.M. service	Meter:		Labor:	30.00	Parts: n Date:				016
Problem:	: 1609799 P.M. service e.	Meter: and check	lights.		30.00	Parts: n Date:				016 Q1
Problem: - P.m. Service - Test battery - Resurface re	: 1609799 P.M. service e. and charging ear brake roto	Meter: and check system.rep prs,replace r	lights. lace bad batt	ery.	30.00 In Parts List 5w20 Engi Napagold	Parts: n Date: ine Oil Oil Filter				016 Qt 6.0 1.0
Problem: - P.m. Service - Test battery - Resurface re lube calipers.f	: 1609799 P.M. service e. and charging ear brake roto flush and blee	Meter: e and check g system.rep ors,replace r d system.	lights. lace bad batt	ery.	30.00 In Parts List 5w20 Engi Napagold 20" Wiper	Parts: n Date: ine Oil Oil Filter Blade	09/20/2016			016 Qt 6.0 1.0 2.0
Problem: - P.m. Service - Test battery - Resurface re lube calipers.f - Replace righ	: 1609799 P.M. service e. and charging ear brake roto lush and blee ht brake lamp	Meter: e and check g system.rep ors,replace r d system. bulb.	lights. lace bad batt	ery.	30.00 Parts List 5w20 Engi Napagold 20" Wiper Washer Fl	Parts: n Date: ne Oil Oil Filter Blade uid Conce	09/20/2016			016 Qt 6.0 1.0 2.0 1.0
Problem: - P.m. Service - Test battery - Resurface re lube calipers.f - Replace righ - Tune-up.rep	: 1609799 P.M. service and charging ear brake roto flush and blee ht brake lamp blace spark plu	Meter: e and check g system.rep ors,replace r d system. bulb. ugs.	lights. lace bad batt ear pads.ser\	ery. vice and	30.00 Parts List 5w20 Engi Napagold 20" Wiper Washer Fl Wd40 Spr	Parts: n Date: ne Oil Oil Filter Blade uid Conce	09/20/2016			016 Qt 6.0 1.0 2.0 1.0 1.0
Problem: - P.m. Service - Test battery - Resurface re lube calipers.f - Replace righ - Tune-up.rep	: 1609799 P.M. service e. and charging ear brake roto lush and blee ht brake lamp	Meter: e and check g system.rep ors,replace r d system. bulb. ugs.	lights. lace bad batt ear pads.ser\	ery. vice and	30.00 Parts List 5w20 Engi Napagold 20" Wiper Washer Fl Wd40 Spr Battery	Parts: n Date: ne Oil Oil Filter Blade uid Conce	09/20/2016			016 Qt 6.0 1.0 2.0 1.0 1.0
Problem: - P.m. Service - Test battery - Resurface re lube calipers.f - Replace righ - Tune-up.rep - Service and injectors. - Replace two	: 1609799 P.M. service e. and charging ear brake roto lush and blee ht brake lamp blace spark plu clean throttle	Meter: e and check g system.rep ors,replace r d system. bulb. ugs. e body and ir	lights. lace bad batt ear pads.serv	ery. vice and em.flush	30.00 Parts List 5w20 Engi Napagold 20" Wiper Washer Fl Wd40 Spr	Parts: n Date: ne Oil Oil Filter Blade uid Conce	09/20/2016			Q1 6.0 1.0 2.0 1.0 1.0 1.0 1.0
Problem: - P.m. Service - Test battery - Resurface re lube calipers of - Replace righ - Tune-up.rep - Service and injectors. - Replace two four.	: 1609799 P.M. service e. and charging ear brake roto flush and blee ht brake lamp blace spark plu clean throttle o tires,repair ri	Meter: e and check g system.rep ors,replace r d system. bulb. ugs. e body and ir ight rear.rota	lights. lace bad batt ear pads.serv nduction syste ate and balan	ery. vice and em.flush	30.00 Parts List 5w20 Engi Napagold 20" Wiper Washer Fl Wd40 Spr Battery Disc Brake	Parts: n Date: ne Oil Oil Filter Blade uid Conce	09/20/2016			016 Qt 6.0 1.0
Problem: - P.m. Service - Test battery - Resurface re- lube calipers.f - Replace righ - Tune-up.rep - Service and injectors. - Replace two four. - Complete w	: 1609799 P.M. service e. and charging ear brake roto lush and blee ht brake lamp blace spark plu clean throttle b tires,repair ri theel alignmer	Meter: e and check g system.rep ors,replace r d system. bulb. ugs. e body and ir ight rear.rota	lights. lace bad batt ear pads.serv nduction syste ate and balan	ery. vice and em.flush	30.00 Parts List 5w20 Engi Napagold 20" Wiper Washer Fl Wd40 Spr Battery Disc Brake Bulb	Parts: n Date: ine Oil Oil Filter Blade uid Conce	09/20/2016			Qt 6.0 1.0 2.0 1.0 1.0 1.0 1.0 1.0
Problem: - P.m. Service - Test battery - Resurface re ube calipers.f - Replace righ - Tune-up.rep - Service and njectors. - Replace two our. - Complete w	: 1609799 P.M. service e. and charging ear brake roto lush and blee ht brake lamp blace spark plu clean throttle b tires,repair ri theel alignmer	Meter: e and check g system.rep ors,replace r d system. bulb. ugs. e body and ir ight rear.rota	lights. lace bad batt ear pads.serv nduction syste ate and balan	ery. vice and em.flush	30.00 In Parts List 5w20 Engi Napagold 20" Wiper Washer Fl Wd40 Spr Battery Disc Brake Bulb spark plug	Parts: n Date: n Date: Oil Filter Blade uid Conce e Pads eaner	09/20/2016			016 Qt 6.0 1.0 2.0 1.0 1.0 1.0 8.0 1.0
Problem: - P.m. Service - Test battery - Resurface re lube calipers of - Replace righ - Tune-up.rep - Service and injectors. - Replace two four.	: 1609799 P.M. service e. and charging ear brake roto lush and blee ht brake lamp blace spark plu clean throttle b tires,repair ri theel alignmer	Meter: e and check g system.rep ors,replace r d system. bulb. ugs. e body and ir ight rear.rota	lights. lace bad batt ear pads.serv nduction syste ate and balan	ery. vice and em.flush	30.00 Parts List 5w20 Engi Napagold 20" Wiper Washer Fl Wd40 Spr Battery Disc Brake Bulb spark plug Injector Cle	Parts: n Date: n Date: oil Filter Blade uid Conco Pads eaner aner Kit	09/20/2016			Q1 6.0 1.0 2.0 1.0 1.0 1.0 1.0 8.0 1.0 1.0
Problem: - P.m. Service - Test battery - Resurface re- lube calipers.f - Replace righ - Tune-up.rep - Service and injectors. - Replace two four. - Complete w	: 1609799 P.M. service e. and charging ear brake roto lush and blee ht brake lamp blace spark plu clean throttle b tires,repair ri theel alignmer	Meter: e and check g system.rep ors,replace r d system. bulb. ugs. e body and ir ight rear.rota	lights. lace bad batt ear pads.serv nduction syste ate and balan	ery. vice and em.flush	30.00 Parts List 5w20 Engi Napagold 20" Wiper Washer Fl Wd40 Spr Battery Disc Brake Bulb spark plug Injector Cle Intake Clea 183783418	Parts: n Date: n Date: ine Oil Oil Filter Blade uid Conce e Pads eaner aner Kit 8 P235-7	09/20/2016			Qt 6.0 1.0 2.0 1.0 1.0 1.0 1.0 8.0
Problem: - P.m. Service - Test battery - Resurface re- lube calipers.f - Replace righ - Tune-up.rep - Service and injectors. - Replace two four. - Complete w	: 1609799 P.M. service e. and charging ear brake roto lush and blee ht brake lamp blace spark plu clean throttle b tires,repair ri theel alignmer	Meter: e and check g system.rep ors,replace r d system. bulb. ugs. e body and ir ight rear.rota	lights. lace bad batt ear pads.serv nduction syste ate and balan	ery. vice and em.flush	30.00 In Parts List 5w20 Engi Napagold 20" Wiper Washer Fli Wd40 Spr Battery Disc Brake Bulb spark plug Injector Cle Intake Clea	Parts: n Date: n Date: oil Filter Blade uid Conco e Pads eaner aner Kit 8 P235-7 plies	09/20/2016			016 Qf 6.0 1.0 2.0 1.0 1.0 1.0 1.0 1.0 2.0

Workorder: Problem:	1612780 Towed in for	Meter: crank but n	62533 o start.			In Date:	12/14/2016	Closed:	01/02/20	017
- Diagnose no Tsb 15-0137.c	o start.burnt fu clear codes an			epair per	Parts Li Sensor	st				Qty 1.00
 Diagnose ch test.replace ba Shop Suppli 					Fuse Re Shop Su	locate Kit pplies				1.00 1.00
		ırs 5.00		Labor:	300.00	Parts:	174.40	Total:	474.40	
Workorder: Problem:	1612791 wont start	Meter:	62532			In Date:	12/14/2016	Closed:	12/14/20	016
- Tow From: (Croc behind O	&m building	g hood up ke	eys in it						
	Hou	ırs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1700199 Right rear tire	Meter: e going flat.	62839			In Date:	01/06/2017	Closed:	01/11/20	017
- Repair and	balance right r	ear tire.			Parts Li	st				Qty
- Shop Suppl	es				Shop Su	pplies				1.00
	Hou	ırs 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1703593 P.M. service.	Meter:	64645			In Date:	04/10/2017	Closed:	04/18/20	017
- P.m. Service	э.				Parts Li	st				Qty
- Inspect and	service rear d	ifferential.			Tpms12	Sensor Tire	e Pr			1.00
- Replace two	tires,rotate a	nd balance	all four.		Tag Lam	np Socket				1.00
- Replace tag	lamp bulb and	l socket.			Lamp As	sy				1.00
- Shop Suppl	es				5w20 Er	igine Oil				6.00
					Napagol	d Oil Filter				1.00
					20" Wipe	er Blade				2.00
					Used Fir	e X Refurb	ished			1.00
					75w140	Ford Axle L	_ube			4.00
					Friction I					2.00
						a Grey 3oz				1.00
						18 P235-7	'0r17			2.00
					Shop Su					1.00
					Tire Dier					2.00
		ırs 5.50			330.00	osal Fee	727.20		1,057.20	

Workorder: 1709826 Meter: 67919 Problem: PM Service			In Date:	10/06/2017	Closed:	10/25/20	17
- P.m. service.		Parts Li	st				Qty
- Right side tail lamp broken .r&r with new.		2-pk 3in	Spot Mirror				1.00
- Left front door check stop broken.r&r with new.		5w20 Er		6.00			
- Rotate and high speed balance all four tires.			d Oil Filter				1.00
- Shop Supplies			d Air Filter				1.00
		20" Wipe					2.00
			el Cov - Fo	rd			1.00
		Lamp As					1.00
		Check A	-				1.00
		Shop Su	ipplies				1.00
Hours 4.30 La	abor:	258.00		225.70	Total:	483.70	
Workorder: 1804714 Meter: 72729			In Date:	05/04/2018	Closed:	05/24/20	18
Problem: P.M. service ,Abs light on and door ajar lig	ght or	n.					
- P.m. service.		Parts Li	st				Qty
- Replace both front rotors and brake pads .service calipe	ers	5w20 Er	ngine Oil				7.00
and flush and bleed brake system .	7	Napagol	d Oil Filter				1.00
 Computer diagnoise Abs light .codes B1342 and C1297 .perform pinpoint test .replace defective right front Abs se 		Used Fir	e X Refurbi	shed			1.00
and Abs module .program new module and clear codes a		20" Wipe	er Blade				2.00
road test.		Brake R	otor				2.00
- Check and replace left front door latch assembly and ca	able	Sensor A	Asy				1.00
 Replace fuel door housing . Balance and rotate all four tires. 		Front Pa					1.00
		Ful Door	ſ				1.00
- Shop Supplies		Fuel Hou	using				1.00
		Door Aja	ar Asy				1.00
		Door Ca	ble				1.00
		Abs Con	trol Module				1.00
		B Fluid [Dot 3-32oz				1.00
		Shop Su	Ipplies				1.00
Hours 11.00 La	abor:	660.00	Parts:	1,564.25	Total:	2,224.25	
Workorder: 1808803 Meter: 74711 Problem: Had to jump start in A/M			In Date:	08/27/2018	Closed:	08/29/20	18
- Charge battery fully . Test battery and charging system		Parts Li	st				Qty
Battery failed load test .r&r defective battery.		Battery					1.00
- Shop Supplies		Shop Su	pplies				1.00
onop oupplies				400.04	-	400.04	
	abor:	60.00	Parts:	130.64	l otal:	190.64	
	abor:	60.00	Parts:	08/30/2018	Closed:	08/30/20	18
Hours 1.00 La	abor:	60.00					18