10174398 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: Problem:	838295 PRE-DEI	<b>Meter:</b> LIVERY INSPE	0 ECTION			In Date:	05/09/2008	Closed:	05/09/20	800
- Pre-delivery	Inspection	n								
		Hours 2.00 :		Labor:	120.00	Parts:	0.00	Total:	120.00	
Workorder: Problem:	847528 PM SER	Meter: VICE	5779			In Date:	12/01/2008	Closed:	12/06/20	800
- Pm Service					Parts Li	st				Qty
- Rotate & Hig	gh Speed	Balance All 4 7	Tires.nitro Fill	То	Shop Su	upplies				1.00
Specs.					Ca1026	2 Air Filter N	/Itc Fa1883 W	/ix 49883		1.00
- Shop Suppli	es				1372 O	il Filter Frm	Ph2 Wix 51:	372		1.00
					G10166	Fuel Filter I	Mtc Fg1083 V	Vix 33243		1.00
					5w20 Er	ngine Oil				7.00
					1066 W	hite Lithium	(crc 05037)			1.00
					Used Fi	rex Refurbe	d Fire Extings	hers		1.00
		Hours 3.75		Labor:	225.00	Parts:	63.20	Total:	288.20	
Workorder: Problem:	939473 P.M. SEF	Meter: RVICE.REMO\	11193 /E COMPUTE	ER STANE	).	In Date:	06/26/2009	Closed:	06/30/20	009
-										
		Hours 0.00 :		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	940111 P.M SER	Meter: VICE, REMO	11193 /E COMP ST	AND		In Date:	07/02/2009	Closed:	07/27/20	009
- P.m service.					Parts Li	st				Qty
- Rotate & ba	lance all fo	our tires.			Shop Su	upplies				1.00
- Remove cus	stomers co	mp stand. rem	nove/reinstall	radios,	1372 O	il Filter Frm	Ph2 Wix 51	372		1.00
firex & person			•		5w20 Er	ngine Oil				7.00
		rrenty floor ma	t replacement	t.	31-20 W	/iper Blades	20" Blade			2.00
- Shop Suppli	es				Floor Ma	ats Front				1.00
		Hours 7.25		Labor:	435.00	Parts:	88.92	Total:	523.92	
Workorder: Problem:	945388 Check al	Meter: I tires for nails.	13560			In Date:	10/28/2009	Closed:	10/28/20	009
- Repair L/f &	L/r tires.				Parts Li	st				Qty
- Shop Suppli					Shop St					1.00
22p 2app		Hours 2.00 :		Labor:	120.00	Parts:	2.00	Total:	122.00	

Workorder:	1000634	Meter:	15582			In Date:	01/15/2010	Closed:	01/26/2	010
Problem:	pm service	also see note	es on cancei	iver						
- P.m service					Parts Li	ist				Qty
- Rotate & ba	lance all four	tires.			Shop Su	upplies				1.00
- Shop Suppl	ies				1372 O	il Filter Frm	n Ph2 Wix 51	372		1.00
					Ca1026	2 Air Filter N	Vitc Fa1883 W	/ix 49883		1.00
					G10166	Fuel Filter	Mtc Fg1083 V	Vix 33243		1.00
					5w20 Er	ngine Oil				7.00
					31-20 W	/iper Blades	20" Blade			2.00
					Used Fi	rex Refurbe	d Fire Extings	hers		1.00
	Ho :	urs 3.75		Labor:	225.00	Parts:	63.13	Total:	288.13	
Workorder: Problem:	1000943 Reprogram	Meter: Canceiver fo	15355 or new fuel c	ard Numbe	er	In Date:	01/26/2010	Closed:	01/26/2	010
- Reprogram	Canceiver				Parts Li	ist				Qty
- Shop Suppl	ies				Shop St	upplies				1.00
	Ho	urs 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1001077 canceiver	Meter:	15582			In Date:	01/29/2010	Closed:	02/02/2	010
- Repair And	Program Car	nceiver As Ne	eeded		Parts Li	ist				Qty
- Shop Suppl	ies				Shop Su	upplies				1.00
	Ho	urs 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1007646 P.M. Service	Meter:	19499			In Date:	07/20/2010	Closed:	08/04/2	010
- Perform pm	service.				Parts Li	ist				Qty
- Rotate and		ur tires.			Shop Su	upplies				1.00
- Transport ve	ehicle to and	from dealer t	o replace fa	iled ac	-		n Ph2 Wix 51:	372		1.00
condenser un			•			ngine Oil				7.00
- Shop Suppl	ies									
	Ho :	urs 5.75		Labor:	345.00	Parts:	17.44	Total:	362.44	
Workorder: Problem:	1008209 reflash cand	Meter: ceiver	19483			In Date:	08/02/2010	Closed:	08/04/2	010
- Reflash Car	nceiver				Parts Li	ist				Qty
- Shop Suppl	ies				Shop St	upplies				1.00
	Но	urs 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	

Workorder: Problem:	1101918 P.M. service.	Meter:	23594			In Date:	02/17/2011	Closed:	02/25/2011
- Perform pm	service.				Parts Li	ist			Qt
•	ew tires.nitroge	en fill and l	balance al	l four.	Shop Su	upplies			1.00
- Perform whe	eel alignment co	omplete.			1372 O	il Filter Frm	n Ph2 Wix 510	372	1.00
- Shop Supplie	es				G10166	Fuel Filter	Mtc Fg1083 V	Vix 33243	1.00
					5w20 Er	ngine Oil			7.00
					Used Fi	rex Refurbe	d Fire Extings	hers	1.00
					31-20 W	/iper Blades	20" Blade		2.00
					1796364	492 Lt245/7	5r17 Wrangle	r Sr-a E	4.0
					Tire Dis	posal Fee			4.00
					Tr416 V	alve Stem			4.00
	Hours :	s 7.25		Labor:	435.00	Parts:	798.77	Total:	1,233.77
Workorder: Problem:	1107082 0 - Wash ticke	Meter: et(s) issued	25401 d			In Date:	07/05/2011	Closed:	07/05/2011
- 0 - Wash tick	ket(s) issued								
	Hours :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1107083 1 - Detail Vehi	Meter: cle Wash	25401 Ticket(s) I	ssued		In Date:	07/05/2011	Closed:	07/05/2011
- 1 - Detail Ve	hicle Wash Tic	ket(s) Issu	ıed						
		s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1107271 1 - Wash ticke	Meter: et(s) issued	25401 d			In Date:	07/11/2011	Closed:	07/11/2011
- 1 - Wash tick	ket(s) issued								
	Hours :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1108757 1 - Wash ticke	Meter: et(s) issued	26808 d			In Date:	08/18/2011	Closed:	08/18/2011
- 1 - Wash tick	ket(s) issued								
	Hours :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1109157 P.M. Service	Meter:	27592			In Date:	08/29/2011	Closed:	09/07/2011
- Perform pm	service.				Parts Li	ist			Qt
•	palance all four	tires			Shop Su	upplies			1.00
- Shop Supplie	es				•		n Ph2 Wix 510	372	1.00
,							Mtc Fa1883 W		1.00
					5w20 Er	ngine Oil			7.00
					31-20 W	/iper Blades	20" Blade		2.00

Workorder: Problem:	1202364 P.M. service a	Meter: and has to	33813 jump start in A	A.M		In Date:	03/08/2012	Closed:	03/21/20	12
- P.m. Service	е.				Parts L	ist				Qty
- Charge and	test battery and	d charging	system.batte	ry failed	Shop S	upplies				1.00
•	ice defective ba	•			1372 C	il Filter Frm	Ph2 Wix 513	372		1.00
	balance all tires	<b>5.</b>			5w20 E	ngine Oil				7.00
- Shop Suppl	ies				31-20 V	Viper Blades	20" Blade			2.00
					Used Fi	rex Refurbe	d Fire Extings	hers		1.00
					Group 6	65 Battery (m	ntc Bxt-65-850	0)		1.00
	Hours :	s 4.75		Labor:	285.00	Parts:	174.22	Total:	459.22	
Workorder: Problem:	1202584 1 - Wash ticke	Meter: et(s) issued	33813 d			In Date:	03/15/2012	Closed:	03/15/20	12
- 1 - Wash tic	ket(s) issued									
	Hours :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1209087 P.M. service a	Meter: and detail.	35885			In Date:	09/21/2012	Closed:	09/28/20	12
- P.m. Service	е.				Parts L	ist				Qty
- Rotate and	balance all tires	<b>5.</b>			Shop S	upplies				1.00
- Shop Suppl	ies				1372 C	il Filter Frm	Ph2 Wix 513	372		1.00
					G10166	Fuel Filter I	Mtc Fg1083 W	Vix 33243		1.00
					5w20 E	ngine Oil				7.00
					Used Fi	rex Refurbe	d Fire Extings	hers		1.00
					31-20 V	Viper Blades	20" Blade			2.00
	Hours :	s 3.75		Labor:	225.00	Parts:	51.87	Total:	276.87	
Workorder: Problem:	1209317 1 - Detail Vehi	Meter: cle Wash	35885 Ticket(s) Issu	ied		In Date:	09/28/2012	Closed:	09/28/20	12
- 1 - Detail Ve	ehicle Wash Tic	ket(s) Issu	ıed							
		s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder:	1212296	Meter:	36492			In Date:	12/21/2012	Closed:	12/28/20	12
Problem:	Left brake lam	p inop and	d lens cracked	d						
	replace cracke	d left tail la	amp assembly	y with	Parts L	ist				Qty
new.install ne					Miniatu	re Bulb				1.00
- Shop Suppl	ies				Lamp					1.00
					Shop S	upplies				1.00
	Hours	s 1.00		Labor:	60.00	Parts:	54.41	Total:	114.41	
	•									

Problem:	1303094 P.M. Service.	Meter:	36542			In Date:	03/29/2013	Closed:	04/05/2	013
- Perform pm	service.				Parts Lis	st				Qty
- Rotate and	balance all four	r tires.			5w20 En	gine Oil				7.00
- Shop Suppli	ies				1372 Oil	Filter				1.00
					Napagol	d Air Filter				1.00
						ex Refurbe				1.00
					Shop Su	pplies				1.00
	Hour	s 3.75		Labor:	225.00	Parts:	53.48	Total:	278.48	
Workorder: Problem:	1312251 Pm service.Re	Meter: equest for	37453 detail vehicle.			In Date:	12/09/2013	Closed:	12/13/2	013
- Perform pm	service.				Parts Lis	st				Qty
	g and charging				5w20 En	gine Oil				7.00
_	replace failed		h new warrant	y part.	Napagol	d Oil Filter				1.00
	balance all four	r tires.			Napagol	d Fuel Filte	r			1.00
- Shop Suppli	ies				Wiper BI	ade				2.00
					Battery 6	<b>3</b> 5				1.00
					Shop Su	pplies				1.00
	Hour	s 4.75		Labor:	285.00	Parts:	182.57	Total:	467.57	
Workorder: Problem:	1312410 1 - Detail Veh	Meter: icle Wash	37281 Ticket(s) Issue	ed		In Date:	12/12/2013	Closed:	12/12/2	013
- 1 - Detail Ve	ehicle Wash Tid	cket(s) Issu	ıed							
- 1 - Detail Ve		cket(s) Issu s 0.00	ued	Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder:		Meter:	39005	Labor:	0.00	Parts:	0.00	Total:	0.00	014
Workorder: Problem:	Hour : 1403675 Low tire press	Meter:	39005 n.			In Date:				
Workorder: Problem: - Repair flat le	Hour: 1403675 Low tire pressent front tire.nitr	Meter:	39005 n.		Parts Lis	In Date:				Qty
Workorder: Problem:	Hour: 1403675 Low tire presseft front tire.nitries	Meter:	39005 n.		Parts Lis	In Date:	04/15/2014	Closed:		Qty
Workorder: Problem: Repair flat le Shop Suppli	Hour: 1403675 Low tire presseft front tire.nitries	Meter: sure light o ogen fill ar rs 1.00  Meter:	39005 n. nd balance san 39184	ne.	Parts Lis	In Date: st pplies	04/15/2014	Closed:	04/21/2	<b>Qty</b> 1.00
Workorder: Problem: - Repair flat le - Shop Suppli Workorder: Problem:	Hour: 1403675 Low tire pressert front tire.nitries Hour: 1404227	Meter: sure light o ogen fill ar s 1.00  Meter: I light inop	39005 n. nd balance san 39184	ne.	Parts Lis	In Date: st pplies Parts: In Date:	04/15/2014	Closed:	04/21/2 62.00	<b>Qty</b> 1.00
Workorder: Problem: - Repair flat le - Shop Suppli Workorder: Problem:	Hour: 1403675 Low tire press eft front tire.nitries Hour: 1404227 Left turnsigna	Meter: sure light o ogen fill ar s 1.00  Meter: I light inop	39005 n. nd balance san 39184	ne.	Parts Lis Shop Su 60.00	In Date: st pplies Parts: In Date:	2.00	Closed: Total: Closed:	04/21/2 62.00	Qty 1.00 014 Qty
Workorder: Problem: - Repair flat le - Shop Suppli  Workorder: Problem: - Replace left	Hour: 1403675 Low tire press eft front tire.nitries Hour: 1404227 Left turnsigna	Meter: sure light o ogen fill ar s 1.00  Meter: I light inop ht bulb. s 0.50  Meter:	39005 n. nd balance san 39184	ne. Labor:	Parts Lis Shop Su 60.00	In Date: st pplies Parts: In Date:	2.00	Closed: Total: Closed:	04/21/2 62.00 05/06/2	Qty 1.00 014 Qty 1.00
Workorder: Problem: - Repair flat le - Shop Suppli  Workorder: Problem: - Replace left  Workorder: Problem:	Hour: 1403675 Low tire press eft front tire.nitries Hour: 1404227 Left turnsignat rear signal ligh Hour: 1405111 Tire pressure	Meter: sure light o ogen fill ar rs 1.00  Meter: I light inop nt bulb. rs 0.50  Meter: light on.	39005 n. and balance san 39184	ne. Labor:	Parts Lis Shop Su 60.00	In Date:  st  pplies Parts:  In Date:  st  Parts:	04/15/2014 2.00 05/01/2014 0.99	Closed:  Total:  Total:	04/21/2 62.00 05/06/2 30.99	Qty 1.00 014 Qty 1.00
Workorder: Problem: - Repair flat le - Shop Suppli  Workorder: Problem: - Replace left  Workorder: Problem:	Hour: 1403675 Low tire press eft front tire.nitries Hour: 1404227 Left turnsignat rear signal ligh Hour: 1405111 Tire pressure	Meter: sure light o ogen fill ar rs 1.00  Meter: I light inop nt bulb. rs 0.50  Meter: light on.	39005 n. and balance san 39184	ne. Labor:	Parts Lis Shop Su 60.00 Parts Lis Bulb 30.00	In Date:  st  pplies     Parts:  In Date:  st  Parts:	04/15/2014 2.00 05/01/2014 0.99	Closed:  Total:  Total:	04/21/2 62.00 05/06/2 30.99	Qty 1.00 014 Qty 1.00

Workorder: 1407468 Meter: 41429 Problem: Pm service.Flat tire.Request to detail v	ehicle.		In Date:	07/30/2014	Closed:	08/11/2014
<ul> <li>Perform pm service.</li> <li>Replace drive belt</li> <li>Repair one flat tire.rotate and balance all four.</li> <li>Shop Supplies</li> </ul> Hours 5.75		5w20 E Napago Wiper B Belt	old Oil Filter ngine Oil old Air Filter Blade re X Refurbi upplies	shed 88.36	Total:	Qty 1.00 7.00 1.00 2.00 1.00 1.00 433.36
:	Labor.	040.00	i arts.	00.00	i Otai.	400.00
Workorder: 1407889 Meter: 41208 Problem: 1 - Detail Vehicle Wash Ticket(s) Issue - 1 - Detail Vehicle Wash Ticket(s) Issued	d		In Date:	08/11/2014	Closed:	08/11/2014
Hours 0.00	Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: 1501230 Meter: 42000 Problem: Pm service and check front shocks.			In Date:	02/03/2015	Closed:	02/19/2015
- Pm service.		Parts L	ist			Qty
- Replace and balance all four tires.		5w20 E	ngine Oil			7.00
- Inspect and replace both defective front lower control	ol arm	Napago	ld Oil Filter			1.00
bump stops.		Napago	ld Fuel Filte	r		1.00
<ul> <li>Inspect and replace all six defective body to frame mounts/insulators.</li> </ul>		Wiper B	Blade			2.00
- Complete front end alignment.		Lt245 7	5r17 M/s2 T	ire		4.00
- Shop Supplies		Tr416 V	alve Stem			4.00
Chief Cuppines		Body M	ount Kit			2.00
		Body M	ount Kit			4.00
		bumper				2.00
		•	eel Cov - Fo	rd		1.00
		Shop S	upplies			1.00
			posal Fee			4.00
Hours 14.25 :	Labor:	855.00	Parts:	1,793.58	Total:	2,648.58

Workorder: Problem:	1505094 Left rear brak	Meter: ces overhe	42422 ating.ABS war	ning light	on.Cup l	In Date: holder broke	05/19/2015 en.Towed in.	Closed:	05/27/20	)15
- Replace rear	brake pads,t	wo rear bra	ake calipers ar	nd two	Parts Li	ist				Qty
rear flexable bi					1401 B	rake Fluid B	bra .			2.00
- Replace brok	ken cup holde	r assembly	<i>1</i> .		Brake C	leaner				2.00
- Shop Supplie	es				Caliper	w/ Hardware	e - Right Rear	(eclips		1.00
					Caliper	w/ Hardware	e - Left Rear (	eclipse		1.00
					Brake H	lose				1.00
					Brake H	lose				1.00
					Holder					1.00
					Brake P	ad				1.00
					Shop Su	upplies				1.00
	Hou :	rs 5.25		Labor:	315.00	Parts:	411.11	Total:	726.11	
Workorder: Problem:	1505231 smoke comin	Meter: g from und	42410 derhood			In Date:	05/19/2015	Closed:	05/26/20	)15
- Tow From: 1 vista		-	les farm equip							
	Hou :	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1512863 Pm service.D	Meter: Detail,exteri	42738 or only.			In Date:	12/21/2015	Closed:	01/20/20	)16
- Pm service.					Parts Li	ist				Qty
- Check starting			battery failed		5w20 Er	ngine Oil				7.00
loadtest.replac		•			Napago	ld Oil Filter				1.00
- Replace defe		•			20" Wip	er Blade				2.00
<ul> <li>Check Abs light C1233.replace</li> </ul>					Washer	Fluid Conce	entr			1.00
codes and road		mont who	71 3pccu 3c113c	n.oleai	Used Fi	re X Refurbi	ished			1.00
- Rotate and b	alance all fou	r tires.			Battery					1.00
- Shop Supplie	es				Bulb					1.00
					Drain Pl	ug				1.00
					Sensor	Asy				1.00
					Shop St	upplies				1.00
	Hou :	rs 7.75		Labor:	465.00	Parts:	245.65	Total:	710.65	
Workorder: Problem:	1600219 1 - Detail Veh	Meter: nicle Wash	42540 Ticket(s) Issu	ed		In Date:	01/07/2016	Closed:	01/07/20	)16
- 1 - Detail Vel	hicle Wash Ti	cket(s) Issi	ued							
		rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1601615 wont fuel	Meter:	42738			In Date:	02/16/2016	Closed:	02/23/20	)16
- test and rem	ove canceive	r issue fuel	card		Parts Li	ist				Qty
- Shop Supplie					Shop Su					1.00
25p		rs 1.00		Labor:	•	Parts:	2.00	Total:	62.00	

Workorder: Problem:	1613140 P.M. Service	Meter: 44 Driver window	4279 v tint peeling	g.Detail.		In Date:	12/29/2016	Closed:	01/11/20	017
- P.m. Service			,	,	Parts Lis	st				Qty
- Rotate and b					Napagol	d Oil Filter				1.00
- Remove driv	er window tin	t and clean off	glue.		5w20 En					7.00
- Inspect and			J		20" Wipe	_				2.00
•		cooling systen	n.flush and	refill	•	Fluid Conce	entr			1.00
system.	·	0 ,			Ptex Ultr	a Grey 3oz				1.00
- Shop Supplie	es				Friction I	Modifier				2.00
					75w140	Ford Axle L	_ube			4.00
					Peak Glo	obal Antifrz				2.00
					Used Fir	e X Refurbi	ished			1.00
					Shop Su	pplies				1.00
	Hou	urs 7.75		Labor:	465.00		210.28	Total:	675.28	
Workorder:	1700150		4246			In Date:	01/05/2017	Closed:	01/05/20	017
Problem:	1 - Detail Vel	hicle Wash Tic	ket(s) Issue	ed						
- 1 - Detail Ve	hicle Wash Ti	icket(s) Issued								
	Hou	urs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1800215 P.M. service	Meter: 45	5017 nts.			In Date:	01/05/2018	Closed:	01/19/20	018
- P.m. service					Parts Lis	st				Qty
- Replace faile	ed light bulb fo	or left rear turn	signal and	both	Parts Lis 5w20 En					-
- Replace faile failed sealed b	ed light bulb fo eam headlam	nps.	-	both	5w20 En					7.00
<ul> <li>Replace faile failed sealed b</li> <li>Replace both</li> </ul>	ed light bulb fo eam headlam h rear failed s	nps. suspenion bum	p stops.	both	5w20 En	igine Oil d Oil Filter				7.00
<ul><li>Replace failed failed sealed b</li><li>Replace both</li><li>Rotate and h</li></ul>	ed light bulb fo eam headlam h rear failed s nigh speed ba	nps.	p stops.	both	5w20 En Napagol 20" Wipe	igine Oil d Oil Filter	ished			7.00 1.00 2.00
<ul> <li>Replace faile failed sealed b</li> <li>Replace both</li> </ul>	ed light bulb fo eam headlam h rear failed s nigh speed ba	nps. suspenion bum	p stops.	both	5w20 En Napagol 20" Wipe Used Fir	igine Oil d Oil Filter er Blade				7.00 1.00 2.00 1.00
<ul><li>Replace failed failed sealed b</li><li>Replace both</li><li>Rotate and h</li></ul>	ed light bulb fo eam headlam h rear failed s nigh speed ba	nps. suspenion bum	p stops.	both	5w20 En Napagol 20" Wipe Used Fir Napagol	igine Oil d Oil Filter er Blade e X Refurb	r			7.00 1.00 2.00 1.00 1.00
<ul><li>Replace failed failed sealed b</li><li>Replace both</li><li>Rotate and h</li></ul>	ed light bulb fo eam headlam h rear failed s nigh speed ba	nps. suspenion bum	p stops.	both	5w20 En Napagol 20" Wipe Used Fir Napagol	igine Oil d Oil Filter er Blade e X Refurbi d Fuel Filte Wheel Co	r			7.00 1.00 2.00 1.00 1.00
<ul><li>Replace failed failed sealed b</li><li>Replace both</li><li>Rotate and h</li></ul>	ed light bulb fo eam headlam h rear failed s nigh speed ba	nps. suspenion bum	p stops.	both	5w20 En Napagol 20" Wipe Used Fir Napagol Steering	igine Oil d Oil Filter er Blade e X Refurbi d Fuel Filte Wheel Co	r			7.00 1.00 2.00 1.00 1.00 1.00 2.00
<ul><li>Replace failed failed sealed b</li><li>Replace both</li><li>Rotate and h</li></ul>	ed light bulb fo eam headlam h rear failed s nigh speed ba	nps. suspenion bum	p stops.	both	5w20 En Napagol 20" Wipe Used Fir Napagol Steering Halogen	igine Oil d Oil Filter er Blade e X Refurbi d Fuel Filte Wheel Co	r			Qty 7.00 1.00 2.00 1.00 1.00 2.00 2.00
<ul><li>Replace failed failed sealed b</li><li>Replace both</li><li>Rotate and h</li></ul>	ed light bulb fo eam headlam h rear failed s nigh speed ba	nps. suspenion bum	p stops.	both	5w20 En Napagol 20" Wipe Used Fir Napagol Steering Halogen Bulb	igine Oil d Oil Filter er Blade e X Refurbi d Fuel Filte Wheel Co	r			7.00 1.00 2.00 1.00 1.00 2.00 2.00
<ul><li>Replace failed failed sealed b</li><li>Replace both</li><li>Rotate and h</li></ul>	ed light bulb for eam headlam In rear failed s nigh speed ba es	nps. suspenion bum	p stops.		5w20 En Napagol 20" Wipe Used Fir Napagol Steering Halogen Bulb Bumper	igine Oil d Oil Filter er Blade e X Refurbi d Fuel Filte Wheel Co Lamp	r	Total:	502.27	7.00 1.00 2.00 1.00 1.00 2.00 2.00 2.00
- Replace failed failed sealed be replace both replace both replace sand he shop Supplied workorder:	ed light bulb for eam headlam In rear failed s nigh speed ba es	nps. suspenion bum lance all four ti	p stops.		5w20 En Napagol 20" Wipe Used Fir Napagol Steering Halogen Bulb Bumper Shop Su	igine Oil d Oil Filter er Blade e X Refurbi d Fuel Filte Wheel Co Lamp	r over	Total:	502.27	7.00 1.00 2.00 1.00 1.00 2.00 2.00 2.00 1.00
- Replace failed failed sealed be replace both replace both replace sand he shop Supplied workorder:	ed light bulb for eam headlam hear failed shigh speed bases  Hou: 1806038 PM Service	nps. suspenion bum lance all four ti	p stops. ires.		5w20 En Napagol 20" Wipe Used Fir Napagol Steering Halogen Bulb Bumper Shop Su	egine Oil d Oil Filter er Blade e X Refurbi d Fuel Filte Wheel Co Lamp  pplies Parts:	r over 169.27			7.00 1.00 2.00 1.00 1.00 2.00 2.00 2.00 1.00
- Replace failed failed sealed be replace both replace both replace some replace some replace some replace rep	ed light bulb for eam headlam headlam headlam headlam headlam headlam headlam headlam headlam ship speed bases  House 1806038 PM Service e.	nps. suspenion bum lance all four ti	p stops. ires.		5w20 En Napagol 20" Wipe Used Fir Napagol Steering Halogen Bulb Bumper Shop Su 333.00	egine Oil d Oil Filter er Blade e X Refurbi d Fuel Filte Wheel Co Lamp  pplies Parts:	r over 169.27			7.00 1.00 2.00 1.00 1.00 2.00 2.00 2.00 1.00
- Replace failed failed sealed be replace both replace both replace both replace some sealed be replaced by replac	ed light bulb for eam headlam hear failed so high speed bases  Hou: 1806038 PM Service Example 1806038	nps. suspenion bum lance all four ti	p stops. ires.		5w20 En Napagoli 20" Wipe Used Fir Napagoli Steering Halogen Bulb Bumper Shop Su 333.00	igine Oil d Oil Filter er Blade e X Refurbi d Fuel Filte Wheel Co Lamp  pplies Parts: In Date: st d Oil Filter igine Oil	169.27 06/13/2018			7.00 1.00 2.00 1.00 1.00 2.00 2.00 2.00 1.00 018
- Replace failed failed sealed be replace both replace both replace some sealed be replaced by the replaced by	ed light bulb for eam headlam hear failed so high speed bases  Hou: 1806038 PM Service Example 1806038	nps. suspenion bum lance all four ti	p stops. ires.		5w20 En Napagoli 20" Wipe Used Fir Napagoli Steering Halogen Bulb Bumper Shop Su 333.00	egine Oil d Oil Filter er Blade e X Refurbi d Fuel Filte Wheel Co Lamp  pplies Parts: In Date: st d Oil Filter	169.27 06/13/2018			7.00 1.00 2.00 1.00 1.00 2.00 2.00 2.00 1.00
- Replace failed failed sealed be replace both replace both replace some sealed be replaced by the replaced by	ed light bulb for eam headlam hear failed so high speed bases  Hou: 1806038 PM Service Example 1806038	nps. suspenion bum lance all four ti	p stops. ires.		5w20 En Napagoli 20" Wipe Used Fir Napagoli Steering Halogen Bulb Bumper Shop Su 333.00	egine Oil d Oil Filter er Blade e X Refurbi d Fuel Filte Wheel Co Lamp  pplies Parts: In Date: st d Oil Filter egine Oil Fluid Conce	169.27 06/13/2018			7.00 1.00 2.00 1.00 1.00 2.00 2.00 2.00 1.00  7.00
- Replace failed failed sealed be - Replace both - Rotate and he - Shop Supplied - Shop Supplied - P.m. Service - Rotate and be - Rotate and b	ed light bulb for eam headlam hear failed so high speed bases  Hou: 1806038 PM Service Example 1806038	nps. suspenion bum lance all four ti	p stops. ires.		5w20 En Napagol 20" Wipe Used Fir Napagol Steering Halogen Bulb Bumper Shop Su 333.00 Parts Lis Napagol 5w20 En Washer	igine Oil d Oil Filter er Blade e X Refurbi d Fuel Filte Wheel Co Lamp  pplies Parts: In Date: st d Oil Filter egine Oil Fluid Concer Blade	169.27 06/13/2018			7.00 1.00 1.00 1.00 1.00 2.00 2.00 2.00 1.00  7.00 1.00 7.00 1.00

**Workorder:** 1809002 **Meter:** 45190 **In Date:** 08/30/2018 **Closed:** 08/30/2018

Problem: Transition Prep Charge

- Transition Prep Charge

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00

: