

55345 Palm Tran Connection v 2.2 Page 1 of 9



WorkOrder: 51319745 **Invoice Number:** 55345-51319745

Client Department:

PM A

MRC: 4505-P 55345M **Equipment:** WO Desc:

Ford E450 Champion Challenger

1FDFE4FS6EDB17167 VIN:

Requested By: TDELVA Status: 40 **Created By: TDELVA Priority:** 1

Class: WO **Driver: Arrangement:** Unassigned Phone: **Potential Warranty:** ETA: No

	Chronology	
Reported	May 31, 2018	11:05 AM
Started	May 31, 2018	
Completed	Jun 1, 2018	8:01 AM
Down T		

Meter	Reading	UOM
WO		DH
Life	155,460	DH
System	155,723	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA
	CAUSE: preventive maintenance
	CORRECTION: perform service lube all Pivoting Points cross rotate tires complete

Activity: 10 999 TOTAL VEHICLE Light Medium Duty PMI **Activity Note:** Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Part Number	Description	Qty. Each Extended
------------------	-------------	--------------------

Labor Posted

Date	Technician	Hours	Rate	Extended
31-May-18	Pierre,Hubert J	6.00	0.00	0.00

Activity 10 Sub Total Parts: 0.00 Labor: 0.00 Labor Hours: 6.00 Sublet Parts: 0.00 Sublet Labor: 0.00 **Activity Sub Total** 0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Date	Part Number	Description	Qty.	Each	Extended
31-May-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



55345 Palm Tran Connection v 2.2 Page 2 of 9



WorkOrder: 51319745
Invoice Number: 55345-51319745

Client Department:

MRC: WO Desc:

PM A

Class:

55345M

Equipment:

4505-P

Ford E450 Champion Challenger

VIN:

1FDFE4FS6EDB17167

Requested By: T Created By:

TDELVA TDELVA WO Status: Priority: Driver: 40 1

Arrangement: Potential Warranty:

Unassigned No Phone: ETA:

Labor Posted

Date	Technician	Hours	Rate	Extended
31-May-18	Pierre,Hubert J	0.42	0.00	0.00

 Activity
 20 Sub Total

 Parts:
 1.96

 Labor:
 0.00

 Labor Hours:
 0.42

 Sublet Parts:
 0.00

 Sublet Labor:
 0.00

 Activity Sub Total
 1.96

Activity: 30

999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 - Inspection, Routine

Work Accomplished: 06 - Inspect

Part Failure:

Activity Comments

Parts Issued

Ι	Date	Part Number	Description	Otv.	Each	Extended	
				-C-/-			

Labor Posted

Date	Technician	Hours	Rate	Extended
31-May-18	Pierre,Hubert J	0.08	0.00	0.00

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.08	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

WorkOrder 51319745 Grand Total	
Parts:	1.96
Labor:	0.00
Labor Hours: 6.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	1.96

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
51319745	1-Jun-18	155,460	WO	PM A
51333006	10-May-18	152,061	WO	The front A/C not working



55345 Palm Tran Connection v 2.2 Page 3 of 9



WorkOrder: **51319745 Invoice Number:** 55345-51319745

Client Department:

MRC: 55345M **Equipment:** 4505-P

WO Desc: Ford E450 Champion Challenger PM A VIN: 1FDFE4FS6EDB17167

Requested By:TDELVAStatus:40Created By:TDELVAPriority:1

Class: WO Driver:
Arrangement: Unassigned Phone:
Potential Warranty: No ETA:

Potentiai W	arranty:	IN	U	E 17	11				
WorkOrder	Date Completed	Life Meter	Class		Description				
51146321	2-May-18	151,149	WO	РМ С					
Scheduled Preventative Maintenance									
Nest		PM	WorkOrd	er	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2
Other Open	Repairs								
WorkOrder8	Date Reported	Life Meter	Class			Description			
51167230	2-Apr-18	147,174	WO	Front Ro	otors /Shocks/Brakes				

PH: Work Order: 51319745 Desc: PM A

Equip: 4505-P Desc: Ford E450 Champion Challenger VIN: 1FDFE4FS6EDB17167

LH: 10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 31-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	May 31, 2018 3:09:50 PM	No	
10,100	Safety Inspection	Done		HPIERRE	May 31, 2018 3:09:50 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	May 31, 2018 3:09:50 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		HPIERRE	May 31, 2018 3:09:50 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	May 31, 2018 3:09:50 PM	No	
10,140	Check Service Brakes	Done		HPIERRE	May 31, 2018 3:09:50 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	May 31, 2018 3:09:51 PM	No	
10,160	FRA Check Instruments and Horns	Done		HPIERRE	May 31, 2018 3:09:51 PM	No	
10,170	Check Fast Idle	Done		HPIERRE	May 31, 2018 3:09:51 PM	No	
10,180	Check Starter Protection Circuit	Done		HPIERRE	May 31, 2018 3:09:51 PM	No	
10,190	Check Reverse Warning System	Done		HPIERRE	May 31, 2018 3:09:51 PM	No	
11,100	Check Parking Brake	Done		HPIERRE	May 31, 2018 3:09:51 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		HPIERRE	May 31, 2018 3:09:51 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	May 31, 2018 3:09:51 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		HPIERRE	May 31, 2018 3:09:52 PM	No	
11,140	Road Test: Check for Proper Operation	Done		HPIERRE	May 31, 2018 3:09:52 PM	No	
11,150	Perform Brake Test	Done		HPIERRE	May 31, 2018 3:09:52 PM	No	
11,152	Decelerometer Results Test 1	FEET	N/A	HPIERRE	May 31, 2018 3:09:52 PM	No	
11,154	Decelerometer Results Test 2	FEET	N/A	HPIERRE	May 31, 2018 3:09:52 PM	No	
11,156	Decelerometer Results Test 3	FEET	N/A	HPIERRE	May 31, 2018 3:09:52 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	N/A	HPIERRE	May 31, 2018 3:09:53 PM	No	
11,162	FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A	HPIERRE	May 31, 2018 3:09:53 PM	No	
11,170	FRA Check Door Operation	Done		HPIERRE	May 31, 2018 3:09:53 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		HPIERRE	May 31, 2018 3:09:53 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		HPIERRE	May 31, 2018 3:09:53 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		HPIERRE	May 31, 2018 3:09:54 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		HPIERRE	May 31, 2018 3:09:54 PM	No	
20,230	FRA Check Wiring Under Dash	Done		HPIERRE	May 31, 2018 3:09:54 PM	No	
20,240	FRA Check Interior Lights	Done		HPIERRE	May 31, 2018 3:09:54 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		HPIERRE	May 31, 2018 3:09:54 PM	No	
20,260	Check Stop Request System	-	N/A	HPIERRE	May 31, 2018 3:09:54 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	May 31, 2018 3:09:54 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	May 31, 2018 3:09:54 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	May 31, 2018 3:09:55 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		HPIERRE	May 31, 2018 3:09:55 PM	No	
22,110	Check Emergency Hatches	Done		HPIERRE	May 31, 2018 3:09:55 PM	No	
22,120	Check All Safety Equipment	Done		HPIERRE	May 31, 2018 3:09:55 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		HPIERRE	May 31, 2018 3:09:55 PM	No	
30,310	Check Passenger Doors	Done		HPIERRE	May 31, 2018 3:09:55 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		HPIERRE	May 31, 2018 3:09:55 PM	No	
30,330	Check Wheelchair Lift Operation	Done		HPIERRE	May 31, 2018 3:09:56 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	May 31, 2018 3:09:55 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		HPIERRE	May 31, 2018 3:09:56 PM	No	
30,360	Check for Physical Damage and Decals	Done		HPIERRE	May 31, 2018 3:09:56 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		HPIERRE	May 31, 2018 3:09:56 PM	No	
30,380	Check Exterior Compartment Doors	Done		HPIERRE	May 31, 2018 3:09:56 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		HPIERRE	May 31, 2018 3:09:56 PM	No	
33,100	Check Lights and Reflectors	Done		HPIERRE	May 31, 2018 3:09:56 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	May 31, 2018 3:09:56 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		HPIERRE	May 31, 2018 3:09:57 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	-	N/A	HPIERRE	May 31, 2018 3:09:57 PM	No	
40,420	Check Hood	Done		HPIERRE	May 31, 2018 3:09:57 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		HPIERRE	May 31, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					3:09:57 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	May 31, 2018 3:09:57 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	May 31, 2018 3:09:57 PM	No	
40,442	Freeze Point	Degree Fahrenheit	N/A	HPIERRE	May 31, 2018 3:09:57 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	May 31, 2018 3:09:57 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	May 31, 2018 3:09:58 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	May 31, 2018 3:09:58 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	May 31, 2018 3:09:58 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		HPIERRE	May 31, 2018 3:09:58 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		HPIERRE	May 31, 2018 3:09:58 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	May 31, 2018 3:09:59 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		HPIERRE	May 31, 2018 3:09:59 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	May 31, 2018 3:09:59 PM	No	
44,130	FRA Check Exhaust System	Done		HPIERRE	May 31, 2018 3:09:59 PM	No	
44,140	FRA Check Intake System	Done		HPIERRE	May 31, 2018 3:09:59 PM	No	
44,150	FRA Inspect Turbocharger	-	N/A	HPIERRE	May 31, 2018 3:09:59 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	May 31, 2018 3:09:59 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		HPIERRE	May 31, 2018 3:10:00 PM	No	
44,180	FRA Check for Leaks	Done		HPIERRE	May 31, 2018 3:10:00 PM	No	
44,190	FRA Perform Battery Inspection	Done		HPIERRE	May 31, 2018 3:10:00 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	May 31, 2018 3:10:00 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		HPIERRE	May 31, 2018 3:10:01 PM	No	
50,510	Check Entire Steering System	Done		HPIERRE	May 31, 2018 3:10:01 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	May 31, 2018 3:10:00 PM	No	
60,610	FRA Check and Record Air Pressure	Done		HPIERRE	May 31, 2018 3:10:01 PM	No	
60,611	Air Pressure RF	65 Pounds per Square Inch		HPIERRE	May 31, 2018 3:10:01 PM	No	
60,612	Air Pressure LF	65 Pounds per Square Inch		HPIERRE	May 31, 2018 3:10:01 PM	No	
60,613	Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	May 31, 2018 3:10:01 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	May 31, 2018 3:10:01 PM	No	
60,615	Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	May 31, 2018 3:10:02 PM	No	
60,616	Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	May 31, 2018 3:10:02 PM	No	
60,620	Check Valve Stems and Caps	Done		HPIERRE	May 31, 2018 3:10:02 PM	No	
60,630	Check and Record Tread Depth	Done		HPIERRE	May 31, 2018 3:10:02 PM	No	
60,631	Tread Depth RF	7 32nds of an inch		HPIERRE	May 31, 2018 3:10:02 PM	No	
60,632	Tread Depth LF	7 32nds of an inch		HPIERRE	May 31, 2018 3:10:02 PM	No	
60,633	Tread Depth RRO	8 32nds of an inch		HPIERRE	May 31, 2018 3:10:02 PM	No	
60,634	Tread Depth RRI	8 32nds of an inch		HPIERRE	May 31, 2018 3:10:02 PM	No	
60,635	Tread Depth LRI	4 32nds of an inch		HPIERRE	May 31, 2018 3:10:03 PM	No	
60,636	Tread Depth LRO	4 32nds of an inch	need rear tires	HPIERRE	May 31, 2018 3:10:03 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		HPIERRE	May 31, 2018 3:10:03 PM	No	
60,650	Check Sidewall Wear	Done		HPIERRE	May 31, 2018 3:10:03 PM	No	
60,660	Inspect for Cuts and Tears	Done		HPIERRE	May 31, 2018 3:10:03 PM	No	
60,670	Check Dual Mating With Square	-	N/A	HPIERRE	May 31, 2018 3:10:03 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	May 31, 2018 3:10:03 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		HPIERRE	May 31, 2018 3:10:03 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		HPIERRE	May 31, 2018 3:10:04 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		HPIERRE	May 31, 2018 3:10:04 PM	No	
70,710	Check Vibration Damper	Done		HPIERRE	May 31, 2018 3:10:04 PM	No	
70,720	Check Engine and Transmission Mounts	Done		HPIERRE	May 31, 2018 3:10:04 PM	No	
70,730	FRA Check Starter	Done		HPIERRE	May 31, 2018 3:10:04 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	May 31, 2018 3:10:04 PM	No	
70,750	FRA Check Transmission for Leaks	Done		HPIERRE	May 31, 2018 3:10:05 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		HPIERRE	May 31, 2018 3:10:05 PM	No	
70,770	FRA Check Exhaust System	Done		HPIERRE	May 31, 2018 3:10:05 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	May 31, 2018 3:10:05 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		HPIERRE	May 31, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					3:10:05 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	May 31, 2018 3:10:05 PM	No	
77,110	FRA Check Fuel Tank	Done		HPIERRE	May 31, 2018 3:10:06 PM	No	
77,120	Check Suspension Components	Done		HPIERRE	May 31, 2018 3:10:06 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	May 31, 2018 3:10:06 PM	No	
77,131	Brake Pad Thickness LF	8 Inch		HPIERRE	May 31, 2018 3:10:06 PM	No	
77,132	Brake Pad Thickness RF	8 Inch		HPIERRE	May 31, 2018 3:10:06 PM	No	
77,133	Brake Pad Thickness LR	8 Inch		HPIERRE	May 31, 2018 3:10:06 PM	No	
77,134	Brake Pad Thickness RR	8 Inch		HPIERRE	May 31, 2018 3:10:06 PM	No	
77,135	Brake Rotor LF	1.6 Inch		HPIERRE	May 31, 2018 3:10:07 PM	No	
77,136	Brake Rotor RF	1.6 Inch		HPIERRE	May 31, 2018 3:10:07 PM	No	
77,137	Brake Rotor LR	1.7 Inch		HPIERRE	May 31, 2018 3:10:07 PM	No	
77,138	Brake Rotor RR	1.7 Inch		HPIERRE	May 31, 2018 3:10:07 PM	No	
77,140	FRA Check Brake Hoses	Done		HPIERRE	May 31, 2018 3:10:07 PM	No	
77,150	Check King Pins	-	N/A	HPIERRE	May 31, 2018 3:10:07 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	May 31, 2018 3:10:07 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		HPIERRE	May 31, 2018 3:10:07 PM	No	
80,810	Completion of PMI Report	Done		HPIERRE	May 31, 2018 3:10:07 PM	No	
90,000	SECTION 9 Completion of PMI	Done		HPIERRE	May 31, 2018 3:10:08 PM	No	
90,910	Vehicle Returned to predetermined location	Done		HPIERRE	May 31, 2018 3:10:08 PM	No	

LH: 20 Desc: PM A

Task: PM A SERVICE Performed by: HPIERRE Performed on: 31-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		HPIERRE	May 31, 2018 3:10:49 PM	No	
101,000	FRA Change Oil Filters	Yes		HPIERRE	May 31, 2018 3:10:50 PM	No	
102,000	FRA Drain Engine Oil	Yes		HPIERRE	May 31, 2018 3:10:49 PM	No	
103,000	FRA Check Transmission Fluid	Done		HPIERRE	May 31, 2018 3:10:50 PM	No	
104,000	Lubricate Chassis	Done		HPIERRE	May 31, 2018 3:10:50 PM	No	
105,000	Replace or Clean A/C Filters	Done		HPIERRE	May 31, 2018 3:10:50 PM	No	
107,000	FRA Change Primary Fuel Filter	Yes		HPIERRE	May 31, 2018 3:10:50 PM	No	
108,000	Lube all pivoting Mechanisms	Done		HPIERRE	May 31, 2018 3:10:50 PM	No	

LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 31-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	May 31, 2018 3:11:17 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	



55345 Palm Tran Connection v 2.2

Page 1 of 9



Invoice Number: 55345-51386147

Client Department:

MRC:

WO Desc: PM A

Requested By: Created By: Class:

Arrangement: Potential Warranty: 55345M

CVERGARA

CVERGARA

WO

No

Equipment:

VIN:

Status: **Priority:** Driver:

Unassigned

Phone: ETA:

4505-P

Ford E450 Champion Challenger 1FDFE4FS6EDB17167

40

1

	Chronology	
Reported	Jun 20, 2018	11:32 AM
Started	Jul 5, 2018	
Completed	Jul 5, 2018	11:18 AM
Do	wn Time	

Meter	Reading	UOM
wo		DH
Life	159,807	DH
System	158,501	DH

WorkOrder Notes Line Comment 10 COMPLAINT: CAUSE: CORRECTION: WAITING FOR PM MILEAGES TO BE DUE RELEASE BY ACCIDENT Preventive maintenance Perform service lube all Pivoting cross Rotate Tires completed

Activity: 10

999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Part Number

Description

Each Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
05-Jul-18	Pierre, Hubert J	6.00	0.00	0.00
		0.00	0.00	0.00

Activity 10 Sub Total

Parts: 0.00 Labor: 0.00 Labor Hours: 6.00 Sublet Parts: 0.00 Sublet Labor:

Activity Sub Total

0.00 0.00

Activity: 20 **Activity Note:**

999 TOTAL VEHICLE

PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A



55345 Palm Tran Connection v 2.2

Page 1 of 8

VIN:



WorkOrder: 51611669 **Invoice Number:** 55345-51611669

UOM

Client Department:

MRC: WO Desc: 55345M

Equipment:

4505-P

32

1

Ford E450 Champion Challenger

1FDFE4FS6EDB17167

PM A Requested By: Created By:

RGASPARD RGASPARD WO

Status: **Priority:**

Class: **Arrangement: Potential Warranty:**

Unassigned No

Driver: Phone: ETA:

	Chronology	

Reported Started Completed Sep 11, 2018 Sep 12, 2018

12:35 PM wo DH Life 168,802 DH 11:29 PM 168,802 System DH

Meter

Reading

Down Time

WorkOrder Notes

Line	Comment
10	Tech performed pmA

Activity: 10 **Activity Note:**

999 TOTAL VEHICLE

Light Medium Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Part Number Description

Qty. Each Extended

Labor Posted

Date

Technician

Hours

Rate Extended

Activity 10 Sub Total

Parts: Labor: 0.00

Labor Hours: 0.00

0.00

Sublet Parts: Sublet Labor:

0.00 0.00

Activity Sub Total

0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
13-Sep-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

Labor Posted

Date Technician Extended Hours Rate

Activity 20 Sub Total



55345 Palm Tran Connection v 2.2 Page 1 of 9



WorkOrder: 51714477 Invoice Number: 55345-51714477

MOU

DH

DH

DH

Client Department:

MRC:

55345M

Equipment:

4505-P

WO Desc:

PM A

VIN:

Ford E450 Champion Challenger 1FDFE4FS6EDB17167

Meter

wo

Life

System

Reading

173,182

173,090

Requested By: Created By:

Started

Completed

AOWENS

Status: **Priority:**

40

Class: **Arrangement:**

AOWENS WO Unassigned

Driver:

1

Potential Warranty:

Phone: ETA:

018 Oct 12, 2018 Oct 12, 2018

9:53 AM

11:09 AM

Down Time

WorkOrder Notes

Line 10 COMPLAINT: PmA

CAUSE: Preventive Maintenance

CORRECTION: perform service lube all Pivoting Points cross Rotate Tires completed

Comment

Activity: 10 **Activity Note:**

999 TOTAL VEHICLE Light Medium Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Part Number Description	Qty. Each Extended

Labor Posted

Date	Technician	Hours	Rate E	Extended	
12-Oct-18	Pierre,Hubert J	5.00	0.00	0.00	-

Activity 10 Sub Total

Parts: Labor:

0.00 0.00

Labor Hours: 5.00 Sublet Parts:

0.00 0.00

Sublet Labor: **Activity Sub Total**

0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note: Reason for Repair:

PM A

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Date Part Number	Description	Qty. Each Extended
12-Oct-18 B329(F)	FILTER, OIL SAME AS LF3681	1.00 1.96 1.96
	마리마트 마시아를 하는데 이번에 어떤 살아가 한민 생각이 모든 경우에 대한 경우로 모대들었다. 아이들에 모든 아니는 아는 그 아는 그는 아는 그	



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 51951275 Invoice Number: 55345-51951275

UOM

Client Department:

MRC: WO Desc: 55345M

Equipment:

4505-P

Ford E450 Champion Challenger

Meter

1FDFE4FS6EDB17167

PM A Requested By:

DKNOTT DKNOTT WO

VIN: Status: **Priority:**

40 1

Created By: Class: Arrangement:

Reported

Completed

Started

Line

Driver: Phone:

Potential Warranty:

Unassigned No

ETA:

Chronology Dec 26, 2018 10:13 AM

Dec 26, 2018 Dec 26, 2018

9:08 PM

Reading WO DH Life 181,916 DH

Down Time

WorkOrder Notes

Comment

COMPLAINT: PMC

CAUSE: Service due

CORRECTION: Performed and completed PmA

Changed engine oil and replaced engine oil filter

Replaced rear AC filter Replaced air intake filter

Activity: 10

999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Part Number Qty. Each Extended Description

Labor Posted

Date	Technician	Hours	Rate	Extended
26-Dec-18	Delva,Terry	1.77	0.00	0.00

Activity 10 Sub Total

Parts: 0.00 Labor: 0.00 Labor Hours: 1.77 Sublet Parts: 0.00 Sublet Labor: 0.00

Activity Sub Total

0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note:

PM A 08 - Preventive Maintenance

Reason for Repair: Work Accomplished: A - PM Level A

Part Failure:

Activity Comments



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52025056 **Invoice Number: 55345-52025056**

Client Department:

MRC: WO Desc:

Started

Completed

55345M

Equipment:

4505-P

Ford E450 Champion Challenger

PM A VIN:

Status:

1FDFE4FS6EDB17167

Requested By: Created By:

TDELVA TDELVA WO

40 **Priority:** 1 Driver:

Class: Arrangement: **Potential Warranty:**

Unassigned

Phone: ETA:

	Chronology
Reported	Jan 23, 2019

Jan 23, 2019 Jan 24, 2019

WO 12:16 AM

1:01 PM

Life 186,127 186,405 System

Reading

UOM

DH

DH

DH

Meter

Down Time

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmA
	CAUSE: Service
	CORRECTION:Perform pmA Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 **Activity Note:**

999 TOTAL VEHICLE

Light Medium Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Part Number Description

Qty. Each Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
23-Jan-19	Gaspard,Ronald	1.55	0.00	0.00

Activity 10 Sub Total

Parts:

0.00

Labor:

0.00

Labor Hours: 1.55 Sublet Parts:

0.00 0.00

Sublet Labor: **Activity Sub Total**

0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note:

PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Date	Part Number	Description	Qty.	Each	Extended
23-Jan-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52173190 **Invoice Number:** 55345-52173190

Client Department:

MRC:

55345M

Equipment:

4505-P

WO Desc: PM A

VIN:

1FDFE4FS6EDB17167

Meter

Ford E450 Champion Challenger

Reading

MOU

DΗ DΗ

DH

Requested By: Created By:

DARTHURS DARTHURS Status: **Priority:**

Class:

10

WO **Arrangement:** Unassigned **Potential Warranty:** No

Down Time

Driver:

40 1

Phone: ETA:

	Chronology	
Reported	Mar 13, 2019	9:46 AM
Started	Mar 13, 2019	
Completed	Mar 14, 2019	12:11 AM

12:11 AM	Life	194,279
	System	194,516

WorkOrder Notes

Line

COMPLAINT: Perform PMA Service.

CAUSE: Service due by Mileage.

CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check Brakes, Clean batteries

Comment

Parts # B329 Qty (1)

Oil 5W 20 Qty (7.0) Qt

999 TOTAL VEHICLE Light Medium Duty PMI 08 - Preventive Maintenance

Reason for Repair: Work Accomplished: A - PM Level A

Part Failure:

Activity Note:

Activity: 10

Activity Comments

Parts Issued

Date Part Number Description

Each Extended

Labor Posted

1	13-Mar-19	Arthurs, Durvin		1.50	0.00	0.00	
:	Date	Technician	F	lours	Rate E	Extended	

Activity 10 Sub Total

Parts: Labor: 0.00 0.00

Labor Hours: 1.50 Sublet Parts: Sublet Labor:

0.00 0.00

Activity Sub Total

0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note:

PM A

Reason for Repair:

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

i						
1	13-Mar-19	B329	FILTER, OIL (FGA0000399/FSC0000399)	1.00	1.96	1.96
	Date		Part Number Description	Qty.	Each	Extended



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52251300 Invoice Number: 55345-52251300

Client Department:

MRC: WO Desc: 55345M

Equipment:

4505-P

Ford E450 Champion Challenger

PM A Requested By:

DARTHURS

VIN: Status:

1FDFE4FS6EDB17167 40

12:16 PM

12:22 AM

Created By: Class:

DARTHURS WO

Priority: **Driver: Phone:**

1

Arrangement: Potential Warranty:

Unassigned

ETA:

Reported	Apr 5, 20:
	Chronology

Started Completed

19 Apr 6, 2019 Apr 6, 2019

WO Life 198,412 System 198,639

Reading

UOM

DH

DН

DH

Meter

Down Time

WorkOrder Notes

Line Comment COMPLAINT: pmA

CAUSE: Service

CORRECTION: Perform pmA Service Oil filter B329 Qty1

Engine oil 5w20 qty 7 Qts

Activity: 10

999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Part Number Description Each Extended

Labor Posted

Date	Technician	Hours	Rate Ex	tended	
06-Apr-19	Gaspard,Ronald	1.58	0.00	0.00	

Activity 10 Sub Total

Parts: 0.00 Labor: 0.00 Labor Hours: 1.58

Subjet Parts: 0.00 Sublet Labor: 0.00

Activity Sub Total 0.00

Activity: 20 **Activity Note:**

999 TOTAL VEHICLE

Reason for Repair:

PM A 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Date	Part Number	Description	Qty. Each Exte	inded
06-Apr-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00 1.96	1.96



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52400876
Invoice Number: 55345-52400876

Client Department:

MRC: WO Desc: 55345M

Equipment:

4505-P

Ford E450 Champion Challenger

1FDFE4FS6EDB17167

PM A Requested By:

VAMRITTEEMAL VAMRITTEEMAL Status: Priority: 40 1

Created By: Class:

WO

Driver:

Arrangement: Potential Warranty: Unassigned No Phone: ETA:

VIN:

	Down Time	9	
1	Completed	Jun 4, 2019	11:23 PM
	Started	Jun 4, 2019	
1	Reported	Jun 4, 2019	11:55 AM
Ì		Chronology	

Meter	Reading	MOU
wo		DH
Life	207,087	DH
System	207,266	DH

WorkOrder Notes

Line 10 Comment

COMPLAINT: Perform PMA Service.

CAUSE: Service due by Mileage.

CORRECTION: Change Oil& Filter. Lube all Pivoting Points . Check Brakes. Clean batteries. Replace A/C Filter.

Parts# B329 Qty (1) Oil 5W20 Qty (7.0) Qt

Activity: 10 Activity Note:

Reason for Repair:

999 TOTAL VEHICLE

Light Medium Duty PMI 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Part Number

Description

y. Each Extended

Labor Posted

 04-Jun-19	Arthurs, Durvin	1,50	65.00	97.50
 Date	Technician	Hours	Rate E	xtended

Activity 10 Sub Total

Parts: Labor: 0.00 97.50

Labor Hours: 1.50 Sublet Parts: Sublet Labor:

0.00

Activity Sub Total

97.50

Activity: 20

999 TOTAL VEHICLE

Activity Note: Reason for Repair:

PM A

ir: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

04-Jun-19	B329(F)	FILTER, OIL SAME AS LF36	81	1.00 1.96	1.96
Date	Part Number		Description	Qty. Each	Extended



55345 Palm Tran Connection v 2.2 Page 1 of 9



WorkOrder: 52489624 Invoice Number: 55345-52489624

Client Department:

MRC:

55345M

Equipment:

4505-P

WO Desc: PM A

DARTHURS

Ford E450 Champion Challenger

1FDFE4FS6EDB17167

Requested By: Created By:

Reported

Completed

Started

DARTHURS

Status: **Priority:** 40 1

Class: **Arrangement:** WO

Jul 1, 2019

Jul 2, 2019

Jul 2, 2019

Chronology

Driver: Phone:

Unassigned **Potential Warranty:** No

Down Time

ETA:

VIN:

Meter Reading UOM 12:55 PM 5:19 PM

wo		DH
Life	211,618	DH
System	211.618	DH

WorkOrder Notes

Comment

Line 10

COMPLAINT: PM A service

CAUSE: Due by Mileage.

CORRECTION: LOF engine oil and filter. Checked and topped off all fluids. Checked wheels and tires. Performed brake inspection.

Activity: 10

999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Part Number Description

Labor Posted

Date	Technician	} }	lours	Rate E	xtended
02-Jul-19	Earl Johnson		1.50	65.00	97.50

Activity 10 Sub Total

Parts: Labor:

0.00 97.50

Labor Hours: 1.50 Sublet Parts: Sublet Labor:

0.00 0.00

Activity Sub Total

97.50

Activity: 20

999 TOTAL VEHICLE

Activity Note: PM A Reason for Repair:

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

02-Jul-19 B329(F	FILTER, OIL	SAME AS LF3681	1.00	1.96	1.96



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52668095 Invoice Number: 55345-52668095

Client Department:

MRC:

55345M

Equipment:

4505-P

WO Desc:

Started

10

Completed

VIN:

Ford E450 Champion Challenger

1

PM A

RRENE

/IN:

ETA:

1FDFE4FS6EDB17167 40

Requested By: Created By:

RRENE

Status: Priority:

Class: Arrangement: WO Unassigned y: .

Arrangement: Potential Warranty:

Unassigi No Driver: Phone:

Chronology
Reported Sep 6, 2019

Sep 6, 2019 Sep 6, 2019

Sep 6, 2019

11:44 AM 8:24 PM

Life	220.391	DH
wo		DH
Meter	Reading	MOU

Down Time

WorkOrder Notes

Line Comment

COMPLAINT: PMA SERVICE

CAUSE: PREVENTIVE MAINTENANCE

CORRECTION: PERFORM AND COMPLETED PMA SERVICE

REPLACED AIR FILTER REPLACED DRAIN PLUG

Activity: 10

999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Part Number

Description

Qty. Each Extended

Labor Posted

06-Sep-19 AMRIT TEEMAL, VISHNU 1.50 65.00 97.50		Date	Technician	Hours	Rate I	Extended
	10000	06-Sep-19	AMRIT TEEMAL, VISHNU	1.50	65.00	97.50

Activity 10 Sub Total

Parts: Labor: 0.00 97.50

Labor Hours: 1.50 Sublet Parts:

0.00

Sublet Labor:

0.00

Activity Sub Total

97.50

Activity: 20 Activity Note:

999 TOTAL VEHICLE

Activity Note: PM A Reason for Repair: 08 - P

08 - Preventive Maintenance

Work Accomplished: A - PM Level A


Part Failure:

Activity Comments



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52765726 **Invoice Number: 55345-52765726**

Client Department:

MRC: WO Desc:

PM A

55345M

Equipment:

4505-P

Ford E450 Champion Challenger

1FDFE4FS6EDB17167

Requested By: Created By:

AOWENS AOWENS VIN: Status: **Priority:**

40

Class: Arrangement: WO Unassigned

Driver: Phone: 1

Potential Warranty:

No

ETA:

 Down Time		
Completed	Oct 7, 2019	3:11 PM
Started	Oct 7, 2019	
Reported	Oct 4, 2019	1:28 PM
page 10 pag	Chronology	

Meter	Reading	UOM
wo		DH
Life	224,953	DH
System	224,953	DH

WorkOrder Notes

Line 10

Comment

COMPLAINT: PMA SERVICE

CAUSE: PREVENTIVE MAINTENANCE

CORRECTION: PERFORM AND COMPLETED PMA SERVICE

Activity: 10 **Activity Note:**

999 TOTAL VEHICLE Light Medium Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Part Number	Description Qty. Each Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
07-Oct-19	AMRIT TEEMAL, VISHNU	1.50	65.00	97.50

Activity 10 Sub Total

Parts: Labor:

0.00 97,50

Labor Hours: 1.50 Sublet Parts:

0.00 0.00

Sublet Labor:

Activity Sub Total

97.50

Activity: 20

999 TOTAL VEHICLE

Activity Note: Reason for Repair:

PM A

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

07-Oct-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00 1.96 1.96
Date	Part Number	Description	Qty. Each Extended



55345 Palm Tran Connection v 2.2 Page 1 of 9



WorkOrder: 52985274 Invoice Number: 55345-52985274

Client Department:

MRC:

55345M

Equipment:

4505-P Ford E450 Champion Challenger

WO Desc: PM A

RRENE

VIN:

1FDFE4FS6EDB17167

Requested By: Created By:

RRENE

Status: **Priority:** Driver:

40 1

Class: Arrangement: **Potential Warranty:**

WO Unassigned No

Phone: ETA:

Chronology Reported Dec 13, 2019

Dec 15, 2019 **Started** Completed Dec 16, 2019 12:00 AM 1:05 PM

Down Time

Meter Reading MOU wo DH Life DH 234,357 System 234,357 DH

WorkOrder Notes

Line Comment 10 COMPLAINT: PMA SERVICE

CAUSE: PREVENTIVE MAINTENANCE

CORRECTION: PERFORM AND COMPLETED PMA SERVICE

REPLACED DRAIN PLUG

Activity: 10

999/999/999 TOTAL VEHICLE

Activity Note:

Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: -

Part Failure:

Activity Comments

Parts Issued

Date Part Number Description Qty. Each Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
15-Dec-19	AMRIT TEEMAL, VISHNU	0.90	65.00	58.50

Activity 10 Sub Total

Parts:

0.00 58.50

Labor: Labor Hours: 0.90

0.00

Sublet Parts: Sublet Labor:

0.00

Activity Sub Total

58.50

Activity: 20 **Activity Note:**

999 TOTAL VEHICLE

Reason for Repair:

PM A

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Dat	e Part Number	Description	Qty.	Each	Extended
15-De	c-19 B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 53101214 **Invoice Number:** 55345-53101214

Client Department:

MRC: WO Desc: 55345M

Equipment:

4505-P

1

Ford E450 Champion Challenger 1FDFE4FS6EDB17167

PM A Requested By:

VAMRITTEEMAL **VAMRITTEEMAL**

40

Created By:

WO

Status: Priority:

Class: **Arrangement:**

Unassigned

Driver: Phone:

Potential Warranty:

No

ETA:

VIN:

	Completed	Jan 21, 2020 Jan 21, 2020	10:17 PM
	Started	,	
	Reported	Jan 21, 2020	10:41 AM
į		Chronology	

Jan 21, 2020 10:17 PM

Meter Reading UOM		
WO		DH
Life	238,564	DH

WorkOrder Notes

Line 10

Comment COMPLAINT: PMA SERVICE

CAUSE: PREVENTIVE MAINTENANCE

CORRECTION: PERFORM AND COMPLETED PMA SERVICE

Down Time

Activity: 10

999/999/999 TOTAL VEHICLE

Activity Note: Reason for Repair: Light Duty PMI

08 - Preventive Maintenance

Work Accomplished: -**Part Failure:**

Activity Comments

Parts Issued

Date Part Number Description Oty. Each Extended	

Labor Posted

Date	Technician	Hours	Rate	Extended
21-Jan-20	AMRIT TEEMAL, VISHNU	0.55	0.00	0.00

Activity 10 Sub Total

Parts: Labor: 0.00 0.00

Labor Hours: 0.55 Sublet Parts:

0.00 0.00

Activity Sub Total

Sublet Labor:

0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note: Reason for Repair:

PM A

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Date	Part Number	Description	Qty. Each Extended
21-Jan-20	B329(F)	FILTER, OIL SAME AS LF3681	1.00 1.96 1.96
		5 - 5 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	Same in the same and an individual elementarium in the feature and in the contract of the same in the



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 53296507 Invoice Number: 55345-53296507

UOM

Client Department:

MRC: WO Desc: 55345M

Equipment:

4505-P

Ford E450 Champion Challenger

PM A

Started

Completed

VAMRITTEEMAL

VIN: Status:

1FDFE4FS6EDB17167 40

Meter

Requested By: Created By:

VAMRITTEEMAL WO

Priority:

Class: **Arrangement: Potential Warranty:**

Unassigned No

Driver:

Phone: ETA:

Chronology Reported

Mar 18, 2020 Mar 19, 2020 Mar 19, 2020 3:55 PM

1

1:52 PM

wo DH Life 246.973 DH Svstem 246,973 DH

Reading

Down Time

Line	Comment	-
10	COMPLAINT: PMA	4
	CAUSE: preventive maintenance	

CORRECTION:perform PMA service lube all pivoting point cross rotate tires completed

Activity: 10

999/999/999 TOTAL VEHICLE

Activity Note: Light Duty PMI Reason for Repair:

08 - Preventive Maintenance

Work Accomplished: -Part Failure:

Activity Comments

Parts Issued

Date Part Number Description Oty. Each Extended

Labor Posted

Date Extended Technician Hours

Activity 10 Sub Total

Parts:

Labor:

0.00

0.00

Labor Hours: 0.00

Sublet Parts: Sublet Labor:

0.00 0.00

Activity Sub Total

0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note: Reason for Repair:

PM A

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Part Number Description Each Extended

Labor Posted



55345 Palm Tran Connection v 2.2 Page 1 of 11



WorkOrder: **53400202 Invoice Number:** 55345-53400202

Client Department:

MRC: 55345M **Equipment:** 4505-P

WO Desc: Ford E450 Champion Challenger

PM A **VIN:** 1FDFE4FS6EDB17167

Requested By:HPIERREStatus:40Created By:HPIERREPriority:1

Class: WO Driver: Arrangement: Unassigned Phone: Potential Warranty: No ETA:

	Chronology	
Reported	May 12, 2020	10:24 AM
Started	May 12, 2020	
Completed	May 12, 2020	11:28 PM

١	Meter	Reading	UOM
	WO		DH
	Life	250,963	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA Service
	CAUSE: Service Due by Mileage.
	CORRECTION: Change Oil & Filter Lube all Pivoting Points. Check brakes. Clean& check batteries. Replace drain Plugs. Parts #65266 Qty (1) Parts # B329 Qty (1) Oil 10 W20 Qty (7.0) Qt

Activity: 10

999/999/999 TOTAL VEHICLE

Activity Note: Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Down Time

Work Accomplished: Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Otv.	Each	Extended	
240		2 000117011	~·,·		_,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

Labor Posted

Date	Technician	Hours	Rate	Extended	
12-May-20	Arthurs, Durvin	1.20	0.00	0.00	

Activity: 20

999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments



55345 Palm Tran Connection v 2.2 Page 1 of 12



WorkOrder: 53673040 **Invoice Number:** 55345-53673040

Client Department:

4505-P MRC: **Equipment:** 55345M WO Desc:

Ford E450 Champion Challenger

VIN: 1FDFE4FS6EDB17167 PM A SERVICE

Requested By: CVERGARA Status: 40 **Created By: CVERGARA** 3 **Priority:**

Class: WO **Driver: Arrangement:** Phone: Unassigned **Potential Warranty:** ETA: No

Chronology

Reported Aug 13, 2020 12:00 AM

Aug 13, 2020 Started Completed Aug 13, 2020 9:27 PM

Down Time

Meter	Reading	UOM
WO		DH
Life	259,572	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PMA Service
	CAUSE: Service Due By Mileage
	CORRECTION: Change Oil &Filter. Lube all Pivoting Points. Check Brakes Clean batteries. replace A/C Filter. Parts # B329 Qty (1) Oil 5W20QTY (7.0) Qt

Activity: 5

999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESSMENT

Reason for Repair: SW - Shop Work Order

Work Accomplished: 06 - Inspect **Part Failure:** 00 - No Failure

Activity Comments

Parts Issued

Date Part Number Qty. Each Extended Description

Labor Posted

Date Technician Extended Hours Rate

Activity 5 Sub Total

Parts: 0.00 Labor: 0.00

Labor Hours: 0.00 Sublet Parts:

0.00 Sublet Labor: 0.00 0.00

Activity Sub Total

Activity: 10

999/999/999 TOTAL VEHICLE

Activity Note: Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: -**Part Failure:**

Activity Comments

Parts Issued

Date Part Number Description Qty. Each Extended

Labor Posted



55345 Palm Tran Connection v 2.2 Page 1 of 10



WorkOrder: **53780673 Invoice Number:** 55345-53780673

UOM

Client Department:

MRC:

Created By:

55345M

Equipment:

4505-P

WO Desc:

VIN:

Ford E450 Champion Challenger 1FDFE4FS6EDB17167

55345-LIGHT DUTY PMA **Requested By:**

DARTHURS DARTHURS Status: Priority: 40 3

Class: Arrangement: Potential Warranty: WO Unassigned

No

Driver: Phone: ETA:

Chronology Sep 25, 2020

 Reported
 Sep 25, 2020

 Started
 Sep 25, 2020

 Completed
 Sep 25, 2020

12:00 AM WO DH

11:22 PM Life 263,862 DH

System 264,052 DH

Reading

Meter

Down Time

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PMA Service
	CAUSE: Service Due by Mileage
	CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check brakes Clean batteries. Parts #B329 Qty (1) Oil 10W30 Qty (7.0) Qt

Activity: 5

999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESSMENT

Reason for Repair: SW - Shop Work Order

Work Accomplished: 06 - Inspect **Part Failure:** 00 - No Failure

Activity Comments

Parts Issued

Date Part Number Description Qty. Each Extended

Labor Posted

Date Technician Hours Rate Extended

Activity 5 Sub Total

Parts: Labor: Sub lotal

Labor Hours: 0.00 Sublet Parts:

0.00 0.00

Activity Sub Total

Sublet Labor:

0.00

0.00

0.00

Activity: 10

999/999/999 TOTAL VEHICLE

Activity Note: Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: Part Failure: -

Activity Comments

Parts Issued

Date Part Number Description Qty. Each Extended

Labor Posted



55345 Palm Tran Connection v 2.2 Page 1 of 10



WorkOrder: 54040735 **Invoice Number:** 55345-54040735

UOM

Client Department:

MRC: WO Desc:

Reported

Completed

Started

55345M

Equipment:

4505-P

40

55345-LIGHT DUTY PMA

VIN:

Ford E450 Champion Challenger 1FDFE4FS6EDB17167

Meter

Requested By: Created By:

DKNOTT **DKNOTT** WO

Status: **Priority: Driver:**

3

Class: **Arrangement: Potential Warranty:**

Unassigned No

Phone: ETA:

Chronology

Jan 20, 2021 Jan 20, 2021

Jan 20, 2021

11:18 AM 3:30 PM

Reading WO DH Life 272,378 DH

Down Time

WorkOrder Notes

Line	Comment						
10	COMPLAINT: Vehicle in for pm service A						
	CAUSE: time for service						
	CORRECTION: pm service complete						

Activity: 5

999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESSMENT

Reason for Repair: SW - Shop Work Order

Work Accomplished: 06 - Inspect **Part Failure:** 00 - No Failure

Activity Comments

Parts Issued

Date Each Extended Part Number Description

Labor Posted

Date	Technician	Hours	Rate	Extended	
20-Jan-21	Junior Hurst	0.02	0.00	0.00	

Activity 5 Sub Total

Parts: Labor: 0.00 0.00

Labor Hours: 0.02 Sublet Parts: Sublet Labor:

0.00 0.00

Activity Sub Total

0.00

Activity: 10

Light Duty PMI **Activity Note:**

Reason for Repair: Work Accomplished: -**Part Failure:**

Activity Comments

Date	Part Number	Description	Qty.	Each	Extended
20-Jan-21	B329(F)	SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1.00	1.96	1.96
20-Jan-21	65266	PLUG, DRAIN, OIL, ENGINE	1.00	4.25	4.25



55345 Palm Tran Connection v 2.2 Page 1 of 10



WorkOrder: 54225790 **Invoice Number:** 55345-54225790

Client Department:

MRC:

Reported Started

Completed

WO Desc:

55345-LIGHT DUTY PMA

Requested By: Created By: Class:

Arrangement: Potential Warranty:

4505-P 55345M **Equipment:**

Ford E450 Champion Challenger

VIN: 1FDFE4FS6EDB17167

11:05 AM

12:00 AM

Status: 40 3 **Priority:** Driver:

Phone: ETA:

Chronology

JUHURST

JUHURST

Unassigned

WO

No

Mar 3, 2021

Mar 3, 2021 Mar 4, 2021

UOM Meter Reading WO DH Life 276,531 DH

Down Time

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA
	CAUSE: Service
	CORRECTION: Perform pmA Service Oil filter B329 qty1 Engine oil 10w30 qty 7 qts Fixed washer fluid hose.

Activity: 5

999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESSMENT

Reason for Repair: SW - Shop Work Order

Work Accomplished: 06 - Inspect **Part Failure:** 00 - No Failure

Activity Comments

Parts Issued

Date Part Number Description Qty. Each Extended

Labor Posted

Date Technician Hours Extended

Activity 5 Sub Total

Parts: 0.00 0.00 Labor:

Labor Hours: 0.00 Sublet Parts: 0.00 Sublet Labor: 0.00

Activity Sub Total 0.00

Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER

Activity Note: Light Duty PMI

Reason for Repair: 05 - Inspection, Routine

Work Accomplished: -**Part Failure:**

Activity Comments

Date	Part Number	Description	Qty.	Each	Extended



55345 Palm Tran Connection v 2.2 Page 1 of 9



WorkOrder: 51483366 Invoice Number: 55345-51483366

Client Department:

MRC: WO Desc: PM B

Class:

55345M

Equipment:

4505-P

Ford E450 Champion Challenger

Meter

1FDFE4FS6EDB17167

VIN: Status: **Priority:**

40 1

HPIERRE HPIERRE WO

Driver:

Unassigned

Phone:

ETA:

Chronology

Reported **Started** Completed

Requested By: Created By:

Arrangement:

Potential Warranty:

Aug 9, 2018 Aug 9, 2018 Aug 9, 2018 11:32 AM 11:58 PM

WO DH Life 164,180 DH

Reading

MOU

Down Time

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmB
	CAUSE:Service
	CORRECTION:Perform pmB Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 **Activity Note:**

999 TOTAL VEHICLE

Light Mediun Duty PMI 08 - Preventive Maintenance

Reason for Repair: Work Accomplished: 06 - Inspect

Part Failure:

Activity Comments

Parts Issued

Date Part Number Description

Qty. Each Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
09-Aug-18	Gaspard,Ronald	1.53	0.00	0.00
05-Aug-10	Gespera, Konieu			

Activity 10 Sub Total

Parts: Labor:

Labor Hours: 1.53

Sublet Parts: Sublet Labor: 0.00 0.00

0.00

0.00

Activity Sub Total

0.00

Activity: 20 **Activity Note:**

999 TOTAL VEHICLE

PM B

Reason for Repair:

08 - Preventive Maintenance

Work Accomplished: B-PM Level B

Part Failure:

Activity Comments

Date	Part Number	Description	Qty.	Each	Extended
09-Aug-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52106733 **Invoice Number: 55345-52106733**

Client Department:

MRC: WO Desc:

PM B

55345M

Equipment:

4505-P

Ford E450 Champion Challenger

1FDFE4FS6EDB17167

Requested By:

RGASPARD RGASPARD Status:

40 1

Created By: Class:

Priority: Driver:

WO Arrangement: Unassigned **Potential Warranty:**

Phone: ETA:

VIN:

Down T		
Completed	Feb 14, 2019	11:32 PM
Started	Feb 14, 2019	
Reported	Feb 14, 2019	10:17 AM
	Chronology	

No

Meter	Reading	UOM
wo		DH
Life	190,121	DH
System	190,356	DH

WorkOrder Notes

Line

Comment

COMPLAINT: PMB Service

CAUSE: Service Due by Mileage.

CORRECTION: Change Oil & Filter. Lube all Pivot Points .check Brakes. Clean batteries. Swap both R/R tire.

Parts# B329 Qty (1) Oil. 5W20QTY (7.0) Qt

Activity: 10 **Activity Note:**

Reason for Repair:

999 TOTAL VEHICLE

Light Mediun Duty PMI 08 - Preventive Maintenance

Work Accomplished: 06 - Inspect

Part Failure:

Activity Comments

Parts Issued

Date

Part Number

Extended

Labor Posted

-	14-Feb-19 Arthurs,Durvin	- Control of the second of the control of the contr	and the second account of the second of the	2.00	0.00	0.00	
	Date	Technician		Hours	Rate E	xtended	1

Activity 10 Sub Total

Parts: Labor: 0.00 0.00

Labor Hours: 2.00 Sublet Parts:

0.00

Sublet Labor:

0.00

Activity Sub Total

0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note:

PM B

Reason for Repair:

08 - Preventive Maintenance

Work Accomplished: B - PM Level B

Part Failure:

Activity Comments

	14-Feb-19	B329(F)	FILTER, OIL	SAME AS LF3681	1.00		1.96	
200	Date	Part Number		Description	Qty.	Each	Extended	1



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52570671 **Invoice Number: 55345-52570671**

Client Department:

MRC: WO Desc: 55345M

Equipment:

4505-P

Ford E450 Champion Challenger

1FDFE4FS6EDB17167

PM B Requested By:

EARJOHNSON EARJOHNSON Status:

VIN:

40

Created By: Class:

Reported

Completed

Started

WO

Priority: Driver: Phone:

1

Arrangement: Potential Warranty:

Unassigned No

ETA:

Chronology Aug 6, 2019 Aug 7, 2019

7:50 AM 7:50 AM

Meter Reading MOU wo DΗ Life 215,997 DH

Down Time

WorkOrder Notes

Line	Comment
10	COMPLAINT:
	CAUSE:
) 	CORRECTION:
20	РМВ
: :	Preventive maintenance
	Perform PMB Service lube all Pivoting Points cross Rotate Tires completed

Activity: 10 **Activity Note:**

999 TOTAL VEHICLE

Light Mediun Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: 06 - Inspect

Part Failure:

Activity Comments

Parts Issued

Date Part Number

Description

Qty. Each Extended

Labor Posted

Date

Technician

Hours

Rate Extended

Activity 10 Sub Total

Parts: Labor: 0.00 0.00

Labor Hours: 0.00 Subjet Parts: Sublet Labor:

0.00

Activity Sub Total

0.00

0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note: Reason for Repair:

PM B

08 - Preventive Maintenance

Work Accomplished: B - PM Level B

Part Failure:

Activity Comments



55345 Palm Tran Connection v 2.2

Page 1 of 10



WorkOrder: 53201955 Invoice Number: 55345-53201955

UOM

DH

DH

Reading

242,869

Client Department:

MRC: WO Desc: 55345M

Equipment:

4505-P

Ford E450 Champion Challenger

1FDFE4FS6EDB17167

Meter

PM B Requested By:

VAMRITTEEMAL VAMRITTEEMAL 40

Created Bv: Class:

WO

Status: Priority: Driver:

1

Arrangement: **Potential Warranty:** Unassigned No

Phone: ETA:

VIN:

Chronology Reported

Feb 18, 2020 Feb 18, 2020 Feb 18, 2020 10:05 AM

WO 3:34 PM Life

Down Time

Comment

WorkOrder Notes

Line 10

Started

Completed

COMPLAINT: PMB SERVICE

CAUSE: PREVENTIVE MAINTENANCE

CORRECTION: PERFORM AND COMPLETED PMB SERVICE

REPLACED AIR FILTER

Activity: 10

999/999/999 TOTAL VEHICLE

Activity Note:

Light Duty PMI

Reason for Repair:

08 - Preventive Maintenance

Work Accomplished: -

Part Failure:

Activity Comments

Parts Issued

Date	Part Number	Description	Qty. Each Extended
18-Feb-20	PA4075	FILTER, AIR	1.00 5.28 5.28

Labor Posted

18-Feb-20 AMRIT TEEMAL,VISHNU 1.07 0.00 (Date	Technician	Hours	Rate	Extende	d	and the same
	18-Feb-20	AMRIT TEEMAL, VISHNU	1.07	0.00	0.0	0	2.4

Activity 10 Sub Total

Parts: 5.28 Labor: 0.00 Labor Hours: 1.07 Sublet Parts: 0.00 Sublet Labor: 0.00

Activity Sub Total

5.28

Activity: 20

999 TOTAL VEHICLE

Activity Note: Reason for Repair:

PM B

08 - Preventive Maintenance

Work Accomplished: B - PM Level B

Part Failure:

Activity Comments



55345 Palm Tran Connection v 2.2 Page 1 of 11



WorkOrder: 53907324
Invoice Number: 55345-53907324

Client Department:

MRC: WO Desc:

Reported

Completed

Started

55345M

Equipment:

VIN:

4505-P

Ford E450 Champion Challenger

55345-LIGHT DUTY PMB

DARTHURS DARTHURS

Nov 8, 2020

Nov 10, 2020

Status: Priority: 1FDFE4FS6EDB17167 40

Requested By: Created By: Class:

DARTHURS WO Unassigned

Driver: Phone: ETA: 3

12:00 AM

Arrangement:
Potential Warranty:

No

Chronology Nov 6, 2020

8:42 AM

Meter Reading UOM
WO DH
Life 268,219 DH

Down Time

WorkOrder Notes

	Workerder Hotes
Line	Comment
10	COMPLAINT: Perform PMB Service
	CAUSE: Service Due by Mileage
	CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check brakes . Clean batteries. Parts # B329 Qty (1) Oil 10W20 Oty (7.0) Ots

Activity: 5

999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESSMENT

Reason for Repair: SW - Shop Work Order

Work Accomplished: 06 - Inspect **Part Failure:** 00 - No Failure

Activity Comments

Parts Issued

DatePart NumberDescriptionQty.EachExtended

Labor Posted

Date Technician Hours Rate Extended

Activity 5 Sub Total

Parts: Labor: 5 Sub rotar

Labor Hours: 0.00 Sublet Parts: Sublet Labor:

0.00

Activity Sub Total

0.00

0.00

0.00

Activity: 10

999/999/999 TOTAL VEHICLE

Activity Note: Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: Part Failure: -

Activity Comments

Parts Issued

Date Part Number Description Qty. Each Extended

Labor Posted



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 51807443 Invoice Number: 55345-51807443

Client Department:

MRC: WO Desc:

Started

Completed

PM C

55345M

Equipment:

4505-P

Ford E450 Champion Challenger

Meter

1FDFE4FS6EDB17167

Requested By:

CVERGARA CVERGARA VIN: Status:

40

Created By: Class:

WO

Priority: Driver:

1

Arrangement: **Potential Warranty:** Unassigned No

Phone: ETA:

Chronology Reported

Nov 28, 2018 Nov 30, 2018 Nov 30, 2018 10:49 AM

10:30 AM

WO DH Life 177,773 DH System 177,557 DH

Reading

UOM

Down Time

WorkOrder Notes

-				44011	
Line	Comment				
10	PMC				
	Preventive maintenance				
	Perform service lube all Pivoting Points cross Rotate Tires complet				

Activity: 10

999 TOTAL VEHICLE

Activity Note: Reason for Repair:

Light Medium Duty PMI 05 - Inspection, Routine

Work Accomplished: 06 - Inspect

Part Failure:

Activity Comments

Parts Issued

Date Part Number

Description

Each Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
30-Nov-18	Pierre,Hubert J	8.00	0.00	0.00
				termination of the second

Activity 10 Sub Total

Parts: Labor: 0.00 0.00

Labor Hours: 8.00 Sublet Parts:

0.00

Sublet Labor:

0.00

Activity Sub Total

0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note:

PM C

Reason for Repair:

08 - Preventive Maintenance

Work Accomplished: C - PM Level C

Part Failure:

Activity Comments

Date	Part Number	Description	Qty.	Each	Extended
30-Nov-18	20021	FILTER, TRANSMISSION, E350, '09 W/RUBBER NECK SEAL SAME AS FT180	1.00	17.27	17.27



55345 Palm Tran Connection v 2.2

Page 1 of 9



Invoice Number: 55345-52320122

Client Department:

MRC:

55345M

Equipment:

4505-P

WO Desc: PM C

Started

Completed

VIN:

Ford E450 Champion Challenger

1FDFE4FS6EDB17167

Requested By: Created By:

RGASPARD RGASPARD

Status: **Priority:** 40 1

Class: Arrangement: WO Unassigned

Driver: Phone:

Potential Warranty:

No

ETA:

Chronology Reported May 2, 2019

Down Time

May 3, 2019 May 3, 2019

10:56 PM

2:21 PM

Meter	Reading	UOM
WO		DH
Life	202,910	DH
System	202,910	DH

WorkOrder Notes

Line Comment PMC SERVICE PREVENTIVE MAINTENANCE PERFORM AND COMPLETED PMC SERVICE REPLACED AIR FILTER

Activity: 10

999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI Reason for Repair: 05 - Inspection, Routine

Work Accomplished: 06 - Inspect

Part Failure:

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
			and the second	-	

Labor Posted

Date	Technician	Hours	Rate	Extended
03-May-19	AMRIT TEEMAL, VISHNU	1.50	65.00	97.50

Activity 10 Sub Total

Parts: 0.00 Labor: 97.50

Labor Hours: 1.50 Sublet Parts: 0.00 Sublet Labor: 0.00 **Activity Sub Total**

97.50

Activity: 20

999 TOTAL VEHICLE

Activity Note: PM C

08 - Preventive Maintenance

Reason for Repair: Work Accomplished: C - PM Level C

Part Failure:

Activity Comments

Date	Part Number	Description	Qty.	Each	Extended	
03-May-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96	
03-May-19	20021	FILTER, TRANSMISSION, E350, '09 W/RUBBER NECK SEAL SAME AS FT180	1.00	17.27	17.27	



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52872426 Invoice Number: 55345-52872426

Client Department:

MRC: WO Desc: 55345M

Equipment:

4505-P

Ford E450 Champion Challenger

1FDFE4FS6EDB17167

PM C Requested By: Created By:

RRENE RRENE

VIN: Status: **Priority:**

40 1

Class: Arrangement: **Potential Warranty:** WO Unassigned No

Driver: Phone:

ETA:

Chronology Reported

Nov 8, 2019

12:00 AM

Started Completed

Nov 11, 2019

8:02 AM

MOU Meter Reading WO DH Life 229,594 DH

Down Time

WorkOrder Notes

Line Comment

Complaint: PMC Service

Cause: preventive maintenance Correction: perform PMC Service

Activity: 10 **Activity Note:** 999 TOTAL VEHICLE Light Medium Duty PMI

Reason for Repair: 05 - Inspection, Routine Work Accomplished: 06 - Inspect

Part Failure:

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended	
10-Nov-19	40520	BLADE, WIPER, WINDSHIELD, 20"	2.00	4.07	8.14	

Labor Posted

Date Technician Hours Rate Extended **Activity 10 Sub Total**

Parts: 8.14 Labor: 0.00 Labor Hours: 0.00 Sublet Parts: 0.00 Sublet Labor: 0.00

Activity Sub Total 8.14

Activity: 20 999 TOTAL VEHICLE **Activity Note:** PM C

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: C-PM Level C

Part Failure:

Activity Comments

Date	Part Number	Description	Qty.	Each	Extended
10-Nov-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96
10-Nov-19	20021	FILTER, TRANSMISSION, E350, '09 W/RUBBER NECK SEAL SAME AS	1.00	17.27	17.27



55345 Palm Tran Connection v 2.2 Page 1 of 11



WorkOrder: **53558489 Invoice Number:** 55345-53558489

Client Department:

MRC:

Reported

Completed

Started

WO Desc:

55345-LIGHT DUTY PMC

Requested By:
Created By:
Class:
Arrangement:
Potential Warranty:

NSTOLFO NSTOLFO WO

Unassigned

No

55345M

Status: Priority: Driver: Phone:

ETA:

VIN:

Equipment:

iority: 3
iver:

4505-P

40

Meter Reading UOM
WO DH
Life 255,270 DH

255,210

DH

Ford E450 Champion Challenger

1FDFE4FS6EDB17167

System

Chronology

| Jul 2, 2020 | 2:48 PM |
| Jul 2, 2020 |
| Jul 6, 2020 | 10:52 AM

WorkOrder Notes

Line	Comment
10	PMC Service Perform PMC service Oil filter B329 Qty1 Engine oil 10w30 qty 7 Qts Drain plug oil 65266 Qty1 Gear Oil 80w90 qty 5 Qts

Activity: 5

999/999/999 TOTAL VEHICLE

Down Time

Activity Note: PERSONAL RISK ASSESSMENT SW - Shop Work Order

Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

DatePart NumberDescriptionQty.EachExtended

Labor Posted

Date Technician Hours Rate Extended

Activity 5 Sub Total Parts:

0.00

0.00

0.00

0.00

0.00

Labor: Labor Hours: 0.00 Sublet Parts:

Sublet Labor:
Activity Sub Total

Activity: 10

999/999/999 TOTAL VEHICLE

Activity Note: Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: Part Failure: -

Activity Comments

Parts Issued

Date Part Number Description Qty. Each Extended

Labor Posted



55345 Palm Tran Connection v 2.2 Page 1 of 11



WorkOrder: 54348649 **Invoice Number:** 55345-54348649

Client Department:

MRC: WO Desc:

55345-LIGHT DUTY PMC

Requested By: Created By: Class:

Arrangement: Potential Warranty:

Reported

Completed

Started

4505-P **Equipment:** 55345M

Ford E450 Champion Challenger

VIN: 1FDFE4FS6EDB17167

Status: 40 **Priority:** 3 **Driver:**

Phone: Unassigned ETA:

RGASPARD

RGASPARD

WO

No

Apr 6, 2021

Apr 6, 2021

Apr 6, 2021

Chronology

Meter	Reading	UOM		
WO		DH		
Life	280,774	DH		

WorkOrder Notes

10:18 AM

6:52 PM

Line Comment Unit came in for service job complete. Need right side radius arm bushing replace two new Bridgestone tires size LT 225/75 R 16. To unit

Activity: 5

999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESSMENT

Reason for Repair: SW - Shop Work Order

Down Time

Work Accomplished: 06 - Inspect **Part Failure:** 00 - No Failure

Activity Comments

Parts Issued

Qty. Each Extended Date Part Number Description

Labor Posted

Date	Technician	Hours	Rate	Extended	
06-Apr-21	Junior Hurst	0.03	0.00	0.00	

Activity 5 Sub Total Parts: 0.00 Labor: 0.00 Labor Hours: 0.03 0.00 Sublet Parts: Sublet Labor: 0.00 **Activity Sub Total** 0.00

Activity: 10 **Activity Note:**

010 CHASSIS GROUP

Light Duty PMI Reason for Repair: 11 - Routine

Work Accomplished: -**Part Failure:**

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
06-Apr-21	B329(F)	SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1.00	1.98	1.98
06-Apr-21	192659	TIRE, LT225/75R16, R500, DURAVIS	2.00	117.57	235.14

Labor Posted