WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51422953
Invoice Number: 55345-51422953

Client Department:			
MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL7FDA04215
Requested By:	DCARTER	**Status:**	40
Created By:	DCARTER	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jul 3, 2018	6:59 AM
Started	Jul 3, 2018	
Completed	Jul 3, 2018	3:18 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	184,419	DH
System	184,443	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PmA CAUSE: preventive maintenance CORRECTION: perform service lube all Pivoting Points cross Rotate Tires completed

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
03-Jul-18	Pierre,Hubert J	6.00	0.00	0.00

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 6.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
03-Jul-18	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

WorkOrder: 51422953
Invoice Number: 55345-51422953

Client Department:

MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL7FDA04215
Requested By:	DCARTER	**Status:**	40
Created By:	DCARTER	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Labor Posted

Date	Technician	Hours	Rate	Extended
03-Jul-18	Pierre,Hubert J	0.42	0.00	0.00

Activity 20 Sub Total

Parts:	1.96
Labor:	0.00
Labor Hours: 0.42	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Activity: 30 **999 TOTAL VEHICLE**

Activity Note:	PRAMETER
Reason for Repair:	05 - Inspection, Routine
Work Accomplished:	06 - Inspect
Part Failure:	-

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
03-Jul-18	Pierre,Hubert J	0.08	0.00	0.00

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.08	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

WorkOrder 51422953 Grand Total

Parts:	1.96
Labor:	0.00
Labor Hours: 6.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	**1.96**

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
51422953	3-Jul-18	184,419	WO	PM A
51443891	20-Jun-18	182,566	WO	ROAD CALL AND REPLACE SEPERTINE BELT AND PULLEYS 2

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51422953
Invoice Number: 55345-51422953

Client Department:			
MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL7FDA04215
Requested By:	DCARTER	**Status:**	40
Created By:	DCARTER	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

WorkOrder	Date Completed	Life Meter	Class	Description
51420987	12-Jun-18	179,999	WO	PM C
51167771	11-Jun-18	174,875	WO	PM A
51420945	11-Jun-18	174,875	WO	FOLLOWUP--REPLACE REAR TIRES

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
51310488	29-Apr-18	172,556	WO	Replace both L/R Tire

PH: Work Order: 51422953 Desc: PM A
Equip: 5411 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FL7FDA04215

LH: 10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 03-JUL-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Jul 3, 2018 11:15:29 AM	No	
10,100	Safety Inspection	Done		HPIERRE	Jul 3, 2018 11:15:29 AM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Jul 3, 2018 11:15:30 AM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		HPIERRE	Jul 3, 2018 11:15:29 AM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Jul 3, 2018 11:15:30 AM	No	
10,140	Check Service Brakes	Done		HPIERRE	Jul 3, 2018 11:15:30 AM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Jul 3, 2018 11:15:30 AM	No	
10,160	FRA Check Instruments and Horns	Done		HPIERRE	Jul 3, 2018 11:15:30 AM	No	
10,170	Check Fast Idle	Done		HPIERRE	Jul 3, 2018 11:15:31 AM	No	
10,180	Check Starter Protection Circuit	Done		HPIERRE	Jul 3, 2018 11:15:31 AM	No	
10,190	Check Reverse Warning System	Done		HPIERRE	Jul 3, 2018 11:15:31 AM	No	
11,100	Check Parking Brake	Done		HPIERRE	Jul 3, 2018 11:15:31 AM	No	
11,110	Check HVAC Switches and Other Controls	Done		HPIERRE	Jul 3, 2018 11:15:32 AM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Jul 3, 2018 11:15:32 AM	No	
11,130	FRA Check Wiper and Washer Operation	Done		HPIERRE	Jul 3, 2018 11:15:32 AM	No	
11,140	Road Test: Check for Proper Operation	Done		HPIERRE	Jul 3, 2018 11:15:32 AM	No	
11,150	Perform Brake Test	Done		HPIERRE	Jul 3, 2018 11:15:32 AM	No	
11,152	Decelerometer Results Test 1	FEET	N/A	HPIERRE	Jul 3, 2018 11:15:32 AM	No	
11,154	Decelerometer Results Test 2	FEET	N/A	HPIERRE	Jul 3, 2018 11:15:32 AM	No	
11,156	Decelerometer Results Test 3	FEET	N/A	HPIERRE	Jul 3, 2018 11:15:33 AM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	N/A	HPIERRE	Jul 3, 2018 11:15:33 AM	No	
11,162	FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A	HPIERRE	Jul 3, 2018 11:15:33 AM	No	
11,170	FRA Check Door Operation	Done		HPIERRE	Jul 3, 2018 11:15:33 AM	No	
11,180	FRA Check Operation of All Other Accessories	Done		HPIERRE	Jul 3, 2018 11:15:34 AM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		HPIERRE	Jul 3, 2018 11:15:34 AM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		HPIERRE	Jul 3, 2018 11:15:34 AM	No	
20,220	Check Accelerator and Brake Pedals	Done		HPIERRE	Jul 3, 2018 11:15:34 AM	No	
20,230	FRA Check Wiring Under Dash	Done		HPIERRE	Jul 3, 2018 11:15:35 AM	No	
20,240	FRA Check Interior Lights	Done		HPIERRE	Jul 3, 2018 11:15:35 AM	No	
20,250	FRA Check Interior Electrical Panels	Done		HPIERRE	Jul 3, 2018 11:15:35 AM	No	
20,260	Check Stop Request System	-	N/A	HPIERRE	Jul 3, 2018 11:15:35 AM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Jul 3, 2018 11:15:36 AM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Jul 3, 2018 11:15:36 AM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Jul 3, 2018 11:15:36 AM	No	
22,100	Check Emergency Windows and Glass Condition	Done		HPIERRE	Jul 3, 2018 11:15:36 AM	No	
22,110	Check Emergency Hatches	Done		HPIERRE	Jul 3, 2018 11:15:36 AM	No	
22,120	Check All Safety Equipment	Done		HPIERRE	Jul 3, 2018 11:15:36 AM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Jul 3, 2018 11:15:36 AM	No	
30,310	Check Passenger Doors	Done		HPIERRE	Jul 3, 2018 11:15:37 AM	No	
30,320	Inspect Step-well and Hand Rails	Done		HPIERRE	Jul 3, 2018 11:15:37 AM	No	
30,330	Check Wheelchair Lift Operation	Done		HPIERRE	Jul 3, 2018 11:15:37 AM	No	
30,340	FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Jul 3, 2018 11:15:37 AM	No	
30,350	FRA Inspect Mirror and Mountings	Done		HPIERRE	Jul 3, 2018 11:15:37 AM	No	
30,360	Check for Physical Damage and Decals	Done		HPIERRE	Jul 3, 2018 11:15:38 AM	No	
30,370	Check Wiper Blade and Arm Condition	Done		HPIERRE	Jul 3, 2018 11:15:38 AM	No	
30,380	Check Exterior Compartment Doors	Done		HPIERRE	Jul 3, 2018 11:15:38 AM	No	
30,390	FRA Check Fuel Tank Cap	Done		HPIERRE	Jul 3, 2018 11:15:38 AM	No	
33,100	Check Lights and Reflectors	Done		HPIERRE	Jul 3, 2018 11:15:39 AM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Jul 3, 2018 11:15:39 AM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Jul 3, 2018 11:15:38 AM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Jul 3, 2018 11:15:39 AM	No	
40,420	Check Hood	Done		HPIERRE	Jul 3, 2018 11:15:39 AM	No	
40,430	Check Fan, Shroud and Radiator	Done		HPIERRE	Jul 3, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					11:15:39 AM		
40,440	Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Jul 3, 2018 11:15:39 AM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Jul 3, 2018 11:15:39 AM	No	
40,442	Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Jul 3, 2018 11:15:40 AM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Jul 3, 2018 11:15:40 AM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	Done		HPIERRE	Jul 3, 2018 11:15:40 AM	No	
40,461	Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Jul 3, 2018 11:15:40 AM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Jul 3, 2018 11:15:40 AM	No	
40,480	FRA Check Coolant Hose Condition	Done		HPIERRE	Jul 3, 2018 11:15:41 AM	No	
40,490	FRA Check Alternator Mount and Condition	Done		HPIERRE	Jul 3, 2018 11:15:41 AM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Jul 3, 2018 11:15:41 AM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Jul 3, 2018 11:15:41 AM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Jul 3, 2018 11:15:42 AM	No	
44,130	FRA Check Exhaust System	Done		HPIERRE	Jul 3, 2018 11:15:42 AM	No	
44,140	FRA Check Intake System	Done		HPIERRE	Jul 3, 2018 11:15:42 AM	No	
44,150	FRA Inspect Turbocharger	-	N/A	HPIERRE	Jul 3, 2018 11:15:42 AM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Jul 3, 2018 11:15:42 AM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Jul 3, 2018 11:15:42 AM	No	
44,180	FRA Check for Leaks	Done		HPIERRE	Jul 3, 2018 11:15:42 AM	No	
44,190	FRA Perform Battery Inspection	Done		HPIERRE	Jul 3, 2018 11:15:43 AM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Jul 3, 2018 11:15:43 AM	No	
50,000	SECTION 5 Steering System Inspection	Done		HPIERRE	Jul 3, 2018 11:15:44 AM	No	
50,510	Check Entire Steering System	Done		HPIERRE	Jul 3, 2018 11:15:43 AM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Jul 3, 2018 11:15:44 AM	No	
60,610	FRA Check and Record Air Pressure	Done		HPIERRE	Jul 3, 2018 11:15:44 AM	No	
60,611	Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Jul 3, 2018 11:15:44 AM	No	
60,612	Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Jul 3, 2018 11:15:44 AM	No	
60,613	Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Jul 3, 2018 11:15:45 AM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Jul 3, 2018 11:15:45 AM	No	
60,615	Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Jul 3, 2018 11:15:45 AM	No	
60,616	Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Jul 3, 2018 11:15:45 AM	No	
60,620	Check Valve Stems and Caps	Done		HPIERRE	Jul 3, 2018 11:15:46 AM	No	
60,630	Check and Record Tread Depth	Done		HPIERRE	Jul 3, 2018 11:15:46 AM	No	
60,631	Tread Depth RF	8 32nds of an inch		HPIERRE	Jul 3, 2018 11:15:46 AM	No	
60,632	Tread Depth LF	8 32nds of an inch		HPIERRE	Jul 3, 2018 11:15:46 AM	No	
60,633	Tread Depth RRO	7 32nds of an inch		HPIERRE	Jul 3, 2018 11:15:47 AM	No	
60,634	Tread Depth RRI	7 32nds of an inch		HPIERRE	Jul 3, 2018 11:15:47 AM	No	
60,635	Tread Depth LRI	7 32nds of an inch		HPIERRE	Jul 3, 2018 11:15:47 AM	No	
60,636	Tread Depth LRO	7 32nds of an inch		HPIERRE	Jul 3, 2018 11:15:47 AM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		HPIERRE	Jul 3, 2018 11:15:48 AM	No	
60,650	Check Sidewall Wear	Done		HPIERRE	Jul 3, 2018 11:15:47 AM	No	
60,660	Inspect for Cuts and Tears	Done		HPIERRE	Jul 3, 2018 11:15:47 AM	No	
60,670	Check Dual Mating With Square	-	N/A	HPIERRE	Jul 3, 2018 11:15:48 AM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Jul 3, 2018 11:15:48 AM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Jul 3, 2018 11:15:48 AM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		HPIERRE	Jul 3, 2018 11:15:48 AM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Jul 3, 2018 11:15:48 AM	No	
70,710	Check Vibration Damper	Done		HPIERRE	Jul 3, 2018 11:15:49 AM	No	
70,720	Check Engine and Transmission Mounts	Done		HPIERRE	Jul 3, 2018 11:15:49 AM	No	
70,730	FRA Check Starter	Done		CVERGARA	Jul 3, 2018 1:12:41 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Jul 3, 2018 11:15:49 AM	No	
70,750	FRA Check Transmission for Leaks	Done		HPIERRE	Jul 3, 2018 11:15:49 AM	No	
70,760	FRA Check Differential Breather and Fluid	Done		HPIERRE	Jul 3, 2018 11:15:50 AM	No	
70,770	FRA Check Exhaust System	Done		HPIERRE	Jul 3, 2018 11:15:50 AM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Jul 3, 2018 11:15:50 AM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		HPIERRE	Jul 3, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					11:15:50 AM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Jul 3, 2018 11:15:50 AM	No	
77,110	FRA Check Fuel Tank	Done		HPIERRE	Jul 3, 2018 11:15:50 AM	No	
77,120	Check Suspension Components	Done		HPIERRE	Jul 3, 2018 11:15:50 AM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Jul 3, 2018 11:15:51 AM	No	
77,131	Brake Pad Thickness LF	10 Inch		HPIERRE	Jul 3, 2018 11:15:51 AM	No	
77,132	Brake Pad Thickness RF	10 Inch		HPIERRE	Jul 3, 2018 11:15:51 AM	No	
77,133	Brake Pad Thickness LR	7 Inch		HPIERRE	Jul 3, 2018 11:15:51 AM	No	
77,134	Brake Pad Thickness RR	7 Inch		HPIERRE	Jul 3, 2018 11:15:51 AM	No	
77,135	Brake Rotor LF	1.5 Inch		HPIERRE	Jul 3, 2018 11:15:51 AM	No	
77,136	Brake Rotor RF	1.5 Inch		HPIERRE	Jul 3, 2018 11:15:52 AM	No	
77,137	Brake Rotor LR	1.6 Inch		HPIERRE	Jul 3, 2018 11:15:52 AM	No	
77,138	Brake Rotor RR	1.6 Inch		HPIERRE	Jul 3, 2018 11:15:52 AM	No	
77,140	FRA Check Brake Hoses	Done		HPIERRE	Jul 3, 2018 11:15:52 AM	No	
77,150	Check King Pins	-	N/A	HPIERRE	Jul 3, 2018 11:15:52 AM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Jul 3, 2018 11:15:53 AM	No	
80,000	SECTION 8 PMI Report Completion	Done		HPIERRE	Jul 3, 2018 11:15:53 AM	No	
80,810	Completion of PMI Report	Done		HPIERRE	Jul 3, 2018 11:15:53 AM	No	
90,000	SECTION 9 Completion of PMI	Done		HPIERRE	Jul 3, 2018 11:15:53 AM	No	
90,910	Vehicle Returned to predetermined location	Done		HPIERRE	Jul 3, 2018 11:15:53 AM	No	

LH: 20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 03-JUL-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		HPIERRE	Jul 3, 2018 11:20:21 AM	No	
101,000	FRA Change Oil Filters	Yes		HPIERRE	Jul 3, 2018 11:20:20 AM	No	
102,000	FRA Drain Engine Oil	Yes		HPIERRE	Jul 3, 2018 11:20:21 AM	No	
103,000	FRA Check Transmission Fluid	Done		HPIERRE	Jul 3, 2018 11:20:21 AM	No	
104,000	Lubricate Chassis	Done		HPIERRE	Jul 3, 2018 11:20:21 AM	No	
105,000	Replace or Clean A/C Filters	Done		HPIERRE	Jul 3, 2018 11:20:21 AM	No	
107,000	FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Jul 3, 2018 11:20:21 AM	No	
108,000	Lube all pivoting Mechanisms	Done		HPIERRE	Jul 3, 2018 11:20:21 AM	No	

LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 03-JUL-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Jul 3, 2018 11:20:51 AM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51480020
Invoice Number: 55345-51480020

Client Department:	55345M	**Equipment:**	5411 Ford E350 Champion Crusaders
MRC:		**VIN:**	1FDEE3FL7FDA04215
WO Desc:		**Status:**	40
PM A		**Priority:**	1
Requested By:	HPIERRE	**Driver:**	
Created By:	HPIERRE	**Phone:**	
Class:	WO	**ETA:**	
Arrangement:	Unassigned		
Potential Warranty:	No		

Chronology

Reported	Aug 3, 2018	1:06 PM
Started	Aug 3, 2018	
Completed	Aug 3, 2018	11:02 PM

Meter	Reading	UOM
WO		DH
Life	188,811	DH
System	188,996	DH

Down Time

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PM-A CAUSE: PREVENTIVE MAINTENANCE CORRECTION: TECH PERFORMED PM-A PART USED OIL FILTER QTY:1 PART#B329 OIL QTY:6.5 Heater hose was leaking

Activity: 10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
03-Aug-18	KARLENS,Cyrius	2.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

FirstBase by First Transit

WorkOrder
55345 Palm Tran Connection
v 2.2

WorkOrder: 51675790
Invoice Number: 55345-51675790

Client Department:			
MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL7FDA04215
Requested By:	CVERGARA	**Status:**	40
Created By:	CVERGARA	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Oct 1, 2018	11:12 AM
Started	Oct 1, 2018	
Completed	Oct 2, 2018	12:03 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	198,091	DH
System	198,091	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE:preventive maintenance CORRECTION: Tech Performed pmA Hubert completed Pm

Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
01-Oct-18	KARLENS,Cyrius	2.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
01-Oct-18	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51774388
Invoice Number: 55345-51774388

Client Department:			
MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL7FDA04215
Requested By:	CVERGARA	**Status:**	32
Created By:	CVERGARA	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Oct 26, 2018	12:03 PM
Started	Oct 26, 2018	
Completed	Oct 26, 2018	11:16 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	202,022	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmA CAUSE:Service CORRECTION:Perform pmA Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
26-Oct-18	Gaspard,Ronald	1.55	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.55	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
26-Oct-18	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51943253
Invoice Number: 55345-51943253

Client Department:			
MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL7FDA04215
Requested By:	CVERGARA	**Status:**	40
Created By:	CVERGARA	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Dec 24, 2018	10:18 AM
Started	Dec 24, 2018	
Completed	Dec 24, 2018	1:07 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	211,019	DH

WorkOrder Notes

Line	Comment
10	PM. Perform pmA service, lube front end, tire rotation, torque and re torque tires (140 f/p), R&R engine oil and filter, road test, all okay at this time. Parts. Engine oil filter part # B329 qty 1 engine oil. 5W20 Qty 6 qts

Activity: 10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
24-Dec-18	Rodriguez,Raul	1.82	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.82	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
24-Dec-18	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52021526
Invoice Number: 55345-52021526

Client Department:
MRC: 55345M
WO Desc:
PM A
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5411
Ford E350 Champion Crusaders
VIN: 1FDEE3FL7FDA04215
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Jan 22, 2019	10:05 AM
Started	Jan 22, 2019	
Completed	Jan 23, 2019	12:56 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	215,262	DH
System	215,262	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PM A CAUSE: Service due CORRECTION: Performed and completed pmA Service Changed engine oil and replaced engine oil filter Changed rear AC filter

Activity: 10 999 **TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
22-Jan-19	Delva,Terry	1.43	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.43	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 999 **TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
22-Jan-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52181335
Invoice Number: 55345-52181335

Client Department:

MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL7FDA04215
Requested By:	VAMRITTEEMAL	**Status:**	40
Created By:	VAMRITTEEMAL	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Mar 15, 2019	8:11 AM
Started	Mar 15, 2019	
Completed	Mar 15, 2019	1:14 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	223,516	DH
System	223,719	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Service A
	CAUSE: Prevention maintenance
	CORRECTION: Tech Perform PM-A

Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
15-Mar-19	KARLENS,Cyrius	2.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
15-Mar-19	B329		FILTER, OIL (FGA0000399/FSC0000399)	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52256941
Invoice Number: 55345-52256941

Client Department:			
MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL7FDA04215
Requested By:	CVERGARA	**Status:**	40
Created By:	CVERGARA	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Apr 11, 2019	10:09 AM
Started	Apr 11, 2019	
Completed	Apr 11, 2019	11:17 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	227,751	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA SERVICE CAUSE: PREVENTIVE MAINTENANCE CORRECTION: PERFORM AND COMPLETED PMA SERVICE REPLACED AIR FILTER

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
11-Apr-19	AMRIT TEEMAL,VISHNU	0.27	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.27	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
11-Apr-19	PA4075		FILTER, AIR, PAPER SAME AS AF25590	1.00	5.28	5.28

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52427111
Invoice Number: 55345-52427111

Client Department:			
MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL7FDA04215
Requested By:	VAMRITTEEMAL	**Status:**	40
Created By:	VAMRITTEEMAL	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jun 14, 2019	12:00 AM
Started		
Completed	Jun 14, 2019	4:29 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	237,296	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PmA service
	CAUSE: preventive maintenance
	CORRECTION:PmA Service Performed

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
14-Jun-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

Labor Posted

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52519845
Invoice Number: 55345-52519845

Client Department:			
MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL7FDA04215
Requested By:	RRENE	**Status:**	40
Created By:	RRENE	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jul 12, 2019	10:24 AM
Started	Jul 12, 2019	
Completed	Jul 12, 2019	10:16 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	241,072	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA SERVICE CAUSE: PREVENTIVE MAINTENANCE CORRECTION: PERFORM AND COMPLETED PMA SERVICE

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
12-Jul-19	AMRIT TEEMAL,VISHNU	1.50	65.00	97.50

Activity 10 Sub Total

Parts:	0.00
Labor:	97.50
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**97.50**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
12-Jul-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52683431
Invoice Number: 55345-52683431

Client Department:

MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL7FDA04215
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Sep 16, 2019	2:13 PM
Started	Sep 17, 2019	
Completed	Sep 18, 2019	12:28 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	250,014	DH
System	250,014	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: Service CORRECTION: perform pmA service Oil filter B329 qty1 Engine oil 5w20 qty 7 Qts Replaced AC filter

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
17-Sep-19	Gaspard,Ronald	1.62	65.00	105.08

Activity 10 Sub Total

Parts:	0.00
Labor:	105.08
Labor Hours: 1.62	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**105.08**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52804543
Invoice Number: 55345-52804543

Client Department:

MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL7FDA04215
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Oct 15, 2019	3:08 PM
Started	Oct 15, 2019	
Completed	Oct 15, 2019	11:57 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	254,351	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PmA CAUSE: Service CORRECTION:perform PmA Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 qts

Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
15-Oct-19	Gaspard,Ronald	1.58	65.00	102.92

Activity 10 Sub Total

Parts:	0.00
Labor:	102.92
Labor Hours: 1.58	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**102.92**

Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
15-Oct-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53016882
Invoice Number: 55345-53016882

Client Department:			
MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL7FDA04215
Requested By:	VAMRITTEEMAL	**Status:**	40
Created By:	VAMRITTEEMAL	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Dec 23, 2019	12:23 PM
Started	Dec 23, 2019	
Completed	Dec 23, 2019	7:36 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	263,493	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: Service CORRECTION: perform pmA service Oil filter B329 qty1 Engine oil 5w29 qty 7 Qts Rotate tires and torque wheels 140 lbs second torque 140 lbs

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
23-Dec-19	Gaspard,Ronald	2.07	65.00	134.55

Activity 10 Sub Total

Parts:	0.00
Labor:	134.55
Labor Hours: 2.07	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**134.55**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

FirstBase by First Transit

WorkOrder
55345 Palm Tran Connection
v 2.2

WorkOrder: 53124815
Invoice Number: 55345-53124815

Client Department:			
MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL7FDA04215
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jan 23, 2020	9:53 AM
Started	Jan 23, 2020	
Completed	Jan 23, 2020	10:09 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	267,588	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PMA Service. CAUSE: Service Due by Mileage. CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check brakes clean batteries. Replace A/C Filter. Parts # B329 Qty (1) Oil 5W20QTY Qty (6.5) Qts

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
23-Jan-20	Arthurs,Durvin	1.58	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.58	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
23-Jan-20	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53320138
Invoice Number: 55345-53320138

Client Department:

MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL7FDA04215
Requested By:	JUHURST	**Status:**	40
Created By:	JUHURST	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Mar 30, 2020	4:29 PM
Started	Mar 30, 2020	
Completed	Mar 31, 2020	12:07 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	275,861	DH
System	275,922	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PmA CAUSE: Service CORRECTION: perform PmA Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 qts

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
30-Mar-20	Gaspard,Ronald	1.55	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.55	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
30-Mar-20	B329(F)		FILTER, OIL, SPIN-ON	1.00	1.96	1.96

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53558540
Invoice Number: 55345-53558540

Client Department:

MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FL7FDA04215
Requested By:	NSTOLFO	**Status:**	40
Created By:	NSTOLFO	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jun 2, 2020	12:21 PM
Started	Jun 2, 2020	
Completed	Jun 3, 2020	12:08 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	280,097	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE:Service CORRECTION:Perform pmA Service Oil filter B329 qty1 Engine oil 10w30 qty 7 Qts Replaced exhaust bracket qty1

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53701841
Invoice Number: 55345-53701841

Client Department:			
MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FL7FDA04215
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Aug 28, 2020	12:00 AM
Started	Aug 28, 2020	
Completed	Aug 29, 2020	12:15 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	288,581	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA CAUSE: service CORRECTION:perform PMA service Oil filter B329 qty 1 Air filter PA4075 qty1 Engine oil 10w30 qty 7 qts

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note:	PERSONAL RISK ASSESSMENT
Reason for Repair:	SW - Shop Work Order
Work Accomplished:	06 - Inspect
Part Failure:	00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note:	Light Duty PMI
Reason for Repair:	08 - Preventive Maintenance
Work Accomplished:	-
Part Failure:	-

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53826304
Invoice Number: 55345-53826304

Client Department:

MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FL7FDA04215
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology

Reported	Oct 7, 2020	12:00 AM
Started	Oct 7, 2020	
Completed	Oct 7, 2020	11:37 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	292,942	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: CAUSE: CORRECTION:

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51081503
Invoice Number: 55345-51081503

Client Department:			
MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL7FDA04215
Requested By:	CVERGARA	**Status:**	40
Created By:	CVERGARA	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Apr 2, 2018	12:06 PM
Started	Apr 2, 2018	
Completed	Apr 2, 2018	11:22 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	170,800	DH
System	170,963	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PM-A CAUSE: Preventive maintenance CORRECTION: Tech Performed PM-A Parts Used Oil filter Qty:1 part# B328 Oil Qty:6qts Air Filter Qty:1 Part#PA4075

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
02-Apr-18	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

Labor Posted

Date	Technician	Hours	Rate	Extended
02-Apr-18	KARLENS,Cyrius	3.00	0.00	0.00

Activity 10 Sub Total

Parts:	1.96
Labor:	0.00
Labor Hours: 3.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

WorkOrder: 51081503
Invoice Number: 55345-51081503

Client Department:			
MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL7FDA04215
Requested By:	CVERGARA	**Status:**	40
Created By:	CVERGARA	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
02-Apr-18	PA4075		FILTER, AIR, PAPER SAME AS AF25590	1.00	5.27	5.27

Labor Posted

Date	Technician	Hours	Rate	Extended
02-Apr-18	KARLENS,Cyrius	2.00	0.00	0.00

Activity 20 Sub Total

Parts:	5.27
Labor:	0.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.27**

Activity: 30 **999 TOTAL VEHICLE**

Activity Note:	PRAMETER
Reason for Repair:	05 - Inspection, Routine
Work Accomplished:	06 - Inspect
Part Failure:	-

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
02-Apr-18	KARLENS,Cyrius	0.50	0.00	0.00

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

WorkOrder 51081503 Grand Total

Parts:	7.23
Labor:	0.00
Labor Hours: 5.50	
Sublet Parts:	0.00
Sublet Labor:	0.00

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51081503
Invoice Number: 55345-51081503

Client Department:			
MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL7FDA04215
Requested By:	CVERGARA	**Status:**	40
Created By:	CVERGARA	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

WorkOrder Grand Total **7.23**

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
51369888	29-May-18	173,023	WO	Engine belt.
51296291	26-Apr-18	172,385	WO	REPLACE WHEEL CHAIR BAG
51081503	2-Apr-18	170,800	WO	PM A
51081288	9-Mar-18	166,974	WO	PmB follow need rear brake pads
51030619	7-Mar-18	166,974	WO	PM B

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
51310488	29-Apr-18	172,556	WO	Replace both L/R Tire

PH: Work Order: 51081503 Desc: PM A
Equip: 5411 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FL7FDA04215

LH: 10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PM A Services Performed by: CKARLENS Performed on: 02-APR-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		CKARLENS	Apr 2, 2018 11:07:40 PM	No	
101,000	FRA Change Oil Filters	Yes		CKARLENS	Apr 2, 2018 11:07:40 PM	No	
102,000	FRA Drain Engine Oil	Yes		CKARLENS	Apr 2, 2018 11:07:40 PM	No	
103,000	FRA Check Transmission Fluid	Done		CKARLENS	Apr 2, 2018 11:07:39 PM	No	
104,000	Lubricate Chassis	Done		CKARLENS	Apr 2, 2018 11:07:40 PM	No	
105,000	Replace or Clean A/C Filters	Done		CKARLENS	Apr 2, 2018 11:07:40 PM	No	
106,000	Drain Water from Fuel Water Separator (where applicable)	Done		CKARLENS	Apr 2, 2018 11:07:40 PM	No	
107,000	FRA Change Primary Fuel Filter	No	NA	CKARLENS	Apr 2, 2018 11:07:40 PM	No	
108,000	Lube all pivoting Mechanisms	Done		CKARLENS	Apr 2, 2018 11:08:06 PM	No	

LH: 20 Desc: PM A
Task: PM A SERVICE Performed by: CKARLENS Performed on: 02-APR-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		CKARLENS	Apr 2, 2018 11:06:56 PM	No	
101,000	FRA Change Oil Filters	Yes		CKARLENS	Apr 2, 2018 11:06:56 PM	No	
102,000	FRA Drain Engine Oil	Yes		CKARLENS	Apr 2, 2018 11:06:56 PM	No	
103,000	FRA Check Transmission Fluid	Done		CKARLENS	Apr 2, 2018 11:06:56 PM	No	
104,000	Lubricate Chassis	Done		CKARLENS	Apr 2, 2018 11:06:56 PM	No	
105,000	Replace or Clean A/C Filters	Done	Tech replace rear A/C filter	CKARLENS	Apr 2, 2018 11:06:56 PM	No	
107,000	FRA Change Primary Fuel Filter	No	NA	CKARLENS	Apr 2, 2018 11:06:56 PM	No	
108,000	Lube all pivoting Mechanisms	Done		CKARLENS	Apr 2, 2018 11:06:57 PM	No	

LH: 30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 02-APR-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Apr 2, 2018 11:05:28 PM	No	
20	Miles					No	
30	Kilometers					No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
40	Hours					No	

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51167771
Invoice Number: 55345-51167771

Client Department:			
MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL7FDA04215
Requested By:	CKARLENS	**Status:**	40
Created By:	CKARLENS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology

Reported	Jun 11, 2018	3:00 PM
Started	Jun 11, 2018	
Completed	Jun 11, 2018	11:05 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	174,875	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PM-A CAUSE: Preventive maintenance CORRECTION: Tech Perform PM-A Parts used Oil filter Qty1 part#B329 Oil Qty:6.5

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
11-Jun-18	KARLENS,Cyrius	1.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

WorkOrder: 51167771
Invoice Number: 55345-51167771

Client Department:
MRC: 55345M
WO Desc:
PM A
Requested By: CKARLENS
Created By: CKARLENS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5411
Ford E350 Champion Crusaders
VIN: 1FDEE3FL7FDA04215
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Date	Part Number		Description	Qty.	Each	Extended
11-Jun-18	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

Labor Posted

Date	Technician	Hours	Rate	Extended
11-Jun-18	KARLENS,Cyrius	1.00	0.00	0.00

Activity 20 Sub Total

Parts:	1.96
Labor:	0.00
Labor Hours: 1.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Activity: 30 **999 TOTAL VEHICLE**

Activity Note: PRAMETER
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
11-Jun-18	KARLENS,Cyrius	0.27	0.00	0.00

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.27	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

WorkOrder 51167771 Grand Total

Parts:	1.96
Labor:	0.00
Labor Hours: 2.27	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	**1.96**

Recent Repair History

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51167771
Invoice Number: 55345-51167771

Client Department:

MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL7FDA04215
Requested By:	CKARLENS	**Status:**	40
Created By:	CKARLENS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

WorkOrder	Date Completed	Life Meter	Class	Description
51167771	11-Jun-18	174,875	WO	PM A
51420945	11-Jun-18	174,875	WO	FOLLOWUP--REPLACE REAR TIRES
51369888	29-May-18	173,023	WO	Engine belt.

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
51310488	29-Apr-18	172,556	WO	Replace both L/R Tire

PH: Work Order: 51167771 Desc: PM A
Equip: 5411 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FL7FDA04215

LH: 10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: CKARLENS Performed on: 11-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		CKARLENS	Jun 11, 2018 10:20:28 PM	No	
10,100	Safety Inspection	Done		CKARLENS	Jun 11, 2018 10:20:28 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		CKARLENS	Jun 11, 2018 10:20:28 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		CKARLENS	Jun 11, 2018 10:20:28 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		CKARLENS	Jun 11, 2018 10:20:29 PM	No	
10,140	Check Service Brakes	Done		CKARLENS	Jun 11, 2018 10:20:29 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		CKARLENS	Jun 11, 2018 10:20:29 PM	No	
10,160	FRA Check Instruments and Horns	Done		CKARLENS	Jun 11, 2018 10:20:29 PM	No	
10,170	Check Fast Idle	Done		CKARLENS	Jun 11, 2018 10:20:30 PM	No	
10,180	Check Starter Protection Circuit	Done		CKARLENS	Jun 11, 2018 10:20:30 PM	No	
10,190	Check Reverse Warning System	Done		CKARLENS	Jun 11, 2018 10:20:30 PM	No	
11,100	Check Parking Brake	Done		CKARLENS	Jun 11, 2018 10:20:29 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		CKARLENS	Jun 11, 2018 10:20:30 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		CKARLENS	Jun 11, 2018 10:20:30 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		CKARLENS	Jun 11, 2018 10:20:30 PM	No	
11,140	Road Test: Check for Proper Operation	Done		CKARLENS	Jun 11, 2018 10:20:30 PM	No	
11,150	Perform Brake Test	Done		CKARLENS	Jun 11, 2018 10:20:31 PM	No	
11,152	Decelerometer Results Test 1	FEET	na	CKARLENS	Jun 11, 2018 10:20:31 PM	No	
11,154	Decelerometer Results Test 2	FEET	na	CKARLENS	Jun 11, 2018 10:20:31 PM	No	
11,156	Decelerometer Results Test 3	FEET	na	CKARLENS	Jun 11, 2018 10:20:31 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	CKARLENS	Jun 11, 2018 10:20:32 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	na	CKARLENS	Jun 11, 2018 10:20:32 PM	No	
11,170	FRA Check Door Operation	Done		CKARLENS	Jun 11, 2018 10:20:32 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		CKARLENS	Jun 11, 2018 10:20:32 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		CKARLENS	Jun 11, 2018 10:20:33 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		CKARLENS	Jun 11, 2018 10:20:32 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		CKARLENS	Jun 11, 2018 10:20:33 PM	No	
20,230	FRA Check Wiring Under Dash	Done		CKARLENS	Jun 11, 2018 10:20:33 PM	No	
20,240	FRA Check Interior Lights	Done		CKARLENS	Jun 11, 2018 10:20:33 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		CKARLENS	Jun 11, 2018 10:20:33 PM	No	
20,260	Check Stop Request System	-	na	CKARLENS	Jun 11, 2018 10:20:33 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	na	CKARLENS	Jun 11, 2018 10:20:34 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		CKARLENS	Jun 11, 2018 10:20:34 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		CKARLENS	Jun 11, 2018 10:20:34 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		CKARLENS	Jun 11, 2018 10:20:34 PM	No	
22,110	Check Emergency Hatches	Done		CKARLENS	Jun 11, 2018 10:20:35 PM	No	
22,120	Check All Safety Equipment	Done		CKARLENS	Jun 11, 2018 10:20:35 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		CKARLENS	Jun 11, 2018 10:20:35 PM	No	
30,310	Check Passenger Doors	Done		CKARLENS	Jun 11, 2018 10:20:35 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		CKARLENS	Jun 11, 2018 10:20:35 PM	No	
30,330	Check Wheelchair Lift Operation	Done		CKARLENS	Jun 11, 2018 10:20:36 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	na	CKARLENS	Jun 11, 2018 10:20:36 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		CKARLENS	Jun 11, 2018 10:20:36 PM	No	
30,360	Check for Physical Damage and Decals	Done		CKARLENS	Jun 11, 2018 10:20:37 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		CKARLENS	Jun 11, 2018 10:20:36 PM	No	
30,380	Check Exterior Compartment Doors	Done		CKARLENS	Jun 11, 2018 10:20:37 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		CKARLENS	Jun 11, 2018 10:20:38 PM	No	
33,100	Check Lights and Reflectors	Done		CKARLENS	Jun 11, 2018 10:20:37 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		CKARLENS	Jun 11, 2018 10:20:37 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		CKARLENS	Jun 11, 2018 10:20:38 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		CKARLENS	Jun 11, 2018 10:20:38 PM	No	
40,420	Check Hood	Done		CKARLENS	Jun 11, 2018 10:20:38 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		CKARLENS	Jun 11, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:20:39 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	na	CKARLENS	Jun 11, 2018 10:20:39 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		CKARLENS	Jun 11, 2018 10:20:39 PM	No	
40,442	Freeze Point	Degree Fahrenheit	na	CKARLENS	Jun 11, 2018 10:20:39 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		CKARLENS	Jun 11, 2018 10:20:39 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	na	CKARLENS	Jun 11, 2018 10:20:39 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	na	CKARLENS	Jun 11, 2018 10:20:40 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		CKARLENS	Jun 11, 2018 10:20:40 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		CKARLENS	Jun 11, 2018 10:20:40 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		CKARLENS	Jun 11, 2018 10:20:40 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		CKARLENS	Jun 11, 2018 10:20:40 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		CKARLENS	Jun 11, 2018 10:20:41 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		CKARLENS	Jun 11, 2018 10:20:41 PM	No	
44,130	FRA Check Exhaust System	Done		CKARLENS	Jun 11, 2018 10:20:42 PM	No	
44,140	FRA Check Intake System	Done		CKARLENS	Jun 11, 2018 10:20:42 PM	No	
44,150	FRA Inspect Turbocharger	-	na	CKARLENS	Jun 11, 2018 10:20:41 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		CKARLENS	Jun 11, 2018 10:20:42 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		CKARLENS	Jun 11, 2018 10:20:42 PM	No	
44,180	FRA Check for Leaks	Done		CKARLENS	Jun 11, 2018 10:20:42 PM	No	
44,190	FRA Perform Battery Inspection	Done		CKARLENS	Jun 11, 2018 10:20:42 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		CKARLENS	Jun 11, 2018 10:20:43 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		CKARLENS	Jun 11, 2018 10:20:42 PM	No	
50,510	Check Entire Steering System	Done		CKARLENS	Jun 11, 2018 10:20:43 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		CKARLENS	Jun 11, 2018 10:20:43 PM	No	
60,610	FRA Check and Record Air Pressure	Done		CKARLENS	Jun 11, 2018 10:20:43 PM	No	
60,611	Air Pressure RF	70 Pounds per Square Inch		CKARLENS	Jun 11, 2018 10:20:43 PM	No	
60,612	Air Pressure LF	70 Pounds per Square Inch		CKARLENS	Jun 11, 2018 10:20:44 PM	No	
60,613	Air Pressure RRO	70 Pounds per Square Inch		CKARLENS	Jun 11, 2018 10:20:44 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	70 Pounds per Square Inch		CKARLENS	Jun 11, 2018 10:20:44 PM	No	
60,615	Air Pressure LRI	70 Pounds per Square Inch		CKARLENS	Jun 11, 2018 10:20:44 PM	No	
60,616	Air Pressure LRO	70 Pounds per Square Inch		CKARLENS	Jun 11, 2018 10:20:45 PM	No	
60,620	Check Valve Stems and Caps	Done		CKARLENS	Jun 11, 2018 10:20:44 PM	No	
60,630	Check and Record Tread Depth	Done		CKARLENS	Jun 11, 2018 10:20:44 PM	No	
60,631	Tread Depth RF	11 32nds of an inch		CKARLENS	Jun 11, 2018 10:20:45 PM	No	
60,632	Tread Depth LF	11 32nds of an inch		CKARLENS	Jun 11, 2018 10:20:45 PM	No	
60,633	Tread Depth RRO	3 32nds of an inch		CKARLENS	Jun 11, 2018 10:20:45 PM	No	
60,634	Tread Depth RRI	3 32nds of an inch		CKARLENS	Jun 11, 2018 10:20:45 PM	No	
60,635	Tread Depth LRI	4 32nds of an inch		CKARLENS	Jun 11, 2018 10:20:46 PM	No	
60,636	Tread Depth LRO	3 32nds of an inch	REPLACE REAR TIRES	CKARLENS	Jun 11, 2018 10:21:47 PM	Yes	51420945
60,640	Check for Mismatched Tread or Casing Design	Done		CKARLENS	Jun 11, 2018 10:20:46 PM	No	
60,650	Check Sidewall Wear	Done		CKARLENS	Jun 11, 2018 10:20:46 PM	No	
60,660	Inspect for Cuts and Tears	Done		CKARLENS	Jun 11, 2018 10:20:47 PM	No	
60,670	Check Dual Mating With Square	Done		CKARLENS	Jun 11, 2018 10:20:47 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		CKARLENS	Jun 11, 2018 10:20:47 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		CKARLENS	Jun 11, 2018 10:20:48 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		CKARLENS	Jun 11, 2018 10:20:47 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		CKARLENS	Jun 11, 2018 10:20:48 PM	No	
70,710	Check Vibration Damper	Done		CKARLENS	Jun 11, 2018 10:20:47 PM	No	
70,720	Check Engine and Transmission Mounts	Done		CKARLENS	Jun 11, 2018 10:20:48 PM	No	
70,730	FRA Check Starter	Done		CKARLENS	Jun 11, 2018 10:20:48 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		CKARLENS	Jun 11, 2018 10:20:48 PM	No	
70,750	FRA Check Transmission for Leaks	Done		CKARLENS	Jun 11, 2018 10:20:49 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		CKARLENS	Jun 11, 2018 10:20:49 PM	No	
70,770	FRA Check Exhaust System	Done		CKARLENS	Jun 11, 2018 10:20:49 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		CKARLENS	Jun 11, 2018 10:20:49 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		CKARLENS	Jun 11, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:20:50 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		CKARLENS	Jun 11, 2018 10:20:50 PM	No	
77,110	FRA Check Fuel Tank	Done		CKARLENS	Jun 11, 2018 10:20:50 PM	No	
77,120	Check Suspension Components	Done		CKARLENS	Jun 11, 2018 10:20:50 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		CKARLENS	Jun 11, 2018 10:20:50 PM	No	
77,131	Brake Pad Thickness LF	9 Inch		CKARLENS	Jun 11, 2018 10:20:51 PM	No	
77,132	Brake Pad Thickness RF	9 Inch		CKARLENS	Jun 11, 2018 10:20:50 PM	No	
77,133	Brake Pad Thickness LR	7 Inch		CKARLENS	Jun 11, 2018 10:20:51 PM	No	
77,134	Brake Pad Thickness RR	7 Inch		CKARLENS	Jun 11, 2018 10:20:51 PM	No	
77,135	Brake Rotor LF	39.8 Inch		CKARLENS	Jun 11, 2018 10:20:51 PM	No	
77,136	Brake Rotor RF	39.8 Inch		CKARLENS	Jun 11, 2018 10:20:52 PM	No	
77,137	Brake Rotor LR	35.8 Inch		CKARLENS	Jun 11, 2018 10:20:52 PM	No	
77,138	Brake Rotor RR	35.8 Inch		CKARLENS	Jun 11, 2018 10:20:52 PM	No	
77,140	FRA Check Brake Hoses	Done		CKARLENS	Jun 11, 2018 10:20:52 PM	No	
77,150	Check King Pins	-	na	CKARLENS	Jun 11, 2018 10:20:52 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		CKARLENS	Jun 11, 2018 10:20:52 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		CKARLENS	Jun 11, 2018 10:20:53 PM	No	
80,810	Completion of PMI Report	Done		CKARLENS	Jun 11, 2018 10:20:53 PM	No	
90,000	SECTION 9 Completion of PMI	Done		CKARLENS	Jun 11, 2018 10:20:53 PM	No	
90,910	Vehicle Returned to predetermined location	Done		CKARLENS	Jun 11, 2018 10:20:53 PM	No	

LH: 20 Desc: PM A
Task: PM A SERVICE Performed by: CKARLENS Performed on: 11-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		CKARLENS	Jun 11, 2018 10:22:40 PM	No	
101,000	FRA Change Oil Filters	Yes		CKARLENS	Jun 11, 2018 10:22:41 PM	No	
102,000	FRA Drain Engine Oil	Yes		CKARLENS	Jun 11, 2018 10:22:41 PM	No	
103,000	FRA Check Transmission Fluid	Done		CKARLENS	Jun 11, 2018 10:22:40 PM	No	
104,000	Lubricate Chassis	Done		CKARLENS	Jun 11, 2018 10:22:41 PM	No	
105,000	Replace or Clean A/C Filters	Done		CKARLENS	Jun 11, 2018 10:22:41 PM	No	
107,000	FRA Change Primary Fuel Filter	No	na	CKARLENS	Jun 11, 2018 10:22:41 PM	No	
108,000	Lube all pivoting Mechanisms	Done		CKARLENS	Jun 11, 2018 10:22:41 PM	No	

LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 11-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Jun 11, 2018 10:23:07 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51567357
Invoice Number: 55345-51567357

Client Department:			
MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
PM B		**VIN:**	1FDEE3FL7FDA04215
Requested By:	CKARLENS	**Status:**	40
Created By:	CKARLENS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Aug 29, 2018	11:28 AM
Started	Aug 31, 2018	
Completed	Aug 31, 2018	1:37 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	193,417	DH
System	193,274	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PmA CAUSE: preventive maintenance CORRECTION:perform service lube all Pivoting Points cross rotate tires complete B329 qty 1

Activity: 10 999 TOTAL VEHICLE

Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
31-Aug-18	Pierre,Hubert J	6.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 6.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

FirstBase by First Transit

WorkOrder
55345 Palm Tran Connection
v 2.2

WorkOrder: 52104771
Invoice Number: 55345-52104771

Client Department:			
MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
PM B		**VIN:**	1FDEE3FL7FDA04215
Requested By:	CVERGARA	**Status:**	40
Created By:	CVERGARA	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Feb 18, 2019	12:13 PM
Started	Feb 18, 2019	
Completed	Feb 18, 2019	11:25 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	219,488	DH
System	219,629	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMB Service CAUSE: Preventive Maintenance CORRECTION: Perform and completed PMB Service Replaced drain plug

Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
18-Feb-19	AMRIT TEEMAL,VISHNU	1.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
18-Feb-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52597600
Invoice Number: 55345-52597600

Client Department:			
MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
PM B		**VIN:**	1FDEE3FL7FDA04215
Requested By:	VAMRITTEEMAL	**Status:**	40
Created By:	VAMRITTEEMAL	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Aug 12, 2019	11:45 AM
Started	Aug 12, 2019	
Completed	Aug 13, 2019	12:19 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	245,398	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmB CAUSE: Service CORRECTION: perform pmB Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 qts

Activity: 10 999 **TOTAL VEHICLE**
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
12-Aug-19	Gaspard,Ronald	1.58	65.00	102.92

Activity 10 Sub Total

Parts:	0.00
Labor:	102.92
Labor Hours: 1.58	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**102.92**

Activity: 20 999 **TOTAL VEHICLE**
Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
12-Aug-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53210703
Invoice Number: 55345-53210703

Client Department:

MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
PM B		**VIN:**	1FDEE3FL7FDA04215
Requested By:	DARTHURS	**Status:**	40
Created By:	DARTHURS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Feb 24, 2020	10:29 AM
Started	Feb 24, 2020	
Completed	Feb 24, 2020	9:42 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	271,789	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Vehicle came in for PM. Service CAUSE: it is for service CORRECTION: Service complete. Replace 6.5 quarts oil to engine on oil filter on one air filter

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
24-Feb-20	Junior Hurst	1.22	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.22	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
24-Feb-20	PA4075(F)		FILTER, AIR	1.00	5.28	5.28
24-Feb-20	B329(F)		FILTER, OIL, SPIN-ON	1.00	1.96	1.96

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53941807
Invoice Number: 55345-53941807

Client Department:			
MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMB		**VIN:**	1FDEE3FL7FDA04215
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Nov 16, 2020	12:00 AM
Started	Nov 17, 2020	
Completed	Nov 18, 2020	12:26 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	297,555	DH
System	297,555	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PMB CAUSE:Service CORRECTION:perform pmB Service Oil filter B329 Qty1 Engine oil 10w30 qty 7 qts Replaced AC filter

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note:	PERSONAL RISK ASSESSMENT
Reason for Repair:	SW - Shop Work Order
Work Accomplished:	06 - Inspect
Part Failure:	00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note:	Light Duty PMI
Reason for Repair:	08 - Preventive Maintenance
Work Accomplished:	-
Part Failure:	-

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51852556
Invoice Number: 55345-51852556

Client Department:			
MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
PM C		**VIN:**	1FDEE3FL7FDA04215
Requested By:	RGASPARD	**Status:**	32
Created By:	RGASPARD	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Nov 26, 2018	2:18 PM
Started		
Completed	Nov 28, 2018	9:26 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	206,707	DH
System	206,707	DH

WorkOrder Notes

Line	Comment
10	PMC Preventive maintenance Perform service lube all Pivoting Points cross Rotate Tires completed No transmission service done

Activity: 10 999 **TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 999 **TOTAL VEHICLE**
Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
27-Nov-18	P9600		FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45

FirstBase by First Transit

WorkOrder
55345 Palm Tran Connection
v 2.2

WorkOrder: 52337104
Invoice Number: 55345-52337104

Client Department:
MRC: 55345M
WO Desc:
PM C
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5411
Ford E350 Champion Crusaders
VIN: 1FDEE3FL7FDA04215
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	May 10, 2019	12:00 AM
Started	May 12, 2019	
Completed	May 13, 2019	11:32 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	232,688	DH
System	232,488	DH

WorkOrder Notes

Line	Comment
10	PMC SERVICE PREVENTIVE MAINTENANCE PERFORM AND COMPLETED PMC SERVICE

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
12-May-19	AMRIT TEEMAL,VISHNU	2.00	65.00	130.00

Activity 10 Sub Total

Parts:	0.00
Labor:	130.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**130.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
12-May-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96
12-May-19	20021		FILTER, TRANSMISSION, E350, '09 W/RUBBER NECK SEAL SAME AS FT180	1.00	17.27	17.27

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52899836
Invoice Number: 55345-52899836

Client Department:			
MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
PM C		**VIN:**	1FDEE3FL7FDA04215
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Nov 18, 2019	12:00 AM
Started	Nov 19, 2019	
Completed	Nov 19, 2019	2:40 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	259,079	DH
System	259,079	DH

WorkOrder Notes

Line	Comment
10	PMC SERVICE PREVENTIVE MAINTENANCE PERFORM AND COMPLETED PMC SERVICE

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
19-Nov-19	AMRIT TEEMAL,VISHNU	2.50	65.00	162.50

Activity 10 Sub Total

Parts:	0.00
Labor:	162.50
Labor Hours: 2.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**162.50**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
19-Nov-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

Labor Posted

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53594750
Invoice Number: 55345-53594750

Client Department:

MRC:	55345M	**Equipment:**	5411
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMC		**VIN:**	1FDEE3FL7FDA04215
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology

Reported	Jul 15, 2020	12:12 PM
Started	Jul 15, 2020	
Completed	Jul 16, 2020	12:04 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	284,315	DH

WorkOrder Notes

Line	Comment
10	PMC Service Perform PMC service Oil filter B329 Qty1 Engine oil 10w30 qty 7 qts Gear Oil 80w90 qty 4 qts

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted