FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51611657
Invoice Number: 55345-51611657

Client Department:			
MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL2FDA06812
Requested By:	CKARLENS	**Status:**	40
Created By:	CKARLENS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Sep 6, 2018	10:43 AM
Started	Sep 6, 2018	
Completed	Sep 6, 2018	11:12 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	193,818	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA Service CAUSE: Service due by Mileage. CORRECTION: Change Oil& Filter. Lube all Pivoting Points. Check Brakes. Clean batteries. Swap R /R Outer Tire. Tread depth. 5/32 all so tap out broken alternator bracket bolts.and replace. Part # B329 Qty (1) Oil 5W20 Qty (6.5) Qts

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
06-Sep-18	Arthurs,Durvin	1.50	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51344822
Invoice Number: 55345-51344822

Client Department:			
MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL2FDA06812
Requested By:	CVERGARA	**Status:**	40
Created By:	CVERGARA	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jun 8, 2018	11:55 AM
Started	Jun 8, 2018	
Completed	Jun 8, 2018	11:35 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	181,095	DH
System	181,246	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmA CAUSE:Service CORRECTION:Perform pmA Service Oil filter B329 qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
08-Jun-18	Gaspard,Ronald	1.57	0.00	0.00

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 1.57	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
08-Jun-18	B329		FILTER, OIL (USE FGA0000399/FSC0000399)	1.00	1.96	1.96

WorkOrder: 51344822
Invoice Number: 55345-51344822

Client Department:

MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL2FDA06812
Requested By:	CVERGARA	**Status:**	40
Created By:	CVERGARA	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Labor Posted

Date	Technician	Hours	Rate	Extended
08-Jun-18	Gaspard,Ronald	1.00	0.00	0.00

Activity 20 Sub Total

Parts:	1.96
Labor:	0.00
Labor Hours: 1.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Activity: 30 **999 TOTAL VEHICLE**

Activity Note:	PRAMETER
Reason for Repair:	05 - Inspection, Routine
Work Accomplished:	06 - Inspect
Part Failure:	-

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
08-Jun-18	Gaspard,Ronald	0.25	0.00	0.00

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.25	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

WorkOrder 51344822 Grand Total

Parts:	1.96
Labor:	0.00
Labor Hours: 2.82	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	**1.96**

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
51344822	8-Jun-18	181,095	WO	PM A
51404778	7-Jun-18	180,775	WO	Needs tag light assembly

WorkOrder: 51344822
Invoice Number: 55345-51344822

Client Department:

MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL2FDA06812
Requested By:	CVERGARA	**Status:**	40
Created By:	CVERGARA	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

WorkOrder	Date Completed	Life Meter	Class	Description
51404242	6-Jun-18	180,775	WO	Upper Glass Housing
51369897	29-May-18	178,995	WO	One of the clearance lights is out. The battery comparment latch
51366739	23-May-18	178,822	WO	Wiper Blades
51341518	14-May-18	177,332	WO	Needs front rotors ;front shoks ; front brakes job and 2 front tires
51240660	14-May-18	177,332	WO	PM C

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description

PH: Work Order: 51344822 Desc: PM A
Equip: 5413 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FL2FDA06812

LH: 10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 08-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Jun 8, 2018 11:31:49 PM	No	
10,100	Safety Inspection	Done		RGASPARD	Jun 8, 2018 11:31:50 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jun 8, 2018 11:31:49 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		RGASPARD	Jun 8, 2018 11:31:50 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Jun 8, 2018 11:31:50 PM	No	
10,140	Check Service Brakes	Done		RGASPARD	Jun 8, 2018 11:31:50 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Jun 8, 2018 11:31:50 PM	No	
10,160	FRA Check Instruments and Horns	Done		RGASPARD	Jun 8, 2018 11:31:50 PM	No	
10,170	Check Fast Idle	Done		RGASPARD	Jun 8, 2018 11:31:50 PM	No	
10,180	Check Starter Protection Circuit	Done		RGASPARD	Jun 8, 2018 11:31:50 PM	No	
10,190	Check Reverse Warning System	Done		RGASPARD	Jun 8, 2018 11:31:51 PM	No	
11,100	Check Parking Brake	Done		RGASPARD	Jun 8, 2018 11:31:50 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		RGASPARD	Jun 8, 2018 11:31:51 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Jun 8, 2018 11:31:51 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		RGASPARD	Jun 8, 2018 11:31:51 PM	No	
11,140	Road Test: Check for Proper Operation	Done		RGASPARD	Jun 8, 2018 11:31:51 PM	No	
11,150	Perform Brake Test	Done		RGASPARD	Jun 8, 2018 11:31:51 PM	No	
11,152	Decelerometer Results Test 1	FEET	na	RGASPARD	Jun 8, 2018 11:31:51 PM	No	
11,154	Decelerometer Results Test 2	FEET	na	RGASPARD	Jun 8, 2018 11:31:52 PM	No	
11,156	Decelerometer Results Test 3	FEET	na	RGASPARD	Jun 8, 2018 11:31:52 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Jun 8, 2018 11:31:52 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Jun 8, 2018 11:31:52 PM	No	
11,170	FRA Check Door Operation	Done		RGASPARD	Jun 8, 2018 11:31:52 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		RGASPARD	Jun 8, 2018 11:31:53 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		RGASPARD	Jun 8, 2018 11:31:53 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		RGASPARD	Jun 8, 2018 11:31:53 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		RGASPARD	Jun 8, 2018 11:31:53 PM	No	
20,230	FRA Check Wiring Under Dash	Done		RGASPARD	Jun 8, 2018 11:31:53 PM	No	
20,240	FRA Check Interior Lights	Done		RGASPARD	Jun 8, 2018 11:31:53 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		RGASPARD	Jun 8, 2018 11:31:53 PM	No	
20,260	Check Stop Request System	-	na	RGASPARD	Jun 8, 2018 11:31:53 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Jun 8, 2018 11:31:53 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Jun 8, 2018 11:31:54 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Jun 8, 2018 11:31:54 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		RGASPARD	Jun 8, 2018 11:31:54 PM	No	
22,110	Check Emergency Hatches	Done		RGASPARD	Jun 8, 2018 11:31:54 PM	No	
22,120	Check All Safety Equipment	Done		RGASPARD	Jun 8, 2018 11:31:54 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Jun 8, 2018 11:31:54 PM	No	
30,310	Check Passenger Doors	Done		RGASPARD	Jun 8, 2018 11:31:55 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		RGASPARD	Jun 8, 2018 11:31:55 PM	No	
30,330	Check Wheelchair Lift Operation	Done		RGASPARD	Jun 8, 2018 11:31:55 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	na	RGASPARD	Jun 8, 2018 11:31:55 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		RGASPARD	Jun 8, 2018 11:31:55 PM	No	
30,360	Check for Physical Damage and Decals	Done		RGASPARD	Jun 8, 2018 11:31:55 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		RGASPARD	Jun 8, 2018 11:31:56 PM	No	
30,380	Check Exterior Compartment Doors	Done		RGASPARD	Jun 8, 2018 11:31:55 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		RGASPARD	Jun 8, 2018 11:31:56 PM	No	
33,100	Check Lights and Reflectors	Done		RGASPARD	Jun 8, 2018 11:31:56 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Jun 8, 2018 11:31:56 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Jun 8, 2018 11:31:56 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Jun 8, 2018 11:31:56 PM	No	
40,420	Check Hood	Done		RGASPARD	Jun 8, 2018 11:31:56 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		RGASPARD	Jun 8, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					11:31:57 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Jun 8, 2018 11:31:57 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Jun 8, 2018 11:31:57 PM	No	
40,442	Freeze Point	Degree Fahrenheit	na	RGASPARD	Jun 8, 2018 11:31:57 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Jun 8, 2018 11:31:57 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Jun 8, 2018 11:31:57 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Jun 8, 2018 11:31:57 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Jun 8, 2018 11:31:57 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		RGASPARD	Jun 8, 2018 11:31:58 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		RGASPARD	Jun 8, 2018 11:31:58 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Jun 8, 2018 11:31:58 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Jun 8, 2018 11:31:58 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Jun 8, 2018 11:31:58 PM	No	
44,130	FRA Check Exhaust System	Done		RGASPARD	Jun 8, 2018 11:31:58 PM	No	
44,140	FRA Check Intake System	Done		RGASPARD	Jun 8, 2018 11:31:58 PM	No	
44,150	FRA Inspect Turbocharger	-	na	RGASPARD	Jun 8, 2018 11:31:59 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Jun 8, 2018 11:31:59 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Jun 8, 2018 11:31:59 PM	No	
44,180	FRA Check for Leaks	Done		RGASPARD	Jun 8, 2018 11:31:59 PM	No	
44,190	FRA Perform Battery Inspection	Done		RGASPARD	Jun 8, 2018 11:31:59 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Jun 8, 2018 11:31:59 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		RGASPARD	Jun 8, 2018 11:31:59 PM	No	
50,510	Check Entire Steering System	Done		RGASPARD	Jun 8, 2018 11:31:59 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Jun 8, 2018 11:31:59 PM	No	
60,610	FRA Check and Record Air Pressure	Done		RGASPARD	Jun 8, 2018 11:32:00 PM	No	
60,611	Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Jun 8, 2018 11:32:00 PM	No	
60,612	Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Jun 8, 2018 11:32:00 PM	No	
60,613	Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Jun 8, 2018 11:32:00 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Jun 8, 2018 11:32:00 PM	No	
60,615	Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Jun 8, 2018 11:32:00 PM	No	
60,616	Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Jun 8, 2018 11:32:01 PM	No	
60,620	Check Valve Stems and Caps	Done		RGASPARD	Jun 8, 2018 11:32:01 PM	No	
60,630	Check and Record Tread Depth	Done		RGASPARD	Jun 8, 2018 11:32:01 PM	No	
60,631	Tread Depth RF	8 32nds of an inch		RGASPARD	Jun 8, 2018 11:32:01 PM	No	
60,632	Tread Depth LF	9 32nds of an inch		RGASPARD	Jun 8, 2018 11:32:01 PM	No	
60,633	Tread Depth RRO	8 32nds of an inch		RGASPARD	Jun 8, 2018 11:32:01 PM	No	
60,634	Tread Depth RRI	9 32nds of an inch		RGASPARD	Jun 8, 2018 11:32:01 PM	No	
60,635	Tread Depth LRI	9 32nds of an inch		RGASPARD	Jun 8, 2018 11:32:01 PM	No	
60,636	Tread Depth LRO	9 32nds of an inch		RGASPARD	Jun 8, 2018 11:32:02 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		RGASPARD	Jun 8, 2018 11:32:02 PM	No	
60,650	Check Sidewall Wear	Done		RGASPARD	Jun 8, 2018 11:32:02 PM	No	
60,660	Inspect for Cuts and Tears	Done		RGASPARD	Jun 8, 2018 11:32:02 PM	No	
60,670	Check Dual Mating With Square	Done		RGASPARD	Jun 8, 2018 11:32:02 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Jun 8, 2018 11:32:02 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Jun 8, 2018 11:32:03 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		RGASPARD	Jun 8, 2018 11:32:02 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Jun 8, 2018 11:32:03 PM	No	
70,710	Check Vibration Damper	Done		RGASPARD	Jun 8, 2018 11:32:03 PM	No	
70,720	Check Engine and Transmission Mounts	Done		RGASPARD	Jun 8, 2018 11:32:03 PM	No	
70,730	FRA Check Starter	Done		RGASPARD	Jun 8, 2018 11:32:03 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Jun 8, 2018 11:32:03 PM	No	
70,750	FRA Check Transmission for Leaks	Done		RGASPARD	Jun 8, 2018 11:32:03 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		RGASPARD	Jun 8, 2018 11:32:03 PM	No	
70,770	FRA Check Exhaust System	Done		RGASPARD	Jun 8, 2018 11:32:03 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Jun 8, 2018 11:32:04 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		RGASPARD	Jun 8, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					11:32:04 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Jun 8, 2018 11:32:04 PM	No	
77,110	FRA Check Fuel Tank	Done		RGASPARD	Jun 8, 2018 11:32:04 PM	No	
77,120	Check Suspension Components	Done		RGASPARD	Jun 8, 2018 11:32:05 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Jun 8, 2018 11:32:05 PM	No	
77,131	Brake Pad Thickness LF	10 Inch		RGASPARD	Jun 8, 2018 11:32:05 PM	No	
77,132	Brake Pad Thickness RF	10 Inch		RGASPARD	Jun 8, 2018 11:32:05 PM	No	
77,133	Brake Pad Thickness LR	6 Inch		RGASPARD	Jun 8, 2018 11:32:05 PM	No	
77,134	Brake Pad Thickness RR	6 Inch		RGASPARD	Jun 8, 2018 11:32:05 PM	No	
77,135	Brake Rotor LF	39 Inch		RGASPARD	Jun 8, 2018 11:32:05 PM	No	
77,136	Brake Rotor RF	39 Inch		RGASPARD	Jun 8, 2018 11:32:06 PM	No	
77,137	Brake Rotor LR	36 Inch		RGASPARD	Jun 8, 2018 11:32:06 PM	No	
77,138	Brake Rotor RR	36 Inch		RGASPARD	Jun 8, 2018 11:32:06 PM	No	
77,140	FRA Check Brake Hoses	Done		RGASPARD	Jun 8, 2018 11:32:06 PM	No	
77,150	Check King Pins	-	na	RGASPARD	Jun 8, 2018 11:32:06 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Jun 8, 2018 11:32:06 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		RGASPARD	Jun 8, 2018 11:32:07 PM	No	
80,810	Completion of PMI Report	Done		RGASPARD	Jun 8, 2018 11:32:07 PM	No	
90,000	SECTION 9 Completion of PMI	Done		RGASPARD	Jun 8, 2018 11:32:07 PM	No	
90,910	Vehicle Returned to predetermined location	Done		RGASPARD	Jun 8, 2018 11:32:07 PM	No	

LH: 20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 08-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		RGASPARD	Jun 8, 2018 11:32:47 PM	No	
101,000	FRA Change Oil Filters	Yes		RGASPARD	Jun 8, 2018 11:32:47 PM	No	
102,000	FRA Drain Engine Oil	Yes		RGASPARD	Jun 8, 2018 11:32:47 PM	No	
103,000	FRA Check Transmission Fluid	Done		RGASPARD	Jun 8, 2018 11:32:47 PM	No	
104,000	Lubricate Chassis	-	na	RGASPARD	Jun 8, 2018 11:32:48 PM	No	
105,000	Replace or Clean A/C Filters	Done		RGASPARD	Jun 8, 2018 11:32:48 PM	No	
107,000	FRA Change Primary Fuel Filter	No	na	RGASPARD	Jun 8, 2018 11:32:48 PM	No	
108,000	Lube all pivoting Mechanisms	Done		RGASPARD	Jun 8, 2018 11:32:48 PM	No	

LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 08-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jun 8, 2018 11:33:10 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51412223
Invoice Number: 55345-51412223

Client Department:			
MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL2FDA06812
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology

Reported	Jul 9, 2018	10:54 AM
Started	Jul 9, 2018	
Completed	Jul 9, 2018	10:55 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	185,330	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PM A CAUSE: PM A Due CORRECTION: Performed and completed PMA Service Changed engine oil and replaced engine oil filter Lube all Pivoting Points Replaced Rear AC filter

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
09-Jul-18	Delva,Terry	1.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

WorkOrder: 51412223
Invoice Number: 55345-51412223

Client Department:

MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL2FDA06812
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Date	Part Number		Description	Qty.	Each	Extended
09-Jul-18	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

Labor Posted

Date	Technician	Hours	Rate	Extended
09-Jul-18	Delva,Terry	1.28	0.00	0.00
09-Jul-18	Delva,Terry	0.95	0.00	0.00

Activity 20 Sub Total

Parts:	1.96
Labor:	0.00
Labor Hours: 2.23	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Activity: 30 **999 TOTAL VEHICLE**

Activity Note:	PRAMETER
Reason for Repair:	05 - Inspection, Routine
Work Accomplished:	06 - Inspect
Part Failure:	-

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

WorkOrder 51412223 Grand Total

Parts:	1.96
Labor:	0.00
Labor Hours: 3.23	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	**1.96**

Recent Repair History

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51412223
Invoice Number: 55345-51412223

Client Department:

MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL2FDA06812
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

WorkOrder	Date Completed	Life Meter	Class	Description
51412223	9-Jul-18	185,330	WO	PM A

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description

PH: Work Order: 51412223 Desc: PM A
Equip: 5413 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FL2FDA06812

LH: 10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: TDELVA Performed on: 09-JUL-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		TDELVA	Jul 9, 2018 10:49:12 PM	No	
10,100	Safety Inspection	Done		TDELVA	Jul 9, 2018 10:49:12 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		TDELVA	Jul 9, 2018 10:49:12 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		TDELVA	Jul 9, 2018 10:49:12 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		TDELVA	Jul 9, 2018 10:49:13 PM	No	
10,140	Check Service Brakes	Done		TDELVA	Jul 9, 2018 10:49:14 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		TDELVA	Jul 9, 2018 10:49:14 PM	No	
10,160	FRA Check Instruments and Horns	Done		TDELVA	Jul 9, 2018 10:49:14 PM	No	
10,170	Check Fast Idle	Done		TDELVA	Jul 9, 2018 10:49:14 PM	No	
10,180	Check Starter Protection Circuit	Done		TDELVA	Jul 9, 2018 10:49:14 PM	No	
10,190	Check Reverse Warning System	Done		TDELVA	Jul 9, 2018 10:49:14 PM	No	
11,100	Check Parking Brake	Done		TDELVA	Jul 9, 2018 10:49:14 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		TDELVA	Jul 9, 2018 10:49:15 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		TDELVA	Jul 9, 2018 10:49:15 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		TDELVA	Jul 9, 2018 10:49:15 PM	No	
11,140	Road Test: Check for Proper Operation	Done		TDELVA	Jul 9, 2018 10:49:15 PM	No	
11,150	Perform Brake Test	Done		TDELVA	Jul 9, 2018 10:49:15 PM	No	
11,152	Decelerometer Results Test 1	FEET	na	TDELVA	Jul 9, 2018 10:49:15 PM	No	
11,154	Decelerometer Results Test 2	FEET	na	TDELVA	Jul 9, 2018 10:49:15 PM	No	
11,156	Decelerometer Results Test 3	FEET	na	TDELVA	Jul 9, 2018 10:49:16 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	TDELVA	Jul 9, 2018 10:49:16 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	na	TDELVA	Jul 9, 2018 10:49:16 PM	No	
11,170	FRA Check Door Operation	Done		TDELVA	Jul 9, 2018 10:49:16 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		TDELVA	Jul 9, 2018 10:49:17 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		TDELVA	Jul 9, 2018 10:49:17 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		TDELVA	Jul 9, 2018 10:49:16 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		TDELVA	Jul 9, 2018 10:49:17 PM	No	
20,230	FRA Check Wiring Under Dash	Done		TDELVA	Jul 9, 2018 10:49:18 PM	No	
20,240	FRA Check Interior Lights	Done		TDELVA	Jul 9, 2018 10:49:18 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		TDELVA	Jul 9, 2018 10:49:18 PM	No	
20,260	Check Stop Request System	-	na	TDELVA	Jul 9, 2018 10:49:18 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	na	TDELVA	Jul 9, 2018 10:49:18 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		TDELVA	Jul 9, 2018 10:49:18 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		TDELVA	Jul 9, 2018 10:49:20 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		TDELVA	Jul 9, 2018 10:49:20 PM	No	
22,110	Check Emergency Hatches	Done		TDELVA	Jul 9, 2018 10:49:20 PM	No	
22,120	Check All Safety Equipment	Done		TDELVA	Jul 9, 2018 10:49:20 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		TDELVA	Jul 9, 2018 10:49:22 PM	No	
30,310	Check Passenger Doors	Done		TDELVA	Jul 9, 2018 10:49:22 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		TDELVA	Jul 9, 2018 10:49:22 PM	No	
30,330	Check Wheelchair Lift Operation	Done		TDELVA	Jul 9, 2018 10:49:22 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	na	TDELVA	Jul 9, 2018 10:49:23 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		TDELVA	Jul 9, 2018 10:49:23 PM	No	
30,360	Check for Physical Damage and Decals	Done		TDELVA	Jul 9, 2018 10:49:23 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		TDELVA	Jul 9, 2018 10:49:23 PM	No	
30,380	Check Exterior Compartment Doors	Done		TDELVA	Jul 9, 2018 10:49:24 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		TDELVA	Jul 9, 2018 10:49:24 PM	No	
33,100	Check Lights and Reflectors	Done		TDELVA	Jul 9, 2018 10:49:24 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		TDELVA	Jul 9, 2018 10:49:24 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		TDELVA	Jul 9, 2018 10:49:24 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		TDELVA	Jul 9, 2018 10:49:24 PM	No	
40,420	Check Hood	Done		TDELVA	Jul 9, 2018 10:49:24 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		TDELVA	Jul 9, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:49:24 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	na	TDELVA	Jul 9, 2018 10:49:25 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	TDELVA	Jul 9, 2018 10:49:25 PM	No	
40,442	Freeze Point	0 Degree Fahrenheit	na	TDELVA	Jul 9, 2018 10:49:25 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		TDELVA	Jul 9, 2018 10:49:25 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	na	TDELVA	Jul 9, 2018 10:49:25 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	na	TDELVA	Jul 9, 2018 10:49:25 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		TDELVA	Jul 9, 2018 10:49:25 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		TDELVA	Jul 9, 2018 10:49:26 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		TDELVA	Jul 9, 2018 10:49:26 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		TDELVA	Jul 9, 2018 10:49:26 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		TDELVA	Jul 9, 2018 10:49:26 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		TDELVA	Jul 9, 2018 10:49:26 PM	No	
44,130	FRA Check Exhaust System	Done		TDELVA	Jul 9, 2018 10:49:26 PM	No	
44,140	FRA Check Intake System	Done		TDELVA	Jul 9, 2018 10:49:27 PM	No	
44,150	FRA Inspect Turbocharger	-	na	TDELVA	Jul 9, 2018 10:49:26 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		TDELVA	Jul 9, 2018 10:49:26 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		TDELVA	Jul 9, 2018 10:49:27 PM	No	
44,180	FRA Check for Leaks	Done		TDELVA	Jul 9, 2018 10:49:27 PM	No	
44,190	FRA Perform Battery Inspection	Done		TDELVA	Jul 9, 2018 10:49:27 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		TDELVA	Jul 9, 2018 10:49:27 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		TDELVA	Jul 9, 2018 10:49:27 PM	No	
50,510	Check Entire Steering System	Done		TDELVA	Jul 9, 2018 10:49:27 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		TDELVA	Jul 9, 2018 10:49:27 PM	No	
60,610	FRA Check and Record Air Pressure	Done		TDELVA	Jul 9, 2018 10:49:27 PM	No	
60,611	Air Pressure RF	65 Pounds per Square Inch		TDELVA	Jul 9, 2018 10:49:27 PM	No	
60,612	Air Pressure LF	65 Pounds per Square Inch		TDELVA	Jul 9, 2018 10:49:28 PM	No	
60,613	Air Pressure RRO	65 Pounds per Square Inch		TDELVA	Jul 9, 2018 10:49:28 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	65 Pounds per Square Inch		TDELVA	Jul 9, 2018 10:49:28 PM	No	
60,615	Air Pressure LRI	65 Pounds per Square Inch		TDELVA	Jul 9, 2018 10:49:28 PM	No	
60,616	Air Pressure LRO	65 Pounds per Square Inch		TDELVA	Jul 9, 2018 10:49:28 PM	No	
60,620	Check Valve Stems and Caps	Done		TDELVA	Jul 9, 2018 10:49:28 PM	No	
60,630	Check and Record Tread Depth	Done		TDELVA	Jul 9, 2018 10:49:28 PM	No	
60,631	Tread Depth RF	11 32nds of an inch		TDELVA	Jul 9, 2018 10:49:28 PM	No	
60,632	Tread Depth LF	10 32nds of an inch		TDELVA	Jul 9, 2018 10:49:29 PM	No	
60,633	Tread Depth RRO	10 32nds of an inch		TDELVA	Jul 9, 2018 10:49:28 PM	No	
60,634	Tread Depth RRI	11 32nds of an inch		TDELVA	Jul 9, 2018 10:49:29 PM	No	
60,635	Tread Depth LRI	11 32nds of an inch		TDELVA	Jul 9, 2018 10:49:29 PM	No	
60,636	Tread Depth LRO	10 32nds of an inch		TDELVA	Jul 9, 2018 10:49:29 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		TDELVA	Jul 9, 2018 10:49:29 PM	No	
60,650	Check Sidewall Wear	Done		TDELVA	Jul 9, 2018 10:49:29 PM	No	
60,660	Inspect for Cuts and Tears	Done		TDELVA	Jul 9, 2018 10:49:29 PM	No	
60,670	Check Dual Mating With Square	-	na	TDELVA	Jul 9, 2018 10:49:29 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		TDELVA	Jul 9, 2018 10:49:29 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		TDELVA	Jul 9, 2018 10:49:30 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		TDELVA	Jul 9, 2018 10:49:30 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		TDELVA	Jul 9, 2018 10:49:30 PM	No	
70,710	Check Vibration Damper	Done		TDELVA	Jul 9, 2018 10:49:30 PM	No	
70,720	Check Engine and Transmission Mounts	Done		TDELVA	Jul 9, 2018 10:49:30 PM	No	
70,730	FRA Check Starter	Done		TDELVA	Jul 9, 2018 10:49:30 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		TDELVA	Jul 9, 2018 10:49:30 PM	No	
70,750	FRA Check Transmission for Leaks	Done		TDELVA	Jul 9, 2018 10:49:30 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		TDELVA	Jul 9, 2018 10:49:30 PM	No	
70,770	FRA Check Exhaust System	Done		TDELVA	Jul 9, 2018 10:49:31 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		TDELVA	Jul 9, 2018 10:49:31 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		TDELVA	Jul 9, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:49:31 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		TDELVA	Jul 9, 2018 10:49:31 PM	No	
77,110	FRA Check Fuel Tank	Done		TDELVA	Jul 9, 2018 10:49:31 PM	No	
77,120	Check Suspension Components	Done		TDELVA	Jul 9, 2018 10:49:31 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		TDELVA	Jul 9, 2018 10:49:31 PM	No	
77,131	Brake Pad Thickness LF	10 Inch		TDELVA	Jul 9, 2018 10:49:31 PM	No	
77,132	Brake Pad Thickness RF	10 Inch		TDELVA	Jul 9, 2018 10:49:31 PM	No	
77,133	Brake Pad Thickness LR	5 Inch		TDELVA	Jul 9, 2018 10:49:32 PM	No	
77,134	Brake Pad Thickness RR	5 Inch		TDELVA	Jul 9, 2018 10:49:32 PM	No	
77,135	Brake Rotor LF	39.7 Inch		TDELVA	Jul 9, 2018 10:49:32 PM	No	
77,136	Brake Rotor RF	39.7 Inch		TDELVA	Jul 9, 2018 10:49:32 PM	No	
77,137	Brake Rotor LR	40.7 Inch		TDELVA	Jul 9, 2018 10:49:33 PM	No	
77,138	Brake Rotor RR	40.7 Inch		TDELVA	Jul 9, 2018 10:49:33 PM	No	
77,140	FRA Check Brake Hoses	Done		TDELVA	Jul 9, 2018 10:49:33 PM	No	
77,150	Check King Pins	-	na	TDELVA	Jul 9, 2018 10:49:33 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		TDELVA	Jul 9, 2018 10:49:33 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		TDELVA	Jul 9, 2018 10:49:33 PM	No	
80,810	Completion of PMI Report	Done		TDELVA	Jul 9, 2018 10:49:33 PM	No	
90,000	SECTION 9 Completion of PMI	Done		TDELVA	Jul 9, 2018 10:49:33 PM	No	
90,910	Vehicle Returned to predetermined location	Done		TDELVA	Jul 9, 2018 10:49:34 PM	No	

LH: 20 Desc: PM A
Task: PM A SERVICE Performed by: TDELVA Performed on: 09-JUL-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		TDELVA	Jul 9, 2018 10:38:23 PM	No	
101,000	FRA Change Oil Filters	Yes		TDELVA	Jul 9, 2018 10:38:23 PM	No	
102,000	FRA Drain Engine Oil	Yes		TDELVA	Jul 9, 2018 10:38:23 PM	No	
103,000	FRA Check Transmission Fluid	Done		TDELVA	Jul 9, 2018 10:38:23 PM	No	
104,000	Lubricate Chassis	Done		TDELVA	Jul 9, 2018 10:38:23 PM	No	
105,000	Replace or Clean A/C Filters	Done		TDELVA	Jul 9, 2018 10:38:24 PM	No	
107,000	FRA Change Primary Fuel Filter	No	na	TDELVA	Jul 9, 2018 10:38:23 PM	No	
108,000	Lube all pivoting Mechanisms	Done		TDELVA	Jul 9, 2018 10:38:24 PM	No	

LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: TDELVA Performed on: 09-JUL-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jul 9, 2018 10:37:35 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51696768
Invoice Number: 55345-51696768

Client Department:			
MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL2FDA06812
Requested By:	DARTHURS	**Status:**	32
Created By:	DARTHURS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Oct 2, 2018	11:04 AM
Started		
Completed	Oct 2, 2018	10:36 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	197,971	DH
System	198,142	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmA CAUSE: Service CORRECTION:Perform pmA Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51869603
Invoice Number: 55345-51869603

Client Department:			
MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL2FDA06812
Requested By:	TDELVA	**Status:**	40
Created By:	TDELVA	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Nov 29, 2018	2:40 PM
Started	Nov 29, 2018	
Completed	Nov 29, 2018	10:43 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	206,466	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA Service CAUSE: Preventive Maintenance CORRECTION: Performed and completed PMA Service Replaced drain plug

Activity: 10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
29-Nov-18	AMRIT TEEMAL,VISHNU	1.50	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

FirstBase by First Transit

WorkOrder
55345 Palm Tran Connection
v 2.2

WorkOrder: 51950237
Invoice Number: 55345-51950237

Client Department:			
MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL2FDA06812
Requested By:	VAMRITTEEMAL	**Status:**	40
Created By:	VAMRITTEEMAL	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Apr 19, 2019	7:29 AM
Started	Apr 19, 2019	
Completed	Apr 22, 2019	10:33 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	210,969	DH
System	210,969	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PmA CAUSE: preventive maintenance CORRECTION: perform PmA Service lube all Pivoting Points cross Rotate Tires and fix Rear A/C problem completed

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
19-Apr-19	Pierre,Hubert J	4.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 4.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
22-Apr-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52468001
Invoice Number: 55345-52468001

Client Department:			
MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL2FDA06812
Requested By:	DKNOTT	**Status:**	40
Created By:	DKNOTT	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jun 25, 2019	4:13 PM
Started	Jun 25, 2019	
Completed	Jun 26, 2019	12:21 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	220,099	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PmA CAUSE: Service CORRECTION:perform PmA Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts Replaced AC filter

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
25-Jun-19	Gaspard,Ronald	1.60	65.00	104.00

Activity 10 Sub Total

Parts:	0.00
Labor:	104.00
Labor Hours: 1.60	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**104.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

FirstBase by First Transit

WorkOrder
55345 Palm Tran Connection
v 2.2

WorkOrder: 52630413
Invoice Number: 55345-52630413

Client Department:

MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL2FDA06812
Requested By:	RRENE	**Status:**	40
Created By:	RRENE	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Aug 21, 2019	6:58 AM
Started		
Completed	Aug 21, 2019	9:15 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	228,601	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PmA service CAUSE: preventive maintenance CORRECTION: perform PmA Service

Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
21-Aug-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

Labor Posted

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52710003
Invoice Number: 55345-52710003

Client Department:

MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL2FDA06812
Requested By:	RRENE	**Status:**	40
Created By:	RRENE	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Sep 19, 2019	12:15 PM
Started	Sep 19, 2019	
Completed	Sep 19, 2019	8:08 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	232,894	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA SERVICE CAUSE: PREVENTIVE MAINTENANCE CORRECTION: PERFORM AND COMPLETED PMA SERVICE REPLACED DRAIN PLUG

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
19-Sep-19	AMRIT TEEMAL,VISHNU	1.50	65.00	97.50

Activity 10 Sub Total

Parts:	0.00
Labor:	97.50
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**97.50**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
19-Sep-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52899838
Invoice Number: 55345-52899838

Client Department:			
MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL2FDA06812
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Nov 13, 2019	12:00 AM
Started	Nov 14, 2019	
Completed	Nov 14, 2019	12:24 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	241,765	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: Service CORRECTION: perform pmA service Oil filter B329 qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
14-Nov-19	Gaspard,Ronald	1.60	65.00	104.00

Activity 10 Sub Total

Parts:	0.00
Labor:	104.00
Labor Hours: 1.60	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**104.00**

Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
14-Nov-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52999573
Invoice Number: 55345-52999573

Client Department:			
MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL2FDA06812
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Dec 14, 2019	12:00 AM
Started	Dec 16, 2019	
Completed	Dec 16, 2019	10:34 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	246,518	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PmA CAUSE: Service CORRECTION: perform PmA Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 qts

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
16-Dec-19	Gaspard,Ronald	2.28	65.00	148.20

Activity 10 Sub Total

Parts:	0.00
Labor:	148.20
Labor Hours: 2.28	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**148.20**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53193451
Invoice Number: 55345-53193451

Client Department:

MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL2FDA06812
Requested By:	DARTHURS	**Status:**	40
Created By:	DARTHURS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Feb 13, 2020	12:21 PM
Started	Feb 14, 2020	
Completed	Feb 14, 2020	10:09 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	255,033	DH
System	255,033	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: CAUSE: CORRECTION:

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
14-Feb-20	B329(F)		FILTER, OIL, SPIN-ON	1.00	1.96	1.96

Labor Posted

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53284428
Invoice Number: 55345-53284428

Client Department:

MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL2FDA06812
Requested By:	HPIERRE	**Status:**	40
Created By:	HPIERRE	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Mar 16, 2020	11:59 AM
Started	Mar 16, 2020	
Completed	Mar 16, 2020	8:35 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	258,980	DH
System	258,980	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA SERVICE CAUSE: PREVENTIVE MAINTENANCE CORRECTION: PERFORM AND COMPLETED PMA SERVICE REPLACED AIR FILTER REPLACED DRAIN PLUG

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
16-Mar-20	AMRIT TEEMAL,VISHNU	0.78	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.78	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
16-Mar-20	65266		PLUG, DRAIN, OIL, ENGINE	1.00	4.25	4.25

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53558542
Invoice Number: 55345-53558542

Client Department:			
MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FL2FDA06812
Requested By:	NSTOLFO	**Status:**	40
Created By:	NSTOLFO	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jun 29, 2020	12:00 AM
Started	Jun 29, 2020	
Completed	Jun 30, 2020	12:29 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	267,396	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PmA CAUSE: Service CORRECTION: perform PmA Service Oil filter B329 Qty1 Engine oil 10w30 qty 7 Qts

Activity: 5 999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 999/999/999 TOTAL VEHICLE

Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53658768
Invoice Number: 55345-53658768

Client Department:			
MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FL2FDA06812
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Aug 11, 2020	12:00 AM
Started	Aug 11, 2020	
Completed	Aug 12, 2020	12:36 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	271,764	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE:Service CORRECTION:Perform pmA Service Oil filter B329 qty1 Engine oil 10w30 qty 7 Qts Replaced 1 exhaust hanger Replaced left side marker light

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53903757
Invoice Number: 55345-53903757

Client Department:			
MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FL2FDA06812
Requested By:	DARTHURS	**Status:**	40
Created By:	DARTHURS	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology

Reported	Nov 3, 2020	12:00 AM
Started	Nov 3, 2020	
Completed	Nov 4, 2020	12:32 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	280,456	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA CAUSE: service CORRECTION: perform PMA service Oil filter B329 qty1 Engine oil 10w30 qty 7 qts

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 54022530
Invoice Number: 55345-54022530

Client Department:

MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FL2FDA06812
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Dec 10, 2020	12:00 AM
Started	Dec 11, 2020	
Completed	Dec 14, 2020	8:26 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	284,984	DH
System	284,984	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PmA CAUSE: Service CORRECTION: perform PmA Service Oil filter B329 Qty1 Engine oil 10w30 qty 7 qts

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**

Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 54213779
Invoice Number: 55345-54213779

Client Department:

MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FL2FDA06812
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology

Reported	Feb 24, 2021	12:00 AM
Started	Feb 24, 2021	
Completed	Feb 25, 2021	12:03 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	293,417	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: Service CORRECTION:Perform pmA Service Oil filter B329 qty1 Engine oil 10w30 qty 7 qts

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**

Activity Note: Light Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 54327912
Invoice Number: 55345-54327912

Client Department:

MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FL2FDA06812
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Apr 2, 2021	10:57 AM
Started	Apr 2, 2021	
Completed	Apr 2, 2021	7:02 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	297,545	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PmA CAUSE: Service CORRECTION: perform PmA Service Oil filter B329 Qty1 Engine oil 10w30 qty 7 qts
20	BUS WAS SENT TO ELPEX GOOD YEAR FOR WHEEL ALIGNAMENT
30	Vehicle came in for service. And also front tires Replace two new tires to unit size LT225/75R16. And oil filter 329F

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
02-Apr-21	Junior Hurst	0.05	0.00	0.00

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.05	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **017 TIRES, TUBES, LINERS & VALVES**

Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51494491
Invoice Number: 55345-51494491

Client Department:			
MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
PM B		**VIN:**	1FDEE3FL2FDA06812
Requested By:	AOWENS	**Status:**	40
Created By:	AOWENS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Aug 9, 2018	11:33 AM
Started		
Completed	Aug 9, 2018	11:39 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	189,603	DH
System	189,796	DH

19

WorkOrder Notes

Line	Comment
10	Tech performed PM-B Parts used Oil filter Qty1 part# B329 Oil Qty6.5 Air filter Qty1 part#PA4075

Activity: 10 999 TOTAL VEHICLE

Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
09-Aug-18	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96
09-Aug-18	PA4075		FILTER, AIR, PAPER SAME AS AF25590	1.00	5.23	5.23

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52362696
Invoice Number: 55345-52362696

Client Department:			
MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
PM B		**VIN:**	1FDEE3FL2FDA06812
Requested By:	CVERGARA	**Status:**	40
Created By:	CVERGARA	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	May 23, 2019	12:00 AM
Started	May 24, 2019	
Completed	May 24, 2019	10:09 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	215,699	DH
System	215,699	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PM-B
	CAUSE: Preventive Maintenanc
	CORRECTION:Tech Performed PM-B

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
24-May-19	KARLENS,Cyrius	2.00	65.00	130.00

Activity 10 Sub Total

Parts:	0.00
Labor:	130.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**130.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
24-May-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52813189
Invoice Number: 55345-52813189

Client Department:

MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
PM B		**VIN:**	1FDEE3FL2FDA06812
Requested By:	VAMRITTEEMAL	**Status:**	40
Created By:	VAMRITTEEMAL	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Oct 15, 2019	3:08 PM
Started	Oct 15, 2019	
Completed	Oct 16, 2019	12:00 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	237,164	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PmB CAUSE: Service CORRECTION: perform pmB Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 qts

Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
15-Oct-19	Gaspard,Ronald	1.60	65.00	104.00

Activity 10 Sub Total

Parts:	0.00
Labor:	104.00
Labor Hours: 1.60	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**104.00**

Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
15-Oct-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53390667
Invoice Number: 55345-53390667

Client Department:

MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
PM B		**VIN:**	1FDEE3FL2FDA06812
Requested By:	VAMRITTEEMAL	**Status:**	40
Created By:	VAMRITTEEMAL	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	May 15, 2020	11:53 AM
Started	May 15, 2020	
Completed	May 15, 2020	11:39 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	263,073	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PMB CAUSE: Service CORRECTION: perform PMB service Oil filter B329 qty1 Engine oil 10w30 qty 7 Qts

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
15-May-20	Gaspard,Ronald	1.57	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.57	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
15-May-20	B329(F)		FILTER, OIL, SPIN-ON SEE BALDWIN B329	1.00	1.96	1.96

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 54131223
Invoice Number: 55345-54131223

Client Department:

MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMB		**VIN:**	1FDEE3FL2FDA06812
Requested By:	DKNOTT	**Status:**	40
Created By:	DKNOTT	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jan 15, 2021	12:08 PM
Started	Jan 15, 2021	
Completed	Jan 16, 2021	12:16 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	289,158	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PMB CAUSE: Service CORRECTION:Perform PMB Service Oil filter B329 qty1 Engine oil 10w30 qty 7 qts

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note:	PERSONAL RISK ASSESSMENT
Reason for Repair:	SW - Shop Work Order
Work Accomplished:	06 - Inspect
Part Failure:	00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**

Activity Note:	Light Duty PMI
Reason for Repair:	05 - Inspection, Routine
Work Accomplished:	-
Part Failure:	-

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51240660
Invoice Number: 55345-51240660

Client Department:			
MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
PM C		**VIN:**	1FDEE3FL2FDA06812
Requested By:	TDELVA	**Status:**	40
Created By:	TDELVA	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	May 11, 2018	4:32 PM
Started	May 11, 2018	
Completed	May 14, 2018	8:00 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	177,332	DH
System	177,524	DH

WorkOrder Notes

Line	Comment
10	PMC Service Perform PMC Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts Transmission filter 20021 qty1 Transmission fluid 10 Qts Gear Oil 80w90 qty 5 Qts

Activity: 10 **999 TOTAL VEHICLE**

Activity Note:	Light Medium Duty PMI
Reason for Repair:	05 - Inspection, Routine
Work Accomplished:	06 - Inspect
Part Failure:	-

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
11-May-18	Gaspard,Ronald	1.55	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.55	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note:	PM C
Reason for Repair:	08 - Preventive Maintenance
Work Accomplished:	C - PM Level C
Part Failure:	-

Activity Comments

Parts Issued

WorkOrder: 51240660
Invoice Number: 55345-51240660

Client Department:

MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
PM C		**VIN:**	1FDEE3FL2FDA06812
Requested By:	TDELVA	**Status:**	40
Created By:	TDELVA	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Date	Part Number		Description	Qty.	Each	Extended
11-May-18	20021		FILTER, TRANSMISSION, E350, '09 W/RUBBER NECK SEAL SAME AS FT180	1.00	17.25	17.25
11-May-18	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96
11-May-18	F75Z-6730-BA		PLUG, DRAIN, OIL, ENGINE, 3.0L	1.00	6.66	6.66

Labor Posted

Date	Technician	Hours	Rate	Extended
11-May-18	Gaspard,Ronald	2.25	0.00	0.00

Activity 20 Sub Total

Parts:	25.87
Labor:	0.00
Labor Hours: 2.25	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**25.87**

Activity: 30 **999 TOTAL VEHICLE**

Activity Note: PRAMETER
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
11-May-18	Gaspard,Ronald	0.27	0.00	0.00

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.27	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 40 **999 TOTAL VEHICLE**

Activity Note:
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: 99 - Replaced Before Failure

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51240660
Invoice Number: 55345-51240660

Client Department:

MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
PM C		**VIN:**	1FDEE3FL2FDA06812
Requested By:	TDELVA	**Status:**	40
Created By:	TDELVA	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 40 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

WorkOrder 51240660 Grand Total

Parts:	25.87
Labor:	0.00
Labor Hours: 4.07	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	**25.87**

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
51369897	29-May-18	178,995	WO	One of the clearance lights is out. The battery comparment latch
51366739	23-May-18	178,822	WO	Wiper Blades
51341518	14-May-18	177,332	WO	Needs front rotors ;front shoks ; front brakes job and 2 front tires
51240660	14-May-18	177,332	WO	PM C
51108075	16-Apr-18	173,269	WO	PM A
51240632	16-Apr-18	173,269	WO	FTLMPMI_FOLLOWUP

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description

PH: Work Order: 51240660 Desc: PM C
Equip: 5413 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FL2FDA06812

LH: 10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 11-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	May 11, 2018 11:36:45 PM	No	
10,100	Safety Inspection	Done		RGASPARD	May 11, 2018 11:36:45 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	May 11, 2018 11:36:45 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		RGASPARD	May 11, 2018 11:36:46 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	May 11, 2018 11:36:46 PM	No	
10,140	Check Service Brakes	Done		RGASPARD	May 11, 2018 11:36:46 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	May 11, 2018 11:36:46 PM	No	
10,160	FRA Check Instruments and Horns	Done		RGASPARD	May 11, 2018 11:36:46 PM	No	
10,170	Check Fast Idle	Done		RGASPARD	May 11, 2018 11:36:47 PM	No	
10,180	Check Starter Protection Circuit	Done		RGASPARD	May 11, 2018 11:36:47 PM	No	
10,190	Check Reverse Warning System	Done		RGASPARD	May 11, 2018 11:36:47 PM	No	
11,100	Check Parking Brake	Done		RGASPARD	May 11, 2018 11:36:47 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		RGASPARD	May 11, 2018 11:36:47 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	May 11, 2018 11:36:47 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		RGASPARD	May 11, 2018 11:36:47 PM	No	
11,140	Road Test: Check for Proper Operation	Done		RGASPARD	May 11, 2018 11:36:47 PM	No	
11,150	Perform Brake Test	Done		RGASPARD	May 11, 2018 11:36:47 PM	No	
11,152	Decelerometer Results Test 1	FEET	NA	RGASPARD	May 11, 2018 11:36:47 PM	No	
11,154	Decelerometer Results Test 2	FEET	NA	RGASPARD	May 11, 2018 11:36:48 PM	No	
11,156	Decelerometer Results Test 3	FEET	NA	RGASPARD	May 11, 2018 11:36:48 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	RGASPARD	May 11, 2018 11:36:48 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	NA	RGASPARD	May 11, 2018 11:36:48 PM	No	
11,170	FRA Check Door Operation	Done		RGASPARD	May 11, 2018 11:36:48 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		RGASPARD	May 11, 2018 11:36:48 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		RGASPARD	May 11, 2018 11:36:48 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		RGASPARD	May 11, 2018 11:36:48 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		RGASPARD	May 11, 2018 11:36:48 PM	No	
20,230	FRA Check Wiring Under Dash	Done		RGASPARD	May 11, 2018 11:36:49 PM	No	
20,240	FRA Check Interior Lights	Done		RGASPARD	May 11, 2018 11:36:49 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		RGASPARD	May 11, 2018 11:36:49 PM	No	
20,260	Check Stop Request System	-	NA	RGASPARD	May 11, 2018 11:36:49 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	NA	RGASPARD	May 11, 2018 11:36:49 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	May 11, 2018 11:36:49 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	May 11, 2018 11:36:49 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		RGASPARD	May 11, 2018 11:36:49 PM	No	
22,110	Check Emergency Hatches	Done		RGASPARD	May 11, 2018 11:36:50 PM	No	
22,120	Check All Safety Equipment	Done		RGASPARD	May 11, 2018 11:36:50 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		RGASPARD	May 11, 2018 11:36:50 PM	No	
30,310	Check Passenger Doors	Done		RGASPARD	May 11, 2018 11:36:50 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		RGASPARD	May 11, 2018 11:36:50 PM	No	
30,330	Check Wheelchair Lift Operation	Done		RGASPARD	May 11, 2018 11:36:50 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	NA	RGASPARD	May 11, 2018 11:36:50 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		RGASPARD	May 11, 2018 11:36:50 PM	No	
30,360	Check for Physical Damage and Decals	Done		RGASPARD	May 11, 2018 11:36:51 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		RGASPARD	May 11, 2018 11:36:50 PM	No	
30,380	Check Exterior Compartment Doors	Done		RGASPARD	May 11, 2018 11:36:51 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		RGASPARD	May 11, 2018 11:36:51 PM	No	
33,100	Check Lights and Reflectors	Done		RGASPARD	May 11, 2018 11:36:51 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	May 11, 2018 11:36:51 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		RGASPARD	May 11, 2018 11:36:51 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	May 11, 2018 11:36:51 PM	No	
40,420	Check Hood	Done		RGASPARD	May 11, 2018 11:36:51 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		RGASPARD	May 11, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					11:36:52 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	NA	RGASPARD	May 11, 2018 11:36:52 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	RGASPARD	May 11, 2018 11:36:52 PM	No	
40,442	Freeze Point	Degree Fahrenheit	NA	RGASPARD	May 11, 2018 11:36:52 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	May 11, 2018 11:36:52 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	NA	RGASPARD	May 11, 2018 11:36:52 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	NA	RGASPARD	May 11, 2018 11:36:52 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	May 11, 2018 11:36:53 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		RGASPARD	May 11, 2018 11:36:52 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		RGASPARD	May 11, 2018 11:36:53 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	May 11, 2018 11:36:53 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		RGASPARD	May 11, 2018 11:36:53 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	May 11, 2018 11:36:53 PM	No	
44,130	FRA Check Exhaust System	Done		RGASPARD	May 11, 2018 11:36:53 PM	No	
44,140	FRA Check Intake System	Done		RGASPARD	May 11, 2018 11:36:53 PM	No	
44,150	FRA Inspect Turbocharger	-	NA	RGASPARD	May 11, 2018 11:36:53 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	May 11, 2018 11:36:54 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		RGASPARD	May 11, 2018 11:36:54 PM	No	
44,180	FRA Check for Leaks	Done		RGASPARD	May 11, 2018 11:36:54 PM	No	
44,190	FRA Perform Battery Inspection	Done		RGASPARD	May 11, 2018 11:36:54 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	May 11, 2018 11:36:54 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		RGASPARD	May 11, 2018 11:36:54 PM	No	
50,510	Check Entire Steering System	Done		RGASPARD	May 11, 2018 11:36:55 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	May 11, 2018 11:36:55 PM	No	
60,610	FRA Check and Record Air Pressure	Done		RGASPARD	May 11, 2018 11:36:55 PM	No	
60,611	Air Pressure RF	70 Pounds per Square Inch		RGASPARD	May 11, 2018 11:36:55 PM	No	
60,612	Air Pressure LF	70 Pounds per Square Inch		RGASPARD	May 11, 2018 11:36:55 PM	No	
60,613	Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	May 11, 2018 11:36:55 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	May 11, 2018 11:36:55 PM	No	
60,615	Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	May 11, 2018 11:36:56 PM	No	
60,616	Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	May 11, 2018 11:36:56 PM	No	
60,620	Check Valve Stems and Caps	Done		RGASPARD	May 11, 2018 11:36:56 PM	No	
60,630	Check and Record Tread Depth	Done		RGASPARD	May 11, 2018 11:36:56 PM	No	
60,631	Tread Depth RF	3 32nds of an inch		RGASPARD	May 11, 2018 11:36:56 PM	No	
60,632	Tread Depth LF	4 32nds of an inch		RGASPARD	May 11, 2018 11:36:56 PM	No	
60,633	Tread Depth RRO	8 32nds of an inch		RGASPARD	May 11, 2018 11:36:56 PM	No	
60,634	Tread Depth RRI	10 32nds of an inch		RGASPARD	May 11, 2018 11:36:56 PM	No	
60,635	Tread Depth LRI	10 32nds of an inch		RGASPARD	May 11, 2018 11:36:56 PM	No	
60,636	Tread Depth LRO	10 32nds of an inch		RGASPARD	May 11, 2018 11:36:57 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		RGASPARD	May 11, 2018 11:36:57 PM	No	
60,650	Check Sidewall Wear	Done		RGASPARD	May 11, 2018 11:36:57 PM	No	
60,660	Inspect for Cuts and Tears	Done		RGASPARD	May 11, 2018 11:36:57 PM	No	
60,670	Check Dual Mating With Square	Done		RGASPARD	May 11, 2018 11:36:57 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	May 11, 2018 11:36:57 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		RGASPARD	May 11, 2018 11:36:57 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		RGASPARD	May 11, 2018 11:36:57 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		RGASPARD	May 11, 2018 11:36:57 PM	No	
70,710	Check Vibration Damper	Done		RGASPARD	May 11, 2018 11:36:58 PM	No	
70,720	Check Engine and Transmission Mounts	Done		RGASPARD	May 11, 2018 11:36:58 PM	No	
70,730	FRA Check Starter	Done		RGASPARD	May 11, 2018 11:36:58 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	May 11, 2018 11:36:58 PM	No	
70,750	FRA Check Transmission for Leaks	Done		RGASPARD	May 11, 2018 11:36:58 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		RGASPARD	May 11, 2018 11:36:58 PM	No	
70,770	FRA Check Exhaust System	Done		RGASPARD	May 11, 2018 11:36:58 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	May 11, 2018 11:36:58 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		RGASPARD	May 11, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					11:36:58 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	May 11, 2018 11:36:59 PM	No	
77,110	FRA Check Fuel Tank	Done		RGASPARD	May 11, 2018 11:36:59 PM	No	
77,120	Check Suspension Components	Done		RGASPARD	May 11, 2018 11:36:59 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	May 11, 2018 11:36:59 PM	No	
77,131	Brake Pad Thickness LF	4 Inch		RGASPARD	May 11, 2018 11:36:59 PM	No	
77,132	Brake Pad Thickness RF	4 Inch		RGASPARD	May 11, 2018 11:36:59 PM	No	
77,133	Brake Pad Thickness LR	6 Inch		RGASPARD	May 11, 2018 11:37:00 PM	No	
77,134	Brake Pad Thickness RR	6 Inch		RGASPARD	May 11, 2018 11:37:00 PM	No	
77,135	Brake Rotor LF	30 Inch		RGASPARD	May 11, 2018 11:37:00 PM	No	
77,136	Brake Rotor RF	30 Inch		RGASPARD	May 11, 2018 11:37:00 PM	No	
77,137	Brake Rotor LR	36 Inch		RGASPARD	May 11, 2018 11:37:00 PM	No	
77,138	Brake Rotor RR	36 Inch		RGASPARD	May 11, 2018 11:37:00 PM	No	
77,140	FRA Check Brake Hoses	Done		RGASPARD	May 11, 2018 11:37:00 PM	No	
77,150	Check King Pins	-	NA	RGASPARD	May 11, 2018 11:37:00 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	May 11, 2018 11:37:01 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		RGASPARD	May 11, 2018 11:37:01 PM	No	
80,810	Completion of PMI Report	Done		RGASPARD	May 11, 2018 11:37:01 PM	No	
90,000	SECTION 9 Completion of PMI	Done		RGASPARD	May 11, 2018 11:37:01 PM	No	
90,910	Vehicle Returned to predetermined location	Done		RGASPARD	May 11, 2018 11:37:01 PM	No	

LH: 20 Desc: PM C
Task: PM C SERVICE Performed by: RGASPARD Performed on: 11-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		RGASPARD	May 11, 2018 11:38:11 PM	No	
101,000	FRA Change Oil Filters	Yes		RGASPARD	May 11, 2018 11:38:11 PM	No	
102,000	FRA Drain Engine Oil	Yes		RGASPARD	May 11, 2018 11:38:11 PM	No	
103,000	FRA Check Transmission Fluid	Done		RGASPARD	May 11, 2018 11:38:11 PM	No	
104,000	Lubricate Chassis	-	NA	RGASPARD	May 11, 2018 11:38:12 PM	No	
105,000	Replace or Clean A/C Filters	Done		RGASPARD	May 11, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					11:38:12 PM		
107,000	FRA Change Primary Fuel Filter	-	NA	RGASPARD	May 11, 2018 11:38:12 PM	No	
108,000	Lube all pivoting Mechanisms	Done		RGASPARD	May 11, 2018 11:38:12 PM	No	
200,000	"B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	May 11, 2018 11:38:13 PM	No	
201,000	Service Crankcase Breather	Done		RGASPARD	May 11, 2018 11:38:13 PM	No	
203,000	FRA Change Automatic Transmission Fluid	Yes		RGASPARD	May 11, 2018 11:38:13 PM	No	
204,000	FRA Change Power Steering Fluid and Filter	No		RGASPARD	May 11, 2018 11:38:13 PM	No	
205,000	Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	May 11, 2018 11:38:13 PM	No	
300,000	"C" PMI SERVICING ITEMS (24 MONTH)	Done		RGASPARD	May 11, 2018 11:38:13 PM	No	
301,000	Check and Lubricate Door Linkages	Done		RGASPARD	May 11, 2018 11:38:13 PM	No	
302,000	Check Toe-In and Record Reading	-	NA	RGASPARD	May 11, 2018 11:38:13 PM	No	
302,001	Record Toe-In Reading	Inches, fraction-actual	NA	RGASPARD	May 11, 2018 11:38:14 PM	No	
304,000	1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		RGASPARD	May 11, 2018 11:38:14 PM	No	
305,000	FRA Change Differential Fluid	Yes		RGASPARD	May 11, 2018 11:38:14 PM	No	

LH: 30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 11-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	May 11, 2018 11:39:01 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51776513
Invoice Number: 55345-51776513

Client Department:

MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
PM C		**VIN:**	1FDEE3FL2FDA06812
Requested By:	AOWENS	**Status:**	32
Created By:	AOWENS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Nov 1, 2018	11:53 AM
Started	Nov 1, 2018	
Completed	Nov 1, 2018	6:11 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	202,339	DH
System	202,339	DH

WorkOrder Notes

Line	Comment
10	Complaint: PM C Cause: Service due CORRECTION: Performed and completed pmC Changed engine oil and replaced engine oil filter Changed Differential fluid Changed transmission fluid..

Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
01-Nov-18	Delva,Terry	1.33	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.33	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51780465
Invoice Number: 55345-51780465

Client Department:			
MRC:	55345M	**Equipment:**	5447 Ford E350 Champion Crusaders
WO Desc: PM A		**VIN:**	1FDEE3FLXFDA02748
Requested By:	RGASPARD	**Status:**	32
Created By:	RGASPARD	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Oct 31, 2018	11:23 AM
Started	Nov 1, 2018	
Completed	Nov 1, 2018	9:03 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	188,075	DH
System	188,075	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PMA Service CAUSE: Service due by Mileage CORRECTION: Change Oil &Filter .lube all Pivoting Points .check Brakes .clean batteries.replace A/C Filter. Parts# B329 Qty (1) Oil 5W20 Qty (6.5) Qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
01-Nov-18	Arthurs,Durvin	1.50	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
01-Nov-18	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52551229
Invoice Number: 55345-52551229

Client Department:			
MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
PM C		**VIN:**	1FDEE3FL2FDA06812
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jul 24, 2019	7:07 AM
Started	Jul 24, 2019	
Completed	Jul 24, 2019	10:59 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	224,352	DH

WorkOrder Notes

Line	Comment
10	Complaint. Pm c Cause. Inspection Correction. Perform pm c Service, changed engine oil and filter, Lube Pivoting Points, Check Brakes, Clean Batteries, Replaced a/c filter, Perform transmission service, differential service.

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
24-Jul-19	Rodriguez,Raul	2.15	65.00	139.75

Activity 10 Sub Total

Parts:	0.00
Labor:	139.75
Labor Hours: 2.15	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**139.75**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
24-Jul-19	20021		FILTER, TRANSMISSION, E350, '09 W/RUBBER NECK SEAL SAME AS	1.00	17.27	17.27

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53103162
Invoice Number: 55345-53103162

Client Department:

MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
PM C		**VIN:**	1FDEE3FL2FDA06812
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jan 17, 2020	10:44 AM
Started	Jan 17, 2020	
Completed	Jan 17, 2020	10:00 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	250,736	DH

WorkOrder Notes

Line	Comment
10	Perform PMC Service. Change Oil & Filter .Lube all Pivoting Points. Check Brakes , Clean batteries. Replace A/C Filter.drain Fill Differential, drain Fill Transmission Fluid& Change Filter. Parts # B329 Qty (1) Parts# 20021 Qty (1) Oil 5W 20 Qty (6.5) Qt Gear Oil 80W90 Qty (3) Qt ATF Fluid Qty (9) Qts

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
17-Jan-20	Arthurs,Durvin	2.25	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 2.25	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
17-Jan-20	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53773952
Invoice Number: 55345-53773952

Client Department:

MRC:	55345M	**Equipment:**	5413
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMC		**VIN:**	1FDEE3FL2FDA06812
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Sep 24, 2020	12:00 AM
Started	Sep 24, 2020	
Completed	Sep 24, 2020	7:26 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	276,064	DH

WorkOrder Notes

Line	Comment
10	Perform PMC Service. Change Oil & Filter Check Brakes. Clean batteries . Replace A/C filter . Replace Air Filter. drain & Fill differential. Parts # B329 Qty (1) Parts # PA 4075 Qty (1) Oil 10W30 Qty (6.5) Qt

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note:	PERSONAL RISK ASSESSMENT
Reason for Repair:	SW - Shop Work Order
Work Accomplished:	06 - Inspect
Part Failure:	00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note:	Light Duty PMI
Reason for Repair:	08 - Preventive Maintenance
Work Accomplished:	-
Part Failure:	-

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted