

1/28/2026
2:07:13 PM

Palm Beach County Fleet Management Asset Maintenance History
10208562 2018 FORD TRANSIT 350 Van, 1 Ton, Cargo

Total Hours: 178.00 Labor: 12,907.00 Parts: 8,667.65 Comm: 6,897.81 Charged: 28472.46

Work Order: 1810649 **Meter:** 320 **In Date:** 10/16/2018 **Closed:** 10/16/2018
Problem: pre delivery inspection

Work Completed

- pre delivery inspection
- Shop Supplies

Parts Issued

Shop Supplies 1.00

Quantity

Hours: 2.00 Comm: 0.00 Labor: 134.00 Parts: 3.00 Total: 137.00

Work Order: 1901770 **Meter:** 5739 **In Date:** 02/14/2019 **Closed:** 02/25/2019
Problem: P.M. service and yellow warning on for lane departure.

Work Completed

- P.m. service. Test yellow light on for lane departure because lane departure was turned off.
- Rotate and high speed balance all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Napagold Oil Filter 1.00
5w20 Engine Oil 6.00
Washer Fluid Concentr 1.00
Used Fire X Refurbished 1.00
Ford Triton Pvc Swc 1.00
2pc Hd Mat Set Blk 1.00
Mac Wite Lithium Gres 1.00
Shop Supplies 1.00

Quantity

Hours: 5.00 Comm: 0.00 Labor: 335.00 Parts: 96.87 Total: 431.87

Work Order: 1903726 **Meter:** 7820 **In Date:** 04/05/2019 **Closed:** 04/10/2019
Problem: Broken right rear tail light.

Work Completed

- Replace broken right rear tail lamp assembly .
- Shop Supplies

Parts Issued

Lamp Assy 1.00
Shop Supplies 1.00

Quantity

Hours: 0.50 Comm: 0.00 Labor: 33.50 Parts: 197.85 Total: 231.35

1/28/2026
2:07:13 PM

Palm Beach County Fleet Management Asset Maintenance History
10208562 2018 FORD TRANSIT 350 Van, 1 Ton, Cargo

Work Order: 1906564 **Meter:** 11692 **In Date:** 06/21/2019 **Closed:** 07/09/2019
Problem: PM Service, Damaged floor panel at rear cargo doors.

Work Completed

- P.m. service.
- Replace damaged fire extinguisher bracket and extinguisher .
- Inspect and replace damaged rear scuff plate .
- Repair right rear tire . Rotate and balance all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
Fire Ext Mount Strap Style	1.00
Cover Cap	2.00
Trim Assy	1.00
Shop Supplies	1.00

Hours: 7.00

Comm: 0.00

Labor: 469.00 Parts: 213.78 Total: 682.78

Work Order: 1911229 **Meter:** 17329 **In Date:** 10/29/2019 **Closed:** 11/06/2019
Problem: P.M. service and front splash shield hanging down .

Work Completed

- P.m. service.
- Remove and replace damaged front lower splash shield .
- Test and adjust right sliding door bottom latch and stricker . Retest .
- Rotate and high speed balance all four tires . Nitrofill all
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Used Fire X Refurbished	1.00
Wiper Blade	1.00
Wiper Blade	1.00
Washer Fluid Concentr	1.00
Mac Wite Lithium Gres	1.00
Deflector	1.00
Shop Supplies	1.00

Hours: 6.60

Comm: 0.00

Labor: 481.80 Parts: 376.09 Total: 857.89

Work Order: 1911506 **Meter:** 17264 **In Date:** 11/05/2019 **Closed:** 11/05/2019
Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00

Comm: 9.54

Labor: 0.00 Parts: 0.00 Total: 9.54

1/28/2026
2:07:13 PM

Palm Beach County Fleet Management Asset Maintenance History
10208562 2018 FORD TRANSIT 350 Van, 1 Ton, Cargo

Work Order: 2001216 **Meter:** 20969 **In Date:** 02/04/2020 **Closed:** 02/04/2020
Problem: Right rear tire going flat .

Work Completed

Parts Issued

Quantity

- Repair right rear tire and balance . Nitrofill all.
- Shop Supplies

Shop Supplies 1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 4.00 Total: 77.00

Work Order: 2003829 **Meter:** 24843 **In Date:** 04/16/2020 **Closed:** 04/30/2020
Problem: P.M. service , relocate fire extiguisher and rear sill panel loose .

Work Completed

Parts Issued

Quantity

- P.m. service.
- Relocate and fire extiguisher bracket . Resecure rear sill plate to floor .
- Replace all four tires and balance . Nitrofill all and reset Tpms .
- Perform complete front end alignment and road test .
- Resurface both rear brake rotors and service calipers . Replace brake pads .
- Flush and bleed brake system . Road test .
- Shop Supplies

5w20 Engine Oil 7.00

Napagold Oil Filter 1.00

Wiper Blade 1.00

Wiper Blade 1.00

Used Fire X Refurbished 1.00

Fire Ext Mount Strap Style 1.00

Tire 235/65/16 4.00

Non-chlor Brake Clnr 1.00

Brk Fluid Dot 4-32oz 1.00

Brake Pad 1.00

Shop Supplies 1.00

Tire Disposal Fee 4.00

Hours: 13.50 Comm: 0.00 Labor: 985.50 Parts: 1,588.70 Total: 2,574.20

Work Order: 2004417 **Meter:** 25122 **In Date:** 05/04/2020 **Closed:** 05/05/2020
Problem: Left rear tire going flat .

Work Completed

Parts Issued

Quantity

- Repair left rear tire and balance . Nitrofill all.
- Shop Supplies

Shop Supplies 1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 4.00 Total: 77.00

1/28/2026
2:07:13 PM

Palm Beach County Fleet Management Asset Maintenance History
10208562 2018 FORD TRANSIT 350 Van, 1 Ton, Cargo

Work Order: 2005541 **Meter:** 26682 **In Date:** 06/03/2020 **Closed:** 06/11/2020
Problem: High mount stop light broken .

Work Completed

- Replace broken high mounted stop light assembly and side covers .
- Shop Supplies

Parts Issued

Quantity

Lamp Asy	1.00
Lamp Asy	1.00
Lamp Asy	1.00
Shop Supplies	1.00

Hours: 0.50

Comm: 0.00

Labor: 36.50

Parts: 558.63

Total: 595.13

Work Order: 2008957 **Meter:** 30936 **In Date:** 09/04/2020 **Closed:** 09/15/2020
Problem: PM Service

Work Completed

- P.m. service.
- Inspect and replace cabin air filter and clean fresh air intake .
- Rotate and high speed balance all four tires . Nitrofill all.
- Charge battery fully . Test battery and charging system . Battery failed load test . Remove left front seat to R&r defective battery .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	2.00
5w20 Engine Oil	14.00
Wiper Blade	2.00
Wiper Blade	2.00
Washer Fluid Concentr	2.00
Cabin Air Filter	2.00
Battry Motorcraft	1.00
Shop Supplies	1.00

Hours: 7.00

Comm: 0.00

Labor: 511.00

Parts: 394.21

Total: 905.21

Work Order: 2008972 **Meter:** 30889 **In Date:** 09/04/2020 **Closed:** 09/04/2020
Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00

Comm: 9.54

Labor: 0.00

Parts: 0.00

Total: 9.54

1/28/2026
2:07:13 PM

Palm Beach County Fleet Management Asset Maintenance History
10208562 2018 FORD TRANSIT 350 Van, 1 Ton, Cargo

Work Order: 2204931 **Meter:** 52846 **In Date:** 05/06/2022 **Closed:** 05/12/2022
Problem: PM Service. Send for Detail. ? repair rear doors damages accident ,need to re-attach corgo matt got damage .

Work Completed

- Preventive Maint. Service
- Rotate and speed balance, nitro fill
- Check & replace cabin filter and clean fresh air intake
- Replace rear cargo sill plate and position mat
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	2.00
Wiper Blade	1.00
Wiper Blade	1.00
Used Fire X Refurbished	1.00
Cabin Filter	1.00
Trim Assy	1.00
Shop Supplies	1.00

Hours: 6.30 Comm: 0.00 Labor: 459.90 Parts: 219.75 Total: 679.65

Work Order: 2206779 **Meter:** 52846 **In Date:** 05/12/2022 **Closed:** 06/28/2022
Problem: Damage to both right side doors & both rear doors

Work Completed

- Damage to both right side doors & both rear doors

Hours: 0.00 Comm: 2,059.70 Labor: 0.00 Parts: 0.00 Total: 2,059.70

Work Order: 2207228 **Meter:** 52846 **In Date:** 07/11/2022 **Closed:** 07/11/2022
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued to: Fernando Tello

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued to: Fernando Tello

Hours: 0.00 Comm: 90.40 Labor: 0.00 Parts: 0.00 Total: 90.40

Work Order: 2207257 **Meter:** 54263 **In Date:** 07/12/2022 **Closed:** 08/10/2022
Problem: repair cover in cargo

Work Completed

- Reinstall left side door harness cover with new clips
- Shop Supplies

Parts Issued

Quantity

Clip	6.00
Shop Supplies	1.00

Hours: 0.50 Comm: 0.00 Labor: 36.50 Parts: 47.86 Total: 84.36

1/28/2026
2:07:13 PM

Palm Beach County Fleet Management Asset Maintenance History
10208562 2018 FORD TRANSIT 350 Van, 1 Ton, Cargo

Work Order: 2209943 **Meter:** 54559 **In Date:** 08/17/2022 **Closed:** 10/04/2022
Problem: Damages to rear bumper, rear doors, right rear fender & hood.

Work Completed

- Damages to rear bumper, rear doors, right rear fender & hood.

Hours: 0.00 Comm: 2,207.33 Labor: 0.00 Parts: 0.00 Total: 2,207.33

Work Order: 2212416 **Meter:** 57541 **In Date:** 12/12/2022 **Closed:** 12/19/2022
Problem: PM Service. Send for Detail. top of van moldy

Work Completed

- Performed P.m. Service & Inspection.

- Mount 2 Tires, Then Balance & Rotate All 4 Wheels, Add Nitro Fill Reset Tpms.

- Performed Front Wheel Alignment, Test Drove Vehicle & Check.

- Front Brakes Were Below Manufacture Specs, Removed Front Brake Pads, Resurface Both Front Brake Rotors, Then Bleed & Flush The Entire Brake System, Test Drove & Burnish Brakes.

- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil 6.00

Napagold Oil Filter 1.00

235/65r16c Gy Fortitudte Ht 2.00

Brake Pad 1.00

Brake Fl-dot 3-4 32oz 1.00

Non-chlor Brake Clnr 1.00

Shop Supplies 1.00

Tire Disposal Fee 2.00

Hours: 12.50 Comm: 0.00 Labor: 912.50 Parts: 458.94 Total: 1,371.44

Work Order: 2212492 **Meter:** 57491 **In Date:** 12/12/2022 **Closed:** 12/13/2022
Problem: 1 - Wash ticket(s) Issued to: Requestor Fernando Tello

Work Completed

- 1 - Wash ticket(s) Issued to: Requestor Fernando Tello

Hours: 0.00 Comm: 8.98 Labor: 0.00 Parts: 0.00 Total: 8.98

Work Order: 2212636 **Meter:** 57491 **In Date:** 12/15/2022 **Closed:** 12/15/2022
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued WO: 2212416 for: Purchasing

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2212416 for: Purchasing

Hours: 0.00 Comm: 90.40 Labor: 0.00 Parts: 0.00 Total: 90.40

1/28/2026
2:07:13 PM

Palm Beach County Fleet Management Asset Maintenance History
10208562 2018 FORD TRANSIT 350 Van, 1 Ton, Cargo

Work Order: 2303745 **Meter:** 62610 **In Date:** 04/14/2023 **Closed:** 04/24/2023

Problem: PM Service. Send for Detail. Please Top of van need to clean

Work Completed

- Preventive Maint. Service
- Found Coolant Tank Low Pressure Tested System And Found Water Pump Leaking R&r Water Pump, Thermostat Housing And Serpentine Belt ,flush Coolant And Bleed And Test Drive
- Load Tested Battery And Checked Charging System, Battery Failed Load Test . Remove Left Front Seat To R&r Battery
- R&r Cabin Air Filter And Clean Fresh Air Intake
- Rotate And Balance Tires With Nitro Fill
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Wiper Blade	1.00
Wiper Blade	1.00
Used Fire X Refurbished	1.00
Air Filter	1.00
V Belt	1.00
Hose Clamp	2.00
Water Pump 3-bolt	1.00
Coolent	1.00
Gasket	1.00
Thermostat Housing Assembly	1.00
Battry Motorcraft	1.00
Cabin Filter	1.00
Shop Supplies	1.00

Hours: 13.90

Comm: 0.00

Labor: 1,014.70

Parts: 556.37

Total: 1,571.07

Work Order: 2303943 **Meter:** 62603 **In Date:** 04/20/2023 **Closed:** 04/20/2023

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued WO: 2303745 for: Purchasing Warehouse

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2303745 for: Purchasing Warehouse

Hours: 0.00

Comm: 90.40

Labor: 0.00

Parts: 0.00

Total: 90.40

Work Order: 2308155 **Meter:** 67077 **In Date:** 08/15/2023 **Closed:** 08/16/2023

Problem: front turn light change

Work Completed

- Lighting, Other. Rf tun signal out. remove bulb and replace shorted out bulb. Reinstall in light. Verify all other lights work.

Parts Issued

Quantity

Boxed Miniatures	1.00
------------------	------

Hours: 0.50

Comm: 0.00

Labor: 36.50

Parts: 1.13

Total: 37.63

1/28/2026
2:07:13 PM

Palm Beach County Fleet Management Asset Maintenance History
10208562 2018 FORD TRANSIT 350 Van, 1 Ton, Cargo

Work Order: 2309779 **Meter:** 69381 **In Date:** 09/26/2023 **Closed:** 10/11/2023
Problem: PM Service. Send for Detail.Check A/C

Work Completed

- Performed P.m. Service & Inspection.
- Mount 2 Tires Then Balance & Rotate All 4 Wheels, Add Nitro Fill Reset Tpms.
- Passenger Side Rear Sliding Door Locks Are Inop. Removed The Door Panel Check For Signal Power & Ground, Found Door Terminal Contacts Damaged, Drilled Old Rivots Out, Then Removed Terminal And Installed New. Rerviot And Check. Working As Design.
- Performed Engine Decarb Cleaning & Fuel Injection Flush Service. Removed Throttle Body And Clean.
- Diagnose Engine Misfire .performed Tune-up, Removed The Intake And All 6 Spark Plugs, Replaced All 6 Spark Plugs And Reverse The Procedure.
- Performed A/c Cooling Performance Test, A/c System Working As Design To Manufacture Specs.
- Shop Supplies

Hours: 15.40

Comm: 0.00

Parts Issued

Quantity

Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
235/65/16 Tire Gooyer	2.00
Motor Tune-up 16oz	1.00
Intake Cleaner Kit	1.00
Plenum Gskt Set	1.00
Napa Quart 5w20	6.00
Moulding	1.00
Spark Plug	6.00
Terminal	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Labor: 1,124.20

Parts: 513.45

Total: 1,637.65

Work Order: 2310188 **Meter:** 69376 **In Date:** 10/05/2023 **Closed:** 10/05/2023
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued WO: 2309779 for: Purchasing WH

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2309779 for: Purchasing Wh

Hours: 0.00

Comm: 90.40

Labor: 0.00

Parts: 0.00

Total: 90.40

Work Order: 2310480 **Meter:** 69714 **In Date:** 10/17/2023 **Closed:** 10/18/2023
Problem: change steering wheel cover

Work Completed

- Install steering wheel cover.

Hours: 0.30

Comm: 0.00

Parts Issued

Quantity

Steering Wheel Cover Large	1.00
Labor: 21.90	Parts: 19.17
Total: 41.07	

1/28/2026
2:07:13 PM

Palm Beach County Fleet Management Asset Maintenance History
10208562 2018 FORD TRANSIT 350 Van, 1 Ton, Cargo

Work Order: 2407999 **Meter:** 89078 **In Date:** 08/19/2024 **Closed:** 08/28/2024
Problem: PM Service. Send for Detail.

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service	Napagold Oil Filter	1.00		
- Rotate and balance four tires. Relearn tire sensors.	5w20 Engine Oil	6.00		
- Shop Supplies	Washer Fluid Concentr	1.00		
	Wiper Blade	1.00		
	Wiper Blade	1.00		
	Used Fire X Refurbished	1.00		
	Shop Supplies	1.00		
Hours: 5.00	Comm: 0.00	Labor: 365.00	Parts: 111.64	Total: 476.64

Work Order: 2408381 **Meter:** 89078 **In Date:** 08/28/2024 **Closed:** 08/29/2024
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued WO: 2407999 for: Mingo, Simpson

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2407999 for: Mingo, Simpson

Hours: 0.00 Comm: 90.40 Labor: 0.00 Parts: 0.00 Total: 90.40

Work Order: 2409561 **Meter:** 86168 **In Date:** 10/02/2024 **Closed:** 10/02/2024
Problem: Low pressure tire sensor come on

Work Completed

Parts Issued

Quantity

- Repair left rear tire and balance . Nitro fill all . reset Tpms	Shop Supplies	1.00		
- Shop Supplies				
Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 2.65	Total: 75.65

1/28/2026
2:07:13 PM

Palm Beach County Fleet Management Asset Maintenance History
10208562 2018 FORD TRANSIT 350 Van, 1 Ton, Cargo

Work Order: 2410835 **Meter:** 88971 **In Date:** 11/12/2024 **Closed:** 11/26/2024
Problem: PM Service. Send for Detail.

Work Completed

- Performed P.m. Service & Inspection.
- Mount & Balance 4 New Tires, Add Nitro Fill, Reset Tpms.
- Performed Front Wheel Alignment & Test Drove Vehicle.
- Both Front & Rear Brake Pads Were Below Manufacture Specs. Removed Both Front & Rear Brake Pads. Resurfaced Both Front & Rear Brake Rotors, Lubricate Caliper Slides, Then Install New Brake Pads, Bleed And Flush Entire Brake System. Burnish Brakes.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
235/65/16 Tire Gooyer	4.00
Brake Pad	1.00
Non-chlor Brake Clnr	2.00
Brk Fluid Dot 4-32oz	1.00
Brake Pad	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 16.50

Comm: 0.00

Labor: 1,204.50

Parts: 818.85

Total: 2,023.35

Work Order: 2411223 **Meter:** 88951 **In Date:** 11/22/2024 **Closed:** 11/22/2024
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued WO: 2410835 for: Mingo

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2410835 for: Mingo

Hours: 0.00

Comm: 86.40

Labor: 0.00

Parts: 0.00

Total: 86.40

Work Order: 2501550 **Meter:** 93993 **In Date:** 02/14/2025 **Closed:** 02/27/2025
Problem: PM Service. Send for Detail.

Work Completed

- perform Preventive Maint. Service
- perform balance rotate and nitro fill, tpms relearn, replaced one valve stem due to leaking air.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
21in Exactfit-beam	1.00
Wiper	1.00
Washer Fluid Concentr	1.00
Shop Supplies	1.00

Hours: 5.00

Comm: 0.00

Labor: 365.00

Parts: 50.16

Total: 415.16

1/28/2026
2:07:13 PM

Palm Beach County Fleet Management Asset Maintenance History
10208562 2018 FORD TRANSIT 350 Van, 1 Ton, Cargo

Work Order: 2501997 **Meter:** 93993 **In Date:** 02/20/2025 **Closed:** 02/27/2025
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued WO: 2501550 for: Mingo, Simpson

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2501550 for: Mingo, Simpson

Hours: 0.00 Comm: 86.40 Labor: 0.00 Parts: 0.00 Total: 86.40

Work Order: 2504901 **Meter:** 99268 **In Date:** 05/27/2025 **Closed:** 06/09/2025
Problem: PM Service. Send for Detail.

Work Completed

- perform Preventive Maint. Service
- perform balance rotate and nitrofill, tpms relearn
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	6.00
Washer Fluid Concentr	1.00
Wiper Blade	1.00
Wiper Blade	1.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 5.00 Comm: 0.00 Labor: 365.00 Parts: 91.06 Total: 456.06

Work Order: 2507496 **Meter:** 103862 **In Date:** 08/11/2025 **Closed:** 08/25/2025
Problem: PM Service. Send for Detail.

Work Completed

- Preventive Maint. Service
- Rear License Plate Bulbs Blown Test Power And Ground Replace Both Bulbs And Retest
- Replace 2 Tires Balance All With Nitor Fill
- Test Drive And Perform Front End Alignment Retest
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Wiper Blade	1.00
Wiper Blade	1.00
Boxed Miniatures	2.00
235/65/16 Tire Gooyer	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 9.00 Comm: 0.00 Labor: 657.00 Parts: 395.75 Total: 1,052.75

1/28/2026
2:07:13 PM

Palm Beach County Fleet Management Asset Maintenance History
10208562 2018 FORD TRANSIT 350 Van, 1 Ton, Cargo

Work Order: 2510318 **Meter:** 103862 **In Date:** 08/27/2025 **Closed:** 10/30/2025
Problem: Damage-to left front door, sliding door & gas lid.

Work Completed

- Damage-to left front door, sliding door & gas lid.

Hours: 0.00 Comm: 1,706.72 Labor: 0.00 Parts: 0.00 Total: 1,706.72

Work Order: 2510780 **Meter:** 104754 **In Date:** 11/17/2025 **Closed:** 11/24/2025
Problem: check engine light is on

Work Completed

- Scan diagnose code P1450, Pin-point test, replace stuck open purge valve.
Perform evap test, clear codes.

Parts Issued	Quantity
Valve Asm	1.00
Shop Supplies	1.00

- Shop Supplies

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 47.83 Total: 193.83

Work Order: 2511289 **Meter:** 105142 **In Date:** 12/04/2025 **Closed:** 12/04/2025
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 178.00 Total Labor: 12,907.00 Total Comm: 6,897.81 Total Parts: 8,667.65