

1/28/2026
2:18:46 PM

Palm Beach County Fleet Management Asset Maintenance History
10202146 2016 FORD F150 Pickup, 1/2 Ton

Total Hours: 172.85 Labor: 12,257.55 Parts: 10,451.39 Comm: 1,986.40 Charged: 24695.34

Work Order: 1700062 **Meter:** 326 **In Date:** 01/04/2017 **Closed:** 01/04/2017
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1701475 **Meter:** 1149 **In Date:** 02/13/2017 **Closed:** 02/28/2017
Problem: Right rear tire flat ,spare on truck.

Work Completed

- Repair and balance rignht rear tire.

- Shop Supplies

Parts Issued

Quantity

Shop Supplies 1.00

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1701478 **Meter:** 1036 **In Date:** 02/10/2017 **Closed:** 02/13/2017
Problem: put on spare/ RR

Work Completed

- Tow From: 8100 forest hill croc

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

Work Order: 1704094 **Meter:** 3333 **In Date:** 04/24/2017 **Closed:** 04/24/2017
Problem: P/R Flat

Work Completed

- Tire Service 4460 Conventry Pt Way, Lake Worth Off Mil s Lw rd - P/r Flat

Hours: 0.00 Comm: 169.49 Labor: 0.00 Parts: 0.00 Total: 169.49

Work Order: 1704095 **Meter:** 3333 **In Date:** 04/24/2017 **Closed:** 04/24/2017
Problem: Service call

Work Completed

- Tire Service Coventry point way, Lake worth - Service call

Hours: 0.00 Comm: 51.56 Labor: 0.00 Parts: 0.00 Total: 51.56

1/28/2026
2:18:46 PM

Palm Beach County Fleet Management Asset Maintenance History
10202146 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 1806563 **Meter:** 22309 **In Date:** 06/27/2018 **Closed:** 07/05/2018
Problem: P.M. service and detail.

Work Completed

- P.m. service.
- Replace all four tire and high speed balance .nitrogen fill tires.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Napagold Air Filter	1.00
183114470 P245-70r17	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 4.00 Comm: 0.00 Labor: 240.00 Parts: 861.51 Total: 1,101.51

Work Order: 1806836 **Meter:** 22238 **In Date:** 07/03/2018 **Closed:** 07/03/2018
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1806899 **Meter:** 22309 **In Date:** 07/05/2018 **Closed:** 07/05/2018
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

Work Order: 1810630 **Meter:** 26815 **In Date:** 10/16/2018 **Closed:** 10/18/2018
Problem: Had to jump start last few days.

Work Completed

- Charge battery fully . Test battery and charging system . Battery failed load test . R&r defective battery.
- Diagnose trailer warning on dash . R&r defective trailer plug due to water and corrosion..rewire as needed. Retest.
- Shop Supplies

Parts Issued

Quantity

Battry Motorcraft	1.00
trailer plug	1.00
Shop Supplies	1.00

Hours: 2.00 Comm: 0.00 Labor: 134.00 Parts: 192.27 Total: 326.27

1/28/2026
2:18:46 PM

Palm Beach County Fleet Management Asset Maintenance History
10202146 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 1904075 **Meter:** 33021 **In Date:** 04/15/2019 **Closed:** 04/18/2019
Problem: P.M. service and rear tires going flat.

Work Completed

- P.m. service.
- Replace all four tires and balance . Nitrofill all and reset Tpms.
- Perform complete front end alignment and road test .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Ford Triton Pvc Swc	1.00
P/245/70/17 Tire	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 6.50

Comm: 0.00

Labor: 435.50 Parts: 950.42 Total: 1,385.92

Work Order: 1910782 **Meter:** 37997 **In Date:** 10/21/2019 **Closed:** 11/02/2019
Problem: P.M. service.

Work Completed

- P.m. service.
- Resurface both rear brake rotors and service calipers . Replace brake pads .
Flush and bleed brake system . Road test .
- Balance and rotate all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Napagold Air Filter	1.00
22" Wiper Blade	2.00
Brake Pad	1.00
Shop Supplies	1.00

Hours: 6.50

Comm: 0.00

Labor: 474.50 Parts: 129.96 Total: 604.46

Work Order: 1913147 **Meter:** 38815 **In Date:** 12/30/2019 **Closed:** 01/08/2020
Problem: Have to jump start in A.M. .

Work Completed

- Charge battery fully . Test battery and charging system . Battery failed load
test . R&r defective battery . Hook up Ids to reset Bsm .
- Shop Supplies

Parts Issued

Quantity

Battry Motorcraft	1.00
Shop Supplies	1.00

Hours: 1.50

Comm: 0.00

Labor: 109.50 Parts: 180.69 Total: 290.19

1/28/2026
2:18:46 PM

Palm Beach County Fleet Management Asset Maintenance History
10202146 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 2105240 **Meter:** 48795 **In Date:** 05/11/2021 **Closed:** 05/14/2021
Problem: PM

Work Completed

- Preventive Maint. Service
- Replaced Cabin Air Filter
- Mount Balance 4 New Tires
- Wash Vehicle And Clean Engine Compartment
- Recharged And Test Battery Has Bad Cell...replaced Battery
- Shop Supplies

Parts Issued

Quantity

22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Napa Quart 5w20	7.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Cabin Air Filter	1.00
245/70/17 Tire Mich	4.00
Battry Motorcraft	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 6.50

Comm: 0.00

Labor: 474.50

Parts: 1,388.40

Total: 1,862.90

Work Order: 2108293 **Meter:** 53840 **In Date:** 08/02/2021 **Closed:** 08/10/2021
Problem: PM Service. Wipers stay on low.

Work Completed

- Preventive Maint. Service
- Diagnose wiper stays on, perform pinpoint test & found bad multifunction switch. replace multi function switch & test operation.
- Clean steering wheel & install cover.
- Plug/patch right front tire, fill all tires with nitrogen, balance, rotate & reset Tpms.
- Shop Supplies

Parts Issued

Quantity

Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Napa Quart 5w20	7.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
Steering Wheel Cover Large	1.00
Wiper Switch	1.00
Shop Supplies	1.00

Hours: 6.00

Comm: 0.00

Labor: 438.00

Parts: 109.11

Total: 547.11

1/28/2026
2:18:47 PM

Palm Beach County Fleet Management Asset Maintenance History
10202146 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 2305277 **Meter:** 68812 **In Date:** 05/26/2023 **Closed:** 06/14/2023

Problem: PM Service. Send for Detail.

Work Completed

- Preventive Maint. Service
- R & L cabin filter and clean fresh air intake
- Check & replace left side tail light bulb
- Rotate and speed balance, nitro fill
- Pressure test cooling system, leaking water pump, R & new water pump asm, R & i water pumpi serp belt R & L thermostat housing asm, R & L a/c belt, flush coolant
- Inspect all brakes, R & L new rear brakes, Resurface both rotors, service caliper slide pins, burnish rotors on road test
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Mac Wite Lithium Gres	1.00
Used Fire X Refurbished	1.00
Cabin Air Filter	1.00
Gasket	1.00
Coolent	2.00
Boxed Miniatures	1.00
Non-chlor Brake Clnr	1.00
Brake Pad	1.00
Coolent	2.00
Gasket	1.00
Water Pump Asy	1.00
Belt	1.00
Thermostat Housing Assembly	1.00
Belt	1.00
Coolent	2.00
Shop Supplies	1.00

Hours: 13.80

Comm: 0.00

Labor: 1,007.40

Parts: 540.87

Total: 1,548.27

Work Order: 2305579

Meter: 68756

In Date: 06/06/2023 **Closed:** 06/06/2023

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued WO: 2305277 for: ashley elbers

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2305277 for: ashley elbers

Hours: 0.00

Comm: 90.40

Labor: 0.00

Parts: 0.00

Total: 90.40

1/28/2026
2:18:47 PM

Palm Beach County Fleet Management Asset Maintenance History
10202146 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 2310066 **Meter:** 73706 **In Date:** 10/03/2023 **Closed:** 10/16/2023
Problem: PM Service. Send for Detail.,Left tail light full of water

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Rotate and speed balance, nitro fill
- Check and R & i two new tail lamp asm, cracked lens Fabricate and reinstall both sides strobe lights
- R & i two broken utility tool box shocks Fabricate and reinstall missing shocks holding bracket, adjust lid to close
- Check all, R & i new front brakes, Resurface both rotors, service caliper slide pins, bleed brakes, burnish , Road test
- Shop Supplies

Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Brake Pad	1.00
Non-chlor Brake Clnr	1.00
Support	2.00
Lamp Assy	1.00
Lamp Assy	1.00
Shop Supplies	1.00

Hours: 8.80 Comm: 0.00 Labor: 642.40 Parts: 275.93 Total: 918.33

Work Order: 2401646 **Meter:** 75591 **In Date:** 02/13/2024 **Closed:** 02/20/2024
Problem: Towed in for wont start, hood up keys inside vehicle. located on S side of car wash

Work Completed

Parts Issued

Quantity

- Charge battery fully . Test battery and charging system , Ok . Perform draw test .08 amps . Rewire light bar controller to ignition power and retest . .003 amps from Gps normal Gps draw .
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 2.65 Total: 75.65

Work Order: 2401895 **Meter:** 75591 **In Date:** 02/13/2024 **Closed:** 02/21/2024
Problem: wont start, hood up keys inside vehicle. located on S side of car wash

Work Completed

- Tow From: 8100 Foresthill, water utilities To: fleet vista Lv shop

Hours: 0.00 Comm: 124.30 Labor: 0.00 Parts: 0.00 Total: 124.30

1/28/2026
2:18:47 PM

Palm Beach County Fleet Management Asset Maintenance History
10202146 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 2412069 **Meter:** 85009 **In Date:** 12/26/2024 **Closed:** 12/27/2024
Problem: PM Service.Towed in for Right front tire flat.

Work Completed

- Perform Pm Service
- Replace right front tire.replace bad Tpms sensor left rear.rotate,balance and nitrogen fill all tires.reset Tpms.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	6.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
245/70r17xl Mich Def Ltx	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 4.00

Comm: 0.00

Labor: 292.00

Parts: 267.87

Total: 559.87

Work Order: 2500160 **Meter:** 85349 **In Date:** 12/23/2024 **Closed:** 01/07/2025
Problem: Tow-Flat tire Right front.

Work Completed

- Tow From: 10995 Hagen Ranch Rd, Boynton Beach 33437 To: 13026 S Jog Rd, Delray Beach 33446

Hours: 0.00

Comm: 118.80

Labor: 0.00

Parts: 0.00

Total: 118.80

1/28/2026
2:18:47 PM

Palm Beach County Fleet Management Asset Maintenance History
10202146 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 2503266

Meter: 89564

In Date: 04/08/2025 **Closed:** 04/14/2025

Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Ac Fan Load .clean Debris From Air Cowl System And Replaced Clogged Cabin Filter
- Mount 2 New Rear Tires. Replaced Both Left Side Tpms Sensors. Rotate Balanced 4 Tires Nitro Filled To Specs. Reset Tpms System.
- Repaired And Replaced Driver's Lower Seat Cushion And Lower Seat Cover Panel
- Repaired And Serviced Toolbox Latches Lubed Pivot Points And Verified Functions.
- Diagnose Radiator Fans Run Continuously On High Speed. Use Scan Tool To Read Outputs And Found Ac Head Pressures Too High.replaced Service Valves Evac/recharge System To Specs. Cleared Memory Codes
- Road Tested To Verify Concern About Coolant Fans
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	6.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Non-chlor Brake Clnr	1.00
Cabin Air Filter	1.00
Kit Tpms Sensor	2.00
245/70r17xl Mich Def Ltx	2.00
Wd40 Spr	1.00
Pad Seat	1.00
Seat Cover Assy	1.00
Freon Sr Shop	2.00
Valve Assy	1.00
A/c Valve	1.00
A/c Valve	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 10.25

Comm: 0.00

Labor: 748.25

Parts: 993.62

Total: 1,741.87

1/28/2026
2:18:47 PM

Palm Beach County Fleet Management Asset Maintenance History
10202146 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 2507076 **Meter:** 94331 **In Date:** 07/31/2025 **Closed:** 08/13/2025
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Rotated and balanced all 4 tires. Nitrogen filled all tires.
- Diagnose oil burning smell. Found pass side valve cover to be leaking oil onto exhaust. Replaced valve cover gasket and clean excessive oil from engine.
- Perform tune up and replaced all 6 spark plugs.
- Perform decarbon service and fuel system flush
- During inspection found both front upper control arms and lower ball joints to have excessive play. R&r upper control arms and lower ball joints.
- Performed full front end alignment. test drove
- Shop Supplies

Parts Issued

Quantity

Wiper Blade	2.00
Napagold Oil Filter	1.00
Napa Quart 5w20	6.00
Non-chlor Brake Clnr	3.00
Spark Plug	6.00
Plenum Gskt Set	1.00
Motor Tune-up 16oz	1.00
Intake Cleaner Kit	1.00
Control Arm Asm	1.00
Grommet Seal	3.00
Seal Val	2.00
Val Cover Gasket	1.00
Control Arm Assy	1.00
Ball Joint	2.00
Control Arm Assy	1.00
Shop Supplies	1.00

Hours: 19.30

Comm: 0.00

Labor: 1,408.90

Parts: 695.41

Total: 2,104.31

Work Order: 2510963 **Meter:** 97192 **In Date:** 11/20/2025 **Closed:** 11/24/2025
Problem: Slow leak on the rear passenger tire

Work Completed

Parts Issued

Quantity

- Repair right rear tire, balance and nitro service.
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 2.65

Total: 75.65

1/28/2026
2:18:47 PM

Palm Beach County Fleet Management Asset Maintenance History
10202146 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 2511111 **Meter:** 97192 **In Date:** 11/26/2025 **Closed:** 12/02/2025
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 172.85

Total Labor: 12,257.55

Total Comm: 1,986.40

Total Parts: 10,451.39