

1/28/2026  
2:27:06 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10204198 2017 FORD F250 Pickup, 3/4 Ton, Crew Cab, 4X4**

---

**Total Hours: 179.80   Labor: 12,879.25   Parts: 13,396.14   Comm: 1,219.38   Charged: 27494.77**

---

**Work Order:** 1801116      **Meter:** 312      **In Date:** 01/30/2018   **Closed:** 02/05/2018  
**Problem:** pre delivery inspection

**Work Completed**

- pre delivery inspection
- wled hitch insert
- Shop Supplies

**Parts Issued**

**Quantity**

Shop Supplies 1.00

Hours: 3.00      Comm: 0.00      Labor: 180.00      Parts: 2.00      Total: 182.00

---

**Work Order:** 1806654      **Meter:** 5418      **In Date:** 06/28/2018   **Closed:** 07/12/2018  
**Problem:** P.M. service and install air horn .

**Work Completed**

- P.m. service.
- Fabricate and install airhorns and switch and pump.test system .
- Diagnose vehicle horn inop. R&r defective horns. Retest.
- Rotate and high speed balance all four tires.
- Shop Supplies

**Parts Issued**

**Quantity**

Horn Assy 1.00

Floor Mat-2pc Rub Bk 1.00

Napagold Oil Filter 1.00

Napa Quart 5w30 7.00

Used Fire X Refurbished 1.00

Ford Triton Pvc Swc 1.00

Switch 1.00

Horn 1.00

Primary Wire 8.00

Primary Wire 6.00

Fab Loom-split Poly 13.00

Fuse Holder 1.00

Horn But 1.00

Shop Supplies 1.00

Hours: 8.55      Comm: 0.00      Labor: 513.00      Parts: 200.44      Total: 713.44



1/28/2026  
2:27:06 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10204198 2018 FORD F250 Pickup, 3/4 Ton, Crew Cab, 4X4**

**Work Order:** 1907603      **Meter:** 16299      **In Date:** 07/23/2019      **Closed:** 07/30/2019  
**Problem:** P.M. service and detail.

**Work Completed**

**Parts Issued**

**Quantity**

- P.m. service.
- Replace two worn tires . Rotate and high speed balance all four tires . Nitrofill all
- Inspect and service winch .
- Shop Supplies

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
245/75/17/tire Nitiro	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 5.75      Comm: 0.00      Labor: 385.25      Parts: 623.97      Total: 1,009.22

**Work Order:** 1907725      **Meter:** 16256      **In Date:** 07/25/2019      **Closed:** 07/25/2019  
**Problem:** 1 - Detail Vehicle Wash Ticket(s) Issued

**Work Completed**

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00      Comm: 96.00      Labor: 0.00      Parts: 0.00      Total: 96.00

**Work Order:** 1911093      **Meter:** 20671      **In Date:** 10/28/2019      **Closed:** 11/02/2019  
**Problem:** P.M. service and vibration at 25-35 mph and had to jump start.

**Work Completed**

**Parts Issued**

**Quantity**

- P.m. service.
- Replace two tires . Rotate and high speed balance all four tires . Nitrofill all
- Charge battery fully . Test battery and charging system . Battery failed load test . R&r defective battery .
- Inspect and service winch .
- Shop Supplies

Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Air Fltr	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
245/75/17/tire Nitiro	2.00
Battery 65	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 6.75      Comm: 0.00      Labor: 492.75      Parts: 811.18      Total: 1,303.93









1/28/2026  
2:27:06 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10204198 2018 FORD F250 Pickup, 3/4 Ton, Crew Cab, 4X4**

---

**Work Order:** 2202685      **Meter:** 59018      **In Date:** 03/10/2022      **Closed:** 03/24/2022  
**Problem:** PM Service, also please check rear left door locks will not open from the inside or outside handle.

**Work Completed**

**Parts Issued**

**Quantity**

- Preventive Maint. Service
- rotate and balance all 4 tire nitro fill all
- release driver side rear door from lock position replace door lock indicator  
check for proper door function after repairs
- Shop Supplies

Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Used Fire X Refurbished	1.00
22" Wiper Blade	2.00
Rod Knob	1.00
Shop Supplies	1.00

Hours: 4.55      Comm: 0.00      Labor: 332.15      Parts: 66.25      Total: 398.40

---

**Work Order:** 2204088      **Meter:** 60605      **In Date:** 04/18/2022      **Closed:** 04/18/2022  
**Problem:** Right rear tire has a nail in it and leaks slow. Will drive down for repair, Thank You

**Work Completed**

**Parts Issued**

**Quantity**

- Repaired Rr tire and balance . Nitro fill all.
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 1.00      Comm: 0.00      Labor: 73.00      Parts: 2.65      Total: 75.65

1/28/2026  
2:27:06 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10204198 2018 FORD F250 Pickup, 3/4 Ton, Crew Cab, 4X4**

**Work Order:** 2207306

**Meter:** 65683

**In Date:** 07/13/2022 **Closed:** 07/28/2022

**Problem:** PM Service.(computer stand.)

**Work Completed**

- Preventive Maint. Service
- check and replaced cabin a/c filter and refresh intake air
- replaced all 4 tires and balance . Nitro fill all.
- check,pin point test and replaced defective washer pump and refill
- check ,replaced broken l/r tail assembly and reinstalled strobes light
- replaced both defective hood supports
- Diagnose engine misfire , performed major engine tune up by replaced all 16 spark plugs,8 plugs wires ,also replaced # 2 &4 coils
- performed top engine decab and injector flush also clean throttle body
- completedfront end alignment and road test
- inspect and service winch
- Fabricate and install computer stand and base
- Shop Supplies

**Parts Issued**

**Quantity**

Laptop Mount 15-19 F-series	1.00
Laptop Tray	1.00
Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
22" Wiper Blade	2.00
Cabin Air Filter	1.00
Lt 245/75/17ttr Mic	4.00
Washer Fluid Concentr	1.00
Washer Pump	1.00
Lamp Asy	1.00
Lift Support	2.00
Spark Plug Wire	8.00
Spark Plug	16.00
Motor Tune-up 16oz	1.00
Intake Cleaner Kit	1.00
Ing Coil	2.00
Coil	2.00
Laptop Mount 15-19 F-series	1.00
Laptop Tray	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 20.95

Comm: 0.00

Labor: 1,529.35

Parts: 3,302.49

Total: 4,831.84

1/28/2026  
2:27:06 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10204198 2018 FORD F250 Pickup, 3/4 Ton, Crew Cab, 4X4**

**Work Order:** 2212741      **Meter:** 72236      **In Date:** 12/20/2022      **Closed:** 01/04/2023  
**Problem:** P.M. service.

**Work Completed**

- Preventive Maint. Service
- Rotate And Balance Four Tires. Relearn Tire Sensors.
- Inspect And Service Power Winch.
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Steering Wheel Cover Large	1.00
Shop Supplies	1.00

Hours: 4.75

Comm: 0.00

Labor: 346.75

Parts: 65.06

Total: 411.81

**Work Order:** 2306061      **Meter:** 81276      **In Date:** 06/20/2023      **Closed:** 06/29/2023  
**Problem:** PM Service, please check all lights, AC system, tires, Wiper, blades

**Work Completed**

- Preventive Maint. Service completed
- balance and rotate all 4 tires . Nitro fill all.
- inspect and service winch
- check and r&r defective strobes lights switch and verify normal operation
- performed transmission service Inspect and service transmission ,flush and replaced filter . Road test .
- service transfer case and adjust to spec
- check battery,chargingn system after fully charge it fails load test,r&r defective battery abd reset bms
- performed a/c performance test,check for leak,abnormal ,but none found evacuate and recharge system ,a/c blows at 43- 44 at the vent
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Used Fire X Refurbished	1.00
22" Wiper Blade	2.00
Led Rocker Switch Round	1.00
Screen Asy	1.00
oil auto	12.00
oil auto	3.00
Battery	1.00
Freon Lv Shop 2	1.00
Shop Supplies	1.00

Hours: 12.05

Comm: 0.00

Labor: 879.65

Parts: 396.87

Total: 1,276.52



1/28/2026  
2:27:06 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10204198 2018 FORD F250 Pickup, 3/4 Ton, Crew Cab, 4X4**

---

**Work Order:** 2405956      **Meter:** 98138      **In Date:** 06/17/2024      **Closed:** 07/01/2024

**Problem:** PM Service and Front windshield has a crack in it, check engine light is on.

**Work Completed**

- Performed P.m. Service & Inspection..
- Tire Pressure Light Is On, Diagnose Tpms System. Connect Scanner, And Scan System, Found Fault Code Related To Concern Perform Pids Test & Check, Found L/r Tpms Defective, Remove & Replace Then Balance Rotate All 4 Wheels. Reset Tpms.
- Load Test Battery, Battery Test Recommended Charge, Chaged Battery Then Retst Battery Failed Bad Cells, Removed And Replaced Then Reset To Basic Settings And Check. Working As Design.
- Performed Service & Inspection On Winch.
- Removed And Replaced The Cabin Air Filter Clean A/c Vents & Check.
- Check Engne Light Is On, Connect Scan Tool And Found Fault Code P0456 Evap Related To The Concern, Perform Pids Test And Found The Evap Purge Valve Stuck Open, Removed And Replaced Then Erase Fault Code And Test Drove Vehicle. Working As Design.
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Tire Sensor	1.00
Battery	1.00
Cabin Air Filter	1.00
Valva Asy	1.00
Tire Sensor	1.00
Shop Supplies	1.00

---

Hours: 8.75      Comm: 0.00      Labor: 638.75      Parts: 432.09      Total: 1,070.84

---

**Work Order:** 2406341      **Meter:** 98144      **In Date:** 06/28/2024      **Closed:** 07/09/2024

**Problem:** replace cracked windshield

**Work Completed**

- setr up repairs & reasset
- Shop Supplies

**Parts Issued**

**Quantity**

Shop Supplies	1.00
---------------	------

---

Hours: 1.00      Comm: 423.84      Labor: 73.00      Parts: 2.65      Total: 499.49



1/28/2026  
2:27:06 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10204198 2018 FORD F250 Pickup, 3/4 Ton, Crew Cab, 4X4**

---

**Work Order:** 2507934      **Meter:** 115507      **In Date:** 08/25/2025      **Closed:** 09/05/2025  
**Problem:** PM Service

**Work Completed**

- Preventive Maint. Service
- Load test battery failed . R&i failed battery and verify repair complete.
- Found Golight in operational. Test remote batteries failed. R&i Golight remote batteries and reprogram remote.
- R&i two failed tire sensors, Rotate and balance four tires.
- Inspect and service power winch.
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Oil Filter	1.00	
Napa Quart 5w30	7.00	
Wiper Blade	2.00	
Used Fire X Refurbished	1.00	
Battery	1.00	
Elec Battery A23	1.00	
Tire Sensor	2.00	
Shop Supplies	1.00	
Labor: 529.25	Parts: 396.45	Total: 925.70

Hours: 7.25      Comm: 0.00

---

**Work Order:** 2511845      **Meter:** 118770      **In Date:** 12/22/2025      **Closed:** 12/29/2025  
**Problem:** Transition Prep Charge

**Work Completed**

- Transition Prep Charge

Hours: 2.00      Comm: 0.00

Labor: 146.00      Parts: 0.00      Total: 146.00

**Total Hours: 179.80**

**Total Labor: 12,879.25**

**Total Comm: 1,219.38**

**Total Parts: 13,396.14**