

1/28/2026
2:32:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10198326 2015 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab

Total Hours: 180.50 Labor: 12,503.00 Parts: 9,190.27 Comm: 0.00 Charged: 21693.27

Work Order: 1508800 **Meter:** 321 **In Date:** 09/02/2015 **Closed:** 09/02/2015
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection
- Make & Apply Decals. Check Fluids, Belts and Operation

Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 0.00 Total: 180.00

Work Order: 1601531 **Meter:** 2156 **In Date:** 02/12/2016 **Closed:** 02/23/2016
Problem: P.M.SERVICE, HITCH PIN

Work Completed

- pm
- rr hitch pin
- repaired open in cabinet for marker
- Shop Supplies

Hours: 5.50 Comm: 0.00

Parts Issued

Quantity

5w20 Syn Blend	8.00
Napagold Oil Filter	1.00
Lock Pin	1.00
Shop Supplies	1.00

Labor: 330.00 Parts: 39.55 Total: 369.55

Work Order: 1609498 **Meter:** 5254 **In Date:** 09/13/2016 **Closed:** 09/27/2016
Problem: P.M. Service

Work Completed

- P.m Service.
- Rotate and balance all six tires
- Shop Supplies

Hours: 5.50 Comm: 0.00

Parts Issued

Quantity

5w20 Engine Oil	8.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
Dickie Floor Mat Blk	1.00
Shop Supplies	1.00

Labor: 330.00 Parts: 76.40 Total: 406.40

1/28/2026
2:32:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10198326 2015 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab

Work Order: 1703395 **Meter:** 8179 **In Date:** 04/05/2017 **Closed:** 04/24/2017
Problem: P.M.SERVICE

Work Completed

- Pm Service.
- Rotate and balance 6 tires
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Napa Quart 5w20	7.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Shop Supplies	1.00

Hours: 5.25

Comm: 0.00

Labor: 315.00 Parts: 49.37 Total: 364.37

Work Order: 1711200 **Meter:** 10917 **In Date:** 11/14/2017 **Closed:** 11/27/2017
Problem: PM Service.Check all lights and water leak by rear windshield.

Work Completed

- Pm service.
- Replace both front tires.
- Replace strobe light lens and both rear brake light.
- Repair water leaking from third brake light cap.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	7.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
179636492 Lt245-75r17	2.00
Led Sup Mdl 44 42 Dio	2.00
Clr Rtv Silcn Sealant	1.00
40 Series Lamp	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 10.00

Comm: 0.00

Labor: 600.00 Parts: 652.16 Total: 1,252.16

1/28/2026
2:32:21 PM

Palm Beach County Fleet Management Asset Maintenance History
10198326 2015 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab

Work Order: 1900753 **Meter:** 16343 **In Date:** 01/18/2019 **Closed:** 02/19/2019
Problem: PM Service.Taglamp and reverse lamp.

Work Completed

- Pm Service.
- Charged and tested battery (failed)replace battery.service cables.clean and repaint hold down assembly.
- Replace tag lamp assembly with new hardware and rivets.replace both strobe lamp lens.reseal with silicone.replace left Led brake lamp assembly..
- Replace 6 way socket and wiring harness.secure harness under bumper and frame.
- Replace front brake pads.service rotors,calipers slides and mount.bleed system.
- Rotate and balance 6 tires.
- Vacume debris from engine compartment.
- Shop Supplies

Parts Issued

Quantity

Napa Quart 5w20	7.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Battery	1.00
Led Sup Mdl 44 42 Dio	1.00
4 Back-up Kit	2.00
License Bracket W/light	1.00
Term 8 12-10 Connectr	20.00
trailer plug	1.00
Non-chlor Brake Clnr	1.00
Front Brake Pad	1.00
Shop Supplies	1.00

Hours: 17.50

Comm: 0.00

Labor: 1,172.50 Parts: 445.49 Total: 1,617.99

1/28/2026
2:32:21 PM

Palm Beach County Fleet Management Asset Maintenance History
10198326 2015 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab

Work Order: 1909331

Meter: 19405

In Date: 09/10/2019 **Closed:** 09/16/2019

Problem: PM Service.

Work Completed

Parts Issued

Quantity

- Pm Service.
- Replace pintle pin.
- Replace both Led brake lamps.
- R/r drive shaft to inspect,no problem found.add friction modifier to reduce noise in rear differential..
- Rotate and balance six tires.
- Clean radiator core debris.
- Tighten and lube rear shackles and springs making noise.
- Computer diagnose for check engine light onpo135.send to dealer for warranty O2 sensor.
- Transport vehicle to and from dealer for replacing bank 1 upstream O2 sensor.
- Shop Supplies

Led Sup Mdl 44 42 Dio	1.00
Napagold Oil Filter	1.00
Napa Quart 5w20	7.00
Used Fire X Refurbished	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Napagold Air Filter	1.00
Pintle Pin W/clip	1.00
Led Sup Mdl 44 42 Dio	1.00
Friction Modifier	1.00
Shop Supplies	1.00

Hours: 13.50

Comm: 0.00

Labor: 904.50

Parts: 213.57

Total: 1,118.07

1/28/2026
2:32:21 PM

Palm Beach County Fleet Management Asset Maintenance History
10198326 2015 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab

Work Order: 2004431 **Meter:** 22580 **In Date:** 05/04/2020 **Closed:** 05/26/2020
Problem: PM Service.Tag lamp bracket.

Work Completed

- Pm Service.
- Replace tag lamp assembly.repaired damage wiring harness and replace blown fuse.
- Rotate and balance tires.
- Shop Supplies

Parts Issued

Quantity

Napa Quart 5w20	7.00	
Napagold Oil Filter	1.00	
Washer Fluid Concentr	1.00	
22" Wiper Blade	2.00	
Alarm	1.00	
License Bracket W/light	1.00	
Bp Fmx-lp F Mx Fuse	3.00	
Vinyl Electrical Tape	1.00	
Butt Connect	10.00	
4 Back-up Kit	1.00	
Cable Tie	1.00	
Shop Supplies	1.00	
Labor: 620.50	Parts: 142.41	Total: 762.91

Hours: 8.50

Comm: 0.00

Work Order: 2100959 **Meter:** 25320 **In Date:** 01/27/2021 **Closed:** 01/27/2021
Problem: Two flat tires

Work Completed

- repair and balance 2 flat tires
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00	
Labor: 146.00	Parts: 4.00	Total: 150.00

Hours: 2.00

Comm: 0.00

1/28/2026
2:32:21 PM

Palm Beach County Fleet Management Asset Maintenance History
10198326 2015 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab

Work Order: 2101278

Meter: 25444

In Date: 02/03/2021 **Closed:** 02/09/2021

Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Replaced right Led Brake lamp assembly
- Replaced pintle pin w/chain and hitch pin
- Replaced 6way socket and repaired wire harness
- Replaced worn decals and reflectors
- clean engine compartment
- Rotate and balance six tires.
- Shop Supplies

Parts Issued

Quantity

Used Fire X Refurbished	1.00
Napagold Oil Filter	1.00
Napa Quart 5w20	7.00
Napagold Air Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Pintle Pin W/clip	1.00
Pin W/clip 5/8 For Hitch	1.00
trailer plug	1.00
Led Sup Mdl 44 42 Dio	1.00
Shop Supplies	1.00

Hours: 10.00

Comm: 0.00

Labor: 730.00

Parts: 159.33

Total: 889.33

1/28/2026
2:32:21 PM

Palm Beach County Fleet Management Asset Maintenance History
10198326 2015 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab

Work Order: 2108822 **Meter:** 27930 **In Date:** 08/13/2021 **Closed:** 09/13/2021
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Mount 6 tires, fill with nitrogen & balance.
- Install steering wheel cover.
- C/s check engine light is on, scan & found code #p06b6, perform pinpoint test & found bad coils & plugs. Replace 2 coil, all spark plugs & wires, clean & tap threads for left rear spark plus.
- Clean fuel system, service throttle body & use lds to clear all codes.
- Test drive before & after repair to verify all repairs are complete.
- Shop Supplies

Parts Issued

Quantity

Napa Quart 5w30	7.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Lt245/75r17 Mich Defend Ltx	6.00
Steering Wheel Cover Large	1.00
Espak Plug Wire	4.00
Espak Plug Wire	1.00
Coil	1.00
Coil	1.00
Spark Plug	16.00
Intake Cleaner Kit	1.00
Shop Supplies	1.00
Tire Disposal Fee	6.00

Hours: 15.25

Comm: 0.00

Labor: 1,113.25 Parts: 1,765.66 Total: 2,878.91

Work Order: 2201717 **Meter:** 29675 **In Date:** 02/15/2022 **Closed:** 02/18/2022
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- replaced both led brake lamps and wiring harnesses
- rotate balanced 6 tires
- Shop Supplies

Parts Issued

Quantity

Used Fire X Refurbished	1.00
Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Led Sup Mdl 44 42 Dio	2.00
Shop Supplies	1.00

Hours: 6.50

Comm: 0.00

Labor: 474.50 Parts: 154.20 Total: 628.70

1/28/2026
2:32:21 PM

Palm Beach County Fleet Management Asset Maintenance History
10198326 2015 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab

Work Order: 2310555 **Meter:** 37498 **In Date:** 10/18/2023 **Closed:** 10/30/2023
Problem: dome light stay on. Battery dead. PM

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Jump Start In Wud Parking Lot Recharge /test Battery.replaced Failed Battery
- Repaired Rear Bumper Damage
- Rotate Balanced 6 Tires
- Scan Check Engine Light On. Cleared Low Voltage Codes For Abs And Bcm Modules
- Shop Supplies

Napagold Oil Filter	1.00
Napa Quart 5w20	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Battery	1.00
Shop Supplies	1.00

Hours: 9.75 Comm: 0.00 Labor: 711.75 Parts: 178.42 Total: 890.17

Work Order: 2403966 **Meter:** 39550 **In Date:** 04/22/2024 **Closed:** 05/21/2024
Problem: PM Service. A/C doesnt work. Power steering noise. Check brakes.

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Ac not working diagnose and found ac blower motor inoperative .replaced blower motor and verified repairs
- hydraulic brake booster leaking .replace brake booster and clean residue from leaks
- replaced rear brake pads serviced calipers rotors and slides.
- mount 2new tires rotate balanced 6 tires
- replaced broken pintle pin and tighten loose hitch ball
- Shop Supplies

Washer Fluid Concentr	1.00
Wiper Blade	2.00
Napagold Oil Filter	1.00
Napa Quart 5w20	7.00
Used Fire X Refurbished	1.00
Blower Motor	1.00
Non-chlor Brake Clnr	3.00
Brakr Booster	1.00
Brake Pad Set	1.00
Tire Lt245/75/17 Mich	2.00
Pintle Pin W/clip	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 12.75 Comm: 0.00 Labor: 930.75 Parts: 1,170.69 Total: 2,101.44

1/28/2026
2:32:21 PM

Palm Beach County Fleet Management Asset Maintenance History
10198326 2015 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab

Work Order: 2406472 **Meter:** 40380 **In Date:** 07/05/2024 **Closed:** 07/26/2024

Problem: PROBLEM WITH THE BRAKES WHEN TOWING HARD TO STOP

Work Completed

- Brakes hard to stop when towing . verified trailer brake module is working correctly. May have issues with trailer brakes not working on trailer.
- Replaced Evaporator Core, Drier, Blower Motor Speed Controll Module,and Evac/recharge System
- Shop Supplies

Parts Issued

Quantity

Evaporator Core	1.00
accumulator	1.00
A/c Resistor	1.00
Freon Sr Shop	2.00
Seal Kits	2.00
Shop Supplies	1.00

Hours: 13.00

Comm: 0.00

Labor: 949.00

Parts: 527.78

Total: 1,476.78

Work Order: 2501016

Meter: 42244

In Date: 01/31/2025 **Closed:** 02/14/2025

Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Fill tires with nitrogen, balance & rotate tires.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	7.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Napagold Air Filter	1.00
Shop Supplies	1.00

Hours: 5.25

Comm: 0.00

Labor: 383.25

Parts: 55.87

Total: 439.12

1/28/2026
2:32:21 PM

Palm Beach County Fleet Management Asset Maintenance History
10198326 2015 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab

Work Order: 2509622 **Meter:** 45110 **In Date:** 10/10/2025 **Closed:** 10/21/2025
Problem: PM Service.

Work Completed

- Pm Service.
- mount balanced 6 tires nitro filled to specs and reset tpms
- recharged and tested battery. replaced failed battery serviced hardware and battery tray
- replaced worn gas cap
- straighten damaged rear bumper
- replaced both led brake lamps
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	7.00
Wiper Blade	2.00
Washer Fluid Concentr	1.00
Napagold Air Filter	1.00
Steering Wheel Cover Large	1.00
Used Fire X Refurbished	1.00
Tire Lt245/75/17 Mich	6.00
Battery	1.00
Led Sup Mdl 44 42 Dio	2.00
Cap Gas Assy	1.00
Shop Supplies	1.00
Tire Disposal Fee	6.00

Hours: 9.25

Comm: 0.00

Labor: 675.25

Parts: 2,311.39

Total: 2,986.64

Work Order: 2511516 **Meter:** 45636 **In Date:** 12/11/2025 **Closed:** 12/18/2025
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 0.00

Total: 146.00

Total Hours: 180.50

Total Labor: 12,503.00

Total Comm: 0.00

Total Parts: 9,190.27