

1/28/2026  
2:33:17 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10195560 2015 FORD F350 Utility Body, 14,000 Gvwr, 4X4**

---

**Total Hours: 218.75    Labor: 15,162.00    Parts: 11,414.17    Comm: 175.30    Charged: 26751.47**

---

**Work Order:** 1500944      **Meter:** 359      **In Date:** 01/27/2015    **Closed:** 01/27/2015  
**Problem:** 1061 - Pre Delivery Inspection

**Work Completed**

- Pre Delivery Inspection
- Travel time

Hours: 4.00      Comm: 0.00      Labor: 240.00      Parts: 0.00      Total: 240.00

---

**Work Order:** 1501041      **Meter:** 359      **In Date:** 01/28/2015    **Closed:** 02/10/2015  
**Problem:** install pump meter

**Work Completed**

- Installed pump meter, fuel filter and fuel hose and nozzle
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Fuel Filter      1.00  
Gallon Meter 3 4 In      1.00  
Shop Supplies      1.00

Hours: 3.00      Comm: 0.00      Labor: 180.00      Parts: 293.20      Total: 473.20

---

**Work Order:** 1501606      **Meter:** 565      **In Date:** 02/12/2015    **Closed:** 02/13/2015  
**Problem:** Floor Matts

**Work Completed**

- Floor Matts

**Parts Issued**

**Quantity**

Floor Mat-2pc Rub Bk      1.00

Hours: 0.00      Comm: 0.00      Labor: 0.00      Parts: 27.69      Total: 27.69

---

**Work Order:** 1505301      **Meter:** 2176      **In Date:** 05/21/2015    **Closed:** 05/27/2015  
**Problem:** RF tire flat

**Work Completed**

- Tire Service Sb military N of Elm Ave - Rf tire flat

Hours: 0.00      Comm: 66.34      Labor: 0.00      Parts: 0.00      Total: 66.34

---

**Work Order:** 1507669      **Meter:** 3459      **In Date:** 07/31/2015    **Closed:**  
**Problem:** PM

**Work Completed**

- 

Hours: 0.00      Comm: 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00





1/28/2026  
2:33:17 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10195560 2015 FORD F350 Utility Body, 14,000 Gvwr, 4X4**

**Work Order:** 1707419      **Meter:** 11941      **In Date:** 07/28/2017      **Closed:** 08/03/2017  
**Problem:** P.M. service.

**Work Completed**

- P.m. service.
- Inspect and install two new tires on front,worn.rotate and high speed balance all six wheels.nitro fill all.
- Check electrical circuit to left rear upper strobe lamp,inop.fabricate and restring harness.
- Inspect and service Aps auxiliary fuel system.
- Perform complete wheel front alignment.road test.
- Shop Supplies

**Parts Issued**

**Quantity**

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Napagold Air Filter	1.00
179636492 Lt245-75r17	2.00
Vtx609c Led Strobe Cl	1.00
Napagold Fuel Filter	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 11.00

Comm: 0.00

Labor: 660.00      Parts: 686.43      Total: 1,346.43

**Work Order:** 1804169      **Meter:** 16878      **In Date:** 04/20/2018      **Closed:** 04/25/2018  
**Problem:** PM Service

**Work Completed**

- P.m. service.
- Perform service and inspection on auxiliary fuel tank.
- Diagnose right rear strobe inop.r&r defective strobe and fabricate new strobe mount. Wire as needed.
- Mount four new tires .rotate and balance all six tires. Nitrofill.
- Shop Supplies

**Parts Issued**

**Quantity**

5w20 Engine Oil	7.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Mac Wite Lithium Gres	1.00
Vtx609c Led Strobe Cl	1.00
Napagold Oil Filter	1.00
179636492 Lt245-75r17	4.00
Napagold Fuel Filter	1.00
Shop Supplies	1.00

Hours: 9.00

Comm: 0.00

Labor: 540.00      Parts: 1,051.25      Total: 1,591.25





1/28/2026  
2:33:17 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10195560 2015 FORD F350 Utility Body, 14,000 Gvwr, 4X4**

**Work Order:** 1908732

**Meter:** 24780

**In Date:** 08/21/2019 **Closed:** 08/29/2019

**Problem:** Right rear tire flat. P.M. service.

**Work Completed**

**Parts Issued**

**Quantity**

- Replace damaged right rear outside tire and balance . Nitrofill all tires .

179636492 Lt245-75r17

1.00

- P.m. service.

22" Wiper Blade

2.00

- Inspect and service aux fuel tank . Replace dry rotten fuel hose from pump to hose reel .

Washer Fluid Concentr

1.00

5w20 Engine Oil

8.00

- Resurface both front brake rotors and service calipers . Replace brake pads . Flush and bleed system . Road test .

Napagold Oil Filter

1.00

Hose

1.00

- Rotate and balance all six tires . Nitrofill all .

Napagold Fuel Filter

1.00

- Shop Supplies

Non-chlor Brake Clnr

1.00

B Fluid Dot 3-32oz

1.00

Front Brake Pad

1.00

Used Fire X Refurbished

1.00

Shop Supplies

1.00

Tire Disposal Fee

1.00

Hours: 12.50

Comm: 0.00

Labor: 837.50

Parts: 451.72

Total: 1,289.22



1/28/2026  
2:33:17 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10195560 2015 FORD F350 Utility Body, 14,000 Gvwr, 4X4**

**Work Order:** 2012623      **Meter:** 33268      **In Date:** 12/17/2020      **Closed:** 12/23/2020  
**Problem:** Dist.1 Steve Ambrose, truck is over due for PM

**Work Completed**

- Preventive Maint. Service
- check ,r@r defective trailer plug and fabricated wires as needed
- inspect and service auxiliary fuel tank
- service transfer case
- check try to service rusted vise but would not operate as design , so drilled 4 new holes and installed new vise
- found leaking left rear . R&r defective left rear axle seal , remove rear brake pads to inspect and clean ,top off fluid . Clean area .
- rotate and balance all six tires . Nitro fill all
- Shop Supplies

Hours: 13.50

Comm: 0.00

**Parts Issued**

**Quantity**

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
22" Wiper Blade	2.00
trailer plug	1.00
Napagold Fuel Filter	1.00
oil auto	3.00
Hd Workshop Vise	1.00
Seal	1.00
Axle Gasket	1.00
Shop Supplies	1.00

Labor: 985.50

Parts: 345.40

Total: 1,330.90

**Work Order:** 2100546      **Meter:** 33640      **In Date:** 01/14/2021      **Closed:** 01/20/2021  
**Problem:** Storm Water Steve, the light bar lights will not turn off

**Work Completed**

- Test and disassembly light bar to Replace emergency light bar control board . Retest .
- Shop Supplies

Hours: 2.00

Comm: 0.00

**Parts Issued**

**Quantity**

Circuit Board - Liberty Lightbar	1.00
Shop Supplies	1.00
Freight Charge	1.00

Labor: 146.00

Parts: 519.84

Total: 665.84

**Work Order:** 2101354      **Meter:** 34124      **In Date:** 02/04/2021      **Closed:** 02/09/2021  
**Problem:** Storm Water Cody, the saddle tank fuel gauge is not wording

**Work Completed**

- Diagnose meter inop . R&r defective meter and retest .
- Shop Supplies

Hours: 1.50

Comm: 0.00

**Parts Issued**

**Quantity**

Gallon Meter 3 4 In	1.00
Shop Supplies	1.00

Labor: 109.50

Parts: 323.74

Total: 433.24



1/28/2026  
2:33:17 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10195560 2015 FORD F350 Utility Body, 14,000 Gvwr, 4X4**

---

**Work Order:** 2200723      **Meter:** 37066      **In Date:** 01/21/2022      **Closed:** 01/26/2022  
**Problem:** PM Service. will turn in tomorrow

**Work Completed**

- Preventive Maint. Service
- Replaced 2 tires. Rotated and balanced all 6 tires. Nitrogen filled all tires.
- Inspect and serviced aux fuel pump and tank.
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Oil Filter	1.00
5w20 Engine Oil	8.00
22" Wiper Blade	2.00
Lt245/75r17 Mich Defend Ltx	2.00
Napagold Fuel Filter	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 7.50

Comm: 0.00

Labor: 547.50      Parts: 474.85      Total: 1,022.35

---

**Work Order:** 2204558      **Meter:** 37816      **In Date:** 04/28/2022      **Closed:** 05/02/2022  
**Problem:** Storm Water Mike, truck has bad battery

**Work Completed**

- Charge battery fully Test battery and charging system . Battery failed load test . R&r defective battery an retest .
- Shop Supplies

**Parts Issued**

**Quantity**

Battery	1.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 73.00      Parts: 144.95      Total: 217.95

1/28/2026  
2:33:17 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10195560 2015 FORD F350 Utility Body, 14,000 Gvwr, 4X4**

**Work Order:** 2207680      **Meter:** 38739      **In Date:** 07/22/2022      **Closed:** 07/27/2022  
**Problem:** PM Service.

**Work Completed**

- Preventive Maint. Service
- Mount Two New Tires, Nitrogen Fill, Rotate And Balance Six.
- R&r Six Worn Front And Rear Body Mounts.
- Service Auxilary Fuel Tank And R&r Cracked Fuel Transfer Hose.
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Steering Wheel Cover Large	1.00
Lt245/75r17 Mich Defend Ltx	2.00
Body Mount Kit	4.00
Body Mount Kit	2.00
3/4" X 12 ' Hardwall UI330&ulc	1.00
Napagold Fuel Filter	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 14.00

Comm: 0.00

Labor: 1,022.00

Parts: 1,123.45

Total: 2,145.45

**Work Order:** 2300436      **Meter:** 40624      **In Date:** 01/13/2023      **Closed:** 01/19/2023  
**Problem:** PM Service. Storm Water Mike , and saddle tank filter needs changing

**Work Completed**

- Preventive Maint. Service
- rotate and balance all 6 tires nitro fill all
- inspected and service saddle tank. Test operation .
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Mac Wite Lithium Gres	1.00
Napagold Fuel Filter	1.00
Shop Supplies	1.00

Hours: 6.50

Comm: 0.00

Labor: 474.50

Parts: 58.77

Total: 533.27

1/28/2026  
2:33:17 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10195560 2015 FORD F350 Utility Body, 14,000 Gvwr, 4X4**

**Work Order:** 2306610

**Meter:** 42733

**In Date:** 07/06/2023 **Closed:** 07/17/2023

**Problem:** PM Service and A/C not working

**Work Completed**

- Preventive Maint. Service
- Replaced 2 tires. Rotated and balanced all 6 tires. Nitrogen filled all tires
- Inspect and serviced aux fuel system.
- Diagnose Ac not cooling. Found evaporator core to be leaking. R&r evaporator and dryer assemblies. Recharge freon to factory spec.
- Diagnose check engine light. Code-p1289. Pinpoint test and found cylinder head temp sensor faulty. Removed intake manifold to replaced faulty temp sensor. Cleared code and test drove.
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Oil Filter	1.00
5w20 Engine Oil	8.00
22" Wiper Blade	2.00
Lt245/75r17 Mich Defend Ltx	2.00
Napagold Fuel Filter	1.00
Freon Lv Shop 2	2.00
Kit O	1.00
accumulator	1.00
Evaporator Core	1.00
Wire Assy	1.00
Tep Sensor	1.00
Gasket	1.00
Gasket	8.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 23.40

Comm: 0.00

Labor: 1,708.20

Parts: 1,062.31

Total: 2,770.51

1/28/2026  
2:33:17 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10195560 2015 FORD F350 Utility Body, 14,000 Gvwr, 4X4**

**Work Order:** 2402481

**Meter:** 45390

**In Date:** 03/08/2024 **Closed:** 03/12/2024

**Problem:** PM Service will turn in today

**Work Completed**

- Preventive Maint. Service
- Diagnose arching from cylinders number 1 and 8 ignition coils. R&r number one and eight ignition coils faulty. Run engine to verify repair complete.
- Inspect and service Auxiliary fuel system.
- R&r front hood supports falling down.
- Rotate and balance six tires. Nitro fill all.
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Mac Wite Lithium Gres	1.00
Coil	1.00
Coil	1.00
Napagold Fuel Filter	1.00
Lift Support	1.00
Lift Support	1.00
Shop Supplies	1.00

Hours: 8.80

Comm: 0.00

Labor: 642.40

Parts: 437.70

Total: 1,080.10

1/28/2026  
2:33:17 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10195560 2015 FORD F350 Utility Body, 14,000 Gvwr, 4X4**

**Work Order:** 2410283      **Meter:** 49198      **In Date:** 10/25/2024      **Closed:** 11/25/2024

**Problem:** PM Service will turn in today, Install cooler rack, Light bar light stays on killing battery.

**Work Completed**

- Preventive Maint. Service
- Rotate and speed balance all Six, nitro fill
- Perform battery analyzing, load test & charging, bad cell, R & i new battery . Cause for light bar staying on .internal short Replace circuit board in emergency light Bar
- Check all, R & i new front brakes. R & i new calipers, Resurface both Rotors, service caliper slide pins, Bleed brake system, road test
- R & i new front Bump stops
- Inspect & service Aps fuel system
- Cut old bolts, Install new cooler rack
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Battery	1.00
Non-chlor Brake Clnr	1.00
Brk Fluid Dot 4-32oz	1.00
Brake Pad	1.00
bumper	2.00
Bracketed Caliper	1.00
Bracketed Caliper	1.00
Napagold Fuel Filter	1.00
Igloo Wire Rack	1.00
Circuit Board - Liberty Lightbar	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 15.30

Comm: 0.00

Labor: 1,116.90

Parts: 1,111.88

Total: 2,228.78

**Work Order:** 2502689      **Meter:** 51633      **In Date:** 03/18/2025      **Closed:** 03/20/2025

**Problem:** 1 - Wash ticket(s) Issued to: Lo Amni Rabanales Bravo

**Work Completed**

- 1 - Wash ticket(s) Issued to: Lo Amni Rabanales Bravo

Hours: 0.00

Comm: 12.96

Labor: 0.00

Parts: 0.00

Total: 12.96

1/28/2026  
2:33:17 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10195560 2015 FORD F350 Utility Body, 14,000 Gvwr, 4X4**

**Work Order:** 2507595      **Meter:** 53731      **In Date:** 08/13/2025      **Closed:** 08/21/2025  
**Problem:** PM Service

**Work Completed**

- Preventive Maint. Service
- performed balance rotate and nitrofill, tpms relearn
- Dtc P06b6-00 perform pinpoint test. R&i intakemanifold, inspected and found knock sensor harness has high resistance, R&r knock sensor harness. R&r 4 coil packs and all 16 spark plugs
- inspect and service aps fuel system
- perform air intake decarb/cleaning and injector flush
- perform rear brakejob. R&r pads, resurface rotors, and service calipers, bleed brakes, burnish pads. road test.
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Napagold Air Filter	1.00
Used Fire X Refurbished	1.00
Coil	2.00
Coil	2.00
Napagold Fuel Filter	1.00
Intake Cleaner Kit	1.00
Brake Pad Set	1.00
Non-chlor Brake Clnr	1.00
Brk Fluid Dot 4-32oz	1.00
Spark Plug	16.00
5w20 Engine Oil	7.00
Gas Shock	1.00
Espak Plug Wire	4.00
Espak Plug Wire	4.00
Wire Assy	1.00
Int Gasket	1.00
Shop Supplies	1.00

Hours: 20.50      Comm: 0.00

Labor: 1,496.50      Parts: 1,133.43      Total: 2,629.93

**Work Order:** 2510856      **Meter:** 53947      **In Date:** 11/18/2025      **Closed:** 11/20/2025  
**Problem:** Transition Prep Charge

**Work Completed**

- Transition Prep Charge

Hours: 2.00      Comm: 0.00

Labor: 146.00      Parts: 0.00      Total: 146.00

**Total Hours: 218.75**

**Total Labor: 15,162.00**

**Total Comm: 175.30**

**Total Parts: 11,414.17**