

1/28/2026  
2:35:08 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201025 2016 FORD F350 Utility Body, 13,700 Gvwr**

---

**Total Hours: 241.75   Labor: 16,727.75   Parts: 17,878.93   Comm: 3,031.09   Charged: 37637.77**

---

**Work Order:** 1609382      **Meter:** 291      **In Date:** 09/08/2016   **Closed:** 09/08/2016  
**Problem:** 1061 - Pre Delivery Inspection

**Work Completed**

- Pre Delivery Inspection

Hours: 3.00      Comm: 0.00      Labor: 180.00      Parts: 0.00      Total: 180.00

---

**Work Order:** 1609456      **Meter:** 293      **In Date:** 09/12/2016   **Closed:** 09/19/2016  
**Problem:** tach weld hitch

**Work Completed**

- Weld hitch insert into place and paint

Hours: 0.50      Comm: 0.00      Labor: 30.00      Parts: 0.00      Total: 30.00

---

**Work Order:** 1611391      **Meter:** 4242      **In Date:** 11/03/2016   **Closed:** 01/24/2017  
**Problem:** Install pipe rack,water tank and spot light.

**Work Completed**

- Fabriczte and install pipe bin on utility bed.install water tank and floor mats.

- Fabricate and install telescopic stand in truck bed for go-light.install wiring.

- Shop Supplies

Hours: 9.00      Comm: 0.00

**Parts Issued**

**Quantity**

Water Tank & Brackets	1.00
Pole Surface Mount	1.00
Golight & Mount Kit	1.00
Pipe Bin	1.00
Stg Wheel Cov - Ford	1.00
Floor Mat-2pc Rub Bk	1.00
Fab Loom-split Poly	20.00
Shop Supplies	1.00
Freight Charge	1.00
<b>Labor: 540.00      Parts: 2,736.51      Total: 3,276.51</b>	



1/28/2026  
2:35:08 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201025 2016 FORD F350 Utility Body, 13,700 Gvwr**

---

**Work Order:** 1801341      **Meter:** 21434      **In Date:** 02/05/2018      **Closed:** 02/12/2018  
**Problem:** P.M. service and go light inop, install bin lighting.

**Work Completed**

**Parts Issued**

**Quantity**

- P.m. service.
- Replaced both front tires .rotated and balanced all six tires.nitrogen filled tires.
- Diagnose inop golight .repair wires going to light and replace blown fuse.fabricate and install bin lighting with lighted switch.
- Battery tested bad .charge battery fully .perfomed load test ,battery failed .r&r defective battery.
- Shop Supplies

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
179636492 Lt245-75r17	2.00
16.4' Waterproof Led Light Strip	1.00
Fuse Holder	1.00
Rocker Led Blk Ambe	1.00
Battery 65	1.00
Electrical Tape	1.00
Primary Wire	17.00
Primary Wire	10.00
Fab Loom-split Poly	20.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 13.50

Comm: 0.00

Labor: 810.00

Parts: 669.36

Total: 1,479.36

---

**Work Order:** 1804189      **Meter:** 24451      **In Date:** 04/20/2018      **Closed:** 04/23/2018  
**Problem:** in accident/ door wont close

**Work Completed**

- Tow From: 8100 forrest hill To: 2601 vist

Hours: 0.00

Comm: 96.00

Labor: 0.00

Parts: 0.00

Total: 96.00

---

**Work Order:** 1804889      **Meter:** 24451      **In Date:** 04/20/2018      **Closed:** 05/10/2018  
**Problem:** Damage to left front fender & door

**Work Completed**

- Damage to left front fender & door

Hours: 0.00

Comm: 2,623.18

Labor: 0.00

Parts: 0.00

Total: 2,623.18

1/28/2026  
2:35:08 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201025 2016 FORD F350 Utility Body, 13,700 Gvwr**

**Work Order:** 1807419      **Meter:** 28689      **In Date:** 07/20/2018      **Closed:** 07/30/2018  
**Problem:** PM Service.

**Work Completed**

- P.m. service.
- Resurface front brake rotors. replace front pads and service calipers . Flush and bleed brake system .
- Replace two tires and rotate and high speed balance all six tires. Nitrogen fill tires.
- Fabricate and drill new holes for new vise .install vise. Replace missing pintle pin.
- Shop Supplies

**Parts Issued**

**Quantity**

Non-chlor Brake Clnr	1.00
B Fluid Dot 3-32oz	1.00
Hd Workshop Vise	1.00
Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Napagold Air Filter	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Front Brake Pad	1.00
Tr416 Valve Stem	1.00
179636492 Lt245-75r17	2.00
Pintle Pin W/clip	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 13.50

Comm: 0.00

Labor: 810.00

Parts: 787.35

Total: 1,597.35

**Work Order:** 1808552      **Meter:** 29593      **In Date:** 08/20/2018      **Closed:** 08/29/2018  
**Problem:** P.M. Service.

**Work Completed**

- P.m. service.
- Rotate and high speed balance all six wheels . Nitrofill all.
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Shop Supplies	1.00

Hours: 5.50

Comm: 0.00

Labor: 330.00

Parts: 29.18

Total: 359.18

1/28/2026  
2:35:08 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201025 2016 FORD F350 Utility Body, 13,700 Gvwr**

**Work Order:** 1900209      **Meter:** 34546      **In Date:** 01/04/2019      **Closed:** 01/17/2019  
**Problem:** P.M. service and check engine light on .

**Work Completed**

- P.m. service.
- Replace four tires . Rotate and balance all six tires . Nitrogen fill all.
- Scan for codes ,p0302 . Perform tune up . Replace all sixteen spark plugs and wire set and number two coil.
- Perform complete air intake decarb and flush injectors .
- Computer diagnose check engine light ,p0172 and P0175 . Perform evap test . R&r defective purge valve assembly . Clear codes and retest.
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Oil Filter	1.00
Napa Quart 5w20	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Napagold Air Filter	1.00
Ford Triton Pvc Swc	1.00
Used Fire X Refurbished	1.00
Tr416 Valve Stem	4.00
Lt245/75r17 Mich Defend Ltx	4.00
Coil	1.00
Espak Plug Wire	4.00
Espak Plug Wire	4.00
Spark Plug	16.00
Pedal Pad	1.00
Intake Cleaner Kit	1.00
Injector Cleaner	1.00
Valva Asy	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 15.00

Comm: 0.00

Labor: 1,005.00

Parts: 1,631.90

Total: 2,636.90

**Work Order:** 1905637      **Meter:** 40441      **In Date:** 05/15/2019      **Closed:** 05/29/2019  
**Problem:** Passenger Rear outside tire flat

**Work Completed**

- Tire Service Croc past fuel pumps - Passenger Rear outside tire flat

Hours: 0.00

Comm: 164.35

Labor: 0.00

Parts: 0.00

Total: 164.35



1/28/2026  
2:35:08 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201025 2016 FORD F350 Utility Body, 13,700 Gvwr**

**Work Order:** 2001364

**Meter:** 47974

**In Date:** 02/07/2020 **Closed:** 02/18/2020

**Problem:** PM Service

**Work Completed**

- P.m. service.
- Replace two tires . Rotate and high speed balance all six tires . Nitrofill all.
- Resurface both rear rotors and service calipers . Replace brake pads . Flush and bleed brake system . Road test .
- Test and replace front marker light and retest .
- Replace broken pintle pin .
- Perform complete front end alignment and road test .
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Lt245/75r17 Mich Defend Ltx	2.00
Non-chlor Brake Clnr	1.00
Brk Fluid Dot 4-32oz	1.00
Brake Pad	1.00
Led M C Lamp	1.00
Pintle Pin W/clip	1.00
Napagold Air Filter	1.00
Brake Caliper	1.00
Brake Caliper	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 14.70

Comm: 0.00

Labor: 1,073.10

Parts: 844.24

Total: 1,917.34

1/28/2026  
2:35:08 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201025 2016 FORD F350 Utility Body, 13,700 Gvwr**

**Work Order:** 2008681      **Meter:** 49011      **In Date:** 08/28/2020      **Closed:** 09/24/2020  
**Problem:** PM Service, Back gate missing bolts, Go light wires, Beacon inop, Inverter inop, Trailer plug, Deta

**Work Completed**

**Parts Issued**

**Quantity**

- P.m. service.
- Replace four tires . Rotate and balance all six tires . Nitrofill all.
- Replace missing pintle pin .replace missing tailgate hinge pin and support pins . Test and replace trailer plug connector . Retest .
- Inspect and test go light . Replace go light harness , power fuse holder and battiers in remote . Test ok . Diagnose power inverter . R&r defective power inverter and remount . Replace remote switch for power inverter . Retest .
- Perform complete front end alignment and road test.
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	8.00
Lt245/75r17 Mich Defend Ltx	4.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Cap Asy	1.00
trailer plug	1.00
Pintle Pin W/clip	1.00
Cobra Inverter Remote	1.00
Power Inverter	1.00
Elec Battery A23	2.00
Go-light Harness	1.00
1500w Ower Inverter	1.00
Bolts	5.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 17.50

Comm: 0.00

Labor: 1,277.50

Parts: 1,780.97

Total: 3,058.47

**Work Order:** 2009063      **Meter:** 48682      **In Date:** 09/09/2020      **Closed:** 09/09/2020  
**Problem:** 1 - Detail Vehicle Wash Ticket(s) Issued

**Work Completed**

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00

Comm: 96.00

Labor: 0.00

Parts: 0.00

Total: 96.00

1/28/2026  
2:35:08 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201025 2016 FORD F350 Utility Body, 13,700 Gvwr**

**Work Order:** 2012422      **Meter:** 50278      **In Date:** 12/15/2020      **Closed:** 12/23/2020

**Problem:** Check engine light on and had to jump start and missing right side long bin shelf .

**Work Completed**

- Scan codes P0455, P0457, Gross leak evap, fuel cap lose. Perform evap test, perform smoke test, identify hose from canister to purge has been chewed through. Replace hose section, Retest, Pass
- Perform starting and charging system tests, battery failed charge analysis, Replace battery and retest, Gps draw indicated.
- Install used shelving and dividers.
- Shop Supplies

**Parts Issued**

**Quantity**

Purge Valve	1.00
Battery 65	1.00
Quality Htr Hose	2.00
Shop Supplies	1.00

Hours: 4.00      Comm: 0.00      Labor: 292.00      Parts: 241.45      Total: 533.45

**Work Order:** 2104994      **Meter:** 53479      **In Date:** 05/04/2021      **Closed:** 05/12/2021

**Problem:** P.M. service.

**Work Completed**

- Preventive Maint. Service
- Check all brakes, R & I new front brakes, Resurface front rotors, Service caliper slide pins bleed brakes, road test
- Repair two flat tires, Rotate and speed balance six wheels, nitro fill all
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Used Fire X Refurbished	1.00
Napagold Air Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Non-chlor Brake Clnr	1.00
Brk Fluid Dot 4-32oz	1.00
Reman/ca	1.00
Reman/ca	1.00
Front Brake Pad	1.00
Shop Supplies	1.00

Hours: 12.00      Comm: 0.00      Labor: 876.00      Parts: 387.90      Total: 1,263.90

1/28/2026  
2:35:08 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201025 2016 FORD F350 Utility Body, 13,700 Gvwr**

**Work Order:** 2108363      **Meter:** 59175      **In Date:** 08/03/2021      **Closed:** 08/10/2021  
**Problem:** PM Service.

**Work Completed**

- Preventive Maint. Service
- Rotated and balanced all 6 tires. Nitrogen filled all tires.
- Computer diagnose engine misfire .replaced all plug wires due to rodent chewing them up. Performed tune up.
- Performed decarbon service and fuel system flush.
- Diagnose fluid leak and noise. Found hydroboost to be leaking. R and R leaking hydroboost. Flushed brake fluid.
- Shop Supplies

**Parts Issued**

**Quantity**

Napa Quart 5w30	8.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Spark Plug	16.00
Espak Plug Wire	4.00
Espak Plug Wire	4.00
Intake Cleaner Kit	1.00
Injector Cleaner	1.00
Non-chlor Brake Clnr	3.00
B Fluid Dot 3-32oz	1.00
oil auto	1.00
Brake Booster	1.00
Shop Supplies	1.00

Hours: 17.00

Comm: 0.00

Labor: 1,241.00      Parts: 525.60      Total: 1,766.60

**Work Order:** 2111841      **Meter:** 60830      **In Date:** 11/02/2021      **Closed:** 11/09/2021  
**Problem:** PM Service. oil change

**Work Completed**

- Preventive Maint. Service
- rotate and balance all 6 tires nitro fill all
- replace right side mirror assembly .
- Shop Supplies

**Parts Issued**

**Quantity**

Napa Quart 5w30	8.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Mirror	1.00
Shop Supplies	1.00

Hours: 7.00

Comm: 0.00

Labor: 511.00      Parts: 317.79      Total: 828.79

1/28/2026  
2:35:08 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201025 2016 FORD F350 Utility Body, 13,700 Gvwr**

---

**Work Order:** 2201137      **Meter:** 66625      **In Date:** 02/01/2022      **Closed:** 03/17/2022  
**Problem:** PM Service.Tail lights/Running light not working.

**Work Completed**

- Preventive Maint. Service
- Replace & rewire center rear marker light bar. Diagnose spot light is not working, perform pinpoint test & found blown fuse, replace fuse & test operation. Diagnose tail lights is not working, perform pinpoint test, found & replace blown fuse.
- Replace both washer nozzle washer nozzle
- Trailer charging circuit is not working, perform pinpoint test, found & replace blown fuse. Replace pintle pin.
- Fill all tires with nitrogen, balance & rotate.
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Led Id Bar 6 Ctrs	1.00
Washer Nozzle	2.00
Pintle Pin W/clip	1.00
Shop Supplies	1.00

Hours: 8.50      Comm: 0.00      Labor: 620.50      Parts: 102.02      Total: 722.52

---

**Work Order:** 2203596      **Meter:** 68410      **In Date:** 04/01/2022      **Closed:** 04/06/2022  
**Problem:** Battery is dead

**Work Completed**

- jump start in wud parking lot tes. Fully charge and load test battery. Battery failed load test.replaced failed Battery. Reset Bms.
- Shop Supplies

**Parts Issued**

**Quantity**

Battery	1.00
Shop Supplies	1.00

Hours: 1.00      Comm: 0.00      Labor: 73.00      Parts: 119.98      Total: 192.98

---

**Work Order:** 2203718      **Meter:** 69358      **In Date:** 04/06/2022      **Closed:** 04/27/2022  
**Problem:** Running light problem

**Work Completed**

- Diagnose running lights not working, trace wire harness & found damage wire harness on drive shaft & blown fuse. Repair wire harness, tie up off drive shaft & replace blown fuse. Lights okay.
- Test drive after repair & verify all repairs are complete. Wiring harness is secure.
- Shop Supplies

**Parts Issued**

**Quantity**

Shop Supplies	1.00
---------------	------

Hours: 2.50      Comm: 0.00      Labor: 182.50      Parts: 2.65      Total: 185.15

1/28/2026  
2:35:08 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201025 2016 FORD F350 Utility Body, 13,700 Gvwr**

**Work Order:** 2210373      **Meter:** 74027      **In Date:** 10/07/2022      **Closed:** 12/02/2022  
**Problem:** PM Service. Light bar. Tires

**Work Completed**

- Preventive Maint. Service
- Replace all 6 tires, fill with nitrogen & balance.
- Diagnose light bar & found bad lod board, replace lod board & check operation.
- Replace pintle pin
- Shop Supplies

**Parts Issued**

**Quantity**

Washer Fluid Concentr	1.00
22" Wiper Blade	1.00
Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Used Fire X Refurbished	1.00
Napagold Air Filter	1.00
Pintle Pin W/clip	1.00
Lt245/75r17 Mich Defend Ltx	6.00
I/o Board - Liberty li	1.00
Shop Supplies	1.00
Tire Disposal Fee	6.00
Freight Charge	1.00

Hours: 9.25

Comm: 0.00

Labor: 675.25      Parts: 2,110.24      Total: 2,785.49

**Work Order:** 2303515      **Meter:** 78465      **In Date:** 04/07/2023      **Closed:** 04/13/2023  
**Problem:** Truck wont start and wrench light came on.

**Work Completed**

- C/s wont start, diagnose & found bad battery. Replace battery.
- Air bag light is on, scan & found code B0001, send to the Dealer for warranty.
- Shop Supplies

**Parts Issued**

**Quantity**

Battery	1.00
Shop Supplies	1.00

Hours: 2.00

Comm: 0.00

Labor: 146.00      Parts: 127.97      Total: 273.97



1/28/2026  
2:35:08 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201025 2016 FORD F350 Utility Body, 13,700 Gvwr**

**Work Order:** 2308936      **Meter:** 82495      **In Date:** 09/01/2023      **Closed:** 09/19/2023  
**Problem:** PM Service.

**Work Completed**

- Preventive Maint. Service
- rotate balanced 6 tires
- replace both washer nozzles and steering wheel cover
- removed debris from radiator and ac condensers to cool properly
- Replaced both front calipers. Replaced front and rear brake pads. Serviced rotors calipers slides and bleed system.
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Napagold Air Filter	1.00
Steering Wheel Cover Large	1.00
Washer Jet	1.00
Front Brake Pad	1.00
Brake Pad Set	1.00
Non-chlor Brake Clnr	3.00
Brake Fl-dot 3-4 32oz	1.00
Brake Caliper	1.00
Brake Caliper	1.00
Shop Supplies	1.00

Hours: 15.00

Comm: 0.00

Labor: 1,095.00

Parts: 455.65

Total: 1,550.65

**Work Order:** 2312040      **Meter:** 84218      **In Date:** 12/04/2023      **Closed:** 12/21/2023  
**Problem:** Wont start. Recall

**Work Completed**

- Jump start, fully recharge battery, check battery & charging system & found bad alternator, replace alternator.
- Recall: Safety Recall 22s35 Dust contamination in clockspring causing air bag light.
- Remove wheel & replace leaking windshield washer reservoir hose.
- Shop Supplies

**Parts Issued**

**Quantity**

Alternator Assy	1.00
Hose	1.00
Washer Fluid Concentr	1.00
Shop Supplies	1.00

Hours: 4.00

Comm: 0.00

Labor: 292.00

Parts: 394.36

Total: 686.36





1/28/2026  
2:35:08 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201025 2016 FORD F350 Utility Body, 13,700 Gvwr**

**Work Order:** 2506156      **Meter:** 97169      **In Date:** 07/02/2025      **Closed:** 07/30/2025  
**Problem:** PM Service.

**Work Completed**

- Preventive Maint. Service
- Diagnose engine is engine vibration & ck engine light is on, found P0302, perform pinpoint test, found broken rocker arm roller # 2 cylinder. Replace right side exhaust rocker arm assembly. remove air filter housing & replace arcing coil # 6 cylinder
- Replace both worn hood support
- Remove right front fender well, replace leaking heater core hoses & bleed air from cooling system.
- Plug/patch right rear outer tire, fill all tires with nitrogen, balance & rotate.
- Test drive after repair to verify vehicle operate as designed.
- Jump start vehicle from Wud parking lot, fully recharge & test battery, battery is ok at this time.
- Shop Supplies

**Parts Issued**

**Quantity**

Washer Fluid Concentr	1.00
Wiper Blade	2.00
Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
Napagold Air Filter	1.00
Non-chlor Brake Clnr	2.00
Arm Assy	1.00
Valve Assy	1.00
Valve Cover Gasket	1.00
Coil	1.00
Lift Support	1.00
Lift Support	1.00
Heater Hose	1.00
Heater Hose	1.00
Coolent	1.00
Shop Supplies	1.00

Hours: 15.50

Comm: 0.00

Labor: 1,131.50

Parts: 623.52

Total: 1,755.02

**Work Order:** 2510648      **Meter:** 97337      **In Date:** 11/12/2025      **Closed:** 11/14/2025  
**Problem:** Truck needs a jump

**Work Completed**

- Jumpstart vehicle from Wud parking lot, fully recharge & teat battery, battery & charging is ok at this time.
- Shop Supplies

**Parts Issued**

**Quantity**

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 2.65

Total: 75.65

1/28/2026  
2:35:08 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201025 2016 FORD F350 Utility Body, 13,700 Gvwr**

---

**Work Order:** 2510745      **Meter:** 97337      **In Date:** 11/14/2025      **Closed:** 11/24/2025  
**Problem:** Transition Prep Charge

**Work Completed**

- Transition Prep Charge

Hours: 2.00      Comm: 0.00      Labor: 146.00      Parts: 0.00      Total: 146.00

**Total Hours: 241.75**

**Total Labor: 16,727.75**

**Total Comm: 3,031.09**

**Total Parts: 17,878.93**