

1/28/2026
2:47:43 PM

Palm Beach County Fleet Management Asset Maintenance History
10200829 2016 FORD F450 Utility Body, 16,500 Gvwr, Heavy Duty Crane

Total Hours: 390.90 Labor: 27,456.30 Parts: 33,226.88 Comm: 17,230.77 Charged: 77913.94

Work Order: 1607715 **Meter:** 335 **In Date:** 07/28/2016 **Closed:** 08/01/2016
Problem: fill def tank

Work Completed

Parts Issued

Quantity

- Fill Def. Def Quart 3.00
Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 4.64 Total: 4.64

Work Order: 1607753 **Meter:** 335 **In Date:** 07/29/2016 **Closed:** 07/29/2016
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection
Hours: 4.00 Comm: 0.00 Labor: 240.00 Parts: 0.00 Total: 240.00

Work Order: 1608585 **Meter:** 1468 **In Date:** 08/18/2016 **Closed:** 09/28/2016
Problem: spot light and tool box

Work Completed

Parts Issued

Quantity

- install remote spotlight Pole Surface Mount 1.00
- install tool box on truck Golight & Mount Kit 1.00
- water test under crane. reseal box tool box 1.00
- air tires Clr Rtv Silcn Sealant 2.00
- add power inverter remote switch Cable Tie 2.00
- Shop Supplies Shop Supplies 1.00
Hours: 9.50 Comm: 0.00 Labor: 570.00 Parts: 2,560.15 Total: 3,130.15

Work Order: 1609822 **Meter:** 1381 **In Date:** 09/20/2016 **Closed:** 09/27/2016
Problem: tires

Work Completed

- 1 Tire
Hours: 0.00 Comm: 425.51 Labor: 0.00 Parts: 0.00 Total: 425.51

1/28/2026
2:47:43 PM

Palm Beach County Fleet Management Asset Maintenance History
10200829 2016 FORD F450 Utility Body, 16,500 Gvwr, Heavy Duty Crane

Work Order: 1612793
Problem: PM/ List

Meter: 5455

In Date: 12/14/2016 **Closed:** 01/12/2017

Work Completed

- pm
- pm crane
- Def
- road test
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	15.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Air Filter (gold), Air Panel	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Washer Fluid Concentr	1.00
Hw Pigmat 15x20 100ct	1.00
Napa Hydraulic Filtr	1.00
Aw68 Hydro Fluid Hydr	30.00
Def Bulk Qts	40.00
Shop Supplies	1.00

Hours: 7.00

Comm: 0.00

Labor: 420.00

Parts: 438.68

Total: 858.68

Work Order: 1703480
Problem: Tire

Meter: 9317

In Date: 04/06/2017 **Closed:** 04/25/2017

Work Completed

- replace right rear outside tire
- Shop Supplies

Parts Issued

Quantity

225/70 R19.5 New He Only	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 1.00

Comm: 0.00

Labor: 60.00

Parts: 519.40

Total: 579.40

1/28/2026
2:47:43 PM

Palm Beach County Fleet Management Asset Maintenance History
10200829 2016 FORD F450 Utility Body, 16,500 Gvwr, Heavy Duty Crane

Work Order: 1704703
Problem: pm/DEF

Meter: 10853

In Date: 05/10/2017 **Closed:** 05/25/2017

Work Completed

- pm
- pm crane
- add Def
- test run
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	15.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Air Filter (gold), Air Panel	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Non-chlor Brake Clnr	1.00
Washer Fluid Concentr	1.00
Napa Hydraulic Filtr	1.00
Aw68 Hydro Fluid Hydr	2.00
Def Bulk Qts	22.00
Shop Supplies	1.00

Hours: 7.00

Comm: 0.00

Labor: 420.00

Parts: 188.17

Total: 608.17

1/28/2026
2:47:43 PM

Palm Beach County Fleet Management Asset Maintenance History
10200829 2016 FORD F450 Utility Body, 16,500 Gvwr, Heavy Duty Crane

Work Order: 1708340
Problem: PM

Meter: 16559

In Date: 08/24/2017 **Closed:** 09/22/2017

Work Completed

- pm
- pm crane
- def
- check lights and replace tail lights
- road test
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	15.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Air Filter (gold), Air Panel	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Washer Fluid Concentr	1.00
Napa Hydraulic Filtr	1.00
Blue Df	1.00
Led Sup Mdl 44 42 Dio	2.00
Pintle Pin W/clip	1.00
Shop Supplies	1.00

Hours: 8.50

Comm: 0.00

Labor: 510.00

Parts: 284.38

Total: 794.38

1/28/2026
2:47:43 PM

Palm Beach County Fleet Management Asset Maintenance History
10200829 2016 FORD F450 Utility Body, 16,500 Gvwr, Heavy Duty Crane

Work Order: 1802836 **Meter:** 23965 **In Date:** 03/13/2018 **Closed:** 03/15/2018
Problem: TIRES

Work Completed

- Tire Service Croc - Tires

Hours: 0.00 Comm: 347.30 Labor: 0.00 Parts: 0.00 Total: 347.30

Work Order: 1804625 **Meter:** 26748 **In Date:** 05/03/2018 **Closed:** 05/07/2018
Problem: Battery dead

Work Completed

- replace batteries check charge system. batteries dead. leaking acid from posts. clean and protect battery end cables
- check engine light on/scan codes with lap top. B1318, U3003, B11d9, clear codes after replacing battery
- test run
- Shop Supplies

Parts Issued	Quantity
Battery 65	2.00
Non-chlor Brake Clnr	3.00
Shop Supplies	1.00

Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 343.00 Total: 523.00

Work Order: 1807700 **Meter:** 27093 **In Date:** 05/24/2018 **Closed:** 07/30/2018
Problem: Damage to right side front bin doors

Work Completed

- Damage to right side front bin doors

Hours: 0.00 Comm: 2,294.40 Labor: 0.00 Parts: 0.00 Total: 2,294.40

1/28/2026
2:47:43 PM

Palm Beach County Fleet Management Asset Maintenance History
10200829 2016 FORD F450 Utility Body, 16,500 Gvwr, Heavy Duty Crane

Work Order: 1909858
Problem: PM

Meter: 37620

In Date: 09/24/2019 **Closed:** 10/23/2019

Work Completed

- pm
- crane pm
- add def
- front brakes
- rear brakes
- several test drives
- fix and weld vise handle. clean shape and weld bumper support and paint
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	15.00
Napagold Oil Filter	1.00
Air Filter (gold), Air Panel	1.00
Napagold Fuel Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Napa Hydraulic Filtr	1.00
Blue Df	2.00
Ford Original Brake Pads	1.00
Brrf65 Front Rotor Mo	2.00
Brake Caliper	1.00
Brake Caliper	2.00
Napa Oil Seal	2.00
F81z1001ba Seal Ring	2.00
B Fluid Dot 3-32oz	2.00
Permatex	1.00
Ford Original Brake Pads	1.00
Brake Caliper	1.00
Brake Caliper	1.00
Brrf3 Rear Rotor Moto	2.00
Non-chlor Brake Clnr	5.00
ridgid vise handle	1.00
Shop Supplies	1.00

Hours: 25.00

Comm: 0.00

Labor: 1,825.00

Parts: 1,745.02

Total: 3,570.02

1/28/2026
2:47:43 PM

Palm Beach County Fleet Management Asset Maintenance History
10200829 2016 FORD F450 Utility Body, 16,500 Gvwr, Heavy Duty Crane

Work Order: 2007349 **Meter:** 49001 **In Date:** 07/27/2020 **Closed:** 10/15/2020
Problem: PM

Work Completed

Parts Issued

Quantity

- pm	225/70r19	2.00
- pm crane	Washer Fluid Concentr	1.00
- test run	Wiper Blade	2.00
- def	15-40 Oil	15.00
- cut spare keys	Napagold Oil Filter	1.00
- replace rh marker light	Napagold Fuel Filter	1.00
- install wiper motor	Air Filter (gold), Air Panel	1.00
- tires	24 175 Uvb Cable Tie	1.00
- Shop Supplies	B Fluid Dot 3-32oz	1.00
	Used Fire X Refurbished	1.00
	Blue Df	2.00
	Cut Key	1.00
	Thinline Marker Amber	1.00
	Motor Asy	1.00
	Napa Hydraulic Filtr	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00

Hours: 13.00 Comm: 0.00 Labor: 949.00 Parts: 1,186.87 Total: 2,135.87

Work Order: 2007555 **Meter:** 49000 **In Date:** 07/31/2020 **Closed:** 07/31/2020
Problem: LRIO

Work Completed

- Tire Service He - Lrio

Hours: 0.00 Comm: 146.36 Labor: 0.00 Parts: 0.00 Total: 146.36

1/28/2026
2:47:43 PM

Palm Beach County Fleet Management Asset Maintenance History
10200829 2016 FORD F450 Utility Body, 16,500 Gvwr, Heavy Duty Crane

Work Order: 2012565
Problem: PM

Meter: 55524

In Date: 12/17/2020 **Closed:** 01/21/2021

Work Completed

- Preventive Maint. Service
- add def fluid
- add coolant replace upper radiator hose and coolant reservoir cap
- replace batteries and clean all corrosion on battery terminals
- pm drain change hydro filter
- replace leaking Pcv crank vent box
- replace serpentine belt and idler pulleys . also replace fan clutch
- replace batteries in accessory light remote
- rotate tires
- test drive road test
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	15.00
Napagold Oil Filter	1.00
Air Filter (gold), Air Panel	1.00
Napagold Fuel Filter	1.00
Washer Fluid Concentr	3.00
Wiper Blade	2.00
New Pig	1.00
Blue Df	1.00
Radiator Hose	1.00
Battery 65	2.00
Napa Hydraulic Filtr	1.00
Separator	1.00
Belt	1.00
Tensioner	1.00
clutch assy	1.00
Tens Pulley	2.00
Coolent	2.00
Big G Degreaser 1 Gal	1.00
Macs Chain Cable Lube	1.00
Cap Assy	1.00
Shop Supplies	1.00

Hours: 15.00

Comm: 0.00

Labor: 1,095.00

Parts: 1,530.39

Total: 2,625.39

1/28/2026
2:47:43 PM

Palm Beach County Fleet Management Asset Maintenance History
10200829 2016 FORD F450 Utility Body, 16,500 Gvwr, Heavy Duty Crane

Work Order: 2106154
Problem: PM

Meter: 60400

In Date: 06/04/2021 **Closed:** 06/17/2021

Work Completed

- Preventive Maint. Service
- out rigger foot
- added def
- crane pm and change filter
- test drive
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	15.00	
Napagold Oil Filter	1.00	
Washer Fluid Concentr	3.00	
Wiper Blade	2.00	
Air Filter (gold), Air Panel	1.00	
Napagold Fuel Filter	1.00	
Napa Hydraulic Filtr	1.00	
Used Fire X Refurbished	1.00	
30 175 Nat Cable Tie	1.00	
Non-chlor Brake Clnr	3.00	
Outrigger Mount	1.00	
Blue Df	1.00	
Shop Supplies	1.00	
Labor: 620.50	Parts: 377.25	Total: 997.75

Hours: 8.50

Comm: 0.00

1/28/2026
2:47:43 PM

Palm Beach County Fleet Management Asset Maintenance History
10200829 2016 FORD F450 Utility Body, 16,500 Gvwr, Heavy Duty Crane

Work Order: 2111518

Meter: 66139

In Date: 10/26/2021 **Closed:** 11/18/2021

Problem: PM Service.

Work Completed

- Preventive Maint. Service
- add def fluid
- pm crane
- add coolant
- diag pulling while braking. right side caliper slides seized , replace all front brakes, inspect rear brakes for functionality. no issues found.
- re apply raptor liner to bed step
- replace leaking power steering gear box.drain Psf refill and bleed system , perform test run and check for leaks.
- test drive road test x2
- diag switch light malfunction, replace switch board .
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	15.00
Napagold Oil Filter	1.00
Air Filter (gold), Air Panel	1.00
Napagold Fuel Filter	1.00
Wiper Blade	2.00
24 175 Uvb Cable Tie	1.00
30 175 Nat Cable Tie	1.00
Big G Degreaser 1 Gal	1.00
Macs Chain Cable Lube	1.00
Napa Hydraulic Filtr	1.00
Brake Pad Kit	1.00
Brake Caliper	1.00
Brake Caliper	1.00
Brrf65 Front Rotor Mo	2.00
Rapt0r Black Bedliner Kit	1.00
pit arm	1.00
Seal	2.00
steering gear box	1.00
oil auto	3.00
aux switch asy	1.00
Braking Module	1.00
Shop Supplies	1.00

Hours: 30.50

Comm: 0.00

Labor: 2,226.50

Parts: 1,828.80

Total: 4,055.30

1/28/2026
2:47:43 PM

Palm Beach County Fleet Management Asset Maintenance History
10200829 2016 FORD F450 Utility Body, 16,500 Gvwr, Heavy Duty Crane

Work Order: 2202271

Meter: 69915

In Date: 02/28/2022 **Closed:** 05/25/2022

Problem: STEERING NOISE WHEN TURN TO LEFT OR FIGHT

Work Completed

- driver states powersteering noise found fluid level low , checked for leaks found hydroboost to be leaking
- preventive maint.service
- add def
- replace batteries
- hood wont stay up replace hood shocks
- to al packer
- diagnose check engine light/replace clock spring by Al packer
- crane pm
- test drove to see for leaks none found
- Shop Supplies

Parts Issued

Quantity

Mobil Delvac 2.5 Gal	4.00
Oil Fil	1.00
Fuel Filter	1.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Motor Tune-up 16oz	1.00
Hydraulic Filter	1.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Air Filter	1.00
New Pig	1.00
Non-chlor Brake Clnr	4.00
Napa Hydraulic Filtr	1.00
Washer Fluid Concentr	3.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Blue Df	2.00
15-40 Oil	15.00
Battery	2.00
Lift Support	1.00
Lift Support	1.00
oil auto	2.00
Shop Supplies	1.00

Hours: 16.00

Comm: 369.02

Labor: 1,168.00

Parts: 1,044.21

Total: 2,581.23

1/28/2026
2:47:43 PM

Palm Beach County Fleet Management Asset Maintenance History
10200829 2016 FORD F450 Utility Body, 16,500 Gvwr, Heavy Duty Crane

Work Order: 2206321 **Meter:** 71048 **In Date:** 06/14/2022 **Closed:** 06/16/2022
Problem: LOUD NOISE IN REAR. WHEELS

Work Completed

- diag rear end noise complaint. test drive vehicle . inspect rear tires found right rear inner tire low on air. refill air pressure test for leaks no leaks found test drive vehicle again no noise found.

- Shop Supplies

Parts Issued

Shop Supplies

Quantity

1.00

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 2.65

Total: 148.65

Work Order: 2206765 **Meter:** 71534 **In Date:** 06/27/2022 **Closed:** 07/08/2022
Problem: Power Steering Noise

Work Completed

- Power steering complaint diag noise and perform road test..
- disconnect battery cables.
- remove air intake and all hoses prior to steering pump repair.
- remove cooling system hoses and radiator hose. remove cooling system fan shroud.
- remove and replace power steering pump. drain all fluid prior to removal. re insall and prime system with fluid.
- replace main serpentine belt and all idler pulleys , tensioner.
- replace fan clutch with new.
- add coolant.
- wash vehicle from power steering fluid drainage
- test drive road test x2
- add def fluid.
- Shop Supplies

Parts Issued

Power Steering Pump

Tens Pulley

Tensioner

Belt

clutch assy

Shop Supplies

Quantity

1.00

2.00

1.00

2.00

1.00

1.00

Hours: 17.00

Comm: 0.00

Labor: 1,241.00

Parts: 796.03

Total: 2,037.03

Work Order: 2207429 **Meter:** 71534 **In Date:** 06/27/2022 **Closed:** 07/15/2022
Problem: LRI flat

Work Completed

- Tire Service: H E shop Problem: Lri flat

Hours: 0.00

Comm: 95.99

Labor: 0.00

Parts: 0.00

Total: 95.99

1/28/2026
2:47:43 PM

Palm Beach County Fleet Management Asset Maintenance History
10200829 2016 FORD F450 Utility Body, 16,500 Gvwr, Heavy Duty Crane

Work Order: 2208985 **Meter:** 73428 **In Date:** 08/26/2022 **Closed:** 09/09/2022
Problem: noise when turning steering

Work Completed

- Steering, bleed out air out of power steering system,
- Found bad cable to control board slowing down hydro flow to rear cylinders, Rr cable retest system working normal operation speed.
- add def
- Shop Supplies

Hours: 5.00

Comm: 0.00

Parts Issued

	Quantity
Psf Qt	2.00
Electrical Tape	2.00
Blue Df	2.00
Shop Supplies	1.00

Labor: 365.00

Parts: 59.06

Total: 424.06

Work Order: 2209500 **Meter:** 74361 **In Date:** 09/12/2022 **Closed:** 03/08/2023
Problem: PM/STEERING NOISE/LED cab interior light please

Work Completed

- Preventive Maint. Service
- service crane. replace bad crane pendant switch inside controller. test system no issues found.
- add def
- diag noise complaint . replace brake booster/ hydroboost system. flush brake system and replace with fresh fluid. bleed brake system along with steering . test vehicle for noise complain no issues found.
- drain coolant, remove coolant resivore hoses and components prior to removal of hydro boost system .
- replace dead battery.
- Jump start and charge batteries.
- test drive road test x2
- replace interior dome lights to Led.
- Shop Supplies

Hours: 22.00

Comm: 0.00

Parts Issued

	Quantity
15-40 Oil	15.00
Napagold Oil Filter	1.00
Air Filter (gold), Air Panel	1.00
Napagold Fuel Filter	1.00
Non-chlor Brake Clnr	4.00
Big G Degreaser 1 Gal	1.00
Napa Hydraulic Filtr	1.00
Nuts	4.00
Brakr Booster	1.00
Battery	2.00
Kimball Hardware	1.00
Kitbldg Twcrnk Rplcmt	1.00
Toggle 3 Way Switch	1.00
Shop Supplies	1.00

Labor: 1,606.00

Parts: 879.41

Total: 2,485.41

1/28/2026
2:47:43 PM

Palm Beach County Fleet Management Asset Maintenance History
10200829 2016 FORD F450 Utility Body, 16,500 Gvwr, Heavy Duty Crane

Work Order: 2305078 **Meter:** 77384 **In Date:** 05/22/2023 **Closed:** 07/26/2023
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- add def
- replace rear brakes
- crane pm
- test drive
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	15.00
Napagold Oil Filter	1.00
Non-chlor Brake Clnr	4.00
Used Fire X Refurbished	1.00
Air Filter (gold), Air Panel	1.00
Fuel Filter Kit	1.00
Wiper Blade	2.00
Washer Fluid Concentr	3.00
Napa Hydraulic Filtr	1.00
B Fluid Dot 3-32oz	4.00
F81z1001ba Seal Ring	2.00
Permatex	2.00
Rear Brake Caliper	1.00
Front Brake Caliper	1.00
Brake Rotor	2.00
Brake Pads	1.00
Napa Oil Seal	2.00
Shop Supplies	1.00

Hours: 14.00

Comm: 0.00

Labor: 1,022.00

Parts: 904.12

Total: 1,926.12

Work Order: 2308716 **Meter:** 80245 **In Date:** 08/29/2023 **Closed:** 07/19/2024
Problem: recall at Ford/BAR LIGHT NOT TURNING OFF

Work Completed

-
- lightbar stuck on, pull fuse before taking to ford
- Recall: Customer Satisfaction Programs 21n02, 21n05, and 21n06 - The on-board diagnostic system may not illuminate the Malfunction Indicator Light (mil)

Parts Issued

Quantity

Radiator Hose	1.00
Thermostat	1.00
Cap Assy	1.00
Separator	1.00
Platinum Filter Kit	1.00
Syn-atf Trans Fluid S	12.00

1/28/2026
2:47:43 PM

Palm Beach County Fleet Management Asset Maintenance History
10200829 2016 FORD F450 Utility Body, 16,500 Gvwr, Heavy Duty Crane

- Recall: Emissions Recall 20e08: The Diesel Particulate Filter may develop a crack during regeneration, which may result in loss of filtration and efficiency.
- Recall: Safety Recall 22s35 Dust contamination in clockspring causing air bag light.
- Recall: Safety Recall # 22s35/22v337 Parts now available for dust contamination to clock spring air bag system
- jump start
- Preventive Maint. Service
- Add Def Fluid
- Service transmission, swap filter, drain, and refill
- Service cooling system, drain and refill coolant system
- Upon inspection found upper radiator hose to be suctioned, replace upper radiator hose, thermostat, and expansion tank cap
- Replace Ccv filter
- Upon inspection found brittle and cracking cab mounts, replace all 6
- Service hydraulic system, verify hydro fluid is full, verify functionality of crane
- Operator states, lightbar wont turn off, replace fuse and pull lightbar apart, upon replicating issue, lightbar isnt staying on, go through all functions to verify lightbar wont stay on, order new Lightbar
- Replace both batteries and brackets due to corrosion, and no start
- Road test to verify service repairs
- Upon inspection found both side markers inside of headlight to be non-functioning, replace and verify
- Upon inspection found front passenger tire to be wore unevenly, verify concern, replace both front wheels and tires due to wear and rust, lugnuts on truck are rusted, replace
- Upon inspection found stripped drain plug, replace drain plug
- Upon inspection found broken fire extinguisher bracket, replace mount bracket
- Upon inspection found leaking pto line, go to mako for replacement x2 , install, and verify line is no longer leaking
- repair oil leak by Ford

Parts Issued	Quantity
Transmission Filter	1.00
Distilled Water 1gal	3.00
Coolent	3.00
Napa Hydraulic Filtr	1.00
Battery Bracket	2.00
Battery	2.00
225/70r19.5 Mounted Gy Endurance	2.00
F75z6730ba Drain Plug	1.00
15-40 Oil	15.00
Napagold Oil Filter	1.00
Air Filter (gold), Air Panel	1.00
Fuel Filter Kit	1.00
Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Brake Parts Cleaner	4.00
Blue Sky Def 2.5gal	1.00
Insualtor	2.00
Insulator	2.00
Wheel Nut	40.00
Fire Ext Mount Strap Style	1.00
Hose Made Mako	1.00
Fittings From Mako	1.00
Liberty li Lightbar 54" Amber	1.00
Grommet Mount Kit	2.00
Fuel Filter	1.00

1/28/2026
2:47:43 PM

Palm Beach County Fleet Management Asset Maintenance History
10200829 2016 FORD F450 Utility Body, 16,500 Gvwr, Heavy Duty Crane

	Parts Issued	Quantity
- to ford 2xs	Washer Jet	1.00
- Found broken wiper sprayer, replace	Shop Supplies	1.00
- to mako	Tire Disposal Fee	2.00
- Shop Supplies	Freight Charge	1.00
Hours: 35.50	Labor: 2,591.50	Parts: 4,507.36
Comm: 4,042.59	Total: 11,141.44	

Work Order: 2408441 **Meter:** 82529 **In Date:** 08/29/2024 **Closed:** 09/27/2024

Problem: ENGINE LIGHT ON

Work Completed

	Parts Issued	Quantity
- scan / verify	Shop Supplies	1.00
- to and from ford		
- wipers / washer		
- test		
- Shop Supplies		
Hours: 5.00	Labor: 365.00	Parts: 2.65
Comm: 0.00	Total: 367.65	

Work Order: 2411175 **Meter:** 84639 **In Date:** 11/21/2024 **Closed:** 06/20/2025

Problem: ENGINE LIGHT ON / PM

Work Completed

	Parts Issued	Quantity
- Truck has check engine light, scan for codes	Battery	2.00
- Blown headlight, replace headlight bulbs, headlight marker bulbs, and side marker light	Seal	1.00
	Solenoid	1.00
- Jump start truck x2, replace batteries	Trans Filter	1.00
- Transmission problems/codes service	Solenoid	1.00
- Truck has codes for Cac Below threshold, replace Cac and hoses	Trans Pan Gasket	1.00
- Power steering leak, replace hoses + reservoir	Cooler Assy	1.00
- Replace Splash Shield	Reservoir	1.00
- pto wires hanging, rewrap loom in electrical tape and secure away from the ground	Tube - Outlet	1.00
	Hose Asy	1.00
- Preventive Maint. Service	Tube Asy	1.00
- Add Def Fluid	Hose Asy	1.00
- A/c Service		

1/28/2026
2:47:43 PM

Palm Beach County Fleet Management Asset Maintenance History
10200829 2016 FORD F450 Utility Body, 16,500 Gvwr, Heavy Duty Crane

	Parts Issued	Quantity
- Replace Ccv Filter	Tube - Outlet	1.00
- Service Crane + Replace Pto Switch	Hose	1.00
- Replace Outrigger foot	Tube Asy	1.00
- Respray front valence	Boxed Capsules	1.00
- Replace Passenger side mud flap	Amber Marker Lamp	1.00
- Replace both rear tail lights	Boxed Miniatures	2.00
- Shop Supplies	Coupling	1.00
	Deflector	1.00
	Tube Asm	1.00
	Air Filter (gold), Air Panel	1.00
	Blue Df	2.00
	Evap Odor Elinitator	1.00
	Napa Hydraulic Filtr	1.00
	Distilled Water 1gal	1.00
	Coolent	1.00
	Non-chlor Brake Clnr	4.00
	Cable Tie	1.00
	15-40 Oil	15.00
	Used Fire X Refurbished	1.00
	Napagold Oil Filter	1.00
	Fuel Filter	1.00
	Washer Fluid Concentr	1.00
	Wiper Blade	2.00
	Separator	1.00
	Bolt	1.00
	Bolt	4.00
	Gl. Blac	1.00
	Sensor Assy	1.00
	Splash Guard	1.00
	Toggle 3 Way Switch	1.00

1/28/2026
2:47:43 PM

Palm Beach County Fleet Management Asset Maintenance History
10200829 2016 FORD F450 Utility Body, 16,500 Gvwr, Heavy Duty Crane

Parts Issued	Quantity
Outrigger Mount	2.00
Led Sup Mdl 44 42 Dio	2.00
Coupling	1.00
Shop Supplies	1.00
Labor: 2,117.00	Parts: 3,446.53
Total: 5,563.53	

Hours: 29.00

Comm: 0.00

Work Order: 2504177

Meter: 84514

In Date: 04/29/2025 **Closed:** 05/02/2025

Problem: Tires: RFAI;LFAO;RFAO;LFAL; Wear. Replace Tire

Work Completed

- Tire Service: he shop Problem: Tires: Rfai;lfao;rfao;lfai; Wear. Replace Tire

Hours: 0.00

Comm: 1,562.80

Labor: 0.00

Parts: 0.00

Total: 1,562.80

Work Order: 2506523

Meter: 85961

In Date: 07/15/2025 **Closed:** 11/26/2025

Problem: Hyd. leak on wash rack/front end issues wobbles

Work Completed

- Hydraulic leak from hydraulic pressure valve + lines caused by rust, replace lines + pressure adjustment valve, including new fittings, replace main pressure and return lines, snake through frame rails over tank etc.

- Coolant leaking from secondary reservoir, replace

- Service Cooling System

- Rear Differential Leak, replace axle shaft seal, clean service and verify repair

- Rear Diff Service

- Replace Outrigger Cylinder, leaking internally, outrigger pins are suck, free pins, repaint outrigger and resecure lines, top off fluid

- To Mako

- Replace Batteries

- Check engine light, scan truck

- To Ford

- Ford repair - nox

- Upon Inspection found Worn Front End, Replace Components As Needed

- Replace Steering Wheel and Clockspring

- Replace Wheel and Tire Combo, Both Fronts

Parts Issued	Quantity
Relief Valve	1.00
Hose Assy	1.00
Coolent	2.00
Distilled Water 1gal	2.00
F81z1001ba Seal Ring	2.00
75w140 Ford Axle Lube	4.00
Px Rust Treatment 10.	1.00
Clamp	1.00
Hose Made Mako	1.00
Gl. Blac	1.00
Self Etching Primer	1.00
Gl Whit	1.00
Outrigger Cylinder	1.00
Battery	2.00
Hose	1.00
Tube Asy	1.00

1/28/2026
2:47:43 PM

Palm Beach County Fleet Management Asset Maintenance History
10200829 2016 FORD F450 Utility Body, 16,500 Gvwr, Heavy Duty Crane

	Parts Issued	Quantity
- Alignment	End Spin	1.00
- To Weber	Rod	2.00
- Extended Test Drive Due To Multiple Ford Repairs, Ford Comebacks	End Assy	2.00
- Replace Hood Struts	Draglink	1.00
- Shop Supplies	Track Bar	1.00
	Nut	1.00
	Nut	1.00
	Ball Joint	1.00
	Damper Asy	1.00
	Nut	4.00
	Steering Wheel	1.00
	Clock Spring	1.00
	Cable Tie	1.00
	225/70r19.5 Mounted Gy Endurance	2.00
	Distilled Water 1gal	3.00
	Bolt And Washer	1.00
	Parts And Service Weber Wheel	1.00
	Lift Support	2.00
	Aw68 Hydro Fluid Hydr	20.00
	White Primer	1.00
	Gl Whit	1.00
	Detent Pin	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours: 36.00	Labor: 2,628.00	Parts: 6,201.54
Comm: 1,137.83		Total: 9,967.38

1/28/2026
2:47:43 PM

Palm Beach County Fleet Management Asset Maintenance History
10200829 2016 FORD F450 Utility Body, 16,500 Gvwr, Heavy Duty Crane

Work Order: 2511559 **Meter:** 87367 **In Date:** 12/11/2025 **Closed:** 12/12/2025
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 390.90

Total Labor: 27,456.30

Total Comm: 17,230.77

Total Parts: 33,226.88