

1/28/2026
2:55:30 PM

Palm Beach County Fleet Management Asset Maintenance History
10200846 2016 TORO GRNDSMSTR 4000D Mower, 11 Ft, Riding

Total Hours: 141.00 Labor: 9,891.00 Parts: 17,500.99 Comm: 616.00 Charged: 28007.99

Work Order: 1601655 **Meter:** 1 **In Date:** 02/17/2016 **Closed:** 02/17/2016
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1702213 **Meter:** 418 **In Date:** 03/03/2017 **Closed:** 03/15/2017
Problem: pm service

Work Completed

- Pm
- Hyd Service
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Air Filter	1.00
Oil Filter	1.00
Fuel Filter	1.00
Fuel Filter	1.00
15-40 Oil	6.00
Hydraulic Filter	1.00
Napa Hydraulic Filtr	1.00
Aw68 Hydro Fluid Hydr	4.00
Shop Supplies	1.00

Hours: 5.00 Comm: 0.00 Labor: 300.00 Parts: 278.32 Total: 578.32

Work Order: 1708583 **Meter:** 663 **In Date:** 08/30/2017 **Closed:** 08/31/2017
Problem: flat tire (tire only)

Work Completed

- Replace Tire
- Shop Supplies

Parts Issued

Quantity

20x10.00x10 Multi Trac	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 144.22 Total: 204.22

1/28/2026
2:55:30 PM

Palm Beach County Fleet Management Asset Maintenance History
10200846 2016 TORO GRNDSMSTR 4000D Mower, 11 Ft, Riding

Work Order: 1805891

Meter: 856

In Date: 06/08/2018 **Closed:** 06/29/2018

Problem: hydraulic leak

Work Completed

- replace leaking hydraulic cooler/radiator assy
- clean unit of hydraulic fluid
- Shop Supplies

Hours: 5.00

Comm: 0.00

Parts Issued

Quantity

Napa Antifreeze Gal	1.00
Aw68 Hydro Fluid Hydr	25.00
Radiator Oil Cooler	1.00
Shop Supplies	1.00
Freight Charge	1.00

Labor: 300.00

Parts: 1,979.70

Total: 2,279.70

1/28/2026
2:55:30 PM

Palm Beach County Fleet Management Asset Maintenance History
10200846 2016 TORO GRNDSMSTR 4000D Mower, 11 Ft, Riding

Work Order: 1904296 **Meter:** 1186 **In Date:** 04/19/2019 **Closed:** 05/09/2019
Problem: pm service

Work Completed

- Pm Service
- Repl. tires and deck wheel
- Hydraulic service
- Repl. blades
- Wash and clean deck surface area
- Service rear differential; repl. drain plug
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Napa Fuel Filter	1.00
Fuel Filter	1.00
20x10.00x10 Multi Trac	1.00
26x12.00x12 6 Ply Mt	2.00
Caster Wheel	1.00
Napa Hydraulic Filtr	1.00
Hydraulic Filter	1.00
Blade	14.00
15-40 Oil	6.00
Aw68 Hydro Fluid Hydr	4.00
Qt Hp Gear Oil 85-140	1.00
Drain Plug	2.00
Shop Supplies	1.00
Tire Disposal Fee	3.00
Freight Charge	1.00
Freight Charge	1.00

Hours: 12.50

Comm: 0.00

Labor: 837.50

Parts: 1,427.67

Total: 2,265.17

Work Order: 1908505 **Meter:** 1346 **In Date:** 08/14/2019 **Closed:** 08/28/2019
Problem: display screen/ see notes

Work Completed

- Diag. Lcd display and replace
- Perform manual regen
- Shop Supplies

Parts Issued

Quantity

Lcd Display	1.00
Shop Supplies	1.00

Hours: 2.50

Comm: 0.00

Labor: 167.50

Parts: 549.24

Total: 716.74

1/28/2026
2:55:31 PM

Palm Beach County Fleet Management Asset Maintenance History
10200846 2016 TORO GRNDSMSTR 4000D Mower, 11 Ft, Riding

Work Order: 2108002 **Meter:** 2032 **In Date:** 07/23/2021 **Closed:** 08/25/2021
Problem: PM/ PTO issues. Thanks!

Work Completed

- Preventive Maint. Service
- Replace 7 blades
- Replace right rear tire
- Hydraulic service
- Replace all deck belts,grease spindles
- Wash equipment
- Diagnose pto issue machine showing code 3719 soot level to high perform man. regen,test mower numerous times
- Replace turnbuckles on both swing decks
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
15-40 Oil	6.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Napa Fuel Filter	1.00
Fuel Filter	1.00
Non-chlor Brake Clnr	1.00
20x10.00x10 Multi Trac	1.00
Aw68 Hydro Fluid Hydr	15.00
Napa Hydraulic Filtr	1.00
Hydraulic Filter	1.00
Deck Belt	2.00
Blade	7.00
Deck Belt	2.00
Rod End	2.00
Shop Supplies	1.00
Tire Disposal Fee	1.00
Freight Charge	1.00
Freight Charge	1.00
Freight Charge	1.00

Hours: 17.00 Comm: 0.00 Labor: 1,241.00 Parts: 760.78 Total: 2,001.78

Work Order: 2110089 **Meter:** 2062 **In Date:** 09/16/2021 **Closed:** 10/21/2021
Problem: Left wing plate loose, bent, repair

Work Completed

- Inspect Left Wing Cover, Cut Off Rusted Bolt, Installed New Nutsert Rivet, Repaired Mangled Cover And Re-installed
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 2.65 Total: 148.65

1/28/2026
2:55:31 PM

Palm Beach County Fleet Management Asset Maintenance History
10200846 2016 TORO GRNDSMSTR 4000D Mower, 11 Ft, Riding

Work Order: 2212661 **Meter:** 2304 **In Date:** 12/16/2022 **Closed:** 02/09/2023
Problem: Steering cylinder issue.

Work Completed

Parts Issued

Quantity

- Diag Hydraulic Leak, Replaced Steering Cylinder Asm, Bleed Hydraulic System
- unload equipment from trailer
- Wash Mower
- Shop Supplies

Aw68 Hydro Fluid Hydr	25.00
Steering Cyl	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 4.00 Comm: 0.00 Labor: 292.00 Parts: 1,352.47 Total: 1,644.47

Work Order: 2302468 **Meter:** 2306 **In Date:** 03/10/2023 **Closed:** 03/15/2023
Problem: Need parts: 32120-72 (x4) 3-6498 (x4) 256-76 (x8) 110-6129 (x2) 70-1160 (x8) Deck belts (x2) Will pickup. TY!

Work Completed

Parts Issued

Quantity

- secure parts for department
- Shop Supplies

Deck Belt	2.00
Bushing	8.00
Idler Arm Assembly	2.00
Bushing	8.00
Washer	4.00
Snap Ring	4.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 0.50 Comm: 0.00 Labor: 36.50 Parts: 400.30 Total: 436.80

Work Order: 2305536 **Meter:** 2356 **In Date:** 06/06/2023 **Closed:** 06/09/2023
Problem: Need some replacement caps (antifreeze tank). I will send you a photo over email.

Work Completed

Parts Issued

Quantity

- secure parts for dept
- Shop Supplies

Reservoir Cap	5.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 0.50 Comm: 0.00 Labor: 36.50 Parts: 140.25 Total: 176.75

1/28/2026
2:55:31 PM

Palm Beach County Fleet Management Asset Maintenance History
10200846 2016 TORO GRNDSMSTR 4000D Mower, 11 Ft, Riding

Work Order: 2307435 **Meter:** 2472 **In Date:** 07/27/2023 **Closed:** 08/11/2023

Problem: PM Service. Check engine light is on. Baffle replacement on underside of deck. Thanks

Work Completed

- Preventive Maint. Service
- Rf Tire Flat And Worn, Replaced Tire
- Replaced 7 Blades
- Replaced 2 Scaliping Wheels
- Battery Failed Load Test, Replaced Battery
- Replaced Reservoir Cap
- Fab And Weld Patch On Baffle
- Shop Supplies

Parts Issued

Quantity

Napa Qt 15w40	6.00
Napagold Oil Filter	1.00
Fuel Filter	1.00
Napa Fuel Filter	1.00
Napagold Air Filter	1.00
Non-chlor Brake Clnr	1.00
26x12.00-12nhs/6 Car Multi-trac	1.00
Battery	1.00
Roller	1.00
Blade	7.00
Roller	1.00
Reservoir Cap	1.00
Air Filter	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00
Freight Charge	1.00
Freight Charge	1.00

Hours: 13.00

Comm: 0.00

Labor: 949.00

Parts: 736.24

Total: 1,685.24

Work Order: 2308288 **Meter:** 2482 **In Date:** 08/18/2023 **Closed:** 08/29/2023

Problem: front deck of toro leaking

Work Completed

- relace 2 damaged hydraulic cylinders and hardware - top off system
- Shop Supplies

Parts Issued

Quantity

Pin Clevis	2.00
Hyd Cylinder	2.00
Pin	2.00
Prem Aw 68 Hyd Fl 5g	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 5.00

Comm: 0.00

Labor: 365.00

Parts: 1,485.84

Total: 1,850.84

1/28/2026
2:55:31 PM

Palm Beach County Fleet Management Asset Maintenance History
10200846 2016 TORO GRNDSMSTR 4000D Mower, 11 Ft, Riding

Work Order: 2401392 **Meter:** 2542 **In Date:** 02/07/2024 **Closed:** 02/13/2024
Problem: Need a tire and rim - 20x10.00-10 also need BOTH deck drive belts. Will send photos.

Work Completed

- Ordered Tire, Rim, And Belts For Department, Mount Tire
- Shop Supplies

Parts Issued

Quantity

Deck Belt	2.00
Tire	1.00
Rim	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 1.50

Comm: 0.00

Labor: 109.50 Parts: 369.12 Total: 478.62

Work Order: 2406563 **Meter:** 2593 **In Date:** 07/09/2024 **Closed:** 07/24/2024
Problem: pm/ hydro leak underneath/ can we change front deck cylinders. Front Driver Tire needs replaced.

Work Completed

- Preventive Maint. Service
- Ck Hydraulic Leak, Filter And Hose Were Leaking, Service Hydraulic System.
- Replace Front Tire
- Replace Asset Numbers And County Stickers
- Wash Debris From Mower For Repair And Service
- Shop Supplies

Parts Issued

Quantity

Napa Qt 15w40	6.00
Napagold Oil Filter	1.00
Napa Fuel Filter	1.00
Fuel Filter	1.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Non-chlor Brake Clnr	12.00
Napa Hydraulic Filtr	1.00
Hydraulic Filter	1.00
26x12.00-12nhs/6 Car Multi-trac	1.00
Prem Aw 68 Hyd Fl 5g	1.00
Mako Hose	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 10.00

Comm: 0.00

Labor: 730.00 Parts: 635.24 Total: 1,365.24

1/28/2026
2:55:31 PM

Palm Beach County Fleet Management Asset Maintenance History
10200846 2016 TORO GRNDSMSTR 4000D Mower, 11 Ft, Riding

Work Order: 2407315 **Meter:** 2694 **In Date:** 07/30/2024 **Closed:** 08/02/2024
Problem: Please order Two (2) Proximity Sensor for Deck Part #IGB3007BANKG. Staff will pick up when ready.

Work Completed

- deck proximity sensors
- Shop Supplies

Parts Issued

Proximity Switch	2.00
Shop Supplies	1.00
Freight Charge	1.00

Quantity

Hours: 0.00

Comm: 0.00

Labor: 0.00

Parts: 312.67

Total: 312.67

Work Order: 2410416 **Meter:** 2720 **In Date:** 10/30/2024 **Closed:** 11/05/2024
Problem: Leaking Hydraulic fluid at the right rear. Will bring in for service.

Work Completed

- Ck Hydraulic Leak, Replace Hydraulic Hose On Right Wing
- Wash Debris From Mower
- Shop Supplies

Parts Issued

Prem Aw 68 Hyd Fl 5g	1.00
Mako Hose	1.00
Shop Supplies	1.00

Quantity

Hours: 3.00

Comm: 0.00

Labor: 219.00

Parts: 236.71

Total: 455.71

Work Order: 2412247 **Meter:** 2738 **In Date:** 12/31/2024 **Closed:** 01/16/2025
Problem: Left Stabilizer Arm is bent. marked on machine

Work Completed

- Repair crank bell and replace crank bell link on left side deck.
- Shop Supplies

Parts Issued

Nut	2.00
Rod End	2.00
Tube-link	1.00
Shop Supplies	1.00
Freight Charge	1.00

Quantity

Hours: 1.50

Comm: 0.00

Labor: 109.50

Parts: 217.08

Total: 326.58

Work Order: 2504717 **Meter:** 2816 **In Date:** 05/20/2025 **Closed:** 06/18/2025
Problem: Blade deck is rusted on both sides, left mower deck bent out of alignment. two rear tires are bald.

Work Completed

- Rusted Deck And Frame Bent , Not Cost Effective To Replace
- Shop Supplies

Parts Issued

Shop Supplies	1.00
---------------	------

Quantity

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 2.65

Total: 75.65

1/28/2026
2:55:31 PM

Palm Beach County Fleet Management Asset Maintenance History
10200846 2016 TORO GRNDSMSTR 4000D Mower, 11 Ft, Riding

Work Order: 2505659 **Meter:** 2816 **In Date:** 05/19/2025 **Closed:** 06/18/2025
Problem: Tow-deck rusted, deck bent, tires bald

Work Completed

- Tow From: 5020 South Congress Maint compound To: 2601 Vista Pkwy,
West Palm Beach 33411

Hours: 0.00 Comm: 118.80 Labor: 0.00 Parts: 0.00 Total: 118.80

Work Order: 2600072 **Meter:** 2816 **In Date:** 01/06/2026 **Closed:** 01/13/2026
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 141.00 Total Labor: 9,891.00 Total Comm: 616.00 Total Parts: 17,500.99